

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b949"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f50",
    "firstName": "Vishwas Mane",
    "email": "0_default_vishwas.mane@janasevabank.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8779298387"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "423720",
    "discussWithPerson": "Vishwas Mane",
    "expectedFees": 211.86,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b949",
  "branchCode": "000002",
  "type": "BRANCH",
  "name": "Borivli (West) Branch",
  "email": "jssbl@mtnl.net.in",
  "mobileNo": "28332893",
  "alternateMobileNo": "",
  "address": "Aravali Business Centre(Phhol Mahal) Ramdas Surtale Marg Off
SOdawala Lane Boriwali (West) Mumbai 4000092",
  "ledgerName": "Janseva Sahakari Bank Borivali (W)",
  "fax": "28998842",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.423598",
  "longitude": " 72.818534"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.818534,
    19.423598
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nilemore ",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "194 & 195",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pooja Palace Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Chakradhar Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "115P & 116P",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "A/G/2",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN Code - 401 203",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nallasopara (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Window_",
    "label": "Aluminium Sliding Window "
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
}
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Vasai_Virar_City_Municipal_Corporation",
  "label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Rashmi Palace CHSL",
  "west": "Internal Road & Prathmesh Complex",
  "south": "Wing - B & Under Construction Building",
  "east": "Other Residential Building"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Part Occupancy Certificate Document No.
```

```
CIDCO / VVSR / EE (BP) / 1505 / W / 630 dated 21.07.1999 issued by CIDCO",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As per Sale Plan attached to the agreement, the composition of Residential Flat is Living Room + Kitchen + Bath + W.C. (i.e. 1RK flat). But as per Site Inspection, Kitchen area converted into Bedroom & W.C. area converted into Kitchen. At present, the composition of Residential flat is 1 Bedroom + Living Room + Kitchen + Toilet (i.e. 1BHK flat).",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "5800",
  "depreciatedBuildingRate": "2600"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "62000",
  "landRate": "18200",
  "igrImage": "cases/6644793e209fc45bb650c1bf/igr_1715842285420_Image.png",
  "squareMeterGuideLineRate": "62000.00",
  "squareFeetGuideLineRate": "5760.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "75",
  "rate": "4743.00",
  "squareFeetGuideLineRate": "4743.00",
  "squareMeterGuideLineRate": "51050.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "4,600/- Expected rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO / VVCMC norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1999",
  "fullDate": "1/1/1999"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Yes",
  "label": "Yes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "25",
"totalLifeBuilding": "60",
"estimatedAge": "35",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
```



```
"finalPlinthArea": {
  "area": "380.00",
  "areaType": "Saleable",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6644793e209fc45bb650c1bf/
routeMap_1715847005409_Image.png",
    "routeLat": "19.414391",
    "routeLng": "72.814547",
    "stationName": "Nallasopara",
    "routeDistance": "750 Mt."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "g5i3i4",
      "name": "g5i3i4",
      "image": "cases/6644793e209fc45bb650c1bf/
routeMap_1715846940090_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2204000.00",
"finalValue": "2204000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1232231.00",
  "selectedBuildUpValue": "259.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6645a35a75934e3f09c4cf06",
      "name":
"externallmg_1715839833207_WhatsApp_Image_20240516_at_94942_AM_1.jpeg",
      "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833207_WhatsApp_Image_20240516_at_94942_AM_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "6645a35a75934e3f09c4cf01",
      "name":
"externallmg_1715839833182_WhatsApp_Image_20240516_at_94940_AM_1.jpeg",
      "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833182_WhatsApp_Image_20240516_at_94940_AM_1.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4cf00",
    "name":
"externallmg_1715839833170_WhatsApp_Image_20240516_at_94939_AM.jpeg",
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833170_WhatsApp_Image_20240516_at_94939_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4cf0a",
    "name":
"externallmg_1715839833233_WhatsApp_Image_20240516_at_94944_AM_1.jpeg",
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833233_WhatsApp_Image_20240516_at_94944_AM_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4cefe",
    "name":
"externallmg_1715839833160_WhatsApp_Image_20240516_at_94936_AM.jpeg",
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833160_WhatsApp_Image_20240516_at_94936_AM.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4cefb",
    "name": "Living Room",
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833141_WhatsApp_Image_20240516_at_94932_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4ceff",
    "name": "Living Room",
```

```
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833166_WhatsApp_Image_20240516_at_94938_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4cf07",
    "name": "Living Room",
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833221_WhatsApp_Image_20240516_at_94942_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6645a35a75934e3f09c4cf08",
    "name": "Living Room",
    "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833225_WhatsApp_Image_20240516_at_94943_AM_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8064.00",
    "max": "9862.00"
  },
  "builtUpRateRange": {
    "min": "6720.00",
    "max": "7522.00"
  },
  "saleableRateRange": {
    "min": "5600.00",
    "max": "6269.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "380.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6644793e209fc45bb650c1bf",
"ownerName": "Mr. Mukeshsingh Rajusingh Bhati & Mrs. Seema Mukeshsingh Bhati",
"ownerPhoneNo": "7875867022",
"appAddress": "A/G/2 Ground floor Pooja Please Co-operative HSG Soc Ltd Village
Nilemore Nallasopara West ",
"remark": "urgent Valution ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "06/03/2006",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Sudhakar Bhalendra Pandey & Mr. Prabhakar Bhalendra Pandey",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Mukeshsingh Rajusingh Bhati & Mrs. Seema Mukeshsingh Bhati",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  },

```

```
    "Document_No": "1862/2006"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "668184",
  "path": "cases/6644793e209fc45bb650c1bf/document_1715763391407_1715763220424_Mukesh_Bhati_Janseva_Borivali_West.pdf",
  "fileName": "document_1715763391407_1715763220424_Mukesh_Bhati_Janseva_Borivali_West.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/07/1999",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO / VVSR / EE (BP) / 1505 / W / 630 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715848765276_136958.pdf",
  "path": "cases/6644793e209fc45bb650c1bf/document_1715848765276_136958.pdf",
  "id": "260028",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu May 16 2024 14:09:25 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "12/11/2008",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    }
  }
}
```

```
    },
    "purchaser": "Mr. Mukeshsingh Rajusingh Bhati & Mrs. Seema Mukeshsingh Bhati",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "27/131-135"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715848818006_65976.pdf",
  "path": "cases/6644793e209fc45bb650c1bf/document_1715848818006_65976.pdf",
  "id": "217348",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu May 16 2024 14:10:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f2",
    "label": "7/12 Extract"
  },
  "inputs": {
    "documentDate": "07/03/1996",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "N.A."
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1715848920834_50509.pdf",
  "path": "cases/6644793e209fc45bb650c1bf/document_1715848920834_50509.pdf",
  "id": "893184",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu May 16 2024 14:12:00 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "008704",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "397171",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 15 2024 14:28:38 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mr. Mukeshsingh Rajusingh Bhati & Mrs. Seema Mukeshsingh Bhati",
    "phone": "7875867022",
    "ownershipShare": "",
    "email": "",
    "id": "534531"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "701433",
    "name": "Living Room",
    "length": "15.17",
    "length1": "15",
    "length2": "2",
    "width": "8.92",
    "width1": "8",
    "width2": "11",
    "totalArea": "135.24",
    "images": [],
    "extraAreas": [],
    "finalArea": "135.24"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "6.25",
    "length1": "6",
    "length2": "3",
    "width": "7.75",
    "width1": "7",
    "width2": "9",
    "totalArea": "48.44",
```

```
"images": [],
"extraAreas": [],
"finalArea": "48.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "6.83",
  "width1": "6",
  "width2": "10",
  "totalArea": "45.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "",
  "length1": "3",
  "length2": "8",
  "width": "",
  "width1": "8",
  "width2": "4",
  "totalArea": "30.56",
  "images": [],
  "finalArea": "30.56",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Saleable",
  "squareMeterArea": "35.30",
  "totalAreaDocument": "380.00",
  "docBuiltpUpPercentage": "",
  "docFinalBuiltpUp": "0.00",
  "docFinalBuiltpUpSquareMeter": "0.00",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "379105"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "580.00",
      "squareMeterArea": "53.88",
      "expectedRate": "8620.69",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "696.00",
      "squareMeterArea": "64.66",
      "expectedRate": "7183.91",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "835.20",
      "squareMeterArea": "77.59",
      "expectedRate": "5986.59",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "6645ad95b276b73f3eb29f83",
    "property": "2 BHK Flat for sale in Pooja Palace For Sale In Nalasopara West",
    "area": "580.00",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "5000000.00",
"expectedRate": "8620.69",
"builtUpExpectedRate": "7183.91",
"image": "cases/6644793e209fc45bb650c1bf/
indicator_1715841559933_Image.png",
"squareMeter": "53.88",
"id": "828555"
},
{
"carpetArea": {
"area": "421.00",
"squareMeterArea": "39.11",
"expectedRate": "9026.13",
"percentage": ""
},
"builtUpArea": {
"area": "505.20",
"squareMeterArea": "46.93",
"expectedRate": "7521.77",
"percentage": "20"
},
"saleableArea": {
"area": "606.24",
"squareMeterArea": "56.32",
"expectedRate": "6268.14",
"percentage": "20"
},
"printInReport": true,
"_id": "6645ad95b276b73f3eb29f84",
"property": "1 BHK Flat In Devashish Buildging Nalasopar West",
"area": "421.00",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "3800000.00",
"expectedRate": "9026.13",
"builtUpExpectedRate": "7521.77",
"image": "cases/6644793e209fc45bb650c1bf/
indicator_1715841742454_Image.png",
```



```
"squareMeter": "39.11",
"id": "219813"
},
{
  "carpetArea": {
    "area": "270.00",
    "squareMeterArea": "25.08",
    "expectedRate": "8888.89",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "324.00",
    "squareMeterArea": "30.10",
    "expectedRate": "7407.41",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "388.80",
    "squareMeterArea": "36.12",
    "expectedRate": "6172.84",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6645ad95b276b73f3eb29f85",
  "property": "1 RK Flat In New Mathuresh Chs In Nala Sopara (West)",
  "area": "324",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "2400000.00",
  "expectedRate": "8888.89",
  "builtUpExpectedRate": "2400000.00",
  "image": "cases/6644793e209fc45bb650c1bf/
indicator_1715842119834_Image.png",
  "squareMeter": "30.10",
  "id": "772521"
},
{
  "carpetArea": {
    "area": "507.00",
    "squareMeterArea": "47.10",
    "expectedRate": "9861.93",
    "percentage": ""
  },
```

```
},
"builtUpArea": {
  "area": "680.00",
  "squareMeterArea": "63.17",
  "expectedRate": "7352.94",
  "percentage": ""
},
"saleableArea": {
  "area": "816.00",
  "squareMeterArea": "75.81",
  "expectedRate": "6127.45",
  "percentage": "20"
},
"printInReport": true,
"_id": "6645ad95b276b73f3eb29f86",
"property": "Pooja Palace, Wagholi, Nalasopara West",
"area": "680.00",
"builtUpPercentage": "0",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "5000000.00",
"expectedRate": "9861.93",
"builtUpExpectedRate": "5000000.00",
"image": "cases/6644793e209fc45bb650c1bf/
indicator_1715842427669_Image.png",
"squareMeter": "63.17",
"id": "955242"
},
{
  "carpetArea": {
    "area": "347.23",
    "squareMeterArea": "32.26",
    "expectedRate": "8063.82",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "416.67",
    "squareMeterArea": "38.71",
    "expectedRate": "6719.95",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "500.00",
```

```
    "squareMeterArea": "46.45",
    "expectedRate": "5600.00",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "6645c81775934e3f09c4fc40",
  "property": "Nallasopara West",
  "area": "500",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Saleable",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "2800000",
  "expectedRate": "5600",
  "builtUpExpectedRate": "6719.95",
  "image": "cases/6644793e209fc45bb650c1bf/
indicator_1715849239593_Image.png",
  "squareMeter": "46.45",
  "id": "303118"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6645a35a75934e3f09c4cefb",
    "name":
"externalImg_1715839833141_WhatsApp_Image_20240516_at_94932_AM.jpeg",
    "path": "cases/6644793e209fc45bb650c1bf/
externalImg_1715839833141_WhatsApp_Image_20240516_at_94932_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6645a35a75934e3f09c4cefc",
    "name":
"externalImg_1715839833148_WhatsApp_Image_20240516_at_94934_AM.jpeg",
    "path": "cases/6644793e209fc45bb650c1bf/
externalImg_1715839833148_WhatsApp_Image_20240516_at_94934_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6645a35a75934e3f09c4cefd",
  "name":
"externallmg_1715839833154_WhatsApp_Image_20240516_at_94935_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833154_WhatsApp_Image_20240516_at_94935_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cefe",
  "name":
"externallmg_1715839833160_WhatsApp_Image_20240516_at_94936_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833160_WhatsApp_Image_20240516_at_94936_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4ceff",
  "name":
"externallmg_1715839833166_WhatsApp_Image_20240516_at_94938_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833166_WhatsApp_Image_20240516_at_94938_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf00",
  "name":
"externallmg_1715839833170_WhatsApp_Image_20240516_at_94939_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833170_WhatsApp_Image_20240516_at_94939_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf01",
  "name":
"externallmg_1715839833182_WhatsApp_Image_20240516_at_94940_AM_1.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833182_WhatsApp_Image_20240516_at_94940_AM_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf02",
  "name":
  "externallmg_1715839833187_WhatsApp_Image_20240516_at_94940_AM_2.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833187_WhatsApp_Image_20240516_at_94940_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf03",
  "name":
  "externallmg_1715839833194_WhatsApp_Image_20240516_at_94940_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833194_WhatsApp_Image_20240516_at_94940_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf04",
  "name":
  "externallmg_1715839833198_WhatsApp_Image_20240516_at_94941_AM_1.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833198_WhatsApp_Image_20240516_at_94941_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf05",
  "name":
  "externallmg_1715839833202_WhatsApp_Image_20240516_at_94941_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833202_WhatsApp_Image_20240516_at_94941_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf06",
```

```
"name":
"externallmg_1715839833207_WhatsApp_Image_20240516_at_94942_AM_1.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833207_WhatsApp_Image_20240516_at_94942_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf07",
  "name":
"externallmg_1715839833221_WhatsApp_Image_20240516_at_94942_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833221_WhatsApp_Image_20240516_at_94942_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf08",
  "name":
"externallmg_1715839833225_WhatsApp_Image_20240516_at_94943_AM_1.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833225_WhatsApp_Image_20240516_at_94943_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf09",
  "name":
"externallmg_1715839833229_WhatsApp_Image_20240516_at_94943_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833229_WhatsApp_Image_20240516_at_94943_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf0a",
  "name":
"externallmg_1715839833233_WhatsApp_Image_20240516_at_94944_AM_1.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833233_WhatsApp_Image_20240516_at_94944_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6645a35a75934e3f09c4cf0b",
  "name":
"externallmg_1715839833243_WhatsApp_Image_20240516_at_94944_AM.jpeg",
  "path": "cases/6644793e209fc45bb650c1bf/
externallmg_1715839833243_WhatsApp_Image_20240516_at_94944_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "8704.xlsx",
  "filename": "1715850348505_8704.xlsx",
  "path": "cases/6644793e209fc45bb650c1bf/
processingDocuments/1715850348505_8704.xlsx",
  "size": "146414",
  "createdAt": "Thu May 16 2024 14:35:48 GMT+0530 (India Standard Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-15T08:58:38.035Z",
"updatedAt": "2024-05-16T10:36:51.266Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60092304a16fab0f2af9b0c2",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. A/G/2, Ground Floor, Wing - A, Pooja Palace Co-
op. Hsg. Soc. Ltd., Plot No. 194 & 195, Chakradhar Nagar, Village - Nilemore ,
Nallasopara (West), Taluka - Vasai, District - Palghar, PIN Code - 401 203, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Mukeshsingh Rajusingh Bhati",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
```

```
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "7875867022",
"buildingServicesRate": "2600",
"finalAreaType": "Saleable Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Saleable Area in Sq. Ft. = 380.00",
"flatRate": "5800",
"landOtherRate": "3200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet",
"carpetTotal": "259.8",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "311.76",
"finalCarpetArea": "259.80",
"finalSalableArea": "374.11",
"salablePercentage": "20",
"toBeAdded": "",
"extendOfSiteRemark": "",
```


"siteMeasurementRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Thu May 16 2024 13:28:54 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-05-16"
}

Name	Length	Width	Total
Composition :			
Living Room	15'2"	8'11"	135.24
Kitchen	6'3"	7'9"	48.44
Bedroom	6'8"	6'10"	45.56
Toilet	3'8"	8'4"	30.56
Other Composition :			