

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa6"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231137",
    "firstName": "Chaitali Parikh",
    "email": "0_default_andherilcb.mumbainorth@bankofindia.co.in",
    "mobileNo": "0_DEFAULT_022-6718565",
    "workMobileNo": "0_DEFAULT_91-0000000000"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa6",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "Andheri Large Corporate Branch",
  "email": "AndheriLCB.MumbaiNorth@bankofindia.co.in",
  "mobileNo": "0222671 8565",
  "alternateMobileNo": "0222671 4550",
  "address": "Bank of India, Andheri Large Corporate Branch,\r\n\r\nM.D.I. Building, First
Floor, 28, S.V.Road, Andheri (West), Mumbai - 400 058.\r\n\r\nTel: 2671 8565/4550/6790
Fax: 2624 7655\r\n\r\nIP NO.: 11705",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e2f41b6576061dae4692f3",
  "zoneName": "Mumbai North Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
}
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "12.762892967366335",
  "longitude": "77.80067882418065"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Zuzuvadi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Hosur ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "105",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ion Exchange (India) Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```

```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Standard System Division, Sipcot Industrial Complex",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "290 (pt)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```

```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```



```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 635 126",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  },
}
```

```
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00"
  },
  "outgoingDetail": {
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "isSiteVisitAllowed": true
  },
  "finalPlinthArea": {
    "area": "0.00"
  },
  "routeMap": {
    "finalLatLng": {
      "coordinates": []
    },
    "locationMapImg": []
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "664498159ab4ee3f051841f7",
"ownerName": "M/s. Ion Exchange (India) Ltd.",
"ownerPhoneNo": "7397505825",
"fullAddress": "Residential Land and Building No. Basement Floor, Ion Exchange
(India) Ltd., Standard System Division, Sipcot Industrial Complex, Plot No. 105, New/
Current Survey No. 290 (pt), Village - Zuzuvadi, District - Hosur , PIN Code - 635 126,
State - Tamil Nadu",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1715771393676_Documents_Patancheru.PDF",
  "path": "cases/664498159ab4ee3f051841f7/
document_1715771393676_Documents_Patancheru.PDF",
  "id": "843988",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Wed May 15 2024 16:40:12 GMT+0530 (India Standard Time)"
```



```
    },
    {
      "documentType": {
        "value": "60ae124eaa6d152c1801b30b",
        "label": "Other"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "fileName": "document_1715771403211_Hosar_Plan.pdf",
      "path": "cases/664498159ab4ee3f051841f7/
document_1715771403211_Hosar_Plan.pdf",
      "id": "907891",
      "uploadedBy": "656aa949cebbe1714411d21b",
      "createdAt": "Wed May 15 2024 16:40:12 GMT+0530 (India Standard Time)"
    }
  ],
  "assignmentType": {
    "value": "Commercial",
    "label": "Commercial"
  },
  "caseNumber": "008715",
  "createdBy": "656aa949cebbe1714411d21b",
  "caseHistory": [
    {
      "id": "638447",
      "title": "Create Lead",
      "description": "Create Lead",
      "datetime": "Wed May 15 2024 16:40:13 GMT+0530 (India Standard Time)"
    }
  ],
  "owners": [
    {
      "name": "M/s. Ion Exchange (India) Ltd.",
      "phone": "7397505825",
      "ownershipShare": "",
      "email": "",
      "id": "384827"
    }
  ],
  "proposePurchasers": [],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
  "documentPerArea": [],
  "images": [],
```

```
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c743e",
    "name":
"externalImg_1719392714994_WhatsApp_Image_20240408_at_90722_AM_1.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externalImg_1719392714994_WhatsApp_Image_20240408_at_90722_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c743f",
    "name":
"externalImg_1719392715004_WhatsApp_Image_20240408_at_90722_AM_2.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externalImg_1719392715004_WhatsApp_Image_20240408_at_90722_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c7440",
    "name":
"externalImg_1719392715027_WhatsApp_Image_20240408_at_90722_AM_3.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externalImg_1719392715027_WhatsApp_Image_20240408_at_90722_AM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c7441",
    "name":
"externalImg_1719392715038_WhatsApp_Image_20240408_at_90722_AM.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externalImg_1719392715038_WhatsApp_Image_20240408_at_90722_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c7442",
```

```
    "name":
"externallmg_1719392715061_WhatsApp_Image_20240408_at_90723_AM_1.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715061_WhatsApp_Image_20240408_at_90723_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7443",
  "name":
"externallmg_1719392715086_WhatsApp_Image_20240408_at_90723_AM_2.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715086_WhatsApp_Image_20240408_at_90723_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7444",
  "name":
"externallmg_1719392715116_WhatsApp_Image_20240408_at_90723_AM_5.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715116_WhatsApp_Image_20240408_at_90723_AM_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7445",
  "name":
"externallmg_1719392715150_WhatsApp_Image_20240408_at_90723_AM_6.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715150_WhatsApp_Image_20240408_at_90723_AM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7446",
  "name":
"externallmg_1719392715171_WhatsApp_Image_20240408_at_90723_AM_7.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715171_WhatsApp_Image_20240408_at_90723_AM_7.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7447",
  "name":
"externallmg_1719392715196_WhatsApp_Image_20240408_at_90723_AM_8.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715196_WhatsApp_Image_20240408_at_90723_AM_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7448",
  "name":
"externallmg_1719392715219_WhatsApp_Image_20240408_at_90723_AM_9.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715219_WhatsApp_Image_20240408_at_90723_AM_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c7449",
  "name":
"externallmg_1719392715241_WhatsApp_Image_20240408_at_90723_AM_10.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715241_WhatsApp_Image_20240408_at_90723_AM_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c744a",
  "name":
"externallmg_1719392715266_WhatsApp_Image_20240408_at_90723_AM_11.jpeg",
  "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715266_WhatsApp_Image_20240408_at_90723_AM_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667bd9cb968b1257131c744b",
  "name":
"externallmg_1719392715294_WhatsApp_Image_20240408_at_90723_AM_12.jpeg",
```

```
    "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715294_WhatsApp_Image_20240408_at_90723_AM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c744c",
    "name":
"externallmg_1719392715324_WhatsApp_Image_20240408_at_90723_AM_19.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715324_WhatsApp_Image_20240408_at_90723_AM_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c744d",
    "name":
"externallmg_1719392715344_WhatsApp_Image_20240408_at_90723_AM_20.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715344_WhatsApp_Image_20240408_at_90723_AM_20.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667bd9cb968b1257131c744e",
    "name":
"externallmg_1719392715369_WhatsApp_Image_20240408_at_90723_AM.jpeg",
    "path": "cases/664498159ab4ee3f051841f7/
externallmg_1719392715369_WhatsApp_Image_20240408_at_90723_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-15T11:10:13.065Z",
"updatedAt": "2024-06-26T09:05:15.559Z",
"__v": 0,
"updatedBy": "656aa949cebbe1714411d21b",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
```

"contactPersonName": "M/s. Ion Exchange (India) Ltd.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7397505825"

}

Name	Length	Width	Total
Composition :			
Other Composition :			