

```
{
  "typeOfReport": {
    "value": "Plant_&_Machinery",
    "label": "Plant & Machinery"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baf3"
    },
    "firstName": "Monika Rath",
    "type": "CREDITOFFICER",
    "_id": "64c770f8a5c3051014f4d3cb",
    "lastName": "Rath",
    "mobileNo": "",
    "workMobileNo": "8805477422",
    "email": "monika.bhaiya@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baf3",
  "branchCode": "000074",
  "type": "BRANCH",
  "name": "Mumbai Large Corporate Branch",
  "email": "Mumbai.Lcbb@bankofindia.co.in",
  "mobileNo": "02261870426",
  "alternateMobileNo": "02222684475",
  "address": "Bank Of India Building,4th Floor 70-80, M.G.Road, Fort",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e2f4336576061dae469362",
  "zoneName": "Mumbai South Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
```

```
"checker": {
  "_id": "62720b21afd7d55eddedc545",
  "profilePhoto": null,
  "firstName": "Avinash",
  "lastName": "Pandey",
  "shortName": "AV",
  "email": "avinash.pandey@vastukala.org",
  "designation": "",
  "mobileNo": "9021605621",
  "role": "MAKER+CHECKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "15.362901807030847",
  "longitude": "73.93514145439075"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-02",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-03-02",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
```

```
    "dateTime": "2024-03-02",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nagoa Quelossim",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
```

```
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "South Goa",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Salcete",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "L-48 & L-49",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ion Exchange (India) Ltd.",
  "label": false
},
"selectArea": {
```

```
"status": false,
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Verna Industrial Estate, Phase - II",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
```

```
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "34",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
```



```
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 403 722",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
```

```
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
```

```
"depreciationPercentage": "",
"depreciatedCostOfConstruction": "",
"totalFairMarketValue": ""
}
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jul 18 2024 12:13:11 GMT+0530 (India Standard Time)",
  "number": "2307274",
  "dayCount": "10",
  "monthCount": "278",
  "generatedBy": "62720b21afd7d55eddedc545"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66449c36a6319f3f44d061c2",
"invoices": [],
"ownerName": "M/s. Ion Exchange (India) Ltd.",
"ownerPhoneNo": "8600005760",
"fullAddress": "Industrial Plant & Machinery No. Basement Floor, Ion Exchange (India)
Ltd., Verna Industrial Estate, Phase - II, Plot No. L-48 & L-49, New/Current Survey No.
34, Village - Nagoa Quelossim, Taluka - Salcete, District - South Goa, PIN Code - 403
722, State - Maharashtra, India",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008717",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "111802",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 15 2024 16:57:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Ion Exchange (India) Ltd.",
    "phone": "8600005760",
    "ownershipShare": "",
    "email": "",
    "id": "190526"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
```

```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c93",
    "name": "externalImg_r_1721285978977_IMG_2263.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalImg_r_1721285978977_IMG_2263.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c94",
    "name": "externalImg_r_1721285978971_IMG_2262.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalImg_r_1721285978971_IMG_2262.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c95",
    "name": "externalImg_r_1721285978987_IMG_2264.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalImg_r_1721285978987_IMG_2264.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c96",
    "name": "externalImg_r_1721285979011_IMG_2265.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalImg_r_1721285979011_IMG_2265.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c97",
    "name": "externalImg_r_1721285979054_IMG_2267.JPG",
```

```
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979054_IMG_2267.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c98",
    "name": "externallmg_r_1721285979034_IMG_2266.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979034_IMG_2266.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c99",
    "name": "externallmg_r_1721285979077_IMG_2268.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979077_IMG_2268.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c9a",
    "name": "externallmg_r_1721285979096_IMG_2269.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979096_IMG_2269.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c9b",
    "name": "externallmg_r_1721285979145_IMG_2272.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979145_IMG_2272.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd5be4681c3f58227c9c",
    "name": "externallmg_r_1721285979166_IMG_2274.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979166_IMG_2274.JPG",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd5be4681c3f58227c9d",
  "name": "externallmg_r_1721285979118_IMG_2270.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979118_IMG_2270.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd5be4681c3f58227c9e",
  "name": "externallmg_r_1721285979186_IMG_2275.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979186_IMG_2275.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd5be4681c3f58227c9f",
  "name": "externallmg_r_1721285979213_IMG_2276.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979213_IMG_2276.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd5be4681c3f58227ca0",
  "name": "externallmg_r_1721285979239_IMG_2277.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979239_IMG_2277.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd5be4681c3f58227ca1",
  "name": "externallmg_r_1721285979267_IMG_2278.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979267_IMG_2278.JPG",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6698bd5be4681c3f58227ca2",
      "name": "externallmg_r_1721285979289_IMG_2279.JPG",
      "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979289_IMG_2279.JPG",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6698bd5be4681c3f58227ca3",
      "name": "externallmg_r_1721285979310_IMG_2280.JPG",
      "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979310_IMG_2280.JPG",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6698bd5be4681c3f58227ca4",
      "name": "externallmg_r_1721285979352_IMG_2282.JPG",
      "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979352_IMG_2282.JPG",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6698bd5be4681c3f58227ca5",
      "name": "externallmg_r_1721285979337_IMG_2281.JPG",
      "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721285979337_IMG_2281.JPG",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6698bd7135f7d73f39339057",
      "name": "externallmg_r_1721286000352_IMG_2284.JPG",
      "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000352_IMG_2284.JPG",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd7135f7d73f39339058",
  "name": "externallmg_r_1721286000365_IMG_2285.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000365_IMG_2285.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd7135f7d73f39339059",
  "name": "externallmg_r_1721286000383_IMG_2286.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000383_IMG_2286.JPG",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd7135f7d73f3933905a",
  "name": "externallmg_r_1721286000307_IMG_2283.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000307_IMG_2283.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd7135f7d73f3933905b",
  "name": "externallmg_r_1721286000409_IMG_2287.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000409_IMG_2287.JPG",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6698bd7135f7d73f3933905c",
  "name": "externallmg_r_1721286000491_IMG_2290.JPG",
  "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000491_IMG_2290.JPG",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f3933905d",
    "name": "externallmg_r_1721286000441_IMG_2288.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000441_IMG_2288.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f3933905e",
    "name": "externallmg_r_1721286000470_IMG_2289.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000470_IMG_2289.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f3933905f",
    "name": "externallmg_r_1721286000518_IMG_2291.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000518_IMG_2291.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f39339060",
    "name": "externallmg_r_1721286000565_IMG_2294.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000565_IMG_2294.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f39339061",
    "name": "externallmg_r_1721286000540_IMG_2293.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externallmg_r_1721286000540_IMG_2293.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6698bd7135f7d73f39339062",
    "name": "externalimg_r_1721286000589_IMG_2295.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalimg_r_1721286000589_IMG_2295.JPG",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f39339063",
    "name": "externalimg_r_1721286000612_IMG_2296.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalimg_r_1721286000612_IMG_2296.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f39339064",
    "name": "externalimg_r_1721286000634_IMG_2308.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalimg_r_1721286000634_IMG_2308.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f39339065",
    "name": "externalimg_r_1721286000683_IMG_2310.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalimg_r_1721286000683_IMG_2310.JPG",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6698bd7135f7d73f39339066",
    "name": "externalimg_r_1721286000658_IMG_2309.JPG",
    "path": "cases/66449c36a6319f3f44d061c2/
externalimg_r_1721286000658_IMG_2309.JPG",
    "orientation": "landscape"
  }
],
"externalDocuments": [
  {
```



```
    "originalname": "1. P&M Valuation Report-Goa-25.04.2024.docx",
    "filename": "1721284974717_1_PM_Valuation_ReportGoa25042024.docx",
    "path": "cases/66449c36a6319f3f44d061c2/
externalDocuments/1721284974717_1_PM_Valuation_ReportGoa25042024.docx",
    "size": "3832716",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Thu Jul 18 2024 12:12:55 GMT+0530 (India Standard Time)",
    "uploadedBy": "62720b21afd7d55eddedc545"
  }
],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "656aa949cebbe1714411d21b",
      "role": "FRONTDESK",
      "firstName": "Priyanka",
      "lastName": "Pawar"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "6698bd2ae4681c3f58227c08",
    "note": "Visit Photo Uploading (Task Reopen)",
    "taskId": "66449c43a6319f3f44d0620c",
    "createdAt": "2024-07-18T06:58:50.053Z"
  }
],
"createdAt": "2024-05-15T11:27:50.873Z",
"updatedAt": "2024-07-18T07:00:01.093Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "M/s. Ion Exchange (India) Ltd.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": ""
```

"relationWithOwner": "self",
"siteVisitContactNo": "8600005760",
"reportGeneratedDate": "Thu Jul 18 2024 12:11:17 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-03-02"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			