

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6645d8d675934e3f09c51134"
    },
    "type": "CREDITOFFICER",
    "_id": "6646f0ad46d99f42db90e6ec",
    "firstName": "Shailesh",
    "lastName": "kokane",
    "mobileNo": "",
    "workMobileNo": "8879150024",
    "email": "1shailesh.kokane@sbicaptrustee.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6645d8d675934e3f09c51134",
  "name": "GIFT City Gandhinagar",
  "branchCode": "",
  "mobileNo": "02243025500",
  "alternateMobileNo": "",
  "email": "shailesh.kokane@sbicaptrustee.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "14th Floor, Hiranandani Signature Tower. GIFT City, Gandhinagar -
382355"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "655da0ac5586e008159055e7",
  "zoneName": "GUjrat"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "21.74657152353434",
  "longitude": "84.05569706008465"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Raghunathpali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Khata No. 254/334",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Sambalpur",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1931, 1932/3209, 1961 & 1931/4178",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "M/s. Apar Industries Limited.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "P. S. Debra",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Sambalpur Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```



```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 768 213",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
```

```
    "title": "Private Cars"
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "66459cc175934e3f09c4c2b9",
"ownerName": "M/s. Apar Industries Limited.",
"ownerPhoneNo": "0000000000",
"fullAddress": "Industrial Land and Building No. Basement Floor, Building No Khata
No. 254/334, M/s. Apar Industries Limited., Sambalpur Road, Plot No. 1931, 1932/3209,
1961 & 1931/4178, P. S. Debra, Village - Raghunathpali, District - Sambalpur, PIN Code
- 768 213, State - Maharashtra, India",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008736",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "963236",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 16 2024 11:12:25 GMT+0530 (India Standard Time)"
  }
],
```



```
"owners": [
  {
    "name": "M/s. Apar Industries Limited.",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "321667"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa66b",
    "name":
"externallmg_1718351398299_WhatsApp_Image_20240131_at_114745_1.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351398299_WhatsApp_Image_20240131_at_114745_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa66c",
    "name":
"externallmg_1718351398308_WhatsApp_Image_20240131_at_114745_3.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351398308_WhatsApp_Image_20240131_at_114745_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa66d",
    "name":
"externallmg_1718351398335_WhatsApp_Image_20240131_at_114745_5.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351398335_WhatsApp_Image_20240131_at_114745_5.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa66e",
    "name":
"externallmg_1718351398349_WhatsApp_Image_20240131_at_114745_6.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351398349_WhatsApp_Image_20240131_at_114745_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa66f",
    "name":
"externallmg_1718351399062_WhatsApp_Image_20240131_at_114745_7.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399062_WhatsApp_Image_20240131_at_114745_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa670",
    "name":
"externallmg_1718351399074_WhatsApp_Image_20240131_at_114745_10.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399074_WhatsApp_Image_20240131_at_114745_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa671",
    "name":
"externallmg_1718351399083_WhatsApp_Image_20240131_at_114745_12.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399083_WhatsApp_Image_20240131_at_114745_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf627772310133b1fa672",
```

```
    "name":
"externallmg_1718351399100_WhatsApp_Image_20240131_at_114745_13.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399100_WhatsApp_Image_20240131_at_114745_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf627772310133b1fa673",
  "name":
"externallmg_1718351399116_WhatsApp_Image_20240131_at_114745_15.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399116_WhatsApp_Image_20240131_at_114745_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf627772310133b1fa674",
  "name":
"externallmg_1718351399131_WhatsApp_Image_20240131_at_114745_16.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399131_WhatsApp_Image_20240131_at_114745_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf627772310133b1fa675",
  "name":
"externallmg_1718351399137_WhatsApp_Image_20240131_at_114745_17.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399137_WhatsApp_Image_20240131_at_114745_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf627772310133b1fa676",
  "name":
"externallmg_1718351399148_WhatsApp_Image_20240131_at_114745_18.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351399148_WhatsApp_Image_20240131_at_114745_18.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6b1",
  "name":
"externallmg_1718351424996_WhatsApp_Image_20240131_at_114745_19.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351424996_WhatsApp_Image_20240131_at_114745_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6b2",
  "name":
"externallmg_1718351424998_WhatsApp_Image_20240131_at_114745_21.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351424998_WhatsApp_Image_20240131_at_114745_21.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6b3",
  "name":
"externallmg_1718351425008_WhatsApp_Image_20240131_at_114745_23.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425008_WhatsApp_Image_20240131_at_114745_23.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6b4",
  "name":
"externallmg_1718351425025_WhatsApp_Image_20240131_at_114745_25.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425025_WhatsApp_Image_20240131_at_114745_25.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6b5",
  "name":
"externallmg_1718351425047_WhatsApp_Image_20240131_at_114745_26.jpeg",
```

```
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425047_WhatsApp_Image_20240131_at_114745_26.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf64159d44b137cf3c6b6",
    "name":
"externallmg_1718351425076_WhatsApp_Image_20240131_at_114745.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425076_WhatsApp_Image_20240131_at_114745.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf64159d44b137cf3c6b7",
    "name":
"externallmg_1718351425096_WhatsApp_Image_20240131_at_114820_1.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425096_WhatsApp_Image_20240131_at_114820_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf64159d44b137cf3c6b8",
    "name":
"externallmg_1718351425126_WhatsApp_Image_20240131_at_114820_2.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425126_WhatsApp_Image_20240131_at_114820_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf64159d44b137cf3c6b9",
    "name":
"externallmg_1718351425165_WhatsApp_Image_20240131_at_114820_3.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425165_WhatsApp_Image_20240131_at_114820_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "666bf64159d44b137cf3c6ba",
  "name":
"externallmg_1718351425194_WhatsApp_Image_20240131_at_114820_5.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425194_WhatsApp_Image_20240131_at_114820_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6bb",
  "name":
"externallmg_1718351425228_WhatsApp_Image_20240131_at_114820_6.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425228_WhatsApp_Image_20240131_at_114820_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6bc",
  "name":
"externallmg_1718351425251_WhatsApp_Image_20240131_at_114820_7.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425251_WhatsApp_Image_20240131_at_114820_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6bd",
  "name":
"externallmg_1718351425283_WhatsApp_Image_20240131_at_114820_8.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425283_WhatsApp_Image_20240131_at_114820_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf64159d44b137cf3c6be",
  "name":
"externallmg_1718351425308_WhatsApp_Image_20240131_at_114820_11.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425308_WhatsApp_Image_20240131_at_114820_11.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf64159d44b137cf3c6bf",
    "name":
"externallmg_1718351425336_WhatsApp_Image_20240131_at_114820_13.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425336_WhatsApp_Image_20240131_at_114820_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf64159d44b137cf3c6c0",
    "name":
"externallmg_1718351425369_WhatsApp_Image_20240131_at_114820_14.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351425369_WhatsApp_Image_20240131_at_114820_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf665fadc0e137dd85ebb",
    "name":
"externallmg_1718351460680_WhatsApp_Image_20240131_at_114820_15.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460680_WhatsApp_Image_20240131_at_114820_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf665fadc0e137dd85ebc",
    "name":
"externallmg_1718351460690_WhatsApp_Image_20240131_at_114820_17.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460690_WhatsApp_Image_20240131_at_114820_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf665fadc0e137dd85ebd",
```

```
"name":
"externallmg_1718351460711_WhatsApp_Image_20240131_at_114820_19.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460711_WhatsApp_Image_20240131_at_114820_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ebe",
  "name":
"externallmg_1718351460740_WhatsApp_Image_20240131_at_114820_21.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460740_WhatsApp_Image_20240131_at_114820_21.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ebf",
  "name":
"externallmg_1718351460769_WhatsApp_Image_20240131_at_114820_22.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460769_WhatsApp_Image_20240131_at_114820_22.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec0",
  "name":
"externallmg_1718351460795_WhatsApp_Image_20240131_at_114820_25.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460795_WhatsApp_Image_20240131_at_114820_25.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec1",
  "name":
"externallmg_1718351460827_WhatsApp_Image_20240131_at_114820_26.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460827_WhatsApp_Image_20240131_at_114820_26.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec2",
  "name":
"externallmg_1718351460857_WhatsApp_Image_20240131_at_114820_27.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460857_WhatsApp_Image_20240131_at_114820_27.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec3",
  "name":
"externallmg_1718351460876_WhatsApp_Image_20240131_at_114820_28.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460876_WhatsApp_Image_20240131_at_114820_28.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec4",
  "name":
"externallmg_1718351460895_WhatsApp_Image_20240131_at_114820_29.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460895_WhatsApp_Image_20240131_at_114820_29.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec5",
  "name":
"externallmg_1718351460919_WhatsApp_Image_20240131_at_114840_1.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460919_WhatsApp_Image_20240131_at_114840_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf665fadc0e137dd85ec6",
  "name":
"externallmg_1718351460937_WhatsApp_Image_20240131_at_114840.jpeg",
```

```
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351460937_WhatsApp_Image_20240131_at_114840.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf67559d44b137cf3c707",
    "name":
"externallmg_1718351477517_WhatsApp_Image_20240131_at_114841_1.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477517_WhatsApp_Image_20240131_at_114841_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf67559d44b137cf3c708",
    "name":
"externallmg_1718351477525_WhatsApp_Image_20240131_at_114841_3.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477525_WhatsApp_Image_20240131_at_114841_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf67559d44b137cf3c709",
    "name":
"externallmg_1718351477562_WhatsApp_Image_20240131_at_114841_5.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477562_WhatsApp_Image_20240131_at_114841_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666bf67559d44b137cf3c70a",
    "name":
"externallmg_1718351477594_WhatsApp_Image_20240131_at_114841_6.jpeg",
    "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477594_WhatsApp_Image_20240131_at_114841_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "666bf67559d44b137cf3c70b",
  "name":
"externallmg_1718351477618_WhatsApp_Image_20240131_at_114841_7.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477618_WhatsApp_Image_20240131_at_114841_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf67559d44b137cf3c70c",
  "name":
"externallmg_1718351477643_WhatsApp_Image_20240131_at_114841_9.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477643_WhatsApp_Image_20240131_at_114841_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf67559d44b137cf3c70d",
  "name":
"externallmg_1718351477671_WhatsApp_Image_20240131_at_114841_10.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477671_WhatsApp_Image_20240131_at_114841_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf67559d44b137cf3c70e",
  "name":
"externallmg_1718351477706_WhatsApp_Image_20240131_at_114841_12.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477706_WhatsApp_Image_20240131_at_114841_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666bf67559d44b137cf3c70f",
  "name":
"externallmg_1718351477734_WhatsApp_Image_20240131_at_114841.jpeg",
  "path": "cases/66459cc175934e3f09c4c2b9/
externallmg_1718351477734_WhatsApp_Image_20240131_at_114841.jpeg",
```

```

    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-16T05:42:25.141Z",
"updatedAt": "2024-06-14T07:51:17.901Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "M/s. Apar Industries Limited.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			