

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6645f27375934e3f09c53547"
    },
    "type": "CREDITOFFICER",
    "_id": "6645f2b875934e3f09c535c4",
    "firstName": "Manoj",
    "lastName": "Wani",
    "mobileNo": "",
    "workMobileNo": "8806615866",
    "email": "1manojwani202@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6645f27375934e3f09c53547",
  "name": "Mahabal Branch",
  "branchCode": "15063",
  "mobileNo": "8806615866",
  "alternateMobileNo": "",
  "email": "manojwani202@gmail.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "C. S. No. 446/1, Plot No. 14/A, Mahabal Area Branch, Jalgaon - 425002"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
```

```
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.180520",
  "longitude": "73.096966"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-18",
      "remark": "Case refered by Umang Sir"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-17",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mangaon",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Casa Foresta",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Palava, Premier Colony Ground",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kalyan Shil Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "53/1, 53/3, 65/15B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "D-602",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN - 421 203",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  }
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
```

```

    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road",
    "west": "'C' Wing of Casa Foresta",
    "south": "Internal Road",
    "east": "E Wing Proposed"
  },
  "asPerDocumentAgreement": {
    "north": "Information not available",
    "west": "Information not available",
    "south": "Information not available",
    "east": "Information not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "As per Agreement Sale Plan, the composition of residential flat is Living Room + 2 Bedrooms + Kitchen + 2 Toilets + Balcony (i.e. 2 BHK with 2 Toilets)",

```

```
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"compositeRate": {
"remark": "As per site inspection, the building is constructed by Lodha and has not
yet given possession of the flats. Internal Photographs and site inspection not
allowed. Hence our report is based on external site visit and documents provided to
us.",
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "33700",
"landRate": "7000",
"igrImage": "cases/6645f31e75934e3f09c53669/igr_1716015596117_Image.png",
"squareMeterGuideLineRate": "35385.00",
"squareFeetGuideLineRate": "3287.00"
},
"igrFinalRate": {
"floorRatePercentage": "5",
"depreciationPercentage": "0",
"rate": "33700.00",
"squareMeterGuideLineRate": "35385.00",
"squareFeetGuideLineRate": "3287.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
```

```
"value": "External_Site_Visit_Only",
"label": "External Site Visit Only"
},
"monthlyRent": "N.A",
"assessmentNo": "Information not available",
"taxPaidHolderName": "Information not available",
"taxAmount": "Information not available",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per local norms",
"tenantName": "",
"maintenanceOfFlat": "External site visit only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Yes",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2024",
  "fullDate": "1/1/2024"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "23",
"flatFloorNo": "6",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
```



```
"finalPlinthArea": {
  "area": "721.60",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6645f31e75934e3f09c53669/
routeMap_1716018619125_Image.png",
    "routeLat": "19.180839",
    "routeLng": "73.097986",
    "stationName": "Dombivli",
    "routeDistance": "5.3 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "80yjo",
      "name": "80yjo",
      "image": "cases/6645f31e75934e3f09c53669/
routeMap_1716018400316_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
```

```
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7544000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "7544000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat May 18 2024 16:45:05 GMT+0530 (India Standard Time)",
  "number": "2306381",
  "dayCount": "14",
  "monthCount": "241",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2371899.00",
  "selectedBuildUpValue": "721.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66483632beacf042d554c8fb",
      "name": "externallmg_r_1716008425818_1716008155807_image_5.jpg",
      "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008425818_1716008155807_image_5.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66483632beacf042d554c8f8",
      "name": "externallmg_r_1716008367348_1716008155807_image_3.jpg",
      "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008367348_1716008155807_image_3.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "66483632beacf042d554c8fc",
    "name": "externallmg_r_1716008447456_1716008155807_image_6.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008447456_1716008155807_image_6.jpg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11294.00",
    "max": "12348.00"
  },
  "builtUpRateRange": {
    "min": "10267.00",
    "max": "11226.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```



```
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "656.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6645f31e75934e3f09c53669",
"ownerName": "Rushikesh Ratan Shinde",
"ownerPhoneNo": "8623009147",
"fullAddress": "Residential Flat No. D-602, 6th Floor, Wing - D, Casa Foresta, Palava,
Premier Colony Ground, Kalyan Shil Road, Village - Mangaon, Dombivli (East), Taluka -
Kalyan, District - Thane, PIN - 421 203, State - Maharashtra, India",
"remark": "Case refered by Umang Sir",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "01/07/2022",
      "from": {
        "value": "Company",
        "label": "Company"
      },
      "Company": "Macrotech Developers Limited",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Rushikesh Ratan Shinde",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "9398/2022"
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "605778",
```

```
"path": "cases/6645f31e75934e3f09c53669/
document_1715860201400_2218495_AFS_2.pdf",
"fileName": "document_1715860201400_2218495_AFS_2.pdf"
},
{
"documentType": {
"value": "60ae124baa6d152c1801b2fd",
"label": "Occupancy Certificate"
},
"inputs": {
"documentDate": "22/03/2024",
"nameOfApprovingAuthority": {
"value": "Assistant_Director,_Nagar_Rachna_Thane",
"label": "Assistant Director, Nagar Rachna Thane"
},
"number": {
"value": "No",
"label": "No"
},
"No": "Bhoda / A.N.V.P. / Mouje Antarli, Khoni & Other / SSThane / 1318"
},
"isHardCopy": false,
"displayStatus": true,
"id": "360465",
"path": "cases/6645f31e75934e3f09c53669/
document_1715860212535_Codename_Premier__OC_2.pdf",
"fileName": "document_1715860212535_Codename_Premier__OC_2.pdf"
},
{
"documentType": {
"value": "60ae1247aa6d152c1801b2ea",
"label": "Commencement Certificate"
},
"inputs": {
"documentDate": "12/01/2022",
"nameOfApprovingAuthority": {
"value": "Assistant_Director,_Nagar_Rachna_Thane",
"label": "Assistant Director, Nagar Rachna Thane"
},
"number": {
"value": "No",
"label": "No"
},
"No": "Integrated City Colony / Mouje Antarli, Khoni & Other / 88 "
},
"isHardCopy": false,
```

```
    "displayStatus": true,
    "id": "583028",
    "path": "cases/6645f31e75934e3f09c53669/document_1716022664160_1_Commen
cement_Certificates___NA_Order_for_plotted_development.pdf",
    "fileName": "document_1716022664160_1_Commencement_Certificates___NA_Or
der_for_plotted_development.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "05/10/2023",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "P51700032683"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1716022819004_P51700032683.pdf",
    "path": "cases/6645f31e75934e3f09c53669/
document_1716022819004_P51700032683.pdf",
    "id": "243204",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Sat May 18 2024 14:30:19 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008764",
"createdBy": "64cde526dc9f3034f3fefa49",
"caseHistory": [
  {
    "id": "451122",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 16 2024 17:20:54 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Rushikesh Ratan Shinde",
    "phone": "8623009147",
    "ownershipShare": "",
    "email": "",
    "id": "713063"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "532969",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "656",
    "squareMeterArea": "60.94",
    "docFinalBuiltUp": "721.6",
    "docFinalBuiltUpSquareMeter": "67.03399999999999",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "656.00",
      "squareMeterArea": "60.94",
      "expectedRate": "12347.56",
      "percentage": ""
    }
  }
]
```

```
},
"builtUpArea": {
  "area": "721.60",
  "squareMeterArea": "67.04",
  "expectedRate": "11225.06",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "6648520946d99f42db9175d2",
"property": "Residential Flat",
"area": "656",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "8100000",
"expectedRate": "12347.56",
"builtUpExpectedRate": "11225.06",
"image": "cases/6645f31e75934e3f09c53669/
indicator_1716015367570_Image.png",
"squareMeter": "60.94",
"id": "475034"
},
{
  "carpetArea": {
    "area": "702.00",
    "squareMeterArea": "65.22",
    "expectedRate": "11725.07",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "772.20",
    "squareMeterArea": "71.74",
    "expectedRate": "10659.16",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
```

```
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6648520946d99f42db9175d3",
"property": "Residential Flat",
"area": "702",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "8231000",
"expectedRate": "11725.07",
"builtUpExpectedRate": "10659.16",
"image": "cases/6645f31e75934e3f09c53669/
indicator_1716015397774_Image.png",
"squareMeter": "65.22",
"id": "259868"
},
{
"carpetArea": {
"area": "464.00",
"squareMeterArea": "43.11",
"expectedRate": "11293.10",
"percentage": ""
},
"builtUpArea": {
"area": "510.40",
"squareMeterArea": "47.42",
"expectedRate": "10266.46",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "6648520946d99f42db9175d4",
"property": "Residential Flat",
"area": "464",
"builtUpPercentage": "10",
```

```
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "5240000",
"expectedRate": "11293.10",
"builtUpExpectedRate": "10266.46",
"image": "cases/6645f31e75934e3f09c53669/
indicator_1716015453026_Image.png",
"squareMeter": "43.11",
"id": "982413"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66483632beacf042d554c8f6",
"name": "externallmg_r_1716008350393_1716008155807_image_1.png",
"path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008350393_1716008155807_image_1.png",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66483632beacf042d554c8f7",
"name": "externallmg_r_1716008352141_1716008155807_image_2.jpg",
"path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008352141_1716008155807_image_2.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66483632beacf042d554c8f8",
"name": "externallmg_r_1716008367348_1716008155807_image_3.jpg",
"path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008367348_1716008155807_image_3.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66483632beacf042d554c8f9",
```

```
    "name": "externallmg_r_1716008323997_1716008155807_image_0.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008323997_1716008155807_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66483632beacf042d554c8fa",
    "name": "externallmg_r_1716008397481_1716008155807_image_4.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008397481_1716008155807_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66483632beacf042d554c8fb",
    "name": "externallmg_r_1716008425818_1716008155807_image_5.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008425818_1716008155807_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66483632beacf042d554c8fc",
    "name": "externallmg_r_1716008447456_1716008155807_image_6.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008447456_1716008155807_image_6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66483632beacf042d554c8fd",
    "name": "externallmg_r_1716008472871_1716008155807_image_7.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008472871_1716008155807_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6648357646d99f42db91553f",
    "name": "externallmg_r_1716008292396_1716008126283_image_0.jpg",
```



```
    "path": "cases/6645f31e75934e3f09c53669/
externallmg_r_1716008292396_1716008126283_image_0.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1716015617329_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716015617329_Calculation_Sheet_NEW.xlsx",
    "size": "2067026",
    "createdAt": "Sat May 18 2024 12:30:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Reference Report - Rekha_Rajeev_Bhagat.pdf",
    "filename": "1716015617361_Reference_Report__Rekha_Rajeev_Bhagat.pdf",
    "path": "cases/6645f31e75934e3f09c53669/processingDocuments/1716015617361
_Reference_Report__Rekha_Rajeev_Bhagat.pdf",
    "size": "1108202",
    "createdAt": "Sat May 18 2024 12:30:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Google Loacation.png",
    "filename": "1716025708177_Google_Loacation.png",
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716025708177_Google_Loacation.png",
    "size": "2756664",
    "createdAt": "Sat May 18 2024 15:18:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Occupancy Certificate.pdf",
    "filename": "1716025708225_Occupancy_Certificate.pdf",
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716025708225_Occupancy_Certificate.pdf",
    "size": "11004371",
    "createdAt": "Sat May 18 2024 15:18:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Reference Report 1.pdf",
    "filename": "1716025708369_Reference_Report_1.pdf",
```

```
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716025708369_Reference_Report_1.pdf",
    "size": "1108202",
    "createdAt": "Sat May 18 2024 15:18:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2022.pdf",
    "filename": "1716025708393_Sale_Deed__2022.pdf",
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716025708393_Sale_Deed__2022.pdf",
    "size": "13449570",
    "createdAt": "Sat May 18 2024 15:18:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details (1).jpg",
    "filename": "1716025708572_Site_Details_1.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716025708572_Site_Details_1.jpg",
    "size": "1993593",
    "createdAt": "Sat May 18 2024 15:18:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details (2).jpg",
    "filename": "1716025708598_Site_Details_2.jpg",
    "path": "cases/6645f31e75934e3f09c53669/
processingDocuments/1716025708598_Site_Details_2.jpg",
    "size": "1993593",
    "createdAt": "Sat May 18 2024 15:18:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "1 Commencement Certificates _ NA Order for plotted
development.pdf",
    "filename": "1716025725217_1_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
    "path": "cases/6645f31e75934e3f09c53669/processingDocuments/1716025725217
_1_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
    "size": "960975",
    "createdAt": "Sat May 18 2024 15:18:45 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-16T11:50:54.494Z",
"updatedAt": "2024-05-18T11:15:30.701Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Rajendra Giri",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "CRM",
"siteVisitContactNo": "8623009147",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 656.00",
"flatRate": "11500",
"landOtherRate": "9000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 601.00\nEBVT Area in Sq. Ft. =
55.00",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
```

```

"reportGeneratedDate": "Sat May 18 2024 14:05:31 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-05-17",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			