

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b31",
    "email": "resham.kulkarni@cosmosbank.in",
    "firstName": "Resham ",
    "mobileNo": "9987780572",
    "workMobileNo": "9987780572",
    "lastName": "Kulkarni"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": ""
}
```

```
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
},
},
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.019085207063178",
  "longitude": "73.0856556644842"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-23T07:25:09.894Z",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],

```

```
"remark": null,
"rateMin": "12000",
"lumpsumValue": "7000000",
"rateMax": "13000",
"areaType": {
  "Name": "Carpet",
  "Value": "Carpet",
  "name": "Carpet",
  "value": "Carpet"
}
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamothe",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
```

```
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "29, 30 & 31",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shubh Shagun Complex ",
```

```
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "34",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Rishikesh Co.-Op. Hsg. Soc. Ltd., Phase 2",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 410 209",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```
"key": "suburb",
"value": "",
"label": false
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "Vitrified_Tile_Flooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
    "label": "Powder coated Aluminum sliding windows",
    "value": "Powder_coated_Aluminum_sliding_windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Normal",
    "value": "Normal"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "d wing",
```

```
"west": "road",
"south": "b wing",
"east": "mansarovar"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  }
}
```

```
    },
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "partitions": {
      "label": "6\" Thk. Brick Masonery",
      "value": "6\"_Thk._Brick_Masonery"
    },
    "waterTank": {
      "label": "CIDCO",
      "value": "CIDCO"
    },
    "pavementLaid": {
      "label": "No",
      "value": "No"
    },
    "carParking": {
      "label": "Stilt + Open Car Parking",
      "value": "Stilt+_Open_Car_Parking"
    },
    "constructionWorkStatus": {
      "label": "Completed",
      "value": "Completed"
    },
    "dateOfConstruction": {
      "date": "1",
      "month": "1",
      "year": "2009",
      "fullDate": "1/1/2009"
    },
    "propertyTypeList": {
      "label": "Residential",
      "value": "Residential"
    },
    "planningArea": {
      "label": "Residential",
      "value": "Residential"
    },
    "typeOfStructure": {
      "label": "R.C.C. Framed Structure",
      "value": "R.C.C._Framed_Structure"
    },
    "qualityOfConstruction": {
      "label": "Normal",
      "value": "Normal"
    }
  },
}
```

```
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "45",
"ageOfBuilding": "15",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "07",
"flatFloorNo": "",
"noOfLifts": "01",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "664886597e75ae1630b8ce39",
"ownerName": "Shri. Chandrakant Ramnath Katkade",
"ownerPhoneNo": "9833022224",
"fullAddress": "Residential Flat No. 401, 4th Floor, Wing - C, Shubh Shagun Complex ,
Rishikesh Co.-Op. Hsg. Soc. Ltd., Phase 2, Plot No. 29, 30 & 31, Sector 34, Village -
Kamothe, Taluka - Panvel, District - Raigad, Navi Mumbai, PIN Code - 410 209, State -
Maharashtra, India",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "12/05/2009",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Bhoomi Realtors",
      "to": {
        "value": "The_Allottees",
        "label": "The Allottees"
      },
      "The_Allottees": "Shri. Chandrakant Ramnath Katkade",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "2497/2009"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1716028995274_Cosmos_gbriad_chandrakant_katkade_401__kamothe.pdf",
    "path": "cases/664886597e75ae1630b8ce39/document_1716028995274_Cosmos_gbriad_chandrakant_katkade_401__kamothe.pdf",
    "id": "407347",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Sat May 18 2024 16:13:36 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "16/05/2023",
      "remark": "issued by Vastukala consultant Pvt. Ltd. for BOI"
    },
    "isHardCopy": false,
    "displayStatus": true,
  }
]
```

```
"id": "402662",
"path": "cases/664886597e75ae1630b8ce39/
document_1716029010557_Thane_Medical_Agency_reports.pdf",
"fileName": "document_1716029010557_Thane_Medical_Agency_reports.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/02/2005",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CIDCO / ATPO / 187 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1716612226417_204014.pdf",
"path": "cases/664886597e75ae1630b8ce39/
document_1716612226417_204014.pdf",
"id": "961091",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Sat May 25 2024 10:18:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "26/11/2009",
    "nameOfApprovingAuthority": {
      "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
      "label": "City and Industrial Development Corp Of Maharashtra Ltd."
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  }
},
```

```
    "No": "CIDCO / BP / ATPO / 1316"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716612342273_275033.pdf",
  "path": "cases/664886597e75ae1630b8ce39/
document_1716612342273_275033.pdf",
  "id": "884773",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Sat May 25 2024 10:18:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "22/12/2022",
    "remark": "issued by Vastukala Consultant pvt. Ltd. for Cosmos"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1716612521334_Valuation_Report_Chandrakant_Katkade_
Sign_Report.pdf",
  "path": "cases/664886597e75ae1630b8ce39/document_1716612521334_Valuation
_Report_Chandrakant_Katkade_Sign_Report.pdf",
  "id": "106482",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Sat May 25 2024 10:18:41 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "008824",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "200236",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat May 18 2024 16:13:37 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Shri. Chandrakant Ramnath Katkade",
  "phone": "9833022224",
  "ownershipShare": "",
  "email": "",
  "id": "391928"
},
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "664eeef1d7ce151854f3fbc5",
    "area": "583",
    "providedByName": "Shri. Chandrakant Ramnath Katkade",
    "providedByContactNo": "9833022224"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "715623",
    "name": "Living Room",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
```



```
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c1b",
    "name": "externalImg_1716449211332_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externalImg_1716449211332_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c1c",
    "name": "externalImg_1716449212334_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externalImg_1716449212334_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c1d",
    "name": "externalImg_1716449213779_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externalImg_1716449213779_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c1e",
    "name": "externalImg_1716449215089_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externalImg_1716449215089_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c1f",
    "name": "externalImg_1716449216674_image.jpeg",
```

```
    "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449216674_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c20",
    "name": "externallmg_1716449217305_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449217305_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c21",
    "name": "externallmg_1716449217754_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449217754_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c22",
    "name": "externallmg_1716449218129_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449218129_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c23",
    "name": "externallmg_1716449218774_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449218774_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664eefce415afe1810494c24",
    "name": "externallmg_1716449219374_image.jpeg",
    "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449219374_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c25",
  "name": "externallmg_1716449219766_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449219766_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c26",
  "name": "externallmg_1716449220064_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449220064_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c27",
  "name": "externallmg_1716449220779_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449220779_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c28",
  "name": "externallmg_1716449221503_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449221503_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c29",
  "name": "externallmg_1716449222044_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449222044_image.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c2a",
  "name": "externallmg_1716449222454_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449222454_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c2b",
  "name": "externallmg_1716449223498_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449223498_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c2c",
  "name": "externallmg_1716449223693_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449223693_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c2d",
  "name": "externallmg_1716449224189_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449224189_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664eefce415afe1810494c2e",
  "name": "externallmg_1716449225108_image.jpeg",
  "path": "cases/664886597e75ae1630b8ce39/
externallmg_1716449225108_image.jpeg",
  "orientation": "portrait"
}
}
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname":
"1711780572109_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "filename": "1716541201237_1711780572109_1703238797922_1701350330944_C
alculation_123_2.xlsx",
    "path": "cases/664886597e75ae1630b8ce39/processingDocuments/171654120123
7_1711780572109_1703238797922_1701350330944_Calculation_123_2.xlsx",
    "size": "4780216",
    "createdAt": "Fri May 24 2024 14:30:05 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "12500 Kamothe.pdf",
    "filename": "1716541242149_12500_Kamothe.pdf",
    "path": "cases/664886597e75ae1630b8ce39/
processingDocuments/1716541242149_12500_Kamothe.pdf",
    "size": "157570",
    "createdAt": "Fri May 24 2024 14:30:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "12700 Shubh.pdf",
    "filename": "1716541242269_12700_Shubh.pdf",
    "path": "cases/664886597e75ae1630b8ce39/
processingDocuments/1716541242269_12700_Shubh.pdf",
    "size": "154980",
    "createdAt": "Fri May 24 2024 14:30:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "15000 Shubh.pdf",
    "filename": "1716541242409_15000_Shubh.pdf",
    "path": "cases/664886597e75ae1630b8ce39/
processingDocuments/1716541242409_15000_Shubh.pdf",
    "size": "160995",
    "createdAt": "Fri May 24 2024 14:30:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Kamothe.pdf",
    "filename": "1716541242534_Kamothe.pdf",
    "path": "cases/664886597e75ae1630b8ce39/
processingDocuments/1716541242534_Kamothe.pdf",
```

```
"size": "157841",
"createdAt": "Fri May 24 2024 14:30:42 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"lastName": "Kuperkar",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "664deecf237ec4489821b11d",
"note": "Rate verification done, pending for visit",
"taskId": "664886606f40574290c1ccce",
"createdAt": "2024-05-22T13:10:39.020Z"
}
],
"createdAt": "2024-05-18T10:43:37.101Z",
"updatedAt": "2024-05-25T04:48:41.631Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Shri. Chandrakant Ramnath Katkade",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833022224",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2024-05-23"
```

} Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			