

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "664c3c856f40574290c21815",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Lloyd's Register Industrial Services (I) Limited Vadodara\t",
"displayName": "Lloyd's Register Industrial Services (I) Limited Vadodara\t",
"initial": "L"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": "",
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
    "firstName": "Jagdish ",
    "email": "jagdish.bhatt@vastukala.org",
    "lastName": "Bhatt",
    "mobileNo": "8425864014",
    "designation": "",
    "shortName": "JB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": null,
  "checker": null,
```

```
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      },
      {
        "title": {
          "value": "Registered_Valuer",
          "label": "Registered Valuer"
        },
        "_id": "60af80072ffdf65bcd658654",
```

```
    "number": "IBBI/RV/07/2018/10366"
  }
],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "22.308669315852622",
  "longitude": "73.16015421849336"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "21/05/2024 11:45 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vadodara",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Race Course Tower",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Race Course Circle",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "206 & 207",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```



```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
"monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
```

```
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "664c3c856f40574290c2181b",
"ownerName": "Lloyd's Register Industrial Services (I) Limited Vadodara\t",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "0000000000",
"contactPersonName": "Mr Prashant",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Lloyd's Register Industrial Services (I) Limited Vadodara\t",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "641548"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Commercial Office No. 206 & 207, 2nd Floor, Race Course Tower,
Race Course Circle, Vadodara, State - Gujrat, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1716272248067_Valuation_Report_Lloyeds_Register__Vadodara.pdf",
    "path": "cases/664c3c856f40574290c2181b/
document_1716272248067_Valuation_Report_Lloyeds_Register__Vadodara.pdf",
    "id": "552273",
```



```
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Tue May 21 2024 11:47:41 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "008849",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "886427",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue May 21 2024 11:47:41 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27e8",
    "name":
"externallmg_1717043572570_WhatsApp_Image_20240530_at_091803_2.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572570_WhatsApp_Image_20240530_at_091803_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27e9",
    "name":
"externallmg_1717043572575_WhatsApp_Image_20240530_at_091803_3.jpeg",
```

```
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572575_WhatsApp_Image_20240530_at_091803_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27ea",
    "name":
"externallmg_1717043572582_WhatsApp_Image_20240530_at_091804_1.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572582_WhatsApp_Image_20240530_at_091804_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27eb",
    "name":
"externallmg_1717043572586_WhatsApp_Image_20240530_at_091804_2.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572586_WhatsApp_Image_20240530_at_091804_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27ec",
    "name":
"externallmg_1717043572592_WhatsApp_Image_20240530_at_091804.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572592_WhatsApp_Image_20240530_at_091804.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27ed",
    "name":
"externallmg_1717043572597_WhatsApp_Image_20240530_at_091805_1.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572597_WhatsApp_Image_20240530_at_091805_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "665801740a6e5305631a27ee",
  "name":
"externallmg_1717043572600_WhatsApp_Image_20240530_at_091805.jpeg",
  "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572600_WhatsApp_Image_20240530_at_091805.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665801740a6e5305631a27ef",
  "name":
"externallmg_1717043572603_WhatsApp_Image_20240530_at_091800_1.jpeg",
  "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572603_WhatsApp_Image_20240530_at_091800_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665801740a6e5305631a27f0",
  "name":
"externallmg_1717043572605_WhatsApp_Image_20240530_at_091800.jpeg",
  "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572605_WhatsApp_Image_20240530_at_091800.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665801740a6e5305631a27f1",
  "name":
"externallmg_1717043572606_WhatsApp_Image_20240530_at_091801_1.jpeg",
  "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572606_WhatsApp_Image_20240530_at_091801_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665801740a6e5305631a27f2",
  "name":
"externallmg_1717043572608_WhatsApp_Image_20240530_at_091801_2.jpeg",
  "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572608_WhatsApp_Image_20240530_at_091801_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f3",
    "name":
"externallmg_1717043572609_WhatsApp_Image_20240530_at_091801.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572609_WhatsApp_Image_20240530_at_091801.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f4",
    "name":
"externallmg_1717043572611_WhatsApp_Image_20240530_at_091802_1.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572611_WhatsApp_Image_20240530_at_091802_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f5",
    "name":
"externallmg_1717043572615_WhatsApp_Image_20240530_at_091802_2.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572615_WhatsApp_Image_20240530_at_091802_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f6",
    "name":
"externallmg_1717043572617_WhatsApp_Image_20240530_at_091802_3.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572617_WhatsApp_Image_20240530_at_091802_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f7",
```

```

    "name":
    "externallmg_1717043572619_WhatsApp_Image_20240530_at_091802.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572619_WhatsApp_Image_20240530_at_091802.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f8",
    "name":
    "externallmg_1717043572622_WhatsApp_Image_20240530_at_091803_1.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572622_WhatsApp_Image_20240530_at_091803_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665801740a6e5305631a27f9",
    "name":
    "externallmg_1717043572625_WhatsApp_Image_20240530_at_091803.jpeg",
    "path": "cases/664c3c856f40574290c2181b/
externallmg_1717043572625_WhatsApp_Image_20240530_at_091803.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-21T06:17:41.955Z",
"updatedAt": "2024-05-30T04:32:52.853Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdcf2"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
