

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "35000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "AM161706-3",
"label": "Chartered Engineer"
},
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.136839159028053",
  "longitude": "72.86161109999159"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Majas",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1 & 2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Jogeshwari (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Ashtavinayak Apartments",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A, B & C",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Ashtavinayak Apartments",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "68, 68/1, to 20, 69, 70, 70/1 to 26, 71, 71/1 to 38, 72, 72/1 to 26, 73, 73/1
to 14, 74 & 74/1 to 17",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400060",
```

```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "664f17580a8d0618471578af",
"ownerName": "M/s. Shiv Shruti Developers LLP ",
"ownerPhoneNo": "7977952834",
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. Basement Floor,
Building No 1 & 2, Wing - A, B & C, Ashtavinayak Apartments, Ashtavinayak
Apartments, CTS No. 68, 68/1, to 20, 69, 70, 70/1 to 26, 71, 71/1 to 38, 72, 72/1 to 26,
73, 73/1 to 14, 74 & 74/1 to 17, Village - Majas, Taluka - Borivali, District - Mumbai
Suburban, Jogeshwari (East), 400060",
"remark": "3rd LIE Report",
"documents": [
  {
    "documentType": {
```

```
    "value": "641d4da529e5586db05ed8e8",
    "label": "CA Certificate"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1716459346677_COST_INCURRED_CERTIFICATE__MAR
24_SHIV_SHRUTI.pdf",
  "path": "cases/664f17580a8d0618471578af/document_1716459346677_COST_INC
URRED_CERTIFICATE__MAR24_SHIV_SHRUTI.pdf",
  "id": "993380",
  "uploadedBy": "60f91822f3dd69653a5922e3",
  "createdAt": "Thu May 23 2024 15:45:52 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008886",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "417884",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 23 2024 15:45:52 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Shiv Shruti Developers LLP ",
    "phone": "7977952834",
    "ownershipShare": "",
    "email": "",
    "id": "325493"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe18104981fc",
  "name": "externallmg_1716459860217_IMG_20240406_130232.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459860217_IMG_20240406_130232.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe18104981fd",
  "name": "externallmg_1716459862729_IMG_20240406_130815.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459862729_IMG_20240406_130815.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe18104981fe",
  "name": "externallmg_1716459863149_IMG_20240406_130817.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459863149_IMG_20240406_130817.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe18104981ff",
  "name": "externallmg_r_1716459857418_IMG_20240406_125837.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459857418_IMG_20240406_125837.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe1810498200",
  "name": "externallmg_r_1716459857692_IMG_20240406_125845.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459857692_IMG_20240406_125845.jpg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664f1959415afe1810498201",
"name": "externallmg_r_1716459858003_IMG_20240406_125943.jpg",
"path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459858003_IMG_20240406_125943.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664f1959415afe1810498202",
"name": "externallmg_r_1716459858351_IMG_20240406_125946.jpg",
"path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459858351_IMG_20240406_125946.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664f1959415afe1810498203",
"name": "externallmg_r_1716459858716_IMG_20240406_125952.jpg",
"path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459858716_IMG_20240406_125952.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664f1959415afe1810498204",
"name": "externallmg_r_1716459858969_IMG_20240406_125958.jpg",
"path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459858969_IMG_20240406_125958.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "664f1959415afe1810498205",
"name": "externallmg_r_1716459859599_IMG_20240406_130118.jpg",
"path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459859599_IMG_20240406_130118.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "664f1959415afe1810498206",
  "name": "externalimg_r_1716459859291_IMG_20240406_130113.jpg",
  "path": "cases/664f17580a8d0618471578af/
externalimg_r_1716459859291_IMG_20240406_130113.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe1810498207",
  "name": "externalimg_r_1716459859841_IMG_20240406_130122.jpg",
  "path": "cases/664f17580a8d0618471578af/
externalimg_r_1716459859841_IMG_20240406_130122.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe1810498208",
  "name": "externalimg_r_1716459860529_IMG_20240406_130307.jpg",
  "path": "cases/664f17580a8d0618471578af/
externalimg_r_1716459860529_IMG_20240406_130307.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe1810498209",
  "name": "externalimg_r_1716459860857_IMG_20240406_130356.jpg",
  "path": "cases/664f17580a8d0618471578af/
externalimg_r_1716459860857_IMG_20240406_130356.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f1959415afe181049820a",
  "name": "externalimg_r_1716459861289_IMG_20240406_130450.jpg",
  "path": "cases/664f17580a8d0618471578af/
externalimg_r_1716459861289_IMG_20240406_130450.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "664f1959415afe181049820b",
    "name": "externallmg_r_1716459861662_IMG_20240406_130457.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459861662_IMG_20240406_130457.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f1959415afe181049820c",
    "name": "externallmg_r_1716459861916_IMG_20240406_130501.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459861916_IMG_20240406_130501.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f1959415afe181049820d",
    "name": "externallmg_r_1716459862298_IMG_20240406_130503.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459862298_IMG_20240406_130503.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f196c99e95b180a31e938",
    "name":
"externallmg_1716459881918_20240406_12614PMBByGPSMapCamera.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459881918_20240406_12614PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f196c99e95b180a31e939",
    "name":
"externallmg_1716459881955_20240406_12616PMBByGPSMapCamera.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459881955_20240406_12616PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "664f196c99e95b180a31e93a",
  "name": "externallmg_1716459881999_IMG_20240404_110413.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459881999_IMG_20240404_110413.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f196c99e95b180a31e93b",
  "name": "externallmg_1716459882211_IMG_20240404_110420.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459882211_IMG_20240404_110420.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f196c99e95b180a31e93c",
  "name": "externallmg_1716459882518_IMG_20240404_110421.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459882518_IMG_20240404_110421.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f196c99e95b180a31e93d",
  "name": "externallmg_1716459882725_IMG_20240404_110424.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459882725_IMG_20240404_110424.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "664f196c99e95b180a31e93e",
  "name": "externallmg_1716459883367_IMG_20240406_112154.jpg",
  "path": "cases/664f17580a8d0618471578af/
externallmg_1716459883367_IMG_20240406_112154.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "664f196c99e95b180a31e93f",
    "name": "externallmg_r_1716459883040_IMG_20240404_110428.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459883040_IMG_20240404_110428.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157abf",
    "name": "externallmg_1716459903808_IMG_20240406_122421.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459903808_IMG_20240406_122421.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac0",
    "name": "externallmg_1716459904219_IMG_20240406_122423.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459904219_IMG_20240406_122423.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac1",
    "name": "externallmg_1716459904582_IMG_20240406_122427.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459904582_IMG_20240406_122427.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac2",
    "name": "externallmg_1716459904943_IMG_20240406_122428.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459904943_IMG_20240406_122428.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac3",
```



```
    "name": "externallmg_1716459906988_IMG_20240406_132919.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459906988_IMG_20240406_132919.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac4",
    "name": "externallmg_1716459907391_IMG_20240406_132931.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459907391_IMG_20240406_132931.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac5",
    "name": "externallmg_1716459907743_IMG_20240406_132933.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_1716459907743_IMG_20240406_132933.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac6",
    "name": "externallmg_r_1716459901623_IMG_20240406_122114.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459901623_IMG_20240406_122114.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac7",
    "name": "externallmg_r_1716459901856_IMG_20240406_122129.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459901856_IMG_20240406_122129.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac8",
    "name": "externallmg_r_1716459902143_IMG_20240406_122139.jpg",
```

```
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459902143_IMG_20240406_122139.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ac9",
    "name": "externallmg_r_1716459902473_IMG_20240406_122340.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459902473_IMG_20240406_122340.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157aca",
    "name": "externallmg_r_1716459902919_IMG_20240406_122343.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459902919_IMG_20240406_122343.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157acb",
    "name": "externallmg_r_1716459903339_IMG_20240406_122348.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459903339_IMG_20240406_122348.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157acc",
    "name": "externallmg_r_1716459905311_IMG_20240406_132903.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459905311_IMG_20240406_132903.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157acd",
    "name": "externallmg_r_1716459905744_IMG_20240406_132906.jpg",
    "path": "cases/664f17580a8d0618471578af/
externallmg_r_1716459905744_IMG_20240406_132906.jpg",
```

```

    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157ace",
    "name": "externalImg_r_1716459906168_IMG_20240406_132908.jpg",
    "path": "cases/664f17580a8d0618471578af/
externalImg_r_1716459906168_IMG_20240406_132908.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "664f19850a8d061847157acf",
    "name": "externalImg_r_1716459906554_IMG_20240406_132909.jpg",
    "path": "cases/664f17580a8d0618471578af/
externalImg_r_1716459906554_IMG_20240406_132909.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-23T10:15:53.031Z",
"updatedAt": "2024-05-23T10:25:09.597Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Mrs. Mona Mehta",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7977952834"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
