

```
{
  "typeOfReport": {
    "value": "Shop",
    "label": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64353bf7a99b2228209dbc5f"
    },
    "type": "CREDITOFFICER",
    "_id": "64353bf7a99b2228209dbc61",
    "firstName": "Vaijayanti ",
    "lastName": "Khade",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "vjbhiw@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64353bf7a99b2228209dbc5f",
  "name": "old Jakatnaka Branch\t",
  "branchCode": "",
  "mobileNo": "02522252724\t",
  "alternateMobileNo": "",
  "email": "vjbhiw@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Old Jakatnaka Branch , SHop No 1 & 2, Konark Arcade, Near Bhiwandi
Municipal Corporation, Bhiwandi, 4211302"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
  },
],
```

```
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.295264958572385",
  "longitude": "73.05859192675285"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-24T06:30:50.865Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-24",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-23",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
}
```

```
"rateMin": "8000",
"lumpsumValue": "2100000",
"rateMax": "9000",
"areaType": {
  "Name": "Carpet",
  "Value": "Carpet",
  "name": "Carpet",
  "value": "Carpet"
}
},
"compositionFlatType": {
  "value": "Single_Unit",
  "label": "Single Unit"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nagaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Fatema Apartment Co-Op. Hsg. Soc. Ltd",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Municipal House No. 220A, Nagaon Bhag - 2, Near Asma Mansion",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "95/1(P)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1144 ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "8",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 302",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "Vitrified_Tile_Flooring"
  },
  "doors": {
    "value": "Aluminium_frame_Glass_door_with_MS_Rolling_Shutter",
    "label": "Aluminium frame Glass door with MS Rolling Shutter"
  },
  "windows": {
    "value": "Alluminum_sliding_windows_with_M._S._Grills",
    "label": "Alluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
    "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  }
}
```

```

},
"townplanApprovedByList": {
  "value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
  "label": "Bhiwandi Nizampur City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Open Plot",
  "west": "Mohammed Apartment",
  "south": "Nagaon Road",
  "east": "Yaseen Mansion Apartment"
},
"asPerDocumentAgreement": {
  "north": "Power Loom Shed of Sanaullah",
  "west": "Property of Mukhtar Khan",
  "south": "40 Ft. Wide Road",
  "east": "Property of Yunus Seth"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Open Plot",
    "east": "Lobby",
    "south": "Shop No. 7",
    "west": "Open Plot"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": ". The Composition of Commercial Shop is Shop + Toilet.",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],

```

```
"documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "1. As per measurement Carpet area is 282.00 Sq. Ft. and as per Agreement Built up area is 250.00 Sq. Ft. For the purpose of valuation we have considered area as per Agreement.<br />\n2. As per Notice No. Assessment/617 dated 16.03.2006 issued by Bhiwandi Nizampur Municipal Council the property is illegal. It is recommended to get legal approvals of the same.<br />\n3. As per Sale Plan attach to the agreement, shops on ground floor are renumbered. \n",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "6562.5",
  "depreciatedBuildingRate": "1862.5"
},
"igrRate": {
  "propertyName": "Shop",
  "rate": "46200",
  "landRate": "7400",
  "igrImage": "cases/66502b8711aa646c01a590a2/igr_1717046027958_Image.png",
  "squareMeterGuideLineRate": "46200.00",
  "squareFeetGuideLineRate": "4292.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "83",
  "rate": "3679.00",
  "squareFeetGuideLineRate": "3679.00",
  "squareMeterGuideLineRate": "39604.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
```

```
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per BNMC norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2007",
```

```
"fullDate": "1/1/2007"
},
"planningArea": {
  "label": "Commercial",
  "value": "Commercial"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
}
```

```
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "43",
"ageOfBuilding": "17",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "4",
"flatFloorNo": "Ground",
"noOfLifts": "0",
"noOfDwellingUnitsInBuilding": "18"
},
"finalPlinthArea": {
  "area": "250.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Sale Deed"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/66502b8711aa646c01a590a2/
routeMap_1717052431248_Image.png",
    "routeLat": "19.301616",
    "routeLng": "73.071233",
    "stationName": "d",
    "routeDistance": "6.5 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "kuhy1",
      "name": "kuhy1",
      "image": "cases/66502b8711aa646c01a590a2/
routeMap_1717052332054_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "1640750.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "1640750.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu May 30 2024 16:18:20 GMT+0530 (India Standard Time)",
  "number": "2306521",
  "dayCount": "10",
  "monthCount": "381",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "919750.00",
  "selectedBuildUpValue": "250.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6650339e29882b6c3aac7c26",
      "name": "externalImg_1716532117768_image.jpeg",
      "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532117768_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6650339e29882b6c3aac7c26",
      "name": "externalImg_1716532117768_image.jpeg",
      "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532117768_image.jpeg",
      "orientation": "portrait"
    }
  ],
  {
    "status": false,
    "_id": "6650339e29882b6c3aac7c28",
    "name": "externalImg_1716532119674_image.jpeg",
```

```
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532119674_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6650339e29882b6c3aac7c27",
    "name": "externallmg_1716532119528_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532119528_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6650339e29882b6c3aac7c2c",
    "name": "externallmg_1716532120978_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532120978_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6650339e29882b6c3aac7c2b",
    "name": "externallmg_1716532120705_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532120705_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6650339e29882b6c3aac7c29",
    "name": "externallmg_1716532119873_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532119873_image.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "8182.00",
    "max": "12001.00"
  }
},
```

```
"builtUpRateRange": {
  "min": "6819.00",
  "max": "10000.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```



```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "250.00",
"empanelmentNo": [
"ZO:MZ:ADV:44:620"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "66502b8711aa646c01a590a2",
"ownerName": "Mr. Mohd. Naseem Mohd. Haroon Ansari",
"ownerPhoneNo": "8412852330",
"fullAddress": "Commercial Shop No. 8, Ground Floor, Fatema Apartment Co-Op. Hsg.
Soc. Ltd, Muncipal House No. 220A, Nagaon Bhag - 2, Near Asma Mansion, Plot No. 3,
New/Current Survey No. 95/1(P), CTS No. 1144 , Village - Nagaon, Taluka - Bhiwandi ,
District - Thane, PIN Code - 421 302, State - Maharashtra, India",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "60ae1245aa6d152c1801b2e3",
    "label": "Sale Deed"
  },
  "inputs": {
    "documentDate": "23/01/2008",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "M/s. Sania Construction ",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Mohd. Naseem Mohd. Haroon Ansari ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "789/2008"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "443062",
  "path": "cases/66502b8711aa646c01a590a2/document_1716626780089_Shop_No_8_Mohammed_Naseem_Mohammed_Haroon_Ansari.pdf",
  "fileName": "document_1716626780089_Shop_No_8_Mohammed_Naseem_Mohammed_Haroon_Ansari.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "18/07/2005",
    "nameOfApprovingAuthority": {
      "value": "Bhiwandi_Nizampur_City_Municipal_Corporation",
      "label": "Bhiwandi Nizampur City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "B.P.K. / 39 / 2005 - 2006 / Case No. NRV / 545 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1717050418918_146344.pdf",
  "path": "cases/66502b8711aa646c01a590a2/
document_1717050418918_146344.pdf",
  "id": "211296",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu May 30 2024 11:56:59 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "inputs": {
    "documentDate": "07/06/2021",
    "remark": " issued by Praksis Consultants & Valuers Pvt. Ltd.",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "PR / PCVPL / VLN / BOB / 18918 / 2021 "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName":
"document_1717050958473_Valuation__Shop_no_8__Naseem_Textiles.pdf",
  "path": "cases/66502b8711aa646c01a590a2/
document_1717050958473_Valuation__Shop_no_8__Naseem_Textiles.pdf",
  "id": "610102",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Thu May 30 2024 12:05:59 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "008890",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "305138",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Fri May 24 2024 11:24:15 GMT+0530 (India Standard Time)"
},
],
"owners": [
{
"name": "Mr. Mohd. Naseem Mohd. Haroon Ansari",
"phone": "8412852330",
"ownershipShare": "",
"email": "",
"id": "390288"
}
],
"proposePurchasers": [],
"siteInspection": [
{
"areaType": {
"label": "Carpet",
"value": "Carpet"
},
"providedBy": {
"label": "Owner",
"value": "Owner"
},
}_id": "665032e511aa646c01a595c4",
"area": "282",
"providedByName": "Mohammed Naseem Mohammed Haroon Ansari",
"providedByContactNo": "8412852330"
}
],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "692819",
"name": "Shop",
"length": "243.00",
"length1": "243",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "243.00",
"images": [],
```

```
"extraAreas": [],
"finalArea": "243.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "39.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "39.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "23.23",
    "totalAreaDocument": "250",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "892527"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "100.00",
      "squareMeterArea": "9.29",
      "expectedRate": "4000.00",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "120.00",
      "squareMeterArea": "11.15",
      "expectedRate": "3333.33",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": false,
    "_id": "66580bc105de72512029c057",
    "property": "Shop",
    "area": "120",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "400000",
    "expectedRate": "4000.00",
    "builtUpExpectedRate": "400000",
    "image": "cases/66502b8711aa646c01a590a2/
indicator_1717045852531_Image.png",
    "squareMeter": "11.15",
    "id": "305212"
  },
  {
    "carpetArea": {
      "area": "208.33",
      "squareMeterArea": "19.35",
      "expectedRate": "12000.19",
      "percentage": ""
    },
  },

```

```
"builtUpArea": {
  "area": "250.00",
  "squareMeterArea": "23.23",
  "expectedRate": "10000.00",
  "percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66580bc105de72512029c058",
"property": "Shop",
"area": "250",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "2500000",
"expectedRate": "12000.19",
"builtUpExpectedRate": "2500000",
"image": "cases/66502b8711aa646c01a590a2/
indicator_1717045888394_Image.png",
"squareMeter": "23.23",
"id": "367205"
},
{
  "carpetArea": {
    "area": "146.67",
    "squareMeterArea": "13.63",
    "expectedRate": "8181.63",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "176.00",
    "squareMeterArea": "16.35",
    "expectedRate": "6818.18",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
```

```
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66580bc105de72512029c059",
  "property": "Shop",
  "area": "176",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "1200000",
  "expectedRate": "8181.63",
  "builtUpExpectedRate": "1200000",
  "image": "cases/66502b8711aa646c01a590a2/
indicator_1717045926794_Image.png",
  "squareMeter": "16.35",
  "id": "401087"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c24",
    "name": "externalImg_1716532116851_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532116851_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c25",
    "name": "externalImg_1716532117409_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532117409_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c26",
    "name": "externalImg_1716532117768_image.jpeg",
```



```
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532117768_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c27",
    "name": "externallmg_1716532119528_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532119528_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c28",
    "name": "externallmg_1716532119674_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532119674_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c29",
    "name": "externallmg_1716532119873_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532119873_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c2a",
    "name": "externallmg_1716532120549_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532120549_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6650339e29882b6c3aac7c2b",
    "name": "externallmg_1716532120705_image.jpeg",
    "path": "cases/66502b8711aa646c01a590a2/
externallmg_1716532120705_image.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6650339e29882b6c3aac7c2c",
  "name": "externalImg_1716532120978_image.jpeg",
  "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532120978_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6650339e29882b6c3aac7c2d",
  "name": "externalImg_1716532121822_image.jpeg",
  "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532121822_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6650339e29882b6c3aac7c2e",
  "name": "externalImg_1716532122027_image.jpeg",
  "path": "cases/66502b8711aa646c01a590a2/
externalImg_1716532122027_image.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2)-shop.xlsx",
    "filename": "1717046201282_Calculation_2shop.xlsx",
    "path": "cases/66502b8711aa646c01a590a2/
processingDocuments/1717046201282_Calculation_2shop.xlsx",
    "size": "16239",
    "createdAt": "Thu May 30 2024 10:46:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1717046201283_igr1.pdf",
    "path": "cases/66502b8711aa646c01a590a2/
processingDocuments/1717046201283_igr1.pdf",
```

```
"size": "153603",
"createdAt": "Thu May 30 2024 10:46:41 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr2.pdf",
  "filename": "1717046201287_igr2.pdf",
  "path": "cases/66502b8711aa646c01a590a2/
processingDocuments/1717046201287_igr2.pdf",
  "size": "148702",
  "createdAt": "Thu May 30 2024 10:46:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr3.pdf",
  "filename": "1717046201292_igr3.pdf",
  "path": "cases/66502b8711aa646c01a590a2/
processingDocuments/1717046201292_igr3.pdf",
  "size": "152735",
  "createdAt": "Thu May 30 2024 10:46:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "igr4.pdf",
  "filename": "1717046201295_igr4.pdf",
  "path": "cases/66502b8711aa646c01a590a2/
processingDocuments/1717046201295_igr4.pdf",
  "size": "148940",
  "createdAt": "Thu May 30 2024 10:46:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
  "originalname": "Summary - shop.xlsx",
  "filename": "1717046201298_Summary__shop.xlsx",
  "path": "cases/66502b8711aa646c01a590a2/
processingDocuments/1717046201298_Summary__shop.xlsx",
  "size": "2566940",
  "createdAt": "Thu May 30 2024 10:46:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
```

```
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "665425a6786c9b043b83da93",
  "note": "Pending for Plan/OC",
  "taskId": "66502b8f11aa646c01a590fc",
  "createdAt": "2024-05-27T06:18:14.380Z"
}
],
"createdAt": "2024-05-24T05:54:15.091Z",
"updatedAt": "2024-05-30T11:00:47.247Z",
"__v": 0,
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Umair",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Representative",
"siteVisitContactNo": "8412852330",
"briefDescOfProperty": "Shop + Toilet",
"carpetTotal": "243.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2024-05-23",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Sale Deed",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 250.00",
"flatRate": "7200",
"landOtherRate": "4700",
"shopDetails": {
  "typeOfShops": {
```

```

    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": true,
  "mall": false
},
"builtupPercentage": "10",
"finalBuiltupArea": "310.20",
"finalCarpetArea": "282.00",
"finalSalableArea": "341.22",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
},
"reportGeneratedDate": "Thu May 30 2024 12:34:08 GMT+0530 (India Standard
Time)"
}

```

Name	Length	Width	Total
Composition :			
Shop	243'00"	1'00"	243.00
Toilet	13'00"	3'00"	39.00

Other  
Composition :

---