

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "665423c2786c9b043b83d7b3"
    },
    "type": "CREDITOFFICER",
    "_id": "665423c2786c9b043b83d7b5",
    "firstName": "Nishant",
    "lastName": "Bhardwaj",
    "mobileNo": "",
    "workMobileNo": "9453010520",
    "email": "nishant.bhardwaj@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "665423c2786c9b043b83d7b3",
  "name": "Specialized Commercial Branch Moradabad",
  "branchCode": "",
  "mobileNo": "05912476206",
  "alternateMobileNo": "",
  "email": "sbi.04113@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Specialized Commercial Branch \nCIVIL LINES, MORADABAD,
\nKUTCHERY ROAD Moradabad 244001 UTTAR PRADESH"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
```

```
"type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
```

```
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},

```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.18348012671091",
  "longitude": "72.86213510030888"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-27",
      "remark": ""
    }
  ]
},
"schedule": []
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Malad (East)",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "44",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Mumbai Suburban",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Omkar Altamonte Tower - A Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": ""
}
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Konkani Pada",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shantaram Talao, Off. Western Express Highway",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "812 (Part), 813, 821(Part), 844",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "4408",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 097",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Proposed_Powder_coated_aluminium_sliding_windows",
"label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering_+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Sole_Ownership",
"label": "Sole Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
}
},
```

```
"asPerActualAgreement": {
  "north": "Slum Area",
  "west": "Omkar SRA Building",
  "south": "Janki Niwas Building",
  "east": "Slum Area "
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "13.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "27695",
  "depreciatedBuildingRate": "2595"
```

```
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "168670",
  "landRate": "72420",
  "igrImage": "cases/6654251a9bc0d00b08d2c125/igr_1716799562290_Image.png",
  "squareMeterGuideLineRate": "202404.00",
  "squareFeetGuideLineRate": "18804.00"
},
"igrFinalRate": {
  "floorRatePercentage": "20",
  "depreciationPercentage": "91",
  "rate": "17717.00",
  "squareFeetGuideLineRate": "17717.00",
  "squareMeterGuideLineRate": "190705.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "Rs. 90,000/- Present rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per SRA norms",
  "tenantName": "Richa Chaturvedi",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located at developing area",
```

```
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "2 Car Parking ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2015",
    "fullDate": "1/1/2015"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
}
```

```
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
```

```
"label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "51",
"ageOfBuilding": "9",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "3",
"noOfFloors": "45",
"flatFloorNo": "44",
"noOfLifts": "7",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "1476.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  },
  "routeMapImg": "cases/6654251a9bc0d00b08d2c125/
routeMap_1716803191159_Image.png",
  "routeLat": "19.183388",
  "routeLng": "72.861490",
  "stationName": "Kurar",
  "routeDistance": "850 Mts"
},
"finalLatLng": {
```



```
"coordinates": [
  null,
  null
],
"type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "drliyk",
    "name": "drliyk",
    "image": "cases/6654251a9bc0d00b08d2c125/
routeMap_1716803076065_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "2",
  "othersRate": "1000000",
```

```
"totalOthersRate": "2000000",
"finalTotal": "36064850.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "34064850.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon May 27 2024 15:33:20 GMT+0530 (India Standard Time)",
  "number": "2306477",
  "dayCount": "10",
  "monthCount": "337",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "26150292.00",
  "selectedBuildUpValue": "1476.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c968",
      "name": "externallmg_1716792408224_1716792246312_image_0.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792408224_1716792246312_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c96a",
      "name": "externallmg_1716792412436_1716792246312_image_2.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792412436_1716792246312_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66542c591f66eb51479f41e1",
      "name": "externallmg_1716792384946_1716792213473_image_4.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792384946_1716792213473_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c96c",
      "name": "Kitchen",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792415696_1716792246312_image_4.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c6a9bc0d00b08d2c970",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792423915_1716792246312_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41e2",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792385075_1716792213473_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41e3",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792386301_1716792213473_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41e9",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792395749_1716792213473_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41eb",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792399543_1716792213473_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41ee",
    "name": "Kitchen",
```

```

    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792402801_1716792213474_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41ed",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792402238_1716792213474_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66542c591f66eb51479f41e7",
    "name": "Kitchen",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792391597_1716792213473_image_10.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26933.00",
    "max": "29938.00"
  },
  "builtUpRateRange": {
    "min": "22444.00",
    "max": "24949.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {

```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1230.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6654251a9bc0d00b08d2c125",
"ownerName": "Mr. Ashvinder Chowdhary",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9873162096",
"contactPersonName": "Mr. Bhagat ",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Ashvinder Chowdhary",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "796580"
  }
],
"caseReferredBy": "60eeaeddf3dd69653a581316",
"relationWithOwner": "Finance Director",
"fullAddress": "Residential Flat No. 4408, 44th Floor, Wing - A, Omkar Altamonte Tower - A Co-Op. Hsg. Soc. Ltd., Near Shantaram Talao, Off. Western Express Highway, Konkani Pada, Village - Malad (East), Taluka - Borivali, District - Mumbai Suburban, PIN - 400 097, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
    }
  }
]
```

```
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "24/07/2019",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mr. Manish Manoj Singh",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mr. Ashvinder Chowdhary",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "6787/2019"
},
"isHardCopy": false,
"displayStatus": true,
"id": "181417",
"path": "cases/6654251a9bc0d00b08d2c125/
document_1716790531473_166787.pdf",
"fileName": "document_1716790531473_166787.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "10/08/2011",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 2143 / PN / PL / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
}
```

```
"id": "263054",
"path": "cases/6654251a9bc0d00b08d2c125/
document_1716790549049_Scanned_Documents.pdf",
"fileName": "document_1716790549049_Scanned_Documents.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "23/12/2015",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 2143 / PN / PL & STGL / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "425779",
  "path": "cases/6654251a9bc0d00b08d2c125/
document_1716801949157_1716799607668_Occupancy_Certificate.pdf",
  "fileName":
"document_1716801949157_1716799607668_Occupancy_Certificate.pdf"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "008927",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "710662",
    "title": "Create Case",
    "description": "Create Case",
```

```
"datetime": "Mon May 27 2024 11:45:54 GMT+0530 (India Standard Time)"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "385568",
  "name": "Living Room",
  "length": "12.00",
  "length1": "12",
  "length2": "0",
  "width": "17.92",
  "width1": "17",
  "width2": "11",
  "totalArea": "215.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "215.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "113.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "113.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "2",
  "name": "Bedroom",
  "length": "16.25",
  "length1": "16",
  "length2": "3",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "177.40",
  "images": [],
  "extraAreas": [],
  "finalArea": "177.40"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "11.67",
  "length1": "11",
  "length2": "8",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "91.39",
  "images": [],
  "extraAreas": [],
  "finalArea": "91.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "11.33",
  "length1": "11",
  "length2": "4",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "123.72",
```

```
"images": [],
"extraAreas": [],
"finalArea": "123.72"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "14.33",
  "length1": "14",
  "length2": "4",
  "width": "5.50",
  "width1": "5",
  "width2": "6",
  "totalArea": "78.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "78.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "11.17",
  "width1": "11",
  "width2": "2",
  "totalArea": "57.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "57.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
```

```
"name": "Toilet",
"length": "4.75",
"length1": "4",
"length2": "9",
"width": "11.00",
"width1": "11",
"width2": "00",
"totalArea": "52.25",
"images": [],
"extraAreas": [],
"finalArea": "52.25"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "16.42",
  "width1": "16",
  "width2": "5",
  "totalArea": "79.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "79.35",
  "percentageBeforeTotal": "79.35",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
}
```



```
"name": {
  "label": "Passage",
  "value": "Passage"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length": "20.25",
"length1": "20",
"length2": "3",
"width": "3.50",
"width1": "3",
"width2": "6",
"totalArea": "70.87",
"images": [],
"extraAreas": [],
"finalArea": "70.87",
"percentageBeforeTotal": "70.87",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "2.50",
  "length1": "2",
  "length2": "6",
  "width": "5.08",
  "width1": "5",
  "width2": "1",
  "totalArea": "12.71",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.71",
```

```
"percentageBeforeTotal": "12.71",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length": "2.67",
  "length1": "2",
  "length2": "8",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "13.78",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.78",
  "percentageBeforeTotal": "13.78",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length": "3.50",
  "length1": "3",
```

```
"length2": "6",
"width": "5.83",
"width1": "5",
"width2": "10",
"totalArea": "20.42",
"images": [],
"extraAreas": [],
"finalArea": "20.42",
"percentageBeforeTotal": "20.42",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Wardrobes",
    "value": "Wardrobes"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "length": "5.08",
  "length1": "5",
  "length2": "1",
  "width": "6.25",
  "width1": "6",
  "width2": "3",
  "totalArea": "31.77",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.77",
  "percentageBeforeTotal": "31.77",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  }
}
```

```
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "length": "5.92",
    "length1": "5",
    "length2": "11",
    "width": "20.92",
    "width1": "20",
    "width2": "11",
    "totalArea": "123.76",
    "images": [],
    "extraAreas": [],
    "finalArea": "123.76",
    "percentageBeforeTotal": "123.76",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "591954",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "1230",
    "squareMeterArea": "114.27",
    "docFinalBuiltUp": "1476",
    "docFinalBuiltUpSquareMeter": "137.124",
    "docBuiltupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"carpetArea": {
  "area": "1048.00",
  "squareMeterArea": "97.36",
  "expectedRate": "26932.25",
  "percentage": ""
},
"builtUpArea": {
  "area": "1257.60",
  "squareMeterArea": "116.83",
  "expectedRate": "22443.54",
  "percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "665448569bc0d00b08d2e64b",
"property": "Residential Flat",
"area": "1048",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "28225000",
"expectedRate": "26932.25",
"builtUpExpectedRate": "22443.54",
"image": "cases/6654251a9bc0d00b08d2c125/
indicator_1716799195392_Image.png",
"squareMeter": "97.36",
"id": "542466"
},
{
  "carpetArea": {
    "area": "808.00",
    "squareMeterArea": "75.07",
    "expectedRate": "27227.72",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "969.60",
    "squareMeterArea": "90.08",
```

```
    "expectedRate": "22689.77",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "665448569bc0d00b08d2e64c",
  "property": "Residential Flat",
  "area": "808",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "22000000",
  "expectedRate": "27227.72",
  "builtUpExpectedRate": "22689.77",
  "image": "cases/6654251a9bc0d00b08d2c125/
indicator_1716799242569_Image.png",
  "squareMeter": "75.07",
  "id": "638341"
},
{
  "carpetArea": {
    "area": "1254.00",
    "squareMeterArea": "116.50",
    "expectedRate": "28708.13",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1504.80",
    "squareMeterArea": "139.80",
    "expectedRate": "23923.44",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```

```
"printlnReport": true,
"_id": "665448569bc0d00b08d2e64d",
"property": "Residential Flat",
"area": "1254",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "36000000",
"expectedRate": "28708.13",
"builtUpExpectedRate": "23923.44",
"image": "cases/6654251a9bc0d00b08d2c125/
indicator_1716799415695_Image.png",
"squareMeter": "116.50",
"id": "905183"
},
{
  "carpetArea": {
    "area": "1286.00",
    "squareMeterArea": "119.47",
    "expectedRate": "29937.79",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1543.20",
    "squareMeterArea": "143.37",
    "expectedRate": "24948.16",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "665448569bc0d00b08d2e64e",
  "property": "Residential Flat",
  "area": "1286",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
```

```
    "source": "magic_bricks",
    "expectedPrice": "38500000",
    "expectedRate": "29937.79",
    "builtUpExpectedRate": "24948.16",
    "image": "cases/6654251a9bc0d00b08d2c125/
indicator_1716799437064_Image.png",
    "squareMeter": "119.47",
    "id": "814810"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66542c6a9bc0d00b08d2c968",
    "name": "externallmg_1716792408224_1716792246312_image_0.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792408224_1716792246312_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66542c6a9bc0d00b08d2c969",
    "name": "externallmg_1716792409862_1716792246312_image_1.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792409862_1716792246312_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66542c6a9bc0d00b08d2c96a",
    "name": "externallmg_1716792412436_1716792246312_image_2.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792412436_1716792246312_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66542c6a9bc0d00b08d2c96b",
    "name": "externallmg_1716792414429_1716792246312_image_3.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792414429_1716792246312_image_3.jpeg",
    "orientation": "portrait"
  }
]
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c96c",
      "name": "externallmg_1716792415696_1716792246312_image_4.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792415696_1716792246312_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c96d",
      "name": "externallmg_1716792417401_1716792246312_image_5.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792417401_1716792246312_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c96e",
      "name": "externallmg_1716792420389_1716792246312_image_6.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792420389_1716792246312_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c96f",
      "name": "externallmg_1716792422121_1716792246312_image_7.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792422121_1716792246312_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66542c6a9bc0d00b08d2c970",
      "name": "externallmg_1716792423915_1716792246312_image_8.jpeg",
      "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792423915_1716792246312_image_8.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41dd",
  "name": "externallmg_1716792376479_1716792213471_image_0.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792376479_1716792213471_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41de",
  "name": "externallmg_1716792380371_1716792213473_image_1.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792380371_1716792213473_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41df",
  "name": "externallmg_1716792381565_1716792213473_image_2.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792381565_1716792213473_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41e0",
  "name": "externallmg_1716792383341_1716792213473_image_3.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792383341_1716792213473_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41e1",
  "name": "externallmg_1716792384946_1716792213473_image_4.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792384946_1716792213473_image_4.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41e2",
    "name": "externallmg_1716792385075_1716792213473_image_5.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792385075_1716792213473_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41e3",
    "name": "externallmg_1716792386301_1716792213473_image_6.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792386301_1716792213473_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41e4",
    "name": "externallmg_1716792387776_1716792213473_image_7.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792387776_1716792213473_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41e5",
    "name": "externallmg_1716792388759_1716792213473_image_8.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792388759_1716792213473_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41e6",
    "name": "externallmg_1716792389503_1716792213473_image_9.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792389503_1716792213473_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "66542c591f66eb51479f41e7",
  "name": "externallmg_1716792391597_1716792213473_image_10.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792391597_1716792213473_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41e8",
  "name": "externallmg_1716792393858_1716792213473_image_11.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792393858_1716792213473_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41e9",
  "name": "externallmg_1716792395749_1716792213473_image_12.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792395749_1716792213473_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41ea",
  "name": "externallmg_1716792397387_1716792213473_image_13.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792397387_1716792213473_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66542c591f66eb51479f41eb",
  "name": "externallmg_1716792399543_1716792213473_image_14.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792399543_1716792213473_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "66542c591f66eb51479f41ec",
    "name": "externallmg_1716792401418_1716792213474_image_15.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792401418_1716792213474_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41ed",
    "name": "externallmg_1716792402238_1716792213474_image_16.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792402238_1716792213474_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41ee",
    "name": "externallmg_1716792402801_1716792213474_image_17.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792402801_1716792213474_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41ef",
    "name": "externallmg_1716792404674_1716792213474_image_18.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792404674_1716792213474_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66542c591f66eb51479f41f0",
    "name": "externallmg_1716792406180_1716792213474_image_19.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/
externallmg_1716792406180_1716792213474_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```

```
    "originalname": "AGR.pdf",
    "filename": "1716799593714_AGR.pdf",
    "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799593714_AGR.pdf",
    "size": "7952408",
    "createdAt": "Mon May 27 2024 14:16:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AGR-1.pdf",
    "filename": "1716799593860_AGR1.pdf",
    "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799593860_AGR1.pdf",
    "size": "5050611",
    "createdAt": "Mon May 27 2024 14:16:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Commencement Certificate.pdf",
    "filename": "1716799593927_Commencement_Certificate.pdf",
    "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799593927_Commencement_Certificate.pdf",
    "size": "750136",
    "createdAt": "Mon May 27 2024 14:16:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1716792376479_1716792213471_image_0.jpeg",
    "filename":
"1716799593944_externallmg_1716792376479_1716792213471_image_0.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/processingDocuments/1716799593944
_externallmg_1716792376479_1716792213471_image_0.jpeg",
    "size": "1510417",
    "createdAt": "Mon May 27 2024 14:16:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1716792380371_1716792213473_image_1.jpeg",
    "filename":
"1716799594012_externallmg_1716792380371_1716792213473_image_1.jpeg",
    "path": "cases/6654251a9bc0d00b08d2c125/processingDocuments/1716799594012
_externallmg_1716792380371_1716792213473_image_1.jpeg",
    "size": "1196652",
    "createdAt": "Mon May 27 2024 14:16:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
}
```

```
{
  "originalname": "externallmg_1716792381565_1716792213473_image_2.jpeg",
  "filename":
"1716799594060_externallmg_1716792381565_1716792213473_image_2.jpeg",
  "path": "cases/6654251a9bc0d00b08d2c125/processingDocuments/1716799594060
_externallmg_1716792381565_1716792213473_image_2.jpeg",
  "size": "1161911",
  "createdAt": "Mon May 27 2024 14:16:34 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1716799600932_IGR01.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600932_IGR01.pdf",
  "size": "150813",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1716799600937_IGR02.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600937_IGR02.pdf",
  "size": "155424",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-03.pdf",
  "filename": "1716799600942_IGR03.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600942_IGR03.pdf",
  "size": "148756",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-04.pdf",
  "filename": "1716799600945_IGR04.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600945_IGR04.pdf",
  "size": "154828",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
}
```

```
{
  "originalname": "IGR-05.pdf",
  "filename": "1716799600950_IGR05.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600950_IGR05.pdf",
  "size": "151350",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-06.pdf",
  "filename": "1716799600953_IGR06.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600953_IGR06.pdf",
  "size": "156310",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-07.pdf",
  "filename": "1716799600956_IGR07.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600956_IGR07.pdf",
  "size": "153674",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-08.pdf",
  "filename": "1716799600959_IGR08.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600959_IGR08.pdf",
  "size": "151111",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-09.pdf",
  "filename": "1716799600962_IGR09.pdf",
  "path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600962_IGR09.pdf",
  "size": "167074",
  "createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
```



```
"originalname": "IGR-10.pdf",
"filename": "1716799600964_IGR10.pdf",
"path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799600964_IGR10.pdf",
"size": "154448",
"createdAt": "Mon May 27 2024 14:16:41 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Occupancy Certificate.pdf",
"filename": "1716799607668_Occupancy_Certificate.pdf",
"path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799607668_Occupancy_Certificate.pdf",
"size": "211822",
"createdAt": "Mon May 27 2024 14:16:47 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=ASHWINDER.xlsx",
"filename": "1716799607674_Summary_NewASHWINDER.xlsx",
"path": "cases/6654251a9bc0d00b08d2c125/
processingDocuments/1716799607674_Summary_NewASHWINDER.xlsx",
"size": "3336863",
"createdAt": "Mon May 27 2024 14:16:47 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-05-27T06:15:54.642Z",
"updatedAt": "2024-05-27T10:24:24.920Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60eeaeddf3dd69653a581316",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1230.00",
"flatRate": "28100",
"landOtherRate": "25100",
"shopDetails": {
"typeOfShops": {
```

```

    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 3 Toilet",
"carpetTotal": "909.72",
"otherCarpetTotal": "352.66",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "352.66",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1388.62",
"finalCarpetArea": "1262.38",
"finalSalableArea": "1527.48",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 1,175.00\nFlower Bed & Other area
in Sq. Ft. = 55.00\n",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	12'0"	17'11"	215.00

Bedroom	11'3"	10'1"	113.44
Bedroom	16'3"	10'11"	177.40
Kitchen	11'8"	7'10"	91.39
Bedroom	11'4"	10'11"	123.72
Toilet	14'4"	5'6"	78.83
Toilet	5'2"	11'2"	57.69
Toilet	4'9"	11'00"	52.25
Other Composition :			
Passage	4'10"	16'5"	79.35
Passage	20'3"	3'6"	70.87
Passage	2'6"	5'1"	12.71
Passage	2'8"	5'2"	13.78
Passage	3'6"	5'10"	20.42
Wardrobes	5'1"	6'3"	31.77
Balcony Area	5'11"	20'11"	123.76