

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "635f6f5de363ef22db2f1680",
    "firstName": "AVINASH ",
    "lastName": "THAKUR",
    "mobileNo": "",
    "email": "jagdish@vastukala.org",
    "workMobileNo": "7387226972"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "AVINASH ",
    "expectedFees": 5000,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.073898616431585",
  "longitude": "73.00056832793075"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.00056832793075,
    19.073898616431585
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "29/05/2024 01:38 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-29T18:02:28.188Z",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-05-29",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "30000",
  "lumpsumValue": "1",
  "rateMax": "31000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vashi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "75, Sector - 17",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vardhaman Market Premises Co-Op. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "428",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 703",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified tile flooring",
    "value": "Vitrified_tile_flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "label": "Powder coated Aluminum sliding windows",
    "value": "Powder_coated_Aluminum_sliding_windows"
  },
  "fittings": {
```

```
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "company_ownership",
    "label": "company ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Vashi Turbhe Road",
    "west": "JK Chambers Building",
    "south": "Internal Road",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Road ",
    "west": "Road ",
    "south": "Plot No. 76",
    "east": "Road "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
```

```
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "The Composition of Commercial Office is Working Area
only. ",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of site visit, external painting work of building is in progress. ",
  "depreciationPercentage": "50.666666666666664",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "20",
  "depreciatedCostOfConstruction": "25581.3333333333332",
  "depreciatedBuildingRate": "1381.3333333333335"
},
"igrRate": {
  "propertyName": "Office",
  "rate": "176700",
  "landRate": "75800",
  "igrImage": "cases/6656d36805de725120293fc8/igr_1717132027679_Image.png",
  "squareMeterGuideLineRate": "176700.00",
  "squareFeetGuideLineRate": "16416.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "62",
  "rate": "12854.00",
  "squareFeetGuideLineRate": "12854.00",
  "squareMeterGuideLineRate": "138358.00"
```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per CIDCO norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
}
```

```
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1986",
  "fullDate": "1/1/1986"
},
"planningArea": {
  "label": "Commercial",
  "value": "Commercial"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
```



```
"ageOfBuilding": "38",
"totalLifeBuilding": "60",
"estimatedAge": "22",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "4",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "13"
},
"finalPlinthArea": {
  "area": "760.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6656d36805de725120293fc8/
routeMap_1717147609146_Image.png",
    "routeLat": "19.073861",
    "routeLng": "73.000028",
    "stationName": "Vashi",
    "routeDistance": "1.2 Km "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "2slmm",
      "name": "2slmm",
      "image": "cases/6656d36805de725120293fc8/
routeMap_1717147636357_Image.png"
```

```
}
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "19441560.00",
  "finalValue": "19441560.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri May 31 2024 16:15:04 GMT+0530 (India Standard Time)",
  "number": "2306545",
  "dayCount": "14",
  "monthCount": "405",
```

```
"generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "9769040.00",
  "selectedBuildUpValue": "760.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66576e2c0a6e5305631a1f6a",
      "name": "externalImg_1717005848470_image.jpeg",
      "path": "cases/6656d36805de725120293fc8/
externalImg_1717005848470_image.jpeg",
```

```
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f6f",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005853305_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f6a",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005848470_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f6c",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005851014_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f6d",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005852005_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f70",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005853655_image.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f71",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005854839_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f72",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005855365_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f75",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005857155_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f74",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005856422_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f77",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005859234_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f78",
    "name": "Working Area",
```

```
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005860464_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66576e2c0a6e5305631a1f79",
    "name": "Working Area",
    "path": "cases/6656d36805de725120293fc8/
externallmg_1717005861309_image.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "30000.00",
    "max": "32666.00"
  },
  "builtUpRateRange": {
    "min": "25000.00",
    "max": "27222.00"
  },
  "saleableRateRange": {
    "min": "20834.00",
    "max": "21787.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```



```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "760.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "ATTACHSIGN",
"invoices": [],
"paymentIds": [],
"_id": "6656d36805de725120293fc8",
"ownerName": "M/s. Progressive Civil Construction Co.(P) Ltd.",
"ownerPhoneNo": "9892829732",
"appAddress": "Office no. 428, 4th Floor, Plot no. 75, Sector - 17, Vardhman Market
Premises, Navi Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "09/12/1985",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Vardhaman Constructions",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "M/s. Progressive Civil Construction Co.(P) Ltd.",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "Not available "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "844347",
    "path": "cases/6656d36805de725120293fc8/document_1716966281936_17169661
17871_SBI_SME_Chembur_428_Progressive_Civil_Const.pdf",
    "fileName": "document_1716966281936_1716966117871_SBI_SME_Chembur_428
```

```
_Progressive_Civil_Const.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/10/1986",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "BP / 9 / 17 / 751 / 288"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1717146094858_825727.pdf",
"path": "cases/6656d36805de725120293fc8/
document_1717146094858_825727.pdf",
"id": "665379",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Fri May 31 2024 14:31:35 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "09/10/1992",
    "remark": " issued by Vardhaman Market Premises Co-Op. Soc. Ltd",
    "to": {
      "value": "Transferee",
      "label": "Transferee"
    },
    "Transferee": "M/s. Progressive Civil Construction Co.(P) Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "146"
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1717146218666_Agreement.pdf",
    "path": "cases/6656d36805de725120293fc8/
document_1717146218666_Agreement.pdf",
    "id": "255969",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Fri May 31 2024 14:33:39 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "008976",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "619618",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 29 2024 12:34:08 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Progressive Civil Construction Co.(P) Ltd.",
    "phone": "9892829732",
    "ownershipShare": "",
    "email": "",
    "id": "890585"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "66576d5f0a6e5305631a1f53",
    "area": "668",
    "providedByName": "Progressive Civil Construction Co. Pvt Ltd ",
    "providedByContactNo": "9892829732"
  }
]
```

```
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Working Area",
    "length": "668.00",
    "length1": "668",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "668.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "668.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "828351",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "760",
    "squareMeterArea": "70.61",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBultupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
```

```
"indicatorArr": [
  {
    "carpetArea": {
      "area": "330.00",
      "squareMeterArea": "30.66",
      "expectedRate": "31212.12",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "396.00",
      "squareMeterArea": "36.79",
      "expectedRate": "26010.10",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "475.20",
      "squareMeterArea": "44.15",
      "expectedRate": "21675.08",
      "percentage": "20"
    },
    "printlnReport": true,
    "_id": "66595b11ae79696a5230ccab",
    "property": "Office",
    "area": "330",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "10300000",
    "expectedRate": "31212.12",
    "builtUpExpectedRate": "26010.10",
    "image": "cases/6656d36805de725120293fc8/
indicator_1717131857047_Image.png",
    "squareMeter": "30.66",
    "id": "702136"
  },
  {
    "carpetArea": {
      "area": "255.00",
      "squareMeterArea": "23.69",
      "expectedRate": "31372.55",
      "percentage": ""
    },
    "builtUpArea": {
```

```
"area": "306.00",
"squareMeterArea": "28.43",
"expectedRate": "26143.79",
"percentage": "20"
},
"saleableArea": {
"area": "367.20",
"squareMeterArea": "34.11",
"expectedRate": "21786.49",
"percentage": "20"
},
"printlnReport": true,
"_id": "66595b11ae79696a5230ccac",
"property": "Office",
"area": "255",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "8000000",
"expectedRate": "31372.55",
"builtUpExpectedRate": "26143.79",
"image": "cases/6656d36805de725120293fc8/
indicator_1717131899847_Image.png",
"squareMeter": "23.69",
"id": "699176"
},
{
"carpetArea": {
"area": "400.00",
"squareMeterArea": "37.16",
"expectedRate": "30000.00",
"percentage": ""
},
"builtUpArea": {
"area": "480.00",
"squareMeterArea": "44.59",
"expectedRate": "25000.00",
"percentage": "20"
},
"saleableArea": {
"area": "576.00",
"squareMeterArea": "53.51",
"expectedRate": "20833.33",
```



```
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "66595b11ae79696a5230ccad",
  "property": "Office",
  "area": "400",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "12000000",
  "expectedRate": "30000.00",
  "builtUpExpectedRate": "25000.00",
  "image": "cases/6656d36805de725120293fc8/
indicator_1717131944379_Image.png",
  "squareMeter": "37.16",
  "id": "890149"
},
{
  "carpetArea": {
    "area": "881.67",
    "squareMeterArea": "81.91",
    "expectedRate": "32665.28",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1058.00",
    "squareMeterArea": "98.29",
    "expectedRate": "27221.17",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66595b11ae79696a5230ccae",
  "property": "Office",
  "area": "1058",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
```

```
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "28800000",
"expectedRate": "32665.28",
"builtUpExpectedRate": "28800000",
"image": "cases/6656d36805de725120293fc8/
indicator_1717131984396_Image.png",
"squareMeter": "98.29",
"id": "988616"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66576e2c0a6e5305631a1f67",
"name": "externalImg_1717005845275_image.jpeg",
"path": "cases/6656d36805de725120293fc8/
externalImg_1717005845275_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66576e2c0a6e5305631a1f68",
"name": "externalImg_1717005846080_image.jpeg",
"path": "cases/6656d36805de725120293fc8/
externalImg_1717005846080_image.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66576e2c0a6e5305631a1f69",
"name": "externalImg_1717005846660_image.jpeg",
"path": "cases/6656d36805de725120293fc8/
externalImg_1717005846660_image.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66576e2c0a6e5305631a1f6a",
"name": "externalImg_1717005848470_image.jpeg",
"path": "cases/6656d36805de725120293fc8/
externalImg_1717005848470_image.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f6b",
  "name": "externallmg_1717005850730_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005850730_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f6c",
  "name": "externallmg_1717005851014_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005851014_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f6d",
  "name": "externallmg_1717005852005_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005852005_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f6e",
  "name": "externallmg_1717005852836_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005852836_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f6f",
  "name": "externallmg_1717005853305_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005853305_image.jpeg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f70",
  "name": "externallmg_1717005853655_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005853655_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f71",
  "name": "externallmg_1717005854839_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005854839_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f72",
  "name": "externallmg_1717005855365_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005855365_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f73",
  "name": "externallmg_1717005855890_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005855890_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f74",
  "name": "externallmg_1717005856422_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005856422_image.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f75",
  "name": "externallmg_1717005857155_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005857155_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f76",
  "name": "externallmg_1717005858014_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005858014_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f77",
  "name": "externallmg_1717005859234_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005859234_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f78",
  "name": "externallmg_1717005860464_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005860464_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66576e2c0a6e5305631a1f79",
  "name": "externallmg_1717005861309_image.jpeg",
  "path": "cases/6656d36805de725120293fc8/
externallmg_1717005861309_image.jpeg",
  "orientation": "landscape"
}
],
```

```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "PROGRESSIVE CIVIL CONSTRUCTION CO. PVT LTD - Office
No. 428 - State Bank Of India ( SME Chembur Branch ).xlsx",
    "filename": "1717132109948_PROGRESSIVE_CIVIL_CONSTRUCTION_CO_PVT_
LTD__Office_No_428__State_Bank_Of_India__SME_Chembur_Branch_.xlsx",
    "path": "cases/6656d36805de725120293fc8/processingDocuments/1717132109948
_PROGRESSIVE_CIVIL_CONSTRUCTION_CO_PVT_LTD__Office_No_428__State_
Bank_Of_India__SME_Chembur_Branch_.xlsx",
    "size": "2408352",
    "createdAt": "Fri May 31 2024 10:38:30 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66581228fdeb5710b5306ea2",
    "note": "Value given for confirmation",
    "taskId": "6656e3341f66eb5147a02e24",
    "createdAt": "2024-05-30T05:44:08.688Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
  }
]
```

```
"status": true,
  "_id": "6658123944a09a10ae6e7974",
  "note": "Value given for confirmation",
  "taskId": "6656e3341f66eb5147a02e24",
  "createdAt": "2024-05-30T05:44:25.693Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "6659c33ae2cb0e7b267e8cf8",
  "note": "for office details (Task Reopen)",
  "taskId": "66599950ad7c5448f4585e08",
  "createdAt": "2024-05-31T12:31:54.747Z"
}
],
"createdAt": "2024-05-29T07:04:08.432Z",
"updatedAt": "2024-05-31T12:33:55.858Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Commercial Office No. 428, 4th Floor, Wing - B, Vardhaman Market
Premises Co-Op. Soc. Ltd., Plot No. 75, Sector - 17, Village - Vashi, Taluka - Thane ,
District - Thane, Navi Mumbai, PIN - 400 703, State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Satish ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Staff ",
```

```
"siteVisitContactNo": "9892829732",
"briefDescOfProperty": "Working Area",
"carpetTotal": "668.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2024-05-29",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 760.00",
"flatRate": "27000",
"landOtherRate": "24200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "734.80",
"finalCarpetArea": "668.00",
"finalSalableArea": "808.28",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Fri May 31 2024 13:55:39 GMT+0530 (India Standard Time)",
```


"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Working Area	668'00"	1'00"	668.00
Other Composition :			