

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba02"
    },
    "firstName": "Kartik",
    "type": "CREDITOFFICER",
    "_id": "652fa4137e32132d40941604",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9894342916",
    "email": "churchgate.mumbaisouth@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Kartik",
    "expectedFees": 4250,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba02",
  "branchCode": "000032",
  "type": "BRANCH",
  "name": "Churchgate Branch",
  "email": "churchgate.mumbaisouth@bankofindia.co.in",
  "mobileNo": "91-9892590375",
  "alternateMobileNo": "",
  "address": "Eros Theatre Building, Hight Court Jamshedji Tata Road, Post Box No.
11013, \r\nMumbai - 400020, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4336576061dae469362",
  "zoneName": "Mumbai South Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62727444afd7d55eddee092c",
  "role": "PICKUPPERSON",
  "firstName": "Shantilal",
  "email": "shantilal@vastukala.org",
  "lastName": "Patel",
  "mobileNo": "9969039853",
  "shortName": "SHP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fd2c2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
```

```
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.438823514856555",
  "longitude": "73.30841561683556"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.30841561683556,
```

```
19.438823514856555
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-04",
      "remark": "Report valuation \n"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-04",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Asangaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": false,
    "name": "City",
```

```
"key": "city",
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Shahapur ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Dham Residency",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
}
```



```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "109/9 (P), 109/11",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 601",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
```

```
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Aluminium_Sliding_Windows_with_window_grills",
  "label": "Aluminium Sliding Windows with window grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  },
  "townplanApprovedByList": {
    "value": "Gram_Panchayat_Asangaon",
    "label": "Gram Panchayat Asangaon"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Krushna Apartment",
    "south": "Tulsi Vihar Building",
    "east": "Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
```

```
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of approved Building plan ware not provided & not
Verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
}
```

```
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "13.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "3162.5",
  "depreciatedBuildingRate": "2162.5"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "37600",
  "landRate": "2600",
  "igrImage": "cases/665989e4ad7c5448f4585013/igr_1717572413725_Image.png",
  "squareMeterGuideLineRate": "37600.00",
  "squareFeetGuideLineRate": "3493.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "91",
  "rate": "3201.00",
  "squareFeetGuideLineRate": "3201.00",
  "squareMeterGuideLineRate": "34450.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "4,000/- Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per Grampanchayat Asangaon norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
```

```
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developing Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\`_Thk._Brick_Masonry",
    "label": "6\` Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2015",
    "fullDate": "1/1/2015"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
```

```
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Average",
"label": "Average"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenancelssues": {
"value": "0",
"label": "No"
}
```



```
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "51",
"ageOfBuilding": "9",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "2",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "615.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/665989e4ad7c5448f4585013/
routeMap_1719055731693_Image.png",
```

```
"routeLat": "19.438914",
"routeLng": "73.308889",
"stationName": "Asangaon",
"routeDistance": "130 Mts."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "m4kc4h",
    "name": "m4kc4h",
    "image": "cases/665989e4ad7c5448f4585013/
routeMap_1719055660326_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "1945245.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "1945245.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Jun 26 2024 17:19:55 GMT+0530 (India Standard Time)",
  "number": "2306921",
  "dayCount": "19",
  "monthCount": "365",
  "generatedBy": "627221f4afd7d55eddeddcb4"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "1968615.00",
  "selectedBuildUpValue": "615.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "665e999aa800141581280250",
      "name": "externallmg_r_1717475705979_1717475540143_image_5.jpg",
      "path": "cases/665989e4ad7c5448f4585013/externallmg_r_1717475705979_1717475540143_image_5.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "665e999aa800141581280253",
      "name": "externallmg_r_1717475716778_1717475540143_image_9.jpg",
      "path": "cases/665989e4ad7c5448f4585013/externallmg_r_1717475716778_1717475540143_image_9.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "665e999aa800141581280250",
      "name": "externallmg_r_1717475705979_1717475540143_image_5.jpg",
      "path": "cases/665989e4ad7c5448f4585013/externallmg_r_1717475705979_1717475540143_image_5.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "665e999aa80014158128025a",
```

```
    "name": "externallmg_r_1717475732221_1717475540143_image_16.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475732221_1717475540143_image_16.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "665e999aa800141581280258",
    "name": "externallmg_r_1717475728216_1717475540143_image_14.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475728216_1717475540143_image_14.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "665e999aa800141581280254",
    "name": "Living Room",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475718900_1717475540143_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "665e999aa800141581280255",
    "name": "Living Room",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475721018_1717475540143_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "665e999aa800141581280256",
    "name": "Living Room",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475723376_1717475540143_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "665e999aa80014158128024f",
    "name": "Living Room",
```

```
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475708854_1717475540143_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "665e999aa80014158128024b",
    "name": "Living Room",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475698192_1717475540143_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "665e999aa800141581280251",
    "name": "Living Room",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475710098_1717475540143_image_7.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "3884.00",
    "max": "5650.00"
  },
  "builtUpRateRange": {
    "min": "3233.00",
    "max": "4706.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```



```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "615.00",
"empanelmentNo": [
  "KZO/CR/19-20/582"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "665989e4ad7c5448f4585013",
"ownerName": "Shri. Dattatraya Shankar Jagale",
"ownerPhoneNo": "8898983134",
"appAddress": "202 \nB wing saidham Recidency \nAshangon \nnear Railway station
\nThane ",
"remark": "Report valuation \n",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "25/06/2013",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "Ms. Saisiddhi Builder's and Developers",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Dattatraya Shankar Jagale",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  },

```

```
    "No": "3836/2013"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "942915",
  "path": "cases/665989e4ad7c5448f4585013/document_1717143999951_1717143840883_Dattatray_Shankar_Jangle_boi_churchgate_.pdf",
  "fileName": "document_1717143999951_1717143840883_Dattatray_Shankar_Jangle_boi_churchgate_.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "13/03/2010",
    "remark": "Issued by Grampanchayat Asangon",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "Tharav No. 56 / 2010"
},
  "isHardCopy": false,
  "displayStatus": false,
  "id": "954892",
  "path": "cases/665989e4ad7c5448f4585013/document_1717225701542_276553.pdf",
  "fileName": "document_1717225701542_276553.pdf"
}
],
"caseNumber": "009027",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "279637",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri May 31 2024 13:57:16 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Dattatraya Shankar Jagale",
    "phone": "8898983134",
```

```
"ownershipShare": "",
"email": "",
"id": "717940"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "7",
"name": "Living Room",
"length": "1.00",
"length1": "14",
"length2": "2",
"width": "0.00",
"width1": "10",
"width2": "0",
"totalArea": "141.67",
"images": [],
"finalArea": "141.66999999999996",
"extraAreas": []
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Bedroom",
"length": "13.33",
"length1": "13",
"length2": "4",
"width": "9.42",
"width1": "9",
"width2": "5",
"totalArea": "125.56",
"images": [],
"extraAreas": [],
"finalArea": "125.56"
},
{
"measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "7.25",
  "width1": "7",
  "width2": "3",
  "totalArea": "62.23",
  "images": [],
  "extraAreas": [],
  "finalArea": "62.23"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "2.58",
  "width1": "2",
  "width2": "7",
  "totalArea": "10.98",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.98"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "4.00",
  "length1": "4",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
```

```
"width2": "0",
"totalArea": "20.00",
"images": [],
"extraAreas": [],
"finalArea": "20.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "",
  "length1": "3",
  "length2": "7",
  "width": "",
  "width1": "8",
  "width2": "0",
  "totalArea": "28.67",
  "images": [],
  "finalArea": "28.67",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "1.42",
  "length1": "1",
  "length2": "5",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "5.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "5.67"
}
],
"otherComposition": [
  {
    "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "10.00",
  "length1": "10",
  "length2": "0",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "31.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.67",
  "percentageBeforeTotal": "31.67",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "57.14",
    "totalAreaDocument": "615.00",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
```



```
"id": "527417"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "412.00",
    "squareMeterArea": "38.28",
    "expectedRate": "3883.50",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "495.00",
    "squareMeterArea": "45.99",
    "expectedRate": "3232.32",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "6660136476299a636b9a9477",
  "property": "Naren Monisha CHSL, Asangaon East ",
  "area": "495.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "1600000.00",
  "expectedRate": "3883.50",
  "builtUpExpectedRate": "1600000.00",
  "image": "cases/665989e4ad7c5448f4585013/
indicator_1717571664581_Image.png",
  "squareMeter": "45.99",
  "id": "261033"
},
{
  "carpetArea": {
    "area": "325.00",
    "squareMeterArea": "30.19",
```

```
    "expectedRate": "5230.77",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "390.00",
    "squareMeterArea": "36.23",
    "expectedRate": "4358.97",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "6660136476299a636b9a9478",
  "property": "Gulmohar Society, near Hotel Royal Residency, Asangaon",
  "area": "390.00",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "1700000.00",
  "expectedRate": "5230.77",
  "builtUpExpectedRate": "1700000.00",
  "image": "cases/665989e4ad7c5448f4585013/
indicator_1717571770050_Image.png",
  "squareMeter": "36.23",
  "id": "432997"
},
{
  "carpetArea": {
    "area": "404",
    "squareMeterArea": "37.53",
    "expectedRate": "4455.45",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "485.00",
    "squareMeterArea": "45.06",
    "expectedRate": "3711.34",
    "percentage": ""
  },
}
```

```
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "6660136476299a636b9a9479",
"property": "1 BHK Flat In Yalow Tree For Sale In Asangaon",
"area": "485.00",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "1800000.00",
"expectedRate": "4455.45",
"builtUpExpectedRate": "1800000.00",
"image": "cases/665989e4ad7c5448f4585013/
indicator_1717571847447_Image.png",
"squareMeter": "45.06",
"id": "539864"
},
{
  "carpetArea": {
    "area": "354.00",
    "squareMeterArea": "32.89",
    "expectedRate": "5649.72",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "425.00",
    "squareMeterArea": "39.48",
    "expectedRate": "4705.88",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "6660136476299a636b9a947a",
  "property": "Rathi Osho Dhara Park For Sale In Asangaon",
```

```
"area": "425.00",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "2000000.00",
"expectedRate": "5649.72",
"builtUpExpectedRate": "2000000.00",
"image": "cases/665989e4ad7c5448f4585013/
indicator_1717571907409_Image.png",
"squareMeter": "39.48",
"id": "369792"
},
{
"carpetArea": {
"area": "516.67",
"squareMeterArea": "48.00",
"expectedRate": "5032.23",
"percentage": ""
},
"builtUpArea": {
"area": "620.00",
"squareMeterArea": "57.60",
"expectedRate": "4193.55",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": false,
"_id": "667bf8f6bc0925575bbb0544",
"property": "Sai Dham Residency, Asangaon",
"area": "620",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "2600000",
"expectedRate": "5032.23",
```

```
    "builtUpExpectedRate": "2600000",
    "image": "cases/665989e4ad7c5448f4585013/
indicator_1719400694356_Image.png",
    "squareMeter": "57.60",
    "id": "854905"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa80014158128024a",
    "name": "externallmg_r_1717475696860_1717475540143_image_1.png",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475696860_1717475540143_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa80014158128024b",
    "name": "externallmg_r_1717475698192_1717475540143_image_2.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475698192_1717475540143_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa80014158128024c",
    "name": "externallmg_r_1717475700808_1717475540143_image_3.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475700808_1717475540143_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa80014158128024d",
    "name": "externallmg_r_1717475694376_1717475540143_image_0.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475694376_1717475540143_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "665e999aa80014158128024e",
    "name": "externallmg_r_1717475703393_1717475540143_image_4.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475703393_1717475540143_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa80014158128024f",
    "name": "externallmg_r_1717475708854_1717475540143_image_6.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475708854_1717475540143_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280250",
    "name": "externallmg_r_1717475705979_1717475540143_image_5.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475705979_1717475540143_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280251",
    "name": "externallmg_r_1717475710098_1717475540143_image_7.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475710098_1717475540143_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280252",
    "name": "externallmg_r_1717475712475_1717475540143_image_8.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475712475_1717475540143_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "665e999aa800141581280253",
    "name": "externallmg_r_1717475716778_1717475540143_image_9.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475716778_1717475540143_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280254",
    "name": "externallmg_r_1717475718900_1717475540143_image_10.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475718900_1717475540143_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280255",
    "name": "externallmg_r_1717475721018_1717475540143_image_11.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475721018_1717475540143_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280256",
    "name": "externallmg_r_1717475723376_1717475540143_image_12.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475723376_1717475540143_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280257",
    "name": "externallmg_r_1717475725554_1717475540143_image_13.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475725554_1717475540143_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280258",
```

```
    "name": "externallmg_r_1717475728216_1717475540143_image_14.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475728216_1717475540143_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa800141581280259",
    "name": "externallmg_r_1717475730022_1717475540143_image_15.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475730022_1717475540143_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e999aa80014158128025a",
    "name": "externallmg_r_1717475732221_1717475540143_image_16.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475732221_1717475540143_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "665e995da8001415812801ee",
    "name": "externallmg_r_1717475674435_1717475522766_image_0.jpg",
    "path": "cases/665989e4ad7c5448f4585013/
externallmg_r_1717475674435_1717475522766_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60092304a16fab0f2af9b0c2",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Nitesh",
      "lastName": "Khedekar",
      "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
```



```
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "666013d076299a636b9a94fc",
    "note": "VALUE CONFIRMATION PENDING",
    "taskId": "66599308ad7c5448f458572a",
    "createdAt": "2024-06-05T07:29:20.584Z"
  }
],
"createdAt": "2024-05-31T08:27:16.320Z",
"updatedAt": "2024-06-26T12:06:15.339Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - B, Sai Dham Residency,
Village - Asangaon, Taluka - Shahapur , District - Thane, PIN Code - 421 601, State -
Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Mrs. Kamini Jagale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Wife",
"siteVisitContactNo": "8898983134",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 615.00",
"flatRate": "3500",
"landOtherRate": "1000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
}
```

```

"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom + 2
Passage",
"carpetTotal": "394.78",
"otherCarpetTotal": "31.67",
"builtupPercentage": "20",
"finalBuiltupArea": "511.74",
"finalCarpetArea": "426.45",
"finalSalableArea": "562.91",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 394.78\nBalcony Area in Sq. Ft.
= 31.67\nTotal Carpet Area in Sq. Ft. = 426.45\nsay = 426.00 Sq. Ft. \n(Area as per
Actual Site Measurement)",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "31.67",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Jun 26 2024 16:42:57 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-06-04"
}

```

Name	Length	Width	Total
Composition :			
Living Room	14'2"	10'0"	141.67
Bedroom	13'4"	9'5"	125.56

Kitchen	8'7"	7'3"	62.23
WC	4'3"	2'7"	10.98
Bathroom	4'0"	5'0"	20.00
Passage	3'7"	8'0"	28.67
Passage	1'5"	4'0"	5.67
Other Composition :			
Balcony Area	10'0"	3'2"	31.67