

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baea"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423121d",
    "firstName": "Ram Thakur",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9423584228"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baea",
  "branchCode": "000077",
  "type": "BRANCH",
  "name": "Thane East Branch",
  "email": "bo3303@pnb.co.in",
  "mobileNo": ".",
  "alternateMobileNo": "",
  "address": "Chatrapati Shivaji CHS,Plot No 1F10,S.V.Nagar,Thane East ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "656aa949cebbe1714411d21b",
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "65829f7c65d49d78457ec7be",
"role": "SITEENGINEER",
"firstName": "Vaibhav",
"email": "vaib1234b@gmail.com",
"lastName": "Bhagat",
"mobileNo": "8779534609",
"designation": "Bachlore Of Engireeing",
"shortName": "Vaibhav",
"workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "FRONTDESK",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
```

```
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.185866061594435",
  "longitude": "72.96761680589887"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "14000",
  "lumpsumValue": "1",
  "rateMax": "15000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
}
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Naupada",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Thane",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sanmitra Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "M.G. Road",
  "label": false
},
"wing": {
```

```
"status": true,
"name": "Wing",
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "35/3 & 36/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "563 to 575 & 103",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```



```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "004",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
    "label": "Powder coated Aluminum sliding windows",
    "value": "Powder_coated_Aluminum_sliding_windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Normal",
    "value": "Normal"
  }
}
```

```
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "shree shivtirth chsl",
    "west": "mg road",
    "south": "dr godbole hospital",
    "east": "building "
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
}
```

```
"carParking": {
  "label": "Open Parking",
  "value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
}
```

```
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "06",
"flatFloorNo": "",
"noOfLifts": "01",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```



```
    },
    "externalDevelopmentFinalFinishing": {
      "label": "External Development & Final Finishing",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": true,
      "status": false
    },
    },
    "workCompleted": {
      "label": "Work Completed (%)",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": true,
      "status": true
    }
  },
  "guidelineDetails": {
    "finalGuidelineValue": "0",
    "selectedBuildUpValue": "0",
    "selectedBuildUpMeasurementType": ""
  },
  "reportImages": {
    "frontPageImages": [],
    "selfieWithSiteVisitImages": [],
    "externalPhotos": [],
    "parkingImages": [],
    "societyNameBoardImage": [],
    "compositionImages": []
  },
  "indicatorRange": {
    "carpetRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
    }
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "665afac6a424b37b20c097c1",
"ownerName": "Mrs. Manisha Dnyaneshwar Pawar",
"ownerPhoneNo": "9076436997",
"fullAddress": "Residential Flat No. 004, Ground Floor, Wing - B, Sanmitra Co.-Op.
Hsg. Soc. Ltd., M.G. Road, Village - Naupada, Taluka - Thane, District - Thane",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "17/11/2020",
      "from": {
        "value": "The_Assignor",
        "label": "The Assignor"
      },
      "The_Assignor": "Mrs. Vidya Surendra Rahalkar & Mr. Surendra G. Rahalkar ",
      "to": {
        "value": "The_Assignee",
        "label": "The Assignee"
      }
    }
  }
],
```

```
    "The_Assignee": "Mrs. Manisha Dnyaneshwar Pawar",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "5049/2020"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1717238463415_PNB_EastPawar.pdf",
  "path": "cases/665afac6a424b37b20c097c1/
document_1717238463415_PNB_EastPawar.pdf",
  "id": "702902",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Sat Jun 01 2024 16:11:09 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009042",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "485268",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jun 01 2024 16:11:10 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Manisha Dnyaneshwar Pawar",
    "phone": "9076436997",
    "ownershipShare": "",
    "email": "",
    "id": "620735"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    }
  }
]
```

```
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "665e13900cceba15c44c6a9e",
    "area": "460",
    "providedByName": "Mrs. Manisha Dnyaneshwar Pawar",
    "providedByContactNo": "9076436997"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "957315",
    "name": "Living Room",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf284a",
    "name": "externalImg_1717441568988_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/externalImg_1717441568988_image.jpeg",
    "orientation": "portrait"
  },

```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665e142fb33b3015bdcf284b",
  "name": "externallmg_1717441569793_image.jpeg",
  "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441569793_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665e142fb33b3015bdcf284c",
  "name": "externallmg_1717441570787_image.jpeg",
  "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441570787_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665e142fb33b3015bdcf284d",
  "name": "externallmg_1717441571808_image.jpeg",
  "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441571808_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665e142fb33b3015bdcf284e",
  "name": "externallmg_1717441572697_image.jpeg",
  "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441572697_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "665e142fb33b3015bdcf284f",
  "name": "externallmg_1717441574692_image.jpeg",
  "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441574692_image.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2850",
    "name": "externallmg_1717441574852_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441574852_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2851",
    "name": "externallmg_1717441576082_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441576082_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2852",
    "name": "externallmg_1717441576668_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441576668_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2853",
    "name": "externallmg_1717441576996_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441576996_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2854",
    "name": "externallmg_1717441578155_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externallmg_1717441578155_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "665e142fb33b3015bdcf2855",
    "name": "externalImg_1717441578540_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externalImg_1717441578540_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2856",
    "name": "externalImg_1717441578543_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externalImg_1717441578543_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2857",
    "name": "externalImg_1717441579052_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externalImg_1717441579052_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665e142fb33b3015bdcf2858",
    "name": "externalImg_1717441579573_image.jpeg",
    "path": "cases/665afac6a424b37b20c097c1/
externalImg_1717441579573_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-01T10:41:10.113Z",
"updatedAt": "2024-06-04T06:48:06.445Z",
"__v": 0,
"updatedBy": "65829f7c65d49d78457ec7be",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
```

"contactPersonName": "Mrs. Manisha Dnyaneshwar Pawar",  
 "email": "",  
 "isExternal": "false",  
 "isUrgent": "false",  
 "ownershipShare": "",  
 "proposePurchaserName": "",  
 "purchaseValueAsPerDocument": "",  
 "relationWithOwner": "self",  
 "siteVisitContactNo": "9076436997",  
 "briefDescOfProperty": "Living Room",  
 "carpetTotal": "1",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "0"

}

Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			