

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8d5"
    },
    "type": "CREDITOFFICER",
    "_id": "663c78f21c6321090f29e183",
    "firstName": "Shubham",
    "lastName": "Sawant",
    "mobileNo": "",
    "workMobileNo": "8369543040",
    "email": "shubham.sawant@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Shubham",
    "expectedFees": 2500,
    "quotedAmount": "4000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8d5",
  "branchCode": "000007",
  "type": "BRANCH",
  "name": "Mulund (West) Branch",
  "email": "cosmos@mulundwestgmail.com",
  "mobileNo": "022-21640621",
  "alternateMobileNo": "022-21646370",
  "address": "Apurva Co-Op. Housing Society, Govardhan Nagar, L.B.S. Road, Mulund
(West), Mumbai - 400 080, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.202931872601862",
  "longitude": "72.97350579731041"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.97350579731041,
    19.202931872601862
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "3/06/2024 03:55 pm"
    }
  ]
},
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "18000",
  "lumpsumValue": "1",
  "rateMax": "19000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Khopat",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Thane",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ramkunj CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp S T Workshop",
```

```
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "V B Phadke Chowk ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
```



```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "104",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```

```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified tile flooring",
    "value": "Vitrified_tile_flooring"
  }
},
}
```

```
"doors": {
  "label": "Teak Wood Door Frame With Flush Shutters",
  "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
},
"windows": {
  "label": "Powder coated Aluminum sliding windows",
  "value": "Powder_coated_Aluminum_sliding_windows"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
  "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "hotel fish kand ",
    "west": "internal road",
    "south": "main road",
    "east": "krishna tower"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
```

```
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"isDisplay": false,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
```

```
"value": "Owner_Occupied"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "Open Car Parking",
    "value": "Open_Car_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2003",
    "fullDate": "1/1/2003"
  },
  "propertyTypeList": {
    "label": "Residential",
    "value": "Residential"
  },
  "planningArea": {
    "label": "Residential",
    "value": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
  "qualityOfConstruction": {
    "label": "Normal",
    "value": "Normal"
  }
}
```

```
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "03",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "02"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
```

```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```



```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "665d9562a80014158127d200",
"ownerName": "Rita Fulchand Pansambal",
"ownerPhoneNo": "9820614357",
"appAddress": "Flat no. A/104, 1st Floor, Ramkunj CHS, Khopat, Thane",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/665d9562a80014158127d200/
document_1717409089705_130544.pdf",
  "fileName": "document_1717409089705_130544.pdf",
  "id": "255932",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
  "createdAt": "Mon Jun 03 2024 15:35:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009059",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "647497",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jun 03 2024 15:35:22 GMT+0530 (India Standard Time)"
  }
]
],
"owners": [
  {
    "name": "Rita Fulchand Pansambal",
    "phone": "9820614357",
    "ownershipShare": "",
    "email": "",
    "id": "464541"
  }
]
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    }
  },
  "_id": "666d033024f3ba1343e478b6",

```

```
"area": "804",
"providedByName": "Rita Fulchand Pansambal",
"providedByContactNo": "9820614357"
},
],
"composition": [
{
"measurementType": {
"label": "Square Feet",
"value": "Square_Feet"
},
"id": "497673",
"name": "Living Room",
"length": "1.00",
"length1": "1",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "1.00",
"images": [],
"extraAreas": [],
"finalArea": "1.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "666d04d024f3ba1343e478d2",
"name": "externalImg_1718420598826_image.jpeg",
"path": "cases/665d9562a80014158127d200/
externalImg_1718420598826_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "666d04d024f3ba1343e478d3",
"name": "externalImg_1718420601470_image.jpeg",
"path": "cases/665d9562a80014158127d200/
externalImg_1718420601470_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478d4",
  "name": "externallmg_1718420603816_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420603816_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478d5",
  "name": "externallmg_1718420604410_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420604410_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478d6",
  "name": "externallmg_1718420606392_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420606392_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478d7",
  "name": "externallmg_1718420608028_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420608028_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478d8",
  "name": "externallmg_1718420608642_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420608642_image.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478d9",
  "name": "externallmg_1718420609301_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420609301_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478da",
  "name": "externallmg_1718420610125_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420610125_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478db",
  "name": "externallmg_1718420612786_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420612786_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478dc",
  "name": "externallmg_1718420617688_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420617688_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478dd",
  "name": "externallmg_1718420622051_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420622051_image.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478de",
  "name": "externallmg_1718420627106_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420627106_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478df",
  "name": "externallmg_1718420629396_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420629396_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478e0",
  "name": "externallmg_1718420637557_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420637557_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478e1",
  "name": "externallmg_1718420640636_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420640636_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666d04d024f3ba1343e478e2",
  "name": "externallmg_1718420650426_image.jpeg",
  "path": "cases/665d9562a80014158127d200/
externallmg_1718420650426_image.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d04d024f3ba1343e478e3",
    "name": "externalImg_1718420664011_image.jpeg",
    "path": "cases/665d9562a80014158127d200/
externalImg_1718420664011_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d04d024f3ba1343e478e4",
    "name": "externalImg_1718420668906_image.jpeg",
    "path": "cases/665d9562a80014158127d200/
externalImg_1718420668906_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666d04d024f3ba1343e478e5",
    "name": "externalImg_1718420674451_image.jpeg",
    "path": "cases/665d9562a80014158127d200/
externalImg_1718420674451_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-03T10:05:22.613Z",
"updatedAt": "2024-06-15T03:05:28.737Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "65829f7c65d49d78457ec7be",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 104, 1st Floor, Wing - A, Ramkunj CHSL, Opp S T
Workshop, V B Phadke Chowk , Village - Khopat, Thane West, Thane",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Rita Fulchand Pansambal",
```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820614357",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"

}

Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other			
Composition :			