

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "firstName": "Rajesh",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmechby@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7000000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 3500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.281944474944385",
  "longitude": "72.87177434740059"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87177434740059,
    19.281944474944385
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "4/06/2024 12:35 pm"
    },
    {
      "dateTime": "4/06/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-05",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Bhayander",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane ",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Seven Square Avenue",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```



```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "475, New Survey No. 118, Hissa No. 5/B",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "705",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 105",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Shree Ashtavinayak Society ",
  "west": "Road ",
  "south": "Chandresh Accord ",
  "east": "Open Plot "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "east": "",
    "south": "",
    "west": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"isDisplay": false,
```

```
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of Flat will be 1 Bedroom + Living Room + Dining + Study Room + Kitchen + 2 Toilets. (i.e. 1.5 BHK + 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. MB / MNP / NR / 7502 / 2018 - 19 dated 30.03.2019 issued by Mira Bhayander Municipal Corporation",
"approvePlanVerified": "Yes ",
"empanelledOfApprovePlan": "Building is under construction ",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of visit, builder has not allowed for Internal inspection of the property. The details about the work progress status have been provided by Mr. Rajesh Sandhi (Sales Person - Mob. No. 9322510680)",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "84900",
  "landRate": "37100",
  "igrImage": "cases/665ea66aa800141581280cfc/igr_1717653309339_Image.png",
  "squareMeterGuideLineRate": "89145.00",
  "squareFeetGuideLineRate": "8282.00"
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "84900.00",
  "squareMeterGuideLineRate": "89145.00",
  "squareFeetGuideLineRate": "8282.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "20,000/- (Expected rental income per month after completion\n of construction works)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
}
```

```
"partitions": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Stilt Car Parking Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
```



```
"value": "Part_Ground_and_Part_Stilt",
"label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "24",
"flatFloorNo": "7",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"area": "783.20",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
},
"routeMapImg": "cases/665ea66aa800141581280cfc/
routeMap_1717676234036_Image.png",
"routeLat": "19.282000",
"routeLng": "72.871611",
"stationName": "Mira Road ",
"routeDistance": "2.00 Km. "
},
"finalLatLng": {
"coordinates": [
null,
null
],
"type": "Point"
},
"showLocation": {
```

```
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "n2hvjrr",
      "name": "n2hvjrr",
      "image": "cases/665ea66aa800141581280cfc/
routeMap_1717676157765_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8544000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "8544000.00"
},
```

```
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jun 06 2024 18:02:37 GMT+0530 (India Standard Time)",
  "number": "2306621",
  "dayCount": "17",
  "monthCount": "65",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "20",
    "percentage": "30.76923076923077",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "16",
    "percentage": "4.31",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "16",
    "percentage": "4.31",
    "isHideFloor": false,
```

```
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "12",
  "percentage": "1.62",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "12",
  "percentage": "1.62",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "52.63",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "6486462.00",
  "selectedBuildUpValue": "783.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66612b40732c0830539d1e42",
      "name":
"externallmg_1717644096412_WhatsApp_Image_20240606_at_080705.jpeg",
      "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096412_WhatsApp_Image_20240606_at_080705.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66612b40732c0830539d1e3e",
      "name":
"externallmg_1717644096391_WhatsApp_Image_20240606_at_080703.jpeg",
      "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096391_WhatsApp_Image_20240606_at_080703.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66612b40732c0830539d1e3c",
      "name":
"externallmg_1717644096377_WhatsApp_Image_20240606_at_080702_1.jpeg",
      "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096377_WhatsApp_Image_20240606_at_080702_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66612b40732c0830539d1e3d",
      "name":
"externallmg_1717644096383_WhatsApp_Image_20240606_at_080703_1.jpeg",
      "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096383_WhatsApp_Image_20240606_at_080703_1.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66612b40732c0830539d1e42",
      "name":
"externallmg_1717644096412_WhatsApp_Image_20240606_at_080705.jpeg",
```

```
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096412_WhatsApp_Image_20240606_at_080705.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66612b40732c0830539d1e45",
    "name":
"externallmg_1717644096422_WhatsApp_Image_20240606_at_080706.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096422_WhatsApp_Image_20240606_at_080706.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66612b40732c0830539d1e41",
    "name":
"externallmg_1717644096408_WhatsApp_Image_20240606_at_080705_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096408_WhatsApp_Image_20240606_at_080705_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "11236.00",
    "max": "14000.00"
  },
  "builtUpRateRange": {
    "min": "10215.00",
    "max": "12728.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "712.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "665ea66aa800141581280cfc",
"ownerName": "Mr. Bhartendu Shivram Tiwari & Mrs. Jagruti Bhartendu Tiwari",
"ownerPhoneNo": "9833840117",
"appAddress": "FLAT NO 705 7TH FLOOR BLDGNO 2 SEVEN SQUARE AVENUE
VILLAGE BHAYNDER THNE 401105",
"remark": "Any query contact surekha gupta 9594632279",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "27/07/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Shubh Realty ",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      }
    }
  },

```

```
"Allottee": "Mr. Bhartendu Shivram Tiwari & Mrs. Jagruti Bhartendu Tiwari",
"number": {
  "value": "No",
  "label": "No"
},
"No": "17973 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "399843",
"path": "cases/665ea66aa800141581280cfc/document_1717478947184_17174785
04809_BHARATENDU_TIWARI__AGREEMENT.pdf",
"fileName": "document_1717478947184_1717478504809_BHARATENDU_TIWARI
__AGREEMENT.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "30/03/2019",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
  },
  "remark": " (As downloaded from RERA site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MB / MNP / NR / 7502 / 2018 - 19"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1717673874077_Plan.pdf",
"path": "cases/665ea66aa800141581280cfc/document_1717673874077_Plan.pdf",
"id": "848684",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jun 06 2024 17:07:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "30/03/2019",
  "nameOfApprovingAuthority": {
    "value": "Mira_Bhayander_Municipal_Corporation",
    "label": "Mira Bhayander Municipal Corporation"
  },
  "remark": " (As downloaded from RERA site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "MB / MNP / NR / 7502 / 2018 - 19"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1717673972438_CC.pdf",
"path": "cases/665ea66aa800141581280cfc/document_1717673972438_CC.pdf",
"id": "250461",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jun 06 2024 17:09:32 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700020490"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1717674096609_P51700020490.pdf",
  "path": "cases/665ea66aa800141581280cfc/
document_1717674096609_P51700020490.pdf",
  "id": "442997",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jun 06 2024 17:11:36 GMT+0530 (India Standard Time)"
}
```

```
},
{
  "documentType": {
    "value": "656489dfcabee433399a9a61",
    "label": "Cost Sheet"
  },
  "inputs": {
    "documentDate": "14/05/2024",
    "remark": " issued by M/s. Shubh Realty"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1717674161553_Cost_Sheet.pdf",
  "path": "cases/665ea66aa800141581280cfc/
document_1717674161553_Cost_Sheet.pdf",
  "id": "754499",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jun 06 2024 17:12:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1285aa6d152c1801b40c",
    "label": "NOC Letter"
  },
  "inputs": {
    "documentDate": "14/05/2024",
    "remark": " in the name of Mr. Bhartendu Shivram Tiwari & Mrs. Jagruti Bhartendu
Tiwari issued by M/s. Shubh Realty"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1717674219946_NOC.pdf",
  "path": "cases/665ea66aa800141581280cfc/document_1717674219946_NOC.pdf",
  "id": "160927",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jun 06 2024 17:13:40 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009073",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "261188",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jun 04 2024 11:00:18 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mr. Bhartendu Shivram Tiwari & Mrs. Jagruti Bhartendu Tiwari",
    "phone": "9833840117",
    "ownershipShare": "",
    "email": "",
    "id": "404899"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "66.15",
    "totalAreaDocument": "712",
    "docBuiltpupPercentage": "10",
    "docFinalBuiltpup": "783.20",
    "docFinalBuiltpupSquareMeter": "72.76",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "853167"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "683.00",
      "squareMeterArea": "63.45",
      "expectedRate": "14000.00",
      "percentage": ""
    }
  }
]
```

```
},
"builtUpArea": {
  "area": "751.30",
  "squareMeterArea": "69.80",
  "expectedRate": "12727.27",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "66614f5a1daaad305a6d878a",
"property": "Seven Square Avenue, Mira Road",
"area": "683",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Higher",
"source": "Housing.Com",
"expectedPrice": "9562000",
"expectedRate": "14000.00",
"builtUpExpectedRate": "12727.27",
"image": "cases/665ea66aa800141581280cfc/
indicator_1717653074601_Image.png",
"squareMeter": "63.45",
"id": "336541"
},
{
  "carpetArea": {
    "area": "678.00",
    "squareMeterArea": "62.99",
    "expectedRate": "13274.34",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "745.80",
    "squareMeterArea": "69.29",
    "expectedRate": "12067.58",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
```

```
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66614f5a1daaad305a6d878b",
"property": "Seven Square Avenue, Mira Road",
"area": "678",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "9000000",
"expectedRate": "13274.34",
"builtUpExpectedRate": "12067.58",
"image": "cases/665ea66aa800141581280cfc/
indicator_1717653120795_Image.png",
"squareMeter": "62.99",
"id": "472538"
},
{
"carpetArea": {
"area": "712.00",
"squareMeterArea": "66.15",
"expectedRate": "11235.96",
"percentage": ""
},
"builtUpArea": {
"area": "783.20",
"squareMeterArea": "72.76",
"expectedRate": "10214.50",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66614f5a1daaad305a6d878c",
"property": "Seven Square Avenue, Mira Road",
"area": "712",
"builtUpPercentage": "10",
```



```
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "17",
"source": "Index_no.2",
"expectedPrice": "8000000",
"expectedRate": "11235.96",
"builtUpExpectedRate": "10214.50",
"image": "cases/665ea66aa800141581280cfc/
indicator_1717653193965_Image.png",
"squareMeter": "66.15",
"id": "466868"
},
{
  "carpetArea": {
    "area": "757.00",
    "squareMeterArea": "70.33",
    "expectedRate": "11889.04",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "832.70",
    "squareMeterArea": "77.36",
    "expectedRate": "10808.21",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66614f5a1daaad305a6d878d",
  "property": "Seven Square Avenue, Mira Road",
  "area": "757",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "14",
  "source": "Index_no.2",
  "expectedPrice": "9000000",
  "expectedRate": "11889.04",
  "builtUpExpectedRate": "10808.21",
  "image": "cases/665ea66aa800141581280cfc/
indicator_1717653227966_Image.png",
```

```
    "squareMeter": "70.33",
    "id": "892402"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e3c",
    "name":
"externallmg_1717644096377_WhatsApp_Image_20240606_at_080702_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096377_WhatsApp_Image_20240606_at_080702_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e3d",
    "name":
"externallmg_1717644096383_WhatsApp_Image_20240606_at_080703_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096383_WhatsApp_Image_20240606_at_080703_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e3e",
    "name":
"externallmg_1717644096391_WhatsApp_Image_20240606_at_080703.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096391_WhatsApp_Image_20240606_at_080703.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e3f",
    "name":
"externallmg_1717644096397_WhatsApp_Image_20240606_at_080704_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096397_WhatsApp_Image_20240606_at_080704_1.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e40",
    "name":
"externallmg_1717644096401_WhatsApp_Image_20240606_at_080704.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096401_WhatsApp_Image_20240606_at_080704.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e41",
    "name":
"externallmg_1717644096408_WhatsApp_Image_20240606_at_080705_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096408_WhatsApp_Image_20240606_at_080705_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e42",
    "name":
"externallmg_1717644096412_WhatsApp_Image_20240606_at_080705.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096412_WhatsApp_Image_20240606_at_080705.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e43",
    "name":
"externallmg_1717644096415_WhatsApp_Image_20240606_at_080706_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096415_WhatsApp_Image_20240606_at_080706_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e44",
    "name":
"externallmg_1717644096418_WhatsApp_Image_20240606_at_080706_2.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096418_WhatsApp_Image_20240606_at_080706_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e45",
    "name":
"externallmg_1717644096422_WhatsApp_Image_20240606_at_080706.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096422_WhatsApp_Image_20240606_at_080706.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e46",
    "name":
"externallmg_1717644096425_WhatsApp_Image_20240606_at_080707_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096425_WhatsApp_Image_20240606_at_080707_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e47",
    "name":
"externallmg_1717644096429_WhatsApp_Image_20240606_at_080707.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096429_WhatsApp_Image_20240606_at_080707.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e48",
    "name":
"externallmg_1717644096432_WhatsApp_Image_20240606_at_080708_1.jpeg",
    "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096432_WhatsApp_Image_20240606_at_080708_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66612b40732c0830539d1e49",
```

```
"name":
"externallmg_1717644096435_WhatsApp_Image_20240606_at_080708.jpeg",
  "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096435_WhatsApp_Image_20240606_at_080708.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66612b40732c0830539d1e4a",
  "name":
"externallmg_1717644096437_WhatsApp_Image_20240606_at_080702.jpeg",
  "path": "cases/665ea66aa800141581280cfc/
externallmg_1717644096437_WhatsApp_Image_20240606_at_080702.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "igr_9655.pdf",
  "filename": "1717653328770_igr_9655.pdf",
  "path": "cases/665ea66aa800141581280cfc/
processingDocuments/1717653328770_igr_9655.pdf",
  "size": "165754",
  "createdAt": "Thu Jun 06 2024 11:25:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "1716026508753_1715323634339_1711606660630_17008919755
73_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
  "filename": "1717653328779_1716026508753_1715323634339_1711606660630_1
700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2.xl
sx",
  "path": "cases/665ea66aa800141581280cfc/processingDocuments/1717653328779
_1716026508753_1715323634339_1711606660630_1700891975573_1695465043548
_1694516251783_1694241590859_Calculation_1_2.xlsx",
  "size": "774908",
  "createdAt": "Thu Jun 06 2024 11:25:29 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_2223.pdf",
  "filename": "1717653329130_igr_2223.pdf",
  "path": "cases/665ea66aa800141581280cfc/
processingDocuments/1717653329130_igr_2223.pdf",
```

```
"size": "159129",
"createdAt": "Thu Jun 06 2024 11:25:29 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "CC.pdf",
"filename": "1717676302083_CC.pdf",
"path": "cases/665ea66aa800141581280cfc/
processingDocuments/1717676302083_CC.pdf",
"size": "435383",
"createdAt": "Thu Jun 06 2024 17:48:22 GMT+0530 (India Standard Time)",
"uploadedBy": "62fe044a48a26047e6552796"
},
{
"originalname": "P51700020490.pdf",
"filename": "1717676302110_P51700020490.pdf",
"path": "cases/665ea66aa800141581280cfc/
processingDocuments/1717676302110_P51700020490.pdf",
"size": "149825",
"createdAt": "Thu Jun 06 2024 17:48:22 GMT+0530 (India Standard Time)",
"uploadedBy": "62fe044a48a26047e6552796"
},
{
"originalname": "Plan.pdf",
"filename": "1717676302119_Plan.pdf",
"path": "cases/665ea66aa800141581280cfc/
processingDocuments/1717676302119_Plan.pdf",
"size": "288541",
"createdAt": "Thu Jun 06 2024 17:48:22 GMT+0530 (India Standard Time)",
"uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"lastName": "Kuperkar",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,

```

```
"status": true,
  "_id": "66614f581daaad305a6d8782",
  "note": "Rate verification done",
  "taskId": "665ebd4259496f15880f1a56",
  "createdAt": "2024-06-06T05:55:36.545Z"
},
],
"createdAt": "2024-06-04T05:30:18.159Z",
"updatedAt": "2024-06-06T12:36:11.236Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
},
"fullAddress": "Residential Flat No. 705, 7th Floor, Building No 2, Seven Square
Avenue, Village - Bhayander, Mira Road (East), Taluka - Thane , District - Thane , PIN -
401 105, State - Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Rajesh Sandhi ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "sales Person ",
"siteVisitContactNo": "9322510680",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 712.00",
"flatRate": "12000",
"landOtherRate": "9200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
```

```

"finalBultupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Thu Jun 06 2024 16:22:24 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-06-05"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			