

```
{
  "typeOfReport": {
    "value": "Plant_&_Machinery",
    "label": "Plant & Machinery"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646869f246e69b7878e9c07a"
    },
    "type": "CREDITOFFICER",
    "_id": "646869f246e69b7878e9c07c",
    "firstName": "Mr. Satish",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "9769699931",
    "email": "satish.sambare@siemens.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": ""
  }
}
```

```
"discussWithPerson": "",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "646867a446e69b7878e9b892",
  "type": "INSTITUTION",
  "name": "Siemens Financial Services Private Limited",
  "displayName": "",
  "initial": "SFS"
},
"branch": {
  "_id": "646869f246e69b7878e9c07a",
  "name": "SFS COF E RU-IN RM AM",
  "branchCode": "",
  "mobileNo": "9769699930",
  "alternateMobileNo": "",
  "email": "satish.sambare@siemens.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Thane Belapur Road\n400708 Thane, India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "6468691f46e69b7878e9be2e",
  "zoneName": "Pan India"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddedd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": ""
}
```

```
"shortName": "AV",
"workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": []
},
"clientType": {
  "value": "INSTITUTION",
  "label": "INSTITUTION"
},
"location": {
  "latitude": "18.746366618688604",
  "longitude": "73.80572622262866"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Pune",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
```

```
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Khed",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "M/s. BMD Engineering located at Plot No. C-39/3",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. Talawade Chakan Road",
  "label": false
},
"street2": {
```

```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Suvarna Fabricators, Mahalunge, MIDC, Chakan, Tarapur M.I.D.C.",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```

```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```



```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code-410 501",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  },
  "auto": {
```

```
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "66614256343f5230b100df12",
"ownerName": "M/s. Anuj Mould & Dies",
"ownerPhoneNo": "0000000000",
"fullAddress": "Industrial Plant & Machinery No. Ground Floor, Near Suvarna
Fabricators, Mahalunge, MIDC, Chakan, Tarapur M.I.D.C., Plot No. M/s. BMD
Engineering located at Plot No. C-39/3, Off. Talawade Chakan Road, Taluka - Khed,
District - Pune, PIN Code-410 501, State - Maharashtra, India",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "009110",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "709159",
    "title": "Create Lead",
    "description": "Create Lead",
```



```
"datetime": "Thu Jun 06 2024 10:30:06 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "M/s. Anuj Mould & Dies",
"phone": "0000000000",
"ownershipShare": "",
"email": "",
"id": "279500"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66614636343f5230b100e388",
"name":
"externallmg_1717650997233_WhatsApp_Image_20240601_at_41902_PM.jpeg",
"path": "cases/66614256343f5230b100df12/
externallmg_1717650997233_WhatsApp_Image_20240601_at_41902_PM.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66614636343f5230b100e389",
"name":
"externallmg_1717650997271_WhatsApp_Image_20240601_at_41903_PM_1.jpeg",
"path": "cases/66614256343f5230b100df12/
externallmg_1717650997271_WhatsApp_Image_20240601_at_41903_PM_1.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66614636343f5230b100e38a",
"name":
"externallmg_1717650997306_WhatsApp_Image_20240601_at_42001_PM.jpeg",
```

```
    "path": "cases/66614256343f5230b100df12/
externallmg_1717650997306_WhatsApp_Image_20240601_at_42001_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614636343f5230b100e38b",
    "name":
"externallmg_1717650997356_WhatsApp_Image_20240601_at_42002_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717650997356_WhatsApp_Image_20240601_at_42002_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614636343f5230b100e38c",
    "name":
"externallmg_1717650997398_WhatsApp_Image_20240601_at_42003_PM_1.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717650997398_WhatsApp_Image_20240601_at_42003_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614636343f5230b100e38d",
    "name":
"externallmg_1717650997433_WhatsApp_Image_20240601_at_42003_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717650997433_WhatsApp_Image_20240601_at_42003_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614636343f5230b100e38e",
    "name":
"externallmg_1717650997465_WhatsApp_Image_20240601_at_42004_PM_1.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717650997465_WhatsApp_Image_20240601_at_42004_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66614636343f5230b100e38f",
  "name":
"externallmg_1717650997532_WhatsApp_Image_20240601_at_42004_PM_2.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717650997532_WhatsApp_Image_20240601_at_42004_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614636343f5230b100e390",
  "name":
"externallmg_1717650997571_WhatsApp_Image_20240601_at_42004_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717650997571_WhatsApp_Image_20240601_at_42004_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614636343f5230b100e391",
  "name":
"externallmg_1717650997615_WhatsApp_Image_20240601_at_42005_PM_1.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717650997615_WhatsApp_Image_20240601_at_42005_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614636343f5230b100e392",
  "name":
"externallmg_1717650997666_WhatsApp_Image_20240601_at_42005_PM_2.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717650997666_WhatsApp_Image_20240601_at_42005_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614636343f5230b100e393",
  "name":
"externallmg_1717650997687_WhatsApp_Image_20240601_at_42005_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717650997687_WhatsApp_Image_20240601_at_42005_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614636343f5230b100e394",
    "name":
"externallmg_1717650997740_WhatsApp_Image_20240601_at_42006_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717650997740_WhatsApp_Image_20240601_at_42006_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661464746c7a930aad2cd82",
    "name":
"externallmg_1717651015648_WhatsApp_Image_20240601_at_41858_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651015648_WhatsApp_Image_20240601_at_41858_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661464746c7a930aad2cd83",
    "name":
"externallmg_1717651015652_WhatsApp_Image_20240601_at_41859_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651015652_WhatsApp_Image_20240601_at_41859_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661464746c7a930aad2cd84",
    "name":
"externallmg_1717651015666_WhatsApp_Image_20240601_at_41900_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651015666_WhatsApp_Image_20240601_at_41900_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661464746c7a930aad2cd85",
```

```
    "name":
"externallmg_1717651015673_WhatsApp_Image_20240601_at_41901_PM_1.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651015673_WhatsApp_Image_20240601_at_41901_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661464746c7a930aad2cd86",
  "name":
"externallmg_1717651015684_WhatsApp_Image_20240601_at_41901_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651015684_WhatsApp_Image_20240601_at_41901_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661464746c7a930aad2cd87",
  "name":
"externallmg_1717651015691_WhatsApp_Image_20240601_at_41902_PM_1.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651015691_WhatsApp_Image_20240601_at_41902_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661464746c7a930aad2cd88",
  "name":
"externallmg_1717651015702_WhatsApp_Image_20240601_at_41903_PM_2.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651015702_WhatsApp_Image_20240601_at_41903_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661464746c7a930aad2cd89",
  "name":
"externallmg_1717651015711_WhatsApp_Image_20240601_at_41903_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651015711_WhatsApp_Image_20240601_at_41903_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661464746c7a930aad2cd8a",
  "name":
"externallmg_1717651015723_WhatsApp_Image_20240601_at_41904_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651015723_WhatsApp_Image_20240601_at_41904_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661465c732c0830539d2cea",
  "name":
"externallmg_1717651035568_WhatsApp_Image_20240601_at_41812_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651035568_WhatsApp_Image_20240601_at_41812_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661465c732c0830539d2ceb",
  "name":
"externallmg_1717651035626_WhatsApp_Image_20240601_at_41813_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651035626_WhatsApp_Image_20240601_at_41813_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661465c732c0830539d2cec",
  "name":
"externallmg_1717651035634_WhatsApp_Image_20240601_at_41814_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651035634_WhatsApp_Image_20240601_at_41814_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661465c732c0830539d2ced",
  "name":
"externallmg_1717651035687_WhatsApp_Image_20240601_at_41815_PM.jpeg",
```

```
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651035687_WhatsApp_Image_20240601_at_41815_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661465c732c0830539d2cee",
    "name":
"externallmg_1717651035745_WhatsApp_Image_20240601_at_41816_PM_1.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651035745_WhatsApp_Image_20240601_at_41816_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661465c732c0830539d2cef",
    "name":
"externallmg_1717651035790_WhatsApp_Image_20240601_at_41816_PM_2.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651035790_WhatsApp_Image_20240601_at_41816_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661465c732c0830539d2cf0",
    "name":
"externallmg_1717651035831_WhatsApp_Image_20240601_at_41816_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651035831_WhatsApp_Image_20240601_at_41816_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6661465c732c0830539d2cf1",
    "name":
"externallmg_1717651035876_WhatsApp_Image_20240601_at_41817_PM_1.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651035876_WhatsApp_Image_20240601_at_41817_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6661465c732c0830539d2cf2",
  "name":
"externallmg_1717651035921_WhatsApp_Image_20240601_at_41817_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651035921_WhatsApp_Image_20240601_at_41817_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6661465c732c0830539d2cf3",
  "name":
"externallmg_1717651035959_WhatsApp_Image_20240601_at_41818_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651035959_WhatsApp_Image_20240601_at_41818_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d3a",
  "name":
"externallmg_1717651055900_WhatsApp_Image_20240601_at_42034_PM_1.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651055900_WhatsApp_Image_20240601_at_42034_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d3b",
  "name":
"externallmg_1717651055922_WhatsApp_Image_20240601_at_42034_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651055922_WhatsApp_Image_20240601_at_42034_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d3c",
  "name":
"externallmg_1717651055971_WhatsApp_Image_20240601_at_42035_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651055971_WhatsApp_Image_20240601_at_42035_PM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614670732c0830539d2d3d",
    "name":
"externallmg_1717651056008_WhatsApp_Image_20240601_at_42036_PM_1.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651056008_WhatsApp_Image_20240601_at_42036_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614670732c0830539d2d3e",
    "name":
"externallmg_1717651056048_WhatsApp_Image_20240601_at_42036_PM_2.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651056048_WhatsApp_Image_20240601_at_42036_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614670732c0830539d2d3f",
    "name":
"externallmg_1717651056085_WhatsApp_Image_20240601_at_42036_PM.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651056085_WhatsApp_Image_20240601_at_42036_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614670732c0830539d2d40",
    "name":
"externallmg_1717651056121_WhatsApp_Image_20240601_at_42037_PM_1.jpeg",
    "path": "cases/66614256343f5230b100df12/
externallmg_1717651056121_WhatsApp_Image_20240601_at_42037_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66614670732c0830539d2d41",
```

```
    "name":
"externallmg_1717651056167_WhatsApp_Image_20240601_at_42037_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056167_WhatsApp_Image_20240601_at_42037_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d42",
  "name":
"externallmg_1717651056213_WhatsApp_Image_20240601_at_42038_PM_1.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056213_WhatsApp_Image_20240601_at_42038_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d43",
  "name":
"externallmg_1717651056257_WhatsApp_Image_20240601_at_42038_PM_2.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056257_WhatsApp_Image_20240601_at_42038_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d44",
  "name":
"externallmg_1717651056305_WhatsApp_Image_20240601_at_42038_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056305_WhatsApp_Image_20240601_at_42038_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d45",
  "name":
"externallmg_1717651056327_WhatsApp_Image_20240601_at_42039_PM_1.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056327_WhatsApp_Image_20240601_at_42039_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d46",
  "name":
"externallmg_1717651056387_WhatsApp_Image_20240601_at_42039_PM_2.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056387_WhatsApp_Image_20240601_at_42039_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66614670732c0830539d2d47",
  "name":
"externallmg_1717651056436_WhatsApp_Image_20240601_at_42039_PM.jpeg",
  "path": "cases/66614256343f5230b100df12/
externallmg_1717651056436_WhatsApp_Image_20240601_at_42039_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-06T05:00:06.997Z",
"updatedAt": "2024-06-06T05:17:36.629Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "Mr. Dyneshwar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7499644329"
}

```

| Name | Length | Width | Total |
|---------------|--------|-------|-------|
| Composition : | | | |

Other
Composition :
