

```
{
  "typeOfReport": {
    "value": "Shop",
    "label": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "665ea03eb33b3015bdcf3444"
    },
    "type": "CREDITOFFICER",
    "_id": "665ea03eb33b3015bdcf3446",
    "firstName": "Mehul",
    "lastName": "Waghela",
    "mobileNo": "",
    "workMobileNo": "9033368436",
    "email": "dbjeta@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "665ea03eb33b3015bdcf3444",
  "name": "Jetalpur Branch",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "dbjeta@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1-6 Ground Floor, Baldevji Complex, Jetal Pur, Swaminarayan Mandir,
Highway Jetalpur, Taluka Daksoi, Dist Ahmedabad 382427"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
```

```
"type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
```

```
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
"value": "BANK",
```

```
"label": "BANK"
},
"location": {
  "latitude": "19.221801784667242",
  "longitude": "72.86143702861207"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "4/06/2024 11:18 am"
    },
    {
      "dateTime": "4/06/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kanheri",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shiv Shakti Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dattapada Cross Road No. 3",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "218, 218/1 to 18",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "5",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 066",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "MS_Rolling_Shutter",
    "label": "MS Rolling Shutter"
  },
  "windows": {
    "value": "N.A.",
    "label": "N.A."
  },
  "fittings": {
```

```
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shreeji Darshan CHSL ",
    "west": "Carter Road No. 2",
    "south": "Indira Apartment ",
    "east": "Matru Krupa Kunj CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "By Cadastral Survey No. 217 of Kanheri Village ",
    "west": "By a Road ",
    "south": "By a Road & beyond that Cadastral Survey No. 219 of Kanheri Village ",
    "east": "By Cadastral Survey No. 303 (Part) & 307 (Part)of Kanheri Village "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
```

```
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "The Composition of Commercial Shop is single unit only. ",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan no. P-8428/2021/(218
And Other)/R/C Ward/KANHERI R/C/CC/1/New dated 12.12.2021 issued by MCGM. ",
"approvePlanVerified": "Yes ",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of site visit, final finishing work is in progress.",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
```

```
"igrRate": {
  "propertyName": "Commercial",
  "rate": "211700",
  "landRate": "48920",
  "igrImage": "cases/66615ca84372ba0957d28f32/igr_1717582117578_Image.png",
  "squareMeterGuideLineRate": "211700.00",
  "squareFeetGuideLineRate": "19668.00"
},
"igrFinalRate": {
  "floorRatePercentage": "80",
  "depreciationPercentage": "0",
  "rate": "211700.00",
  "squareMeterGuideLineRate": "169360.00",
  "squareFeetGuideLineRate": "15734.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_use",
    "label": "Commercial use"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": " 1 45,000/- (Expected rental income per month)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Final finishing work is in progress "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
```

```
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open / Covered Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2024",
    "fullDate": "1/1/2024"
  },
  "planningArea": {
    "value": "Residential_cum_Commercial",
    "label": "Residential cum Commercial"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
```

```
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "New_Building",
"label": "New Building"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
}
```

```
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "60",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "3",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "Ground",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "10"
},
"finalPlinthArea": {
  "area": "361.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  },
  "routeMapImg": "cases/66615ca84372ba0957d28f32/
routeMap_1717655361892_Image.png",
  "routeLat": "19.224722",
  "routeLng": "72.859694",
  "stationName": "Devipada ",
  "routeDistance": "600 Mtrs. "
},
"finalLatLng": {
  "coordinates": [
```



```
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "8qc3gl",
    "name": "8qc3gl",
    "image": "cases/66615ca84372ba0957d28f32/
routeMap_1717655172621_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "13093500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "13093500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jun 06 2024 14:28:42 GMT+0530 (India Standard Time)",
  "number": "2306611",
  "dayCount": "7",
  "monthCount": "55",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "5683121.00",
  "selectedBuildUpValue": "361.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "665efa7c59496f15880f51bc",
      "name":
"externallmg_1717500540383_WhatsApp_Image_20240604_at_152136.jpeg",
      "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540383_WhatsApp_Image_20240604_at_152136.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "665efa7c59496f15880f51bc",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540383_WhatsApp_Image_20240604_at_152136.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "665efa7c59496f15880f51b6",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540360_WhatsApp_Image_20240604_at_152133.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe2a",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728561_WhatsApp_Image_20240605_at_24411_PM_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe2b",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/externallmg_1717657728563_WhatsApp_Image_20240605_at_24411_PM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe2c",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/externallmg_1717657728566_WhatsApp_Image_20240605_at_24411_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe26",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/externallmg_1717657728546_WhatsApp_Image_20240605_at_24409_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe28",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/externallmg_1717657728556_WhatsApp_Image_20240605_at_24410_PM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe2d",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/externallmg_1717657728568_WhatsApp_Image_20240605_at_24412_PM.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66616081343f5230b100fe24",
      "name": "Working Area",
      "path": "cases/66615ca84372ba0957d28f32/externallmg_1717657728522_WhatsApp_Image_20240605_at_24409_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "665efa7c59496f15880f51bb",
    "name": "Working Area",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540378_WhatsApp_Image_20240604_at_152136_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "44757.00",
    "max": "48149.00"
  },
  "builtUpRateRange": {
    "min": "37298.00",
    "max": "40124.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```



```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "true",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "301.00",
```

```
"empanelmentNo": [
  "ZO:MZ:ADV:44:620"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentIds": [],
"_id": "66615ca84372ba0957d28f32",
"ownerName": "Mr. Shailesh Vrajlal Chauhan ",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9321092703",
"contactPersonName": "Mr. Sahil ",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Mr. Shailesh Vrajlal Chauhan ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "165845"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Sales Person ",
"fullAddress": "Commercial Shop No. 5, Ground Floor, Shiv Shakti Co-Op. Hsg. Soc.
Ltd. , CTS No. 218, 218/1 to 18, Dattapada Cross Road No. 3, Village - Kanheri, Borivali
(East), Taluka - Borivali, District - Mumbai Suburban , PIN - 400 066, State -
Maharashtra, Country - India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1265aa6d152c1801b374",
      "label": "Agreement For Permanent Alternate Accomodation"
    },
    "inputs": {
      "documentDate": "29/12/2021",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Amar Associates ",
      "to": {
```

```
    "value": "Member",
    "label": "Member"
  },
  "Member": "Mr. Shailesh Vrajlal Chauhan "
},
"isHardCopy": false,
"displayStatus": true,
"id": "336959",
"path": "cases/66615ca84372ba0957d28f32/
document_1717652255430_Shop_No_4.pdf",
"fileName": "document_1717652255430_Shop_No_4.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "12/05/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "remark": " (As downloaded from RERA site)",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800045346"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "887793",
  "path": "cases/66615ca84372ba0957d28f32/
document_1717652599766_P51800045346.pdf",
  "fileName": "document_1717652599766_P51800045346.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
```

```

    "label": "Municipal Corporation of Greater Mumbai"
  },
  "remark": " (As downloaded from RERA site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": " P-8428/2021/(218 And Other)/R/C Ward/KANHERI R/C/CC/1/New"
},
"isHardCopy": false,
"displayStatus": false,
"id": "622998",
"path": "cases/66615ca84372ba0957d28f32/document_1717652661150_CC.pdf",
"fileName": "document_1717652661150_CC.pdf"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "12/12/2021",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    }
  },
  "remark": " (As downloaded from RERA site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P-8428/2021/(218 And Other)/R/C Ward/KANHERI R/C/CC/1/New"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1717654473932_Drawing.pdf",
"path": "cases/66615ca84372ba0957d28f32/
document_1717654473932_Drawing.pdf",
"id": "869137",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jun 06 2024 11:44:34 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",

```

```
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "009117",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "573578",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Jun 04 2024 11:26:48 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Working Area",
    "length": "14.58",
    "length1": "14",
    "length2": "7",
    "width": "20.33",
    "width1": "20",
    "width2": "4",
    "totalArea": "296.53",
    "images": [],
    "finalArea": "296.53",
    "extraAreas": []
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1265aa6d152c1801b374",
      "label": "Agreement For Permanent Alternate Accomodation"
    },
    "docMeasurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "955287",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "301",
  "squareMeterArea": "27.96",
  "docFinalBuiltUp": "361.2",
  "docFinalBuiltUpSquareMeter": "33.552",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "534.00",
      "squareMeterArea": "49.61",
      "expectedRate": "44756.55",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "640.80",
      "squareMeterArea": "59.53",
      "expectedRate": "37297.13",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "66603b10dad2986535defd4c",
  "property": "Dattapada Road, Borivali East",
  "area": "534",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Ground",
  "source": "Housing.Com",
```

```
"expectedPrice": "23900000",
"expectedRate": "44756.55",
"builtUpExpectedRate": "37297.13",
"image": "cases/66615ca84372ba0957d28f32/
indicator_1717581926802_Image.png",
"squareMeter": "49.61",
"id": "732627"
},
{
  "carpetArea": {
    "area": "135.00",
    "squareMeterArea": "12.54",
    "expectedRate": "48148.15",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "162.00",
    "squareMeterArea": "15.05",
    "expectedRate": "40123.46",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66603b10dad2986535defd4e",
  "property": "Carter Road, Dattapada Borivali East",
  "area": "135",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Ground",
  "source": "Nobroker.com",
  "expectedPrice": "6500000",
  "expectedRate": "48148.15",
  "builtUpExpectedRate": "40123.46",
  "image": "cases/66615ca84372ba0957d28f32/
indicator_1717582383281_Image.png",
  "squareMeter": "12.54",
  "id": "563972"
}
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51af",
    "name":
"externalImg_1717500540322_WhatsApp_Image_20240604_at_152137_1.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externalImg_1717500540322_WhatsApp_Image_20240604_at_152137_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51b0",
    "name":
"externalImg_1717500540332_WhatsApp_Image_20240604_at_152137_2.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externalImg_1717500540332_WhatsApp_Image_20240604_at_152137_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51b5",
    "name":
"externalImg_1717500540352_WhatsApp_Image_20240604_at_152133_1.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externalImg_1717500540352_WhatsApp_Image_20240604_at_152133_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51b6",
    "name":
"externalImg_1717500540360_WhatsApp_Image_20240604_at_152133.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externalImg_1717500540360_WhatsApp_Image_20240604_at_152133.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51b9",
    "name":
"externalImg_1717500540369_WhatsApp_Image_20240604_at_152135_1.jpeg",
```



```
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540369_WhatsApp_Image_20240604_at_152135_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51ba",
    "name":
"externallmg_1717500540374_WhatsApp_Image_20240604_at_152135.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540374_WhatsApp_Image_20240604_at_152135.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51bb",
    "name":
"externallmg_1717500540378_WhatsApp_Image_20240604_at_152136_1.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540378_WhatsApp_Image_20240604_at_152136_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "665efa7c59496f15880f51bc",
    "name":
"externallmg_1717500540383_WhatsApp_Image_20240604_at_152136.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717500540383_WhatsApp_Image_20240604_at_152136.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66616081343f5230b100fe24",
    "name":
"externallmg_1717657728522_WhatsApp_Image_20240605_at_24409_PM_1.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728522_WhatsApp_Image_20240605_at_24409_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66616081343f5230b100fe25",
  "name":
"externallmg_1717657728525_WhatsApp_Image_20240605_at_24409_PM_2.jpeg",
  "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728525_WhatsApp_Image_20240605_at_24409_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66616081343f5230b100fe26",
  "name":
"externallmg_1717657728546_WhatsApp_Image_20240605_at_24409_PM.jpeg",
  "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728546_WhatsApp_Image_20240605_at_24409_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66616081343f5230b100fe27",
  "name":
"externallmg_1717657728553_WhatsApp_Image_20240605_at_24410_PM_1.jpeg",
  "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728553_WhatsApp_Image_20240605_at_24410_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66616081343f5230b100fe28",
  "name":
"externallmg_1717657728556_WhatsApp_Image_20240605_at_24410_PM_2.jpeg",
  "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728556_WhatsApp_Image_20240605_at_24410_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66616081343f5230b100fe29",
  "name":
"externallmg_1717657728559_WhatsApp_Image_20240605_at_24410_PM.jpeg",
  "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728559_WhatsApp_Image_20240605_at_24410_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66616081343f5230b100fe2a",
    "name":
"externallmg_1717657728561_WhatsApp_Image_20240605_at_24411_PM_1.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728561_WhatsApp_Image_20240605_at_24411_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66616081343f5230b100fe2b",
    "name":
"externallmg_1717657728563_WhatsApp_Image_20240605_at_24411_PM_2.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728563_WhatsApp_Image_20240605_at_24411_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66616081343f5230b100fe2c",
    "name":
"externallmg_1717657728566_WhatsApp_Image_20240605_at_24411_PM.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728566_WhatsApp_Image_20240605_at_24411_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66616081343f5230b100fe2d",
    "name":
"externallmg_1717657728568_WhatsApp_Image_20240605_at_24412_PM.jpeg",
    "path": "cases/66615ca84372ba0957d28f32/
externallmg_1717657728568_WhatsApp_Image_20240605_at_24412_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
```

```
    "originalname": "Shop.xlsx",
    "filename": "1717582620911_Shop.xlsx",
    "path": "cases/66615ca84372ba0957d28f32/
processingDocuments/1717582620911_Shop.xlsx",
    "size": "1553554",
    "createdAt": "Wed Jun 05 2024 15:47:01 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1717657891807_CC.pdf",
    "path": "cases/66615ca84372ba0957d28f32/
processingDocuments/1717657891807_CC.pdf",
    "size": "174061",
    "createdAt": "Thu Jun 06 2024 12:41:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Drawing.pdf",
    "filename": "1717657891811_Drawing.pdf",
    "path": "cases/66615ca84372ba0957d28f32/
processingDocuments/1717657891811_Drawing.pdf",
    "size": "9257473",
    "createdAt": "Thu Jun 06 2024 12:41:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "P51800045346.pdf",
    "filename": "1717657891963_P51800045346.pdf",
    "path": "cases/66615ca84372ba0957d28f32/
processingDocuments/1717657891963_P51800045346.pdf",
    "size": "150796",
    "createdAt": "Thu Jun 06 2024 12:41:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Shop No. 5.pdf",
    "filename": "1717657891969_Shop_No_5.pdf",
    "path": "cases/66615ca84372ba0957d28f32/
processingDocuments/1717657891969_Shop_No_5.pdf",
    "size": "13180396",
    "createdAt": "Thu Jun 06 2024 12:41:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-06T06:52:24.189Z",
"updatedAt": "2024-06-06T09:44:37.838Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60f915d3f3dd69653a592199",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Permanent Alternate Accomodation",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 301.00",
"flatRate": "43500",
"landOtherRate": "40500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "296.53",
"extendOfSiteRemark": "",
"finalBuiltupArea": "326.18",
"finalCarpetArea": "296.53",
"finalSalableArea": "358.80",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "Working Area",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": ""
```

```
"leasePeriod": 0,  
"leaseFrom": "",  
"leaseTo": "",  
"remainingLeasePeriod": 0,  
"leaseDate": ""  
}  
,  
"reportGeneratedDate": "Thu Jun 06 2024 10:33:35 GMT+0530 (India Standard  
Time)",  
"siteVisitDate": "2024-06-04",  
"invoiceId": null  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Working Area	14'7"	20'4"	296.53
<hr/>			
Other Composition :			
<hr/>			