

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dd"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f89",
    "firstName": "Nayan Tarak ",
    "email": "10_default_@cosmosbank.co.in",
    "mobileNo": "912224476023",
    "workMobileNo": "9321889545",
    "lastName": "Bosamia"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Nayan Tarak ",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dd",
  "branchCode": "000006",
  "type": "BRANCH",
  "name": "MRO-A1, Vile Parle (East) Branch",
  "email": "vileparleeast@cosmosbank.in",
  "mobileNo": "022-26131060",
  "alternateMobileNo": "022-26132085 / 86",
  "address": "Pratik Avenue, 1st Floor, Opp. Shivsagar Hotel, Nehru Road, Vile Parle
(East), Mumbai - 400 057, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
```

```
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60016f965256c07aec8e6dd6",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.79256075957872",
  "longitude": "72.70577852188991"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.70577852188991,
```

```
19.79256075957872
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "8/06/2024 01:04 pm"
    },
    {
      "dateTime": "8/06/2024 12:00 am"
    },
    {
      "dateTime": "8/06/2024 12:00 am"
    },
    {
      "dateTime": "8/06/2024 12:00 am"
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Pamtembhi",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Boisar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
}
```

```
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "T 5",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tarapur Industrial Area M I D C ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Navapur Road ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
```



```
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Boisar West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6662a7461daaad305a6e3e16",
"ownerName": "Indian Metal And Chemicals Corporation ",
"ownerPhoneNo": "9819392597",
"appAddress": "location - Tarapur industrial estate ",
"remark": "value given by Binu sir \n contact person - Jitendra purohit ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6662a7461daaad305a6e3e16/
document_1717741303508_.1717741145073_Indian_metal_",
    "fileName": "document_1717741303508_.1717741145073_Indian_metal_",
    "id": "511460",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Fri Jun 07 2024 11:53:02 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1717832309417_Valuation_report_Indian_Metal__Chemicals_Corpn.pdf",
    "path": "cases/6662a7461daaad305a6e3e16/
document_1717832309417_Valuation_report_Indian_Metal__Chemicals_Corpn.pdf",
    "id": "127426",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Sat Jun 08 2024 13:08:53 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1717832328820_Property_Documents_Indian_Metal__Chemicals_Corpn.pdf",
"path": "cases/6662a7461daaad305a6e3e16/document_1717832328820_Property_Documents_Indian_Metal__Chemicals_Corpn.pdf",
"id": "499541",
"uploadedBy": "6006d4ce5080a310ac1fd2",
"createdAt": "Sat Jun 08 2024 13:08:53 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009144",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "825378",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 07 2024 11:53:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Indian Metal And Chemicals Corporation ",
    "phone": "9819392597",
    "ownershipShare": "",
    "email": "",
    "id": "897266"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "66682a5d2ae3637b0ee9a621",
    "name":
"externallmg_1718102620950_WhatsApp_Image_20240611_at_154204_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620950_WhatsApp_Image_20240611_at_154204_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a622",
    "name":
"externallmg_1718102620955_WhatsApp_Image_20240611_at_154204_2.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620955_WhatsApp_Image_20240611_at_154204_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a623",
    "name":
"externallmg_1718102620958_WhatsApp_Image_20240611_at_154204.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620958_WhatsApp_Image_20240611_at_154204.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a624",
    "name":
"externallmg_1718102620961_WhatsApp_Image_20240611_at_154205_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620961_WhatsApp_Image_20240611_at_154205_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a625",
    "name":
"externallmg_1718102620964_WhatsApp_Image_20240611_at_154205.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620964_WhatsApp_Image_20240611_at_154205.jpeg",
    "orientation": "landscape"
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a5d2ae3637b0ee9a626",
  "name":
"externallmg_1718102620967_WhatsApp_Image_20240611_at_154206_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620967_WhatsApp_Image_20240611_at_154206_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a5d2ae3637b0ee9a627",
  "name":
"externallmg_1718102620973_WhatsApp_Image_20240611_at_154206.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620973_WhatsApp_Image_20240611_at_154206.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a5d2ae3637b0ee9a628",
  "name":
"externallmg_1718102620975_WhatsApp_Image_20240611_at_154140.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620975_WhatsApp_Image_20240611_at_154140.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a5d2ae3637b0ee9a629",
  "name":
"externallmg_1718102620979_WhatsApp_Image_20240611_at_154148.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620979_WhatsApp_Image_20240611_at_154148.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a5d2ae3637b0ee9a62a",
  "name":
"externallmg_1718102620984_WhatsApp_Image_20240611_at_154149_1.jpeg",
```

```
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620984_WhatsApp_Image_20240611_at_154149_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a62b",
    "name":
"externallmg_1718102620988_WhatsApp_Image_20240611_at_154149.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620988_WhatsApp_Image_20240611_at_154149.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a62c",
    "name":
"externallmg_1718102620992_WhatsApp_Image_20240611_at_154150_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620992_WhatsApp_Image_20240611_at_154150_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a62d",
    "name":
"externallmg_1718102620995_WhatsApp_Image_20240611_at_154150.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620995_WhatsApp_Image_20240611_at_154150.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a62e",
    "name":
"externallmg_1718102620998_WhatsApp_Image_20240611_at_154151_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102620998_WhatsApp_Image_20240611_at_154151_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a62f",
    "name":
"externallmg_1718102621003_WhatsApp_Image_20240611_at_154151.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102621003_WhatsApp_Image_20240611_at_154151.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a630",
    "name":
"externallmg_1718102621009_WhatsApp_Image_20240611_at_154152_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102621009_WhatsApp_Image_20240611_at_154152_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a631",
    "name":
"externallmg_1718102621012_WhatsApp_Image_20240611_at_154152.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102621012_WhatsApp_Image_20240611_at_154152.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a632",
    "name":
"externallmg_1718102621016_WhatsApp_Image_20240611_at_154153_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102621016_WhatsApp_Image_20240611_at_154153_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a633",
    "name":
"externallmg_1718102621021_WhatsApp_Image_20240611_at_154153_2.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102621021_WhatsApp_Image_20240611_at_154153_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a5d2ae3637b0ee9a634",
    "name":
"externallmg_1718102621023_WhatsApp_Image_20240611_at_154153.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102621023_WhatsApp_Image_20240611_at_154153.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e327",
    "name":
"externallmg_1718102642698_WhatsApp_Image_20240611_at_154154_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642698_WhatsApp_Image_20240611_at_154154_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e328",
    "name":
"externallmg_1718102642704_WhatsApp_Image_20240611_at_154154.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642704_WhatsApp_Image_20240611_at_154154.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e329",
    "name":
"externallmg_1718102642708_WhatsApp_Image_20240611_at_154155_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642708_WhatsApp_Image_20240611_at_154155_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e32a",
```



```
    "name":
"externallmg_1718102642713_WhatsApp_Image_20240611_at_154155.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642713_WhatsApp_Image_20240611_at_154155.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e32b",
    "name":
"externallmg_1718102642717_WhatsApp_Image_20240611_at_154156_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642717_WhatsApp_Image_20240611_at_154156_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e32c",
    "name":
"externallmg_1718102642720_WhatsApp_Image_20240611_at_154156.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642720_WhatsApp_Image_20240611_at_154156.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e32d",
    "name":
"externallmg_1718102642726_WhatsApp_Image_20240611_at_154157_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642726_WhatsApp_Image_20240611_at_154157_1.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e32e",
    "name":
"externallmg_1718102642730_WhatsApp_Image_20240611_at_154157_2.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642730_WhatsApp_Image_20240611_at_154157_2.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a72f605307b0194e32f",
  "name":
"externallmg_1718102642735_WhatsApp_Image_20240611_at_154157.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642735_WhatsApp_Image_20240611_at_154157.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a72f605307b0194e330",
  "name":
"externallmg_1718102642738_WhatsApp_Image_20240611_at_154158_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642738_WhatsApp_Image_20240611_at_154158_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a72f605307b0194e331",
  "name":
"externallmg_1718102642741_WhatsApp_Image_20240611_at_154158.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642741_WhatsApp_Image_20240611_at_154158.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a72f605307b0194e332",
  "name":
"externallmg_1718102642744_WhatsApp_Image_20240611_at_154159_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642744_WhatsApp_Image_20240611_at_154159_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a72f605307b0194e333",
  "name":
"externallmg_1718102642748_WhatsApp_Image_20240611_at_154159_2.jpeg",
```

```
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642748_WhatsApp_Image_20240611_at_154159_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e334",
    "name":
"externallmg_1718102642752_WhatsApp_Image_20240611_at_154159.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642752_WhatsApp_Image_20240611_at_154159.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e335",
    "name":
"externallmg_1718102642755_WhatsApp_Image_20240611_at_154200_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642755_WhatsApp_Image_20240611_at_154200_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e336",
    "name":
"externallmg_1718102642758_WhatsApp_Image_20240611_at_154200.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642758_WhatsApp_Image_20240611_at_154200.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a72f605307b0194e337",
    "name":
"externallmg_1718102642760_WhatsApp_Image_20240611_at_154201_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642760_WhatsApp_Image_20240611_at_154201_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66682a72f605307b0194e338",
  "name":
"externallmg_1718102642763_WhatsApp_Image_20240611_at_154201.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642763_WhatsApp_Image_20240611_at_154201.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a72f605307b0194e339",
  "name":
"externallmg_1718102642767_WhatsApp_Image_20240611_at_154202_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102642767_WhatsApp_Image_20240611_at_154202_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a7f1386b87b142df578",
  "name":
"externallmg_1718102655141_WhatsApp_Image_20240611_at_154201.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655141_WhatsApp_Image_20240611_at_154201.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a7f1386b87b142df579",
  "name":
"externallmg_1718102655149_WhatsApp_Image_20240611_at_154202_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655149_WhatsApp_Image_20240611_at_154202_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a7f1386b87b142df57a",
  "name":
"externallmg_1718102655157_WhatsApp_Image_20240611_at_154202_2.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655157_WhatsApp_Image_20240611_at_154202_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a7f1386b87b142df57b",
    "name":
"externallmg_1718102655163_WhatsApp_Image_20240611_at_154202.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655163_WhatsApp_Image_20240611_at_154202.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a7f1386b87b142df57c",
    "name":
"externallmg_1718102655166_WhatsApp_Image_20240611_at_154203_1.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655166_WhatsApp_Image_20240611_at_154203_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a7f1386b87b142df57d",
    "name":
"externallmg_1718102655173_WhatsApp_Image_20240611_at_154203.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655173_WhatsApp_Image_20240611_at_154203.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a7f1386b87b142df57e",
    "name":
"externallmg_1718102655176_WhatsApp_Image_20240611_at_150431.jpeg",
    "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655176_WhatsApp_Image_20240611_at_150431.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66682a7f1386b87b142df57f",
```

```
"name":
"externallmg_1718102655180_WhatsApp_Image_20240611_at_154138.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655180_WhatsApp_Image_20240611_at_154138.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a7f1386b87b142df580",
  "name":
"externallmg_1718102655185_WhatsApp_Image_20240611_at_154139_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655185_WhatsApp_Image_20240611_at_154139_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66682a7f1386b87b142df581",
  "name":
"externallmg_1718102655188_WhatsApp_Image_20240611_at_154139.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718102655188_WhatsApp_Image_20240611_at_154139.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666930d12ae3637b0ee9e32d",
  "name":
"externallmg_1718169809849_WhatsApp_Image_20240612_at_100755.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718169809849_WhatsApp_Image_20240612_at_100755.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666930d12ae3637b0ee9e32e",
  "name":
"externallmg_1718169809854_WhatsApp_Image_20240612_at_095914_1.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externallmg_1718169809854_WhatsApp_Image_20240612_at_095914_1.jpeg",
  "orientation": "portrait"
},
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666930d12ae3637b0ee9e32f",
  "name":
"externalImg_1718169809858_WhatsApp_Image_20240612_at_095914.jpeg",
  "path": "cases/6662a7461daaad305a6e3e16/
externalImg_1718169809858_WhatsApp_Image_20240612_at_095914.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-07T06:23:03.012Z",
"updatedAt": "2024-06-12T05:23:29.974Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Land and Building No. Basement Floor, Plot No. T 5,
Tarapur Industrial Area M I D C , Navapur Road , Village - Pamtembhi, Boisar West,
Boisar, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Indian Metal And Chemicals Corporation ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819392597"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
