

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb1b"
    },
    "type": "CREDITOFFICER",
    "_id": "6526967c703d7c40db9b3f63",
    "firstName": "Vidita",
    "lastName": "Vange",
    "mobileNo": "",
    "workMobileNo": "7977425956",
    "email": "goregaon@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4502599",
    "discussWithPerson": "Vidita",
    "expectedFees": 2251.2995,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb1b",
  "branchCode": "000025",
  "type": "BRANCH",
  "name": "Goregaon (East) Branch",
  "email": "goregaon@cosmosbank.in",
  "mobileNo": "02226856763 ",
  "alternateMobileNo": "",
  "address": "D Definity, Shop No. 95, ground floor no 364, 3, Jay Prakash Nagar Rd
No-3, Jay Prakash Nagar, Goregaon (East), Mumbai - 400063, State - Maharashtra,
Country - India ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
```

```
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
```

```
"location": {
  "latitude": "19.013596638208483",
  "longitude": "72.8342730179429"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8342730179429,
    19.013596638208483
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/06/2024 02:15 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
```

```
"key": "village",
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "7",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Manik Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "567 Bhavani Shankar Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "72",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dadar West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6662b719732c0830539dcd99",
"ownerName": "Bipin Dayalal Mehta ",
"ownerPhoneNo": "9821321799",
"appAddress": "Flat no 72 7 th floor Manik Apartment Co-operative HSG Soc Ltd
Bhavani Shankar Road Dadar West Mumbai 400028",
"remark": "Visit time Approvad Plan copy ricived ya photo Leneko bole Engg ko ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6662b719732c0830539dcd99/
document_1717745415380_1717745265626_DocScanner_06Jun2024_616_pm.pdf",
    "fileName":
"document_1717745415380_1717745265626_DocScanner_06Jun2024_616_pm.pdf",
    "id": "238126",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Jun 07 2024 13:00:33 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009152",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "685340",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 07 2024 13:00:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bipin Dayalal Mehta ",
    "phone": "9821321799",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "736394"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6663cc8d732c0830539e1bd5",
    "name": "externalImg_1717816461116_1717816312076_image_0.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externalImg_1717816461116_1717816312076_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6663cc8e732c0830539e1bd6",
    "name": "externalImg_1717816461191_1717816312076_image_1.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externalImg_1717816461191_1717816312076_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6663cc8e732c0830539e1bd7",
    "name": "externalImg_1717816461394_1717816312076_image_2.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externalImg_1717816461394_1717816312076_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cca8732c0830539e1bf7",
    "name": "externalImg_1717816484802_1717816335087_image_0.jpeg",
```

```
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816484802_1717816335087_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cca8732c0830539e1bf8",
    "name": "externallmg_1717816484926_1717816335087_image_1.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816484926_1717816335087_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cca8732c0830539e1bf9",
    "name": "externallmg_1717816485127_1717816335087_image_2.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816485127_1717816335087_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cca8732c0830539e1bfa",
    "name": "externallmg_1717816485770_1717816335087_image_3.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816485770_1717816335087_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cca8732c0830539e1bfb",
    "name": "externallmg_1717816486067_1717816335087_image_4.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816486067_1717816335087_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cca8732c0830539e1bfc",
    "name": "externallmg_1717816486454_1717816335087_image_5.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816486454_1717816335087_image_5.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cca8732c0830539e1bfd",
  "name": "externallmg_1717816486816_1717816335087_image_6.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816486816_1717816335087_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cca8732c0830539e1bfe",
  "name": "externallmg_1717816487099_1717816335087_image_7.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816487099_1717816335087_image_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cca8732c0830539e1bff",
  "name": "externallmg_1717816487789_1717816335087_image_8.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816487789_1717816335087_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c34",
  "name": "externallmg_1717816543501_1717816393760_image_0.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816543501_1717816393760_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c35",
  "name": "externallmg_1717816543826_1717816393760_image_1.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816543826_1717816393760_image_1.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6663cce6732c0830539e1c36",
      "name": "externallmg_1717816544026_1717816393760_image_2.jpeg",
      "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816544026_1717816393760_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6663cce6732c0830539e1c37",
      "name": "externallmg_1717816544596_1717816393760_image_3.jpeg",
      "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816544596_1717816393760_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6663cce6732c0830539e1c38",
      "name": "externallmg_1717816545112_1717816393760_image_4.jpeg",
      "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816545112_1717816393760_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6663cce6732c0830539e1c39",
      "name": "externallmg_1717816545402_1717816393760_image_5.jpeg",
      "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816545402_1717816393760_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6663cce6732c0830539e1c3a",
      "name": "externallmg_1717816545938_1717816393760_image_6.jpeg",
      "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816545938_1717816393760_image_6.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c3b",
  "name": "externallmg_1717816546262_1717816393760_image_7.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816546262_1717816393760_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c3c",
  "name": "externallmg_1717816546884_1717816393760_image_8.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816546884_1717816393760_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c3d",
  "name": "externallmg_1717816547546_1717816393760_image_9.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816547546_1717816393760_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c3e",
  "name": "externallmg_1717816547745_1717816393760_image_10.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816547745_1717816393760_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663cce6732c0830539e1c3f",
  "name": "externallmg_1717816548278_1717816393760_image_11.jpeg",
  "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816548278_1717816393760_image_11.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cce6732c0830539e1c40",
    "name": "externallmg_1717816548929_1717816393760_image_12.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816548929_1717816393760_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cce6732c0830539e1c41",
    "name": "externallmg_1717816549214_1717816393760_image_13.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816549214_1717816393760_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cce6732c0830539e1c42",
    "name": "externallmg_1717816549682_1717816393760_image_14.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816549682_1717816393760_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cd001daaad305a6eada8",
    "name": "externallmg_1717816571300_1717816420201_image_0.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816571300_1717816420201_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cd001daaad305a6eada9",
    "name": "externallmg_1717816571534_1717816420201_image_1.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816571534_1717816420201_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6663cd001daaad305a6eadaa",
    "name": "externallmg_1717816571923_1717816420201_image_2.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816571923_1717816420201_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cd001daaad305a6eadab",
    "name": "externallmg_1717816572642_1717816420201_image_3.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816572642_1717816420201_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cd001daaad305a6eadac",
    "name": "externallmg_1717816573004_1717816420201_image_4.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816573004_1717816420201_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cd001daaad305a6eadad",
    "name": "externallmg_1717816573696_1717816420201_image_5.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816573696_1717816420201_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663cd001daaad305a6eadae",
    "name": "externallmg_1717816574535_1717816420201_image_6.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externallmg_1717816574535_1717816420201_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```

    "_id": "6663cd001daaad305a6eadaf",
    "name": "externalimg_1717816575346_1717816420201_image_7.jpeg",
    "path": "cases/6662b719732c0830539dcd99/
externalimg_1717816575346_1717816420201_image_7.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-07T07:30:33.868Z",
"updatedAt": "2024-06-08T03:16:16.284Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 72, 7th Floor, Manik Apartment, 567 Bhavani
Shankar Road, Dadar West, Mumbai",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Bipin Dayalal Mehta ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9821321799"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			