

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9df"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b33",
    "email": "guruprasad.nadkarni@cosmosbank.in",
    "firstName": "GURUPRASAD NADKARNI",
    "mobileNo": "9869261322",
    "workMobileNo": "9869261322",
    "lastName": "NADKARNI"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "GURUPRASAD NADKARNI",
    "expectedFees": 3750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9df",
  "branchCode": "000013",
  "type": "BRANCH",
  "name": "Dahisar (East) Branch",
  "email": "vidyadhar.rangnekar@cosmosbank.in",
  "mobileNo": "02228975314",
  "alternateMobileNo": "",
  "address": "Sanghvi Exotica, Near Maratha Colony, Vamanrao Sawant Marg,
Maratha Colony, Dahisar (East), Mumbai - 400068, State - Maharashtra, Country -
India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64c777a8a5c3051014f4dd1f",
  "role": "SITEENGINEER",
  "firstName": "Pratik",
  "email": "pratikjain2277@gmail.com",
  "lastName": "Jain",
  "mobileNo": "9619286285",
  "designation": "",
  "shortName": "Pratik",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.28396871647847",
  "longitude": "72.86386906447984"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86386906447984,
    19.28396871647847
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "7/06/2024 04:59 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "5",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Siddharth Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```



```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6662ea91732c0830539dfcb9",
"ownerName": "MR DERIC JEROME HENRIQUIES",
"ownerPhoneNo": "9820475621",
"appAddress": "FLAT NO 302 3RD FLOOR BLDG NO 5 SHUP KARNA CO OP HSG
LTD SIDDHARTH NAGAR STATION ROAD MIRA ROAD EAST THANE 401107",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6662ea91732c0830539dfcb9/
document_1717758196553_1717758046910_Shupkarna_Agreement_for_Sale.pdf",
    "fileName":
"document_1717758196553_1717758046910_Shupkarna_Agreement_for_Sale.pdf",
    "id": "719835",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Fri Jun 07 2024 16:40:09 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Occupation Certificate",
      "value": "60ae1293aa6d152c1801b447"
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6662ea91732c0830539dfcb9/
document_1717758300892_1717758152138_Shupkarna_OC.pdf",
    "fileName": "document_1717758300892_1717758152138_Shupkarna_OC.pdf",
    "id": "785415",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Fri Jun 07 2024 16:40:09 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Society NOC Letter",
      "value": "60ae1266aa6d152c1801b379"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6662ea91732c0830539dfcb9/
document_1717758343198_1717758178634_Society_NOC.pdf",
    "fileName": "document_1717758343198_1717758178634_Society_NOC.pdf",
    "id": "775140",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Fri Jun 07 2024 16:40:09 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009165",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "618564",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 07 2024 16:40:09 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "MR DERIC JEROME HENRIQUIES",
    "phone": "9820475621",
    "ownershipShare": "",
    "email": "",
    "id": "505166"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d80d1daaad305a6eb44b",
    "name":
"externalImg_1717819404382_WhatsApp_Image_20240608_at_092326.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externalImg_1717819404382_WhatsApp_Image_20240608_at_092326.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d80d1daaad305a6eb44c",
    "name":
"externalImg_1717819404387_WhatsApp_Image_20240608_at_092327.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externalImg_1717819404387_WhatsApp_Image_20240608_at_092327.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d80d1daaad305a6eb44d",
    "name":
"externalImg_1717819404397_WhatsApp_Image_20240608_at_092328.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externalImg_1717819404397_WhatsApp_Image_20240608_at_092328.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d80d1daaad305a6eb44e",
    "name":
"externalImg_1717819404405_WhatsApp_Image_20240608_at_092329.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externalImg_1717819404405_WhatsApp_Image_20240608_at_092329.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663d80d1daaad305a6eb44f",
  "name":
"externallmg_1717819404410_WhatsApp_Image_20240608_at_092330.jpeg",
  "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819404410_WhatsApp_Image_20240608_at_092330.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663d80d1daaad305a6eb450",
  "name":
"externallmg_1717819404414_WhatsApp_Image_20240608_at_092331.jpeg",
  "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819404414_WhatsApp_Image_20240608_at_092331.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663d80d1daaad305a6eb451",
  "name":
"externallmg_1717819404418_WhatsApp_Image_20240608_at_092333_1.jpeg",
  "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819404418_WhatsApp_Image_20240608_at_092333_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663d80d1daaad305a6eb452",
  "name":
"externallmg_1717819404423_WhatsApp_Image_20240608_at_092333.jpeg",
  "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819404423_WhatsApp_Image_20240608_at_092333.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6663d80d1daaad305a6eb453",
  "name":
"externallmg_1717819404427_WhatsApp_Image_20240608_at_092337_1.jpeg",
```

```
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819404427_WhatsApp_Image_20240608_at_092337_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d80d1daaad305a6eb454",
    "name":
"externallmg_1717819404430_WhatsApp_Image_20240608_at_092337_2.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819404430_WhatsApp_Image_20240608_at_092337_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b54c",
    "name":
"externallmg_1717819420615_WhatsApp_Image_20240608_at_092337.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420615_WhatsApp_Image_20240608_at_092337.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b54d",
    "name":
"externallmg_1717819420625_WhatsApp_Image_20240608_at_092338_1.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420625_WhatsApp_Image_20240608_at_092338_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b54e",
    "name":
"externallmg_1717819420630_WhatsApp_Image_20240608_at_092338.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420630_WhatsApp_Image_20240608_at_092338.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6663d81c46c7a930aad3b54f",
    "name":
"externallmg_1717819420631_WhatsApp_Image_20240608_at_092339_1.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420631_WhatsApp_Image_20240608_at_092339_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b550",
    "name":
"externallmg_1717819420640_WhatsApp_Image_20240608_at_092339_2.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420640_WhatsApp_Image_20240608_at_092339_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b551",
    "name":
"externallmg_1717819420644_WhatsApp_Image_20240608_at_092339.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420644_WhatsApp_Image_20240608_at_092339.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b552",
    "name":
"externallmg_1717819420648_WhatsApp_Image_20240608_at_092340_1.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420648_WhatsApp_Image_20240608_at_092340_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b553",
    "name":
"externallmg_1717819420654_WhatsApp_Image_20240608_at_092340_2.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420654_WhatsApp_Image_20240608_at_092340_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b554",
    "name":
"externallmg_1717819420656_WhatsApp_Image_20240608_at_092340.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420656_WhatsApp_Image_20240608_at_092340.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b555",
    "name":
"externallmg_1717819420659_WhatsApp_Image_20240608_at_092341_1.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420659_WhatsApp_Image_20240608_at_092341_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b556",
    "name":
"externallmg_1717819420663_WhatsApp_Image_20240608_at_092341.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420663_WhatsApp_Image_20240608_at_092341.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b557",
    "name":
"externallmg_1717819420667_WhatsApp_Image_20240608_at_092342_1.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420667_WhatsApp_Image_20240608_at_092342_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b558",
```

```
    "name":
"externallmg_1717819420672_WhatsApp_Image_20240608_at_092342_2.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420672_WhatsApp_Image_20240608_at_092342_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b559",
    "name":
"externallmg_1717819420677_WhatsApp_Image_20240608_at_092342.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420677_WhatsApp_Image_20240608_at_092342.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b55a",
    "name":
"externallmg_1717819420680_WhatsApp_Image_20240608_at_092343_1.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420680_WhatsApp_Image_20240608_at_092343_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b55b",
    "name":
"externallmg_1717819420684_WhatsApp_Image_20240608_at_092343_2.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420684_WhatsApp_Image_20240608_at_092343_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6663d81c46c7a930aad3b55c",
    "name":
"externallmg_1717819420688_WhatsApp_Image_20240608_at_092343.jpeg",
    "path": "cases/6662ea91732c0830539dfcb9/
externallmg_1717819420688_WhatsApp_Image_20240608_at_092343.jpeg",
    "orientation": "landscape"
}
}
```



```

],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-07T11:10:09.857Z",
"updatedAt": "2024-06-08T04:03:40.908Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 302, 3rd Floor, Building No 5, Siddharth Nagar,
Mira Road East, Mira Road",
"updatedBy": "6006d4ce5080a310ac1fd2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MR DERIC JEROME HENRIQUIES",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820475621"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			