

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "640f306e63e4271bcefdbb9e"
    },
    "type": "CREDITOFFICER",
    "_id": "64b7cf4dd0368073e3faafb0",
    "firstName": "Chintamani",
    "lastName": "Joshi",
    "mobileNo": "",
    "workMobileNo": "9819008564",
    "email": "chintamani.joshi@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "640f306e63e4271bcefd9bb9e",
  "name": "Kalyan Khadakpada Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "kalyan@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground floor, Shiv Villa Apt. Opp. gagangiri Soc. Sai Chowk, Khadakpada
Kalyan West 421301\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.24639730640441",
  "longitude": "73.1211562255868"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kalyan",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Asha Tower",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```

```
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "411/5 Part",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```



```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop No. 1 To 6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6666bf872ae3637b0ee8f8d8",
"ownerName": "Mr. Kalpesh Vasant Thakkar, Mr. Bhavesh Vasant Thakkar, Mr.
Govindram Mali & Mr. Deepak Sharma",
"ownerPhoneNo": "9820895067",
"fullAddress": "Commercial Flat No. Shop No. 1 To 6, Ground Floor, Asha Tower,
Village - Kalyan, Taluka - Kalyan, District - Thane, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1718009729140_Thakkar_shop_Agr_Cos_K.pdf",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
document_1718009729140_Thakkar_shop_Agr_Cos_K.pdf",
    "id": "121730",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Mon Jun 10 2024 14:25:35 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1718010162698_101386.pdf",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
document_1718010162698_101386.pdf",
```

```
    "id": "529269",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Mon Jun 10 2024 14:32:44 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009190",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "212211",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jun 10 2024 14:25:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Kalpesh Vasant Thakkar, Mr. Bhavesh Vasant Thakkar, Mr. Govindram
Mali & Mr. Deepak Sharma",
    "phone": "9820895067",
    "ownershipShare": "",
    "email": "",
    "id": "324678"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6667d61209a0de7b00a3c230",
    "name": "externalimg_r_1718081040379_1718080896524_image_0.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externalimg_r_1718081040379_1718080896524_image_0.jpg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a4c",
    "name": "externallmg_1718081092480_1718080933878_image_0.png",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_1718081092480_1718080933878_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a4d",
    "name": "externallmg_r_1718081093418_1718080933878_image_1.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081093418_1718080933878_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a4e",
    "name": "externallmg_r_1718081096159_1718080933878_image_4.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081096159_1718080933878_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a4f",
    "name": "externallmg_r_1718081095211_1718080933878_image_3.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081095211_1718080933878_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a50",
    "name": "externallmg_r_1718081094309_1718080933878_image_2.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081094309_1718080933878_image_2.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6667d65a2ae3637b0ee94a51",
  "name": "externallmg_r_1718081098625_1718080933878_image_5.jpg",
  "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081098625_1718080933878_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6667d65a2ae3637b0ee94a52",
  "name": "externallmg_r_1718081101004_1718080933878_image_7.jpg",
  "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081101004_1718080933878_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6667d65a2ae3637b0ee94a53",
  "name": "externallmg_r_1718081101919_1718080933878_image_8.jpg",
  "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081101919_1718080933878_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6667d65a2ae3637b0ee94a54",
  "name": "externallmg_r_1718081099883_1718080933878_image_6.jpg",
  "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081099883_1718080933878_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6667d65a2ae3637b0ee94a55",
  "name": "externallmg_r_1718081102884_1718080933878_image_9.jpg",
  "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081102884_1718080933878_image_9.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a56",
    "name": "externallmg_r_1718081104806_1718080933878_image_11.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081104806_1718080933878_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a57",
    "name": "externallmg_r_1718081103792_1718080933878_image_10.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081103792_1718080933878_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a58",
    "name": "externallmg_r_1718081105746_1718080933878_image_12.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081105746_1718080933878_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a59",
    "name": "externallmg_r_1718081106719_1718080933878_image_13.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081106719_1718080933878_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a5a",
    "name": "externallmg_r_1718081108475_1718080933878_image_15.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081108475_1718080933878_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a5b",
    "name": "externallmg_r_1718081107581_1718080933878_image_14.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081107581_1718080933878_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a5c",
    "name": "externallmg_r_1718081109359_1718080933878_image_16.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081109359_1718080933878_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a5d",
    "name": "externallmg_r_1718081111059_1718080933878_image_18.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081111059_1718080933878_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a5e",
    "name": "externallmg_r_1718081110269_1718080933878_image_17.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081110269_1718080933878_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d65a2ae3637b0ee94a5f",
    "name": "externallmg_r_1718081111794_1718080933878_image_19.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externallmg_r_1718081111794_1718080933878_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6667d6752ae3637b0ee94a7f",
    "name": "externalimg_r_1718081131388_1718080986434_image_0.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externalimg_r_1718081131388_1718080986434_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d6752ae3637b0ee94a80",
    "name": "externalimg_r_1718081135972_1718080986434_image_1.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externalimg_r_1718081135972_1718080986434_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d6752ae3637b0ee94a81",
    "name": "externalimg_r_1718081139094_1718080986434_image_3.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externalimg_r_1718081139094_1718080986434_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6667d6752ae3637b0ee94a82",
    "name": "externalimg_r_1718081137720_1718080986434_image_2.jpg",
    "path": "cases/6666bf872ae3637b0ee8f8d8/
externalimg_r_1718081137720_1718080986434_image_2.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-10T08:55:36.043Z",
"updatedAt": "2024-06-11T04:45:41.051Z",
"__v": 0,
"updatedBy": "63fc4680ce84bf289ba9c7fc",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Kalpesh Vasant Thakkar, Mr. Bhavesh Vasant Thakkar, Mr.
```

Govindram Mali & Mr. Deepak Sharma",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820895067"

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			