

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64475d5ad11ef125ab24cd9f"
    },
    "type": "CREDITOFFICER",
    "_id": "66696a9709a0de7b00a48aa6",
    "firstName": "Padma",
    "lastName": "Magdum",
    "mobileNo": "",
    "workMobileNo": "9096473962",
    "email": "1brmgr1216@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64475d5ad11ef125ab24cd9f",
  "name": "T M C Branch Thanet",
  "branchCode": "",
  "mobileNo": "02225335859\t",
  "alternateMobileNo": "",
  "email": "brmgr1216@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Thane Muncpal Corporation Building, Ground FLOOR, Panchpakhadi
Thane ( West)-400602\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.2149446181002",
  "longitude": "72.96819748628654"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-06-12T17:08:30.328Z",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-06-12",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-06-12",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-06-12",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "20000",
  "lumpsumValue": "0",
  "rateMax": "21000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "4BHK",
  "label": "4 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Panchpakhadi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "18",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "C",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Thane (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "The Address By GS Tower C",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```



```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Pokharan Road No. 1",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "65(Part), 66, 118/1(Part), 118/2(Part), 119/A/1/B, 119/A/2(Part), 119/
B(Part), 120/1/3, 131/A1(Part) & Others",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1806",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```

```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 606",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  }
},
}
```

```
"doors": {
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
  "label": "Proposed Teak wood door frame with flush doors"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Proposed_Cement_Plastering",
  "label": "Proposed Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Raymond Realty Road",
    "south": "Open Plot",
    "east": "Raymond Ground"
  },
  "asPerDocumentAgreement": {
```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan V.P. No. .S04 / 0189 /
22 / TMC / TD-DP / TPS 4437 / 23 Dated 07.07.2023 issued by Thane Municipal
Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
}
```

```
},
"compositeRate": {
  "remark": "Internal visit not allowed at site. The site details and site photographs
about the work progress status has been provided by Sales Person Ms. Pooja (Contact
No. 022 - 68373801).",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "101800",
  "landRate": "46000",
  "igrImage": "cases/66696ea6f605307b01957ef2/igr_1718267984459_Image.png",
  "squareMeterGuideLineRate": "111980.00",
  "squareFeetGuideLineRate": "10403.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "101800.00",
  "squareMeterGuideLineRate": "111980.00",
  "squareFeetGuideLineRate": "10403.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Proposed Residential Purpose",
    "value": "Proposed_Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
```

```
"floorSpaceIndex": "As per TMC norms",
"tenantName": "",
"maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Along with Three Parking Space",
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2028",
    "fullDate": "1/1/2028"
  },
  "planningArea": {
    "value": "Residential",
```

```
"label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "label": "Building is under construction ",
  "value": "Building_is_under_construction_"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
```



```
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "Lower_Ground+_Upper_Ground_Floor",
  "label": "Lower Ground + Upper Ground Floor"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "0",
"totalLifeBuilding": "60",
"estimatedAge": "0",
"noOfBasement": "1",
"noOfPodium": "4",
"noOfAmenityFloors": "0",
"noOfFloors": "40",
"flatFloorNo": "18",
"noOfLifts": "7",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "1683.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
```

```
    "label": "Railway Station"
  },
  "routeMapImg": "cases/66696ea6f605307b01957ef2/
routeMap_1718344198159_Image.png",
  "routeLat": "19.210611",
  "routeLng": "72.965982",
  "stationName": "Thane",
  "routeDistance": "5.1 Km"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "z65dw9",
    "name": "z65dw9",
    "image": "cases/66696ea6f605307b01957ef2/
routeMap_1718343701559_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "33660000.00",
"finalValue": "33660000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Jun 14 2024 18:33:09 GMT+0530 (India Standard Time)",
  "number": "2306765",
  "dayCount": "34",
  "monthCount": "209",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
    "label": "External Development & Final Finishing",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": false
  },
  "workCompleted": {
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "17508249.00",
  "selectedBuildUpValue": "1683.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "666c3c8624f3ba1343e47085",
      "name":
"externallmg_1718369414345_WhatsApp_Image_20240614_at_61450_PM.jpeg",
      "path": "cases/66696ea6f605307b01957ef2/
externallmg_1718369414345_WhatsApp_Image_20240614_at_61450_PM.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "666c3c8624f3ba1343e47085",
      "name": "Living Room",
      "path": "cases/66696ea6f605307b01957ef2/
externallmg_1718369414345_WhatsApp_Image_20240614_at_61450_PM.jpeg",
      "orientation": "landscape"
    }
  ]
},
}
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "19414.00",
    "max": "26136.00"
  },
  "builtUpRateRange": {
    "min": "17649.00",
    "max": "23760.00"
  },
  "saleableRateRange": {
    "min": "14708.00",
    "max": "19800.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1530.00",
"empanelmentNo": [
  "AX33 /CREMON/Valuer/Empanelment/Sr No.55/2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"invoices": [],
"paymentIds": [],
"_id": "66696ea6f605307b01957ef2",
"ownerName": "Mrs. Suvarna Rajan Relekar & Mr. Rajan Gajanan Relekar",
"ownerPhoneNo": "9820477550",
"fullAddress": "Residential Flat No. 1806, 18th Floor, Building No C, The Address By
```

GS Tower C, Pokharan Road No. 1, Village - Panchpakhadi, Taluka - Thane, District - Thane, Thane (West), PIN Code - 400 606, State - Maharashtra, India",

"remark": "",

"documents": [

{
 "documentType": {
 "value": "60af48bf2ffdf65bcd6585fa",
 "label": "Agreement for sale"

},

"inputs": {
 "documentDate": "25/10/2023",
 "from": {
 "value": "Promoter",
 "label": "Promoter"

},

"Promoter": "Raymond Limited",

"to": {
 "value": "Allottee",
 "label": "Allottee"

},

"Allottee": "Mrs. Suvarna Rajan Relekar & Mr. Rajan Gajanan Relekar",

"number": {
 "value": "No",
 "label": "No"

},

"No": "17169/2023"

},

"isHardCopy": false,

"displayStatus": true,

"id": "434254",

"path": "cases/66696ea6f605307b01957ef2/

document_1718185633003_BOM_TMC_Thane_br_Mr__Ralekar.pdf",

"fileName": "document_1718185633003_BOM_TMC_Thane_br_Mr__Ralekar.pdf"

},

{
 "documentType": {
 "value": "60ae129faa6d152c1801b47d",
 "label": "RERA Certificate"

},

"inputs": {
 "documentDate": "19/07/2023",
 "nameOfApprovingAuthority": {
 "value": "Maharashtra_Real_Estate_Regulatory_Authority",
 "label": "Maharashtra Real Estate Regulatory Authority"

},

"number": {

```
    "value": "No",
    "label": "No"
  },
  "No": "P51700052008"
},
"isHardCopy": false,
"displayStatus": true,
"id": "452925",
"path": "cases/66696ea6f605307b01957ef2/
document_1718343052348_171685.pdf",
"fileName": "document_1718343052348_171685.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "07/07/2023",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "V.P._No._",
      "label": "V.P. No. "
    },
    "V.P._No._": "S04 / 0189 / 22 / TMC / TDD / 4427 / 23"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1718343264219_170291.pdf",
  "path": "cases/66696ea6f605307b01957ef2/
document_1718343264219_170291.pdf",
  "id": "833892",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Jun 14 2024 11:04:24 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "07/07/2023",
    "nameOfApprovingAuthority": {
```

```
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "number": {
    "value": "V.P._No._",
    "label": "V.P. No. "
  },
  "V.P._No._": "S04 / 0189 / 22 / TMC / TD-DP / TPS 4437 / 23"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1718345153276_9_Building_Plan_Approval___NA_Order_f
or_plotted_development_9.pdf",
"path": "cases/66696ea6f605307b01957ef2/document_1718345153276_9_Building
_Plan_Approval___NA_Order_for_plotted_development_9.pdf",
"id": "207745",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Jun 14 2024 11:35:53 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009244",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "707791",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 12 2024 15:17:18 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Suvarna Rajan Relekar & Mr. Rajan Gajanan Relekar",
    "phone": "9820477550",
    "ownershipShare": "",
    "email": "",
    "id": "377487"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
```

```
"areaType": {
  "label": "Carpet",
  "value": "Carpet"
},
"providedBy": {
  "label": "Owner",
  "value": "Owner"
},
"_id": "6669d633fad8e879fe3de15f",
"area": "1433",
"providedByName": "Mrs. Suvarna Rajan Relekar & Mr. Rajan Gajanan Relekar",
"providedByContactNo": "9820477550"
}],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "270932",
    "name": "Living Room",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
    "width": "0.00",
    "width1": "0",
    "width2": "00",
    "totalArea": "0.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "0.00"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "5",
    "name": "Dining",
    "length": "",
    "length1": "0",
    "length2": "0",
    "width": "",
    "width1": "0",
    "width2": "0",
```

```
"totalArea": "0.00",
"images": [],
"finalArea": "0.00",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },

```

```
"id": "5",
"name": "Bedroom",
"length": "",
"length1": "0",
"length2": "0",
"width": "",
"width1": "0",
"width2": "0",
"totalArea": "0.00",
"images": [],
"finalArea": "0.00",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Toilet",
```



```
"length": "0.00",
"length1": "0",
"length2": "00",
"width": "0.00",
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "142.14",
    "totalAreaDocument": "1530",
    "docBuiltpPercentage": "10",
```

```
"docFinalBuiltUp": "1683.00",
"docFinalBuiltUpSquareMeter": "156.36",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "819477"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "1093.00",
"squareMeterArea": "101.54",
"expectedRate": "25526.08",
"percentage": ""
},
"builtUpArea": {
"area": "1311.60",
"squareMeterArea": "121.85",
"expectedRate": "21271.73",
"percentage": "20"
},
"saleableArea": {
"area": "1573.92",
"squareMeterArea": "146.22",
"expectedRate": "17726.44",
"percentage": "20"
},
"printlnReport": true,
"_id": "666ab0c1d4bc7979fdcfff2a",
"property": "Flat",
"area": "1093",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Dwello.com",
"expectedPrice": "27900000",
"expectedRate": "25526.08",
"builtUpExpectedRate": "21271.73",
"image": "cases/66696ea6f605307b01957ef2/
indicator_1718267732089_Image.png",
"squareMeter": "101.54",
"id": "743328"
```

```
},
{
  "carpetArea": {
    "area": "1530.00",
    "squareMeterArea": "142.14",
    "expectedRate": "19413.72",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1683.00",
    "squareMeterArea": "156.36",
    "expectedRate": "17648.84",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "2019.60",
    "squareMeterArea": "187.63",
    "expectedRate": "14707.36",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "666ab0c1d4bc7979fdcfff2b",
  "property": "Flat",
  "area": "1530",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "29702990",
  "expectedRate": "19413.72",
  "builtUpExpectedRate": "17648.84",
  "image": "cases/66696ea6f605307b01957ef2/
indicator_1718267799573_Image.png",
  "squareMeter": "142.14",
  "id": "238319"
},
{
  "carpetArea": {
    "area": "991.00",
    "squareMeterArea": "92.07",
    "expectedRate": "26135.22",
    "percentage": ""
  },
  "builtUpArea": {
```

```
"area": "1090.10",
"squareMeterArea": "101.27",
"expectedRate": "23759.29",
"percentage": "10"
},
"saleableArea": {
  "area": "1308.12",
  "squareMeterArea": "121.53",
  "expectedRate": "19799.41",
  "percentage": "20"
},
"printlnReport": true,
"_id": "666ab0c1d4bc7979fdcfff2c",
"property": "Flat",
"area": "991",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Raymond_Reality",
"expectedPrice": "25900000",
"expectedRate": "26135.22",
"builtUpExpectedRate": "23759.29",
"image": "cases/66696ea6f605307b01957ef2/
indicator_1718267917946_Image.png",
"squareMeter": "92.07",
"id": "536813"
},
{
  "carpetArea": {
    "area": "2015.00",
    "squareMeterArea": "187.20",
    "expectedRate": "22701.08",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "2216.50",
    "squareMeterArea": "205.92",
    "expectedRate": "20637.34",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "2659.80",
    "squareMeterArea": "247.10",
    "expectedRate": "17197.79",
```

```
    "percentage": "20"
  },
  "printlnReport": false,
  "_id": "666ab4eed607d979c004256c",
  "property": "Flat",
  "area": "2015",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "45742670",
  "expectedRate": "22701.08",
  "builtUpExpectedRate": "20637.34",
  "image": "cases/66696ea6f605307b01957ef2/
indicator_1718269012151_Image.png",
  "squareMeter": "187.20",
  "id": "205794"
},
{
  "carpetArea": {
    "area": "1455.00",
    "squareMeterArea": "135.17",
    "expectedRate": "23459.92",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1600.50",
    "squareMeterArea": "148.69",
    "expectedRate": "21327.20",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "1920.60",
    "squareMeterArea": "178.43",
    "expectedRate": "17772.66",
    "percentage": "20"
  },
  "printlnReport": false,
  "_id": "666ab4eed607d979c004256d",
  "property": "Flat",
  "area": "1455",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
```

```
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "34134177",
"expectedRate": "23459.92",
"builtUpExpectedRate": "21327.20",
"image": "cases/66696ea6f605307b01957ef2/
indicator_1718269099281_Image.png",
"squareMeter": "135.17",
"id": "215510"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6669d65fd4bc7979fdcfafe9",
"name": "externalImg_1718212184550_image.jpeg",
"path": "cases/66696ea6f605307b01957ef2/
externalImg_1718212184550_image.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "666c3c8624f3ba1343e47084",
"name":
"externalImg_1718369414339_WhatsApp_Image_20240614_at_61450_PM_1.jpeg",
"path": "cases/66696ea6f605307b01957ef2/
externalImg_1718369414339_WhatsApp_Image_20240614_at_61450_PM_1.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "666c3c8624f3ba1343e47085",
"name":
"externalImg_1718369414345_WhatsApp_Image_20240614_at_61450_PM.jpeg",
"path": "cases/66696ea6f605307b01957ef2/
externalImg_1718369414345_WhatsApp_Image_20240614_at_61450_PM.jpeg",
"orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
```

```
    "originalname": "SUVARNA RAJAN RELEKAR & MR. RAJAN GAJANAN
RELEKAR -Flat No. 1806 - Bank Of Maharashtra ( T M C Branch Thane ).xlsx",
    "filename": "1718269339766_SUVARNA_RAJAN_RELEKAR__MR_RAJAN_GAJAN
AN_RELEKAR___Flat_No_1806__Bank_Of_Maharashtra__T_M_C_Branch_Thane_.xl
sx",
    "path": "cases/66696ea6f605307b01957ef2/processingDocuments/1718269339766
_SUVARNA_RAJAN_RELEKAR__MR_RAJAN_GAJANAN_RELEKAR___Flat_No_180
6__Bank_Of_Maharashtra__T_M_C_Branch_Thane_.xlsx",
    "size": "1969277",
    "createdAt": "Thu Jun 13 2024 14:32:19 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "666a9163d4bc7979fdcfddf5",
    "note": "Value given for confirmation",
    "taskId": "66696eb41386b87b142e6b53",
    "createdAt": "2024-06-13T06:27:47.126Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "CHECKER",
    "display": true,
    "status": true,
    "_id": "666d2211fad0e137dd8c204",
```

```
"note": "for remarks (Task Reopen)",
"taskId": "666be5cef9bf96455debc580",
"createdAt": "2024-06-15T05:09:37.788Z"
}
],
"createdAt": "2024-06-12T09:47:18.359Z",
"updatedAt": "2024-06-15T05:11:22.278Z",
"__v": 0,
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Ms. Pooja - Sales Person Contact No. 02268373801 / Mrs.
Suvarna Rajan Relekar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Self",
"siteVisitContactNo": "9820477550",
"briefDescOfProperty": "4 Bedroom + Living Room + Kitchen + Dining + 4 Toilet",
"carpetTotal": "0.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"siteVisitDate": "2024-06-12",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1530.00",
"flatRate": "22000",
"landOtherRate": "19200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 1438.00\nExclusive Balcony
```



```

Area in Sq. Ft. = 92.00",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Fri Jun 14 2024 09:54:56 GMT+0530 (India Standard Time)",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	0'00"	0'00"	0.00
Dining	0'0"	0'0"	0.00
Bedroom	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Bedroom	0'0"	0'0"	0.00
Bedroom	0'00"	0'00"	0.00
Kitchen	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00

Toilet	0'00"	0'00"	0.00
--------	-------	-------	------

Other
Composition :
