

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7dca191f7b344b003ede"
    },
    "type": "CREDITOFFICER",
    "_id": "65c33048b0ec7f2151fdb8bc",
    "firstName": "Shashank ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7905284698",
    "email": "shashank.kumar@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6750000",
    "discussWithPerson": "Shashank ",
    "expectedFees": 3375,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7dca191f7b344b003ede",
  "name": "UBI-GOREGAON (EAST)",
  "branchCode": "",
  "mobileNo": "\022-26863400 022-26862835",
  "alternateMobileNo": "",
  "email": "goregaon@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "172/73, Shree Sadan, Shantaben Estate, Goregoan (East), Mumbai -
400 063."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
  "_id": "6084131a13f01f158c6ea1f4",
```

```
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.185264285875203",
  "longitude": "72.85029392528698"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85029392528698,
    19.185264285875203
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-13",
      "remark": "Contact person Nimit Shah "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-13",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"schedule": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Valanai",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "3",
```

```
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Mahavir Darshan (G. K -3) Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "G. K. Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Malad Shankar Lane",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "68 (Part), 67 (Part) & 92 (Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "4",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (West), Mumbai",
  "label": false
}
```

```

},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {

```

```
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
  "north": "Paras Nagar CHSL",
  "west": "Shree Paras Darshan CHSL",
  "south": "Shankar Lane",
  "east": "Mahavir Temple"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
```

```
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "58.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "22062",
"depreciatedBuildingRate": "1162"
},
"igrRate": {
"propertyName": "Residential ",
"rate": "165880.00",
"landRate": "76250",
"igrImage": "cases/66697b76f605307b01958fe4/igr_1718257144736_Image.png",
"squareMeterGuideLineRate": "165880.00",
"squareFeetGuideLineRate": "15411.00"
},
"igrFinalRate": {
"floorRatePercentage": "0",
"depreciationPercentage": "61",
"rate": "12163.00",
"squareFeetGuideLineRate": "12163.00",
"squareMeterGuideLineRate": "130924.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
}
```

```
"monthlyRent": "20,000/- Present rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "Devanank Shah",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
```

```
"date": "1",
"month": "1",
"year": "1985",
"fullDate": "1/1/1985"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
```

```
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_agreement",
"label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "21",
"ageOfBuilding": "39",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "6",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "0.00"
},
}
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/66697b76f605307b01958fe4/
routeMap_1718278875642_Image.png",
    "routeLat": "19.198288",
    "routeLng": "72.841294",
    "stationName": "Kandivali",
    "routeDistance": "1.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "2xb5q",
      "name": "2xb5q",
      "image": "cases/66697b76f605307b01958fe4/
routeMap_1718278240131_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8273250.00",
"finalValue": "8273250.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4561125.00",
  "selectedBuildUpValue": "375.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "666ab547d4bc7979fdd00368",
      "name": "externallmg_1718269240113_1718269063839_image_3.jpeg",
      "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269240113_1718269063839_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "666ab547d4bc7979fdd0036b",
      "name": "externallmg_1718269245371_1718269063839_image_6.jpeg",
      "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269245371_1718269063839_image_6.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "666ab547d4bc7979fdd00369",
      "name": "externallmg_1718269242091_1718269063839_image_4.jpeg",
      "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269242091_1718269063839_image_4.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "666ab547d4bc7979fdd0036c",
    "name": "externallmg_1718269245469_1718269063839_image_7.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269245469_1718269063839_image_7.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "666ab547d4bc7979fdd0036a",
    "name": "externallmg_1718269244075_1718269063839_image_5.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269244075_1718269063839_image_5.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "666ab550d4bc7979fdd00394",
    "name": "Living Room",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269259177_1718269109814_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "666ab547d4bc7979fdd00370",
    "name": "Living Room",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269249580_1718269063840_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "666ab547d4bc7979fdd00374",
    "name": "Living Room",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269254215_1718269063840_image_15.jpeg",
    "orientation": "portrait"
  }
]
```

```
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26230.00",
    "max": "28261.00"
  },
  "builtUpRateRange": {
    "min": "21858.00",
    "max": "23551.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "375.00",
"empanelmentNo": [
  "ROS:ADV:Valuer/033:008:2021-22",
  "RO(S):ADV:VAL:012: 2018-19"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
```

```
"_id": "66697b76f605307b01958fe4",
"ownerName": "Mr. Rajesh B. Shah & Mrs. Rekha R. Shah",
"ownerPhoneNo": "8976179249",
"appAddress": "FLAT no 04 Ground floor G.K Nagar BLDG no 3 Shree Mahavir
Darshan Co-op HSG Soc Ltd Near Malad Shankar Lane Kandivali West Mumbai
400067",
"remark": "Contact person Nimit Shah ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "30/10/1998",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Shri. Manilal Amichand Parmar & Shri. Bhogilal Amichand Parmar",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Rajesh B. Shah & Mrs. Rekha R. Shah",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "-"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "176267",
    "path": "cases/66697b76f605307b01958fe4/document_1718188685420_171818854
0582_Rajesh_B_Shah_Flat_no_4_UBI_Goregoan_East_1.pdf",
    "fileName": "document_1718188685420_1718188540582_Rajesh_B_Shah_Flat_no
_4_UBI_Goregoan_East_1.pdf"
  },
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b325",
      "label": "Society NOC Letter "
    },
    "inputs": {
      "documentDate": "10/05/2023"
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "272701",
    "path": "cases/66697b76f605307b01958fe4/
document_1718188848879_1718188703449_Sanjaybhai_report.pdf",
    "fileName": "document_1718188848879_1718188703449_Sanjaybhai_report.pdf"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "02/10/1999",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Rajesh B. Shah & Mrs. Rekha R. Shah",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "04"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1718338394266_75608.pdf",
    "path": "cases/66697b76f605307b01958fe4/document_1718338394266_75608.pdf",
    "id": "358026",
    "uploadedBy": "627221f4afd7d55eddeddcb4",
    "createdAt": "Fri Jun 14 2024 09:43:14 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009250",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "564227",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 12 2024 16:11:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Mr. Rajesh B. Shah & Mrs. Rekha R. Shah",
  "phone": "8976179249",
  "ownershipShare": "",
  "email": "",
  "id": "462914"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "111196",
    "name": "Living Room",
    "length": "12.17",
    "length1": "12",
    "length2": "2",
    "width": "10.42",
    "width1": "10",
    "width2": "5",
    "totalArea": "126.74",
    "images": [],
    "extraAreas": [],
    "finalArea": "126.74"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "6.67",
    "length1": "6",
    "length2": "8",
    "width": "7.42",
    "width1": "7",
    "width2": "5",
    "totalArea": "49.44",
    "images": [],
    "extraAreas": [],
    "finalArea": "49.44"
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
  "width": "12.33",
  "width1": "12",
  "width2": "4",
  "totalArea": "87.36",
  "images": [],
  "extraAreas": [],
  "finalArea": "87.36"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "27.43",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.43"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
  },

```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "34.84",
"totalAreaDocument": "375.00",
"docBuiltpPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "804259"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "610.00",
    "squareMeterArea": "56.67",
    "expectedRate": "26229.51",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "732.00",
    "squareMeterArea": "68.01",
    "expectedRate": "21857.92",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "666a87ffd607d979c003e03f",
  "property": "2 BHK Flat In New Padmavati Krupa Chsl, Kandivali (West), Mumbai",
  "area": "610.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": ""
}
```

```
"source": "https://www.99acres.com/",
"expectedPrice": "16000000.00",
"expectedRate": "26229.51",
"builtUpExpectedRate": "21857.92",
"image": "cases/66697b76f605307b01958fe4/
indicator_1718255599655_Image.png",
"squareMeter": "56.67",
"id": "318193"
},
{
"carpetArea": {
"area": "485.00",
"squareMeterArea": "45.06",
"expectedRate": "26804.12",
"percentage": ""
},
"builtUpArea": {
"area": "582.00",
"squareMeterArea": "54.07",
"expectedRate": "22336.77",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "666a87ffd607d979c003e040",
"property": "Maunishree Chs, For Sale In Malad West",
"area": "485.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "13000000.00",
"expectedRate": "26804.12",
"builtUpExpectedRate": "22336.77",
"image": "cases/66697b76f605307b01958fe4/
indicator_1718255758945_Image.png",
"squareMeter": "45.06",
"id": "733842"
},
```

```
{
  "carpetArea": {
    "area": "685.00",
    "squareMeterArea": "63.64",
    "expectedRate": "26715.33",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "822.00",
    "squareMeterArea": "76.37",
    "expectedRate": "22262.77",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "666a87ffd607d979c003e041",
  "property": "2 BHK Flat In Kanakia Sky High For Sale In Kandivali West",
  "area": "685.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "18300000.00",
  "expectedRate": "26715.33",
  "builtUpExpectedRate": "22262.77",
  "image": "cases/66697b76f605307b01958fe4/
indicator_1718255862266_Image.png",
  "squareMeter": "63.64",
  "id": "153846"
},
{
  "carpetArea": {
    "area": "460.00",
    "squareMeterArea": "42.74",
    "expectedRate": "28260.87",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "552.00",
```



```
    "squareMeterArea": "51.28",
    "expectedRate": "23550.72",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "666a87ffd607d979c003e042",
  "property": "Royal Sapphire Kandivali West ",
  "area": "460.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "13000000.00",
  "expectedRate": "28260.87",
  "builtUpExpectedRate": "23550.72",
  "image": "cases/66697b76f605307b01958fe4/
indicator_1718256983386_Image.png",
  "squareMeter": "42.74",
  "id": "652690"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666ab550d4bc7979fdd00394",
    "name": "externalImg_1718269259177_1718269109814_image_0.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externalImg_1718269259177_1718269109814_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666ab550d4bc7979fdd00395",
    "name": "externalImg_1718269261677_1718269109814_image_1.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externalImg_1718269261677_1718269109814_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00365",
  "name": "externallmg_1718269236946_1718269063837_image_0.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269236946_1718269063837_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00366",
  "name": "externallmg_1718269237766_1718269063839_image_1.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269237766_1718269063839_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00367",
  "name": "externallmg_1718269238369_1718269063839_image_2.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269238369_1718269063839_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00368",
  "name": "externallmg_1718269240113_1718269063839_image_3.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269240113_1718269063839_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00369",
  "name": "externallmg_1718269242091_1718269063839_image_4.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269242091_1718269063839_image_4.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "666ab547d4bc7979fdd0036a",
    "name": "externallmg_1718269244075_1718269063839_image_5.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269244075_1718269063839_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "666ab547d4bc7979fdd0036b",
    "name": "externallmg_1718269245371_1718269063839_image_6.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269245371_1718269063839_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "666ab547d4bc7979fdd0036c",
    "name": "externallmg_1718269245469_1718269063839_image_7.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269245469_1718269063839_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "666ab547d4bc7979fdd0036d",
    "name": "externallmg_1718269246496_1718269063840_image_8.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269246496_1718269063840_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "666ab547d4bc7979fdd0036e",
    "name": "externallmg_1718269247667_1718269063840_image_9.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269247667_1718269063840_image_9.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd0036f",
  "name": "externallmg_1718269249301_1718269063840_image_10.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269249301_1718269063840_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00370",
  "name": "externallmg_1718269249580_1718269063840_image_11.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269249580_1718269063840_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00371",
  "name": "externallmg_1718269250127_1718269063840_image_12.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269250127_1718269063840_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00372",
  "name": "externallmg_1718269252253_1718269063840_image_13.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269252253_1718269063840_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "666ab547d4bc7979fdd00373",
  "name": "externallmg_1718269253167_1718269063840_image_14.jpeg",
  "path": "cases/66697b76f605307b01958fe4/
externallmg_1718269253167_1718269063840_image_14.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "666ab547d4bc7979fdd00374",
    "name": "externalImg_1718269254215_1718269063840_image_15.jpeg",
    "path": "cases/66697b76f605307b01958fe4/
externalImg_1718269254215_1718269063840_image_15.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalName": "9250.xlsx",
    "filename": "1718339401775_9250.xlsx",
    "path": "cases/66697b76f605307b01958fe4/
processingDocuments/1718339401775_9250.xlsx",
    "size": "9560",
    "createdAt": "Fri Jun 14 2024 10:00:01 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-12T10:41:58.300Z",
"updatedAt": "2024-06-14T05:24:46.713Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 4, Ground Floor, Building No 3, Shree Mahavir
Darshan (G. K -3) Co-op. Hsg. Soc. Ltd., G. K. Nagar, Near Malad Shankar Lane,
Village - Valanai, Kandivali (West), Mumbai, Taluka - Borivali, District - Mumbai
Suburban District, PIN Code - 400 067, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Devanank Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
```

```
"siteVisitContactNo": "8976179249",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 375.00",
"flatRate": "23700",
"landOtherRate": "20900",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet",
"carpetTotal": "290.97",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "349.16",
"finalCarpetArea": "290.97",
"finalSalableArea": "384.08",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"reportGeneratedDate": "Fri Jun 14 2024 09:31:20 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-06-13",
```

"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	12'2"	10'5"	126.74
Kitchen	6'8"	7'5"	49.44
Bedroom	7'1"	12'4"	87.36
Toilet	4'2"	6'7"	27.43
Other Composition :			