

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "firstName": "Rajesh",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmecbhy@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10025000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 5012.5,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
```

```
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.290312149994698",
  "longitude": "72.87598133178794"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.87598133178794,
19.290312149994698
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "12/06/2024 06:09 pm"
    },
    {
      "dateTime": "12/06/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-13",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
```

```
"status": true,
"name": "Village",
"key": "village",
"value": "Navghar",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "26",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mira Road (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
```

```
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Walchand Paradise",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
```



```
"name": "Wing",
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "442",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "115, Hissa No. 1, 2, 3, 4, 5/B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
}
```

```
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
```

```
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 107",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Subhashish Apartment / Internal Road",
  "west": "NG Diamond Hill",
  "south": "Shree Pancham Building",
  "east": "Building No. 2 / Open Space"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"isDisplay": false,
```

```
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living / Dining + Kitchen + 2 Bedrooms + 2 Toilets + Passage (i.e. 2 BHK with 2 Toilets)",
"dateOfIssusApprovePlan": " Copy of Approved Building Plan No. MB / MNP / NR / 1519/ 2022-2023 dated 19.07.2022 issued by Mira - Bhayandar Municipal Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As building is under construction, Internal visit not allowed at site. The details about the work progress status has been provided by Sales Person Mr. Harshad (Contact No. 8850294375)",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "98300",
  "landRate": "29950",
  "igrImage": "cases/6669927ed4bc7979fdcfa67d/igr_1718355072313_Image.png",
  "squareMeterGuideLineRate": "113045.00",
  "squareFeetGuideLineRate": "10502.00"
```

```
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
  "rate": "98300.00",
  "squareMeterGuideLineRate": "113045.00",
  "squareFeetGuideLineRate": "10502.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "External visit only"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
```

```
"value": "Proposed_6" _Thk._Brick_Masonry",
"label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"carParking": "Proposed Covered Parking Space",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2024",
"fullDate": "1/1/2024"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
```

```
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenancelssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"groundStilt": {
  "value": "stilt",
```



```
"label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "27",
"flatFloorNo": "26",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
  "area": "710.60",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6669927ed4bc7979fdcfa67d/
routeMap_1718348620038_Image.png",
    "routeLat": "19.290989",
    "routeLng": "72.876730",
    "stationName": "Mira Road",
    "routeDistance": "2.8 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,

```

```
"finalatlng": true
},
"locationMapImg": [
  {
    "id": "2oi2c",
    "name": "2oi2c",
    "image": "cases/6669927ed4bc7979fdcfa67d/
routeMap_1718348518153_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "10659000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "10659000.00"
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "29",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "29",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "29",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "29",
    "percentage": "3.50",
```

```
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "29",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "29",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
>window": {
  "label": "Window",
  "floorsCompleted": "29",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "29",
  "percentage": "10.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "86.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "7462721.00",
"selectedBuildUpValue": "710.60",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "666ac767fad8e879fe3e5574",
"name":
"externalimg_1718273895585_WhatsApp_Image_20240613_at_142438_1.jpeg",
```

```
    "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895585_WhatsApp_Image_20240613_at_142438_1.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "666ac767fad8e879fe3e556f",
    "name":
"externallmg_1718273895563_WhatsApp_Image_20240613_at_142434_1.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895563_WhatsApp_Image_20240613_at_142434_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "666ac767fad8e879fe3e5571",
    "name":
"externallmg_1718273895570_WhatsApp_Image_20240613_at_142434.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895570_WhatsApp_Image_20240613_at_142434.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "666ac767fad8e879fe3e5578",
    "name":
"externallmg_1718273895600_WhatsApp_Image_20240613_at_142439.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895600_WhatsApp_Image_20240613_at_142439.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16259.00",
    "max": "18572.00"
  },
  "builtUpRateRange": {
```

```
"min": "14781.00",
"max": "16884.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "646.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3",
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "6669927ed4bc7979fdcfa67d",
"ownerName": "Mr. Kailash Solanki",
"ownerPhoneNo": "8286436371",
"appAddress": "FLAT NO 2601 26TH FLOOR WALCHAND PARADISE BLDG NO 1
NAVGHAR VILLAGE MIRA ROAD EAST THANE 401107",
"remark": "ANY QUERY CALL AWNISH SINGH 8005342180",
"documents": [
  {
    "documentType": {
```

```
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "17/11/2023",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "Pramanik Housing Private Limited",
    "to": {
      "value": "Allottee",
      "label": "Allottee"
    },
    "Allottee": "Mr. Kailash Solanki & Mr. Dr. Prerit Kailash Solanki",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "21184/2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1718350187798_Sale_Deed__2023.pdf",
  "path": "cases/6669927ed4bc7979fdcfa67d/
document_1718350187798_Sale_Deed__2023.pdf",
  "id": "280715",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Fri Jun 14 2024 12:59:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "14/03/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700033946"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1718350254497_P51700033946.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/
document_1718350254497_P51700033946.pdf",
    "id": "432519",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Fri Jun 14 2024 13:00:54 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "19/07/2022",
      "nameOfApprovingAuthority": {
        "value": "Mira_Bhayander_Municipal_Corporation",
        "label": "Mira Bhayander Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "MNP / NR / 1519/ 2022-2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1718350662696_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/document_1718350662696_2_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
    "id": "229913",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Fri Jun 14 2024 13:07:42 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "19/07/2022",
      "nameOfApprovingAuthority": {
        "value": "Mira_Bhayander_Municipal_Corporation",
```

```
    "label": "Mira Bhayander Municipal Corporation"
  },
  "remark": "(Downloaded from RERA Site)",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "M.B. / MNP / NR / 1519/ 2022-2023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1718351506499_8_Building_Plan_Approval__NA_Order_f
or_plotted_development.pdf",
"path": "cases/6669927ed4bc7979fdcfa67d/document_1718351506499_8_Building_
Plan_Approval__NA_Order_for_plotted_development.pdf",
"id": "919180",
"uploadedBy": "60f91b6f344e052188ffd1fc",
"createdAt": "Fri Jun 14 2024 13:21:46 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009252",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "395738",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 12 2024 17:50:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Kailash Solanki",
    "phone": "8286436371",
    "ownershipShare": "",
    "email": "",
    "id": "344556"
  },
  {
    "name": "Mr. Dr. Prerit Kailash Solanki",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "220883"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "606493",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "646",
    "squareMeterArea": "60.01",
    "docFinalBuiltUp": "710.6",
    "docFinalBuiltUpSquareMeter": "66.011",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "490.00",
      "squareMeterArea": "45.52",
      "expectedRate": "18571.43",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "539.00",
      "squareMeterArea": "50.07",
      "expectedRate": "16883.12",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
```

```
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "666c04b524f3ba1343e417f0",
  "property": "Residential Flat",
  "area": "490",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "9100000",
  "expectedRate": "18571.43",
  "builtUpExpectedRate": "16883.12",
  "image": "cases/6669927ed4bc7979fdcfa67d/
indicator_1718354655526_Image.png",
  "squareMeter": "45.52",
  "id": "829406"
},
{
  "carpetArea": {
    "area": "663.00",
    "squareMeterArea": "61.59",
    "expectedRate": "17647.06",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "729.30",
    "squareMeterArea": "67.75",
    "expectedRate": "16042.78",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "666c04b524f3ba1343e417f1",
  "property": "Residential Flat",
  "area": "663",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "11700000",
"expectedRate": "17647.06",
"builtUpExpectedRate": "16042.78",
"image": "cases/6669927ed4bc7979fdcfa67d/
indicator_1718354697122_Image.png",
"squareMeter": "61.59",
"id": "271806"
},
{
  "carpetArea": {
    "area": "646.00",
    "squareMeterArea": "60.02",
    "expectedRate": "16258.51",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "710.60",
    "squareMeterArea": "66.02",
    "expectedRate": "14780.47",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "666c04b524f3ba1343e417f2",
  "property": "Residential Flat",
  "area": "646",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "10503000",
  "expectedRate": "16258.51",
  "builtUpExpectedRate": "14780.47",
  "image": "cases/6669927ed4bc7979fdcfa67d/
indicator_1718354764970_Image.png",
  "squareMeter": "60.02",
```

```
    "id": "321070"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666ac767fad8e879fe3e556f",
    "name":
"externalImg_1718273895563_WhatsApp_Image_20240613_at_142434_1.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externalImg_1718273895563_WhatsApp_Image_20240613_at_142434_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666ac767fad8e879fe3e5570",
    "name":
"externalImg_1718273895566_WhatsApp_Image_20240613_at_142434_2.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externalImg_1718273895566_WhatsApp_Image_20240613_at_142434_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666ac767fad8e879fe3e5571",
    "name":
"externalImg_1718273895570_WhatsApp_Image_20240613_at_142434.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externalImg_1718273895570_WhatsApp_Image_20240613_at_142434.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "666ac767fad8e879fe3e5572",
    "name":
"externalImg_1718273895573_WhatsApp_Image_20240613_at_142435.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
externalImg_1718273895573_WhatsApp_Image_20240613_at_142435.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "666ac767fad8e879fe3e5573",
  "name":
"externallmg_1718273895579_WhatsApp_Image_20240613_at_142437.jpeg",
  "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895579_WhatsApp_Image_20240613_at_142437.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666ac767fad8e879fe3e5574",
  "name":
"externallmg_1718273895585_WhatsApp_Image_20240613_at_142438_1.jpeg",
  "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895585_WhatsApp_Image_20240613_at_142438_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666ac767fad8e879fe3e5575",
  "name":
"externallmg_1718273895591_WhatsApp_Image_20240613_at_142438_2.jpeg",
  "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895591_WhatsApp_Image_20240613_at_142438_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666ac767fad8e879fe3e5576",
  "name":
"externallmg_1718273895594_WhatsApp_Image_20240613_at_142438.jpeg",
  "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895594_WhatsApp_Image_20240613_at_142438.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666ac767fad8e879fe3e5577",
  "name":
"externallmg_1718273895598_WhatsApp_Image_20240613_at_142439_1.jpeg",
  "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895598_WhatsApp_Image_20240613_at_142439_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "666ac767fad8e879fe3e5578",
  "name":
"externallmg_1718273895600_WhatsApp_Image_20240613_at_142439.jpeg",
  "path": "cases/6669927ed4bc7979fdcfa67d/
externallmg_1718273895600_WhatsApp_Image_20240613_at_142439.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1718355124174_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6669927ed4bc7979fdcfa67d/
processingDocuments/1718355124174_Calculation_Sheet_NEW.xlsx",
    "size": "25854",
    "createdAt": "Fri Jun 14 2024 14:22:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "2 Commencement Certificates _ NA Order for plotted
development.pdf",
    "filename": "1718356807350_2_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/processingDocuments/1718356807350_
2_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
    "size": "680001",
    "createdAt": "Fri Jun 14 2024 14:50:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "8 Building Plan Approval _ NA Order for plotted development.pdf",
    "filename": "1718356807373_8_Building_Plan_Approval__NA_Order_for_plotted_
development.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/processingDocuments/1718356807373_
8_Building_Plan_Approval__NA_Order_for_plotted_development.pdf",
    "size": "1815430",
    "createdAt": "Fri Jun 14 2024 14:50:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {

```

```
    "originalname": "Google Location.jpeg",
    "filename": "1718356807407_Google_Location.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
processingDocuments/1718356807407_Google_Location.jpeg",
    "size": "160745",
    "createdAt": "Fri Jun 14 2024 14:50:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2023.pdf",
    "filename": "1718356807410_Sale_Deed__2023.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/
processingDocuments/1718356807410_Sale_Deed__2023.pdf",
    "size": "4885989",
    "createdAt": "Fri Jun 14 2024 14:50:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1718356807543_Site_Details.jpeg",
    "path": "cases/6669927ed4bc7979fdcfa67d/
processingDocuments/1718356807543_Site_Details.jpeg",
    "size": "151226",
    "createdAt": "Fri Jun 14 2024 14:50:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "P51700033946.pdf",
    "filename": "1718356816611_P51700033946.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/
processingDocuments/1718356816611_P51700033946.pdf",
    "size": "152718",
    "createdAt": "Fri Jun 14 2024 14:50:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "WALCHAND PARADISE.pdf",
    "filename": "1718356816616_WALCHAND_PARADISE.pdf",
    "path": "cases/6669927ed4bc7979fdcfa67d/
processingDocuments/1718356816616_WALCHAND_PARADISE.pdf",
    "size": "1578094",
    "createdAt": "Fri Jun 14 2024 14:50:16 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "666bea1824f3ba1343e3f4c4",
    "note": "Value Given For The Confirmation",
    "taskId": "66699796d607d979c003a7c4",
    "createdAt": "2024-06-14T06:58:32.901Z"
  }
],
"createdAt": "2024-06-12T12:20:14.381Z",
"updatedAt": "2024-06-14T09:54:26.395Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2601, 26th Floor, Building No 1, Walchand
Paradise, Village - Navghar, Taluka - Thane, District - Thane, Mira Road (East), PIN -
401 107, State - Maharashtra, India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Harshad",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8850294375",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
```

```

"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 646.00",
"buildingServicesRate": "14000",
"flatRate": "16500",
"landOtherRate": "2500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Fri Jun 14 2024 14:36:57 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-06-13",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---