

Architecture and Interior Design 1st Floor, Dwarka, 57, Tagore Road. Santacruz (W), Mumbai 400 054 O - +9122 26482236 / 37 | M - +919820143289

Annexure A FORM-1 [see Regulation 3] ARCHITECT'S CERTIFICATE

Date: 24.04.2024

To,
M/s. Om Shanti Housing Development Company
Peninsula Business Park, B wing, 13th Floor,
Opp Peninsula Corporate Park,
Senapati Bapat Marg, Lower Parel (West),
Mumbai – 400013.

Subject: Certificate of Percentage of Completion of Construction Work of <u>Polestar</u> having MahaRERA Registration Number <u>P5190051220</u> being developed by Om Shanti Housing Development Company.

Sir,

I, Amey Dahanukar, have been assigned as Architect / Licensed Surveyor of certifying percentage of Completion of Construction Work of <u>Polestar</u> having Maharera Registration Number <u>P5190051220</u> being developed by Om Shanti Housing Development Company.

Based on Site Inspection, with respect to Layout / each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/wing of the Real Estate Project under Maharera is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE-A

Layout / Building / Wing Number 1

Tasks /Activity	Percentage of work done
Excavation	100%
Basement (if any)	90%
Podiums (if any)	<u>0%</u>
	80%
	Excavation Basement (if any)



Architecture and Interior Design 1st Floor, Dwarka, 57, Tagore Road. Santacruz (W), Mumbai 400 054 O - +9122 26482236 / 37 | M - +919820143289

5	Stilt Floor	0%
6	Slabs of Super Street	070
U	Slabs of Super Structure	0%
7	Internal walls, Internal Plaster, Floorings, Doors, and window within Flats/Premises	0%
8	Sanitary Fittings within the Flat/Premises	0%
9	Staircases, Lifts Wells and Lobbies at each Floor level Overhead and Underground Water Tanks	0%
10	External plumbing and external plaster, elevation, completion of terraces with waterproofing of Building / Wing.	0%
11	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings, mechanical equipment, Compliance to conditions of environment /CRZ NOC, finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to complete as per specifications in agreement of sale. Any other activities.	0%

TABLE-B Common Areas (Internal and External Development Works) in respect of the entire Registered Phase / Project Number

Sr.No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths.	NO	NA	
2	Water Supply	YES	0%	
3	Sewerage (chamber, lines, Septic Tank ,STP)	YES	0%	
4	Storm Water Drains	NO	NA	



Architecture and Interior Design 1st Floor, Dwarka, 57, Tagore Road. Santacruz (W), Mumbai 400 054 O - +9122 26482236 / 37 | M - +919820143289

5	Landscaping& Tree Planting	NO	NA	
6	Street Lighting	NO	NA	
7	Community Buildings	NO	NA	
8	Treatment and disposal of sewage and sullage water	NO	NA	
9	Solid Waste management & Disposal	YES	100%	
10	Water conservation, Rain water harvesting.	NO	NA	
11	Energy management	NO	NA	
12	Fire protection and fire safety requirements	YES	0%	1,54
13	Electrical meter room, sub-station, receiving station	YES	0%	
14	Others (Option to Add more)	NO	NA	

Yours Faithfully

Signature & Name of L.S/Architect

(License No. CA/2011/52941)

MR. AMEY DAHANUKAR

Agreed and accepted by

M/s. OM SHANTI HOUSING DEVELOPMENT CO

PARTNER