

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ddb566ccaf1e7b7f6501e2"
    },
    "firstName": "Jyotishmita",
    "type": "CREDITOFFICER",
    "_id": "66713243772310133b210fdb",
    "email": "jyotishmita.c@eximbankindia.in",
    "lastName": "Chanda",
    "mobileNo": "022861575",
    "workMobileNo": "7506177556"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "64ddae96ccaf1e7b7f64ee29",
  "type": "BANK",
  "name": "India EXIM Bank (IEB)",
  "displayName": "India EXIM Bank",
  "initial": "EXIM"
},
"branch": {
  "_id": "64ddb566ccaf1e7b7f6501e2",
  "name": "Administration Group",
  "branchCode": "",
  "mobileNo": "+91 22-2217 2891",
  "alternateMobileNo": "",
  "email": "vineet.s@eximbankindia.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Administration Group \n\nCentre One Building, Floor 21, World Trade
Centre Complex,\nCuffe Parade, Mumbai 400 005."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "64ddb4beccaf1e7b7f64fde0",
  "zoneName": "Mumbai"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
```

```
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62720b21afd7d55eddedc545",
"role": "MAKER+CHECKER",
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "62720b21afd7d55eddedc545",
"role": "MAKER+CHECKER",
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62720b21afd7d55eddedc545",
"role": "MAKER+CHECKER",
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"checker": {
"type": "EMPLOYEE",
```

```
"_id": "62720b21afd7d55eddedc545",
"role": "MAKER+CHECKER",
"firstName": "Avinash",
"email": "avinash.pandey@vastukala.org",
"lastName": "Pandey",
"mobileNo": "9021605621",
"designation": "",
"shortName": "AV",
"workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      }
    }
  ]
}
```

```
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "23.118271944509434",
  "longitude": "70.0906647040019"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Varsamedi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Kachchh",
    "label": true
  }
}
```

```
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Anjar",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
```

```
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Welspun City",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "Survey No. 674/P & 890/P",
  "label": true
},
```



```
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
```

```
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 370 110",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  }
}
```

```
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
}
```

```
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```



```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "667134d559d44b137cf533e2",
"ownerName": "M/s. Welspun Home Solutions Ltd.",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. Ground Floor,
Welspun City, New/Current Survey No. Survey No. 674/P & 890/P, Village - Varsamedi,
Taluka - Anjar, District - Kachchh, PIN Code - 370 110, State - Gujarat",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "009345",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
```

```
{
  "id": "107130",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Tue Jun 18 2024 12:48:45 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "M/s. Welspun Home Solutions Ltd.",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "172973"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf5359f",
    "name":
"externallmg_1718695493996_WhatsApp_Image_20240419_at_75051_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695493996_WhatsApp_Image_20240419_at_75051_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a0",
    "name":
"externallmg_1718695494018_WhatsApp_Image_20240419_at_75219_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494018_WhatsApp_Image_20240419_at_75219_PM.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a1",
    "name":
"externallmg_1718695494051_WhatsApp_Image_20240419_at_75405_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494051_WhatsApp_Image_20240419_at_75405_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a2",
    "name":
"externallmg_1718695494081_WhatsApp_Image_20240419_at_75559_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494081_WhatsApp_Image_20240419_at_75559_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a3",
    "name":
"externallmg_1718695494111_WhatsApp_Image_20240419_at_75728_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494111_WhatsApp_Image_20240419_at_75728_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a4",
    "name":
"externallmg_1718695494146_WhatsApp_Image_20240419_at_75932_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494146_WhatsApp_Image_20240419_at_75932_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a5",
    "name":
"externallmg_1718695494179_WhatsApp_Image_20240419_at_80211_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494179_WhatsApp_Image_20240419_at_80211_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a6",
    "name":
"externallmg_1718695494210_WhatsApp_Image_20240419_at_80411_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494210_WhatsApp_Image_20240419_at_80411_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a7",
    "name":
"externallmg_1718695494255_WhatsApp_Image_20240419_at_80533_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494255_WhatsApp_Image_20240419_at_80533_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a8",
    "name":
"externallmg_1718695494298_WhatsApp_Image_20240419_at_80539_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494298_WhatsApp_Image_20240419_at_80539_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535a9",
    "name":
"externallmg_1718695494336_WhatsApp_Image_20240419_at_80542_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494336_WhatsApp_Image_20240419_at_80542_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671364759d44b137cf535aa",
```

```
"name":
"externallmg_1718695494420_WhatsApp_Image_20240419_at_80552_PM.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494420_WhatsApp_Image_20240419_at_80552_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535ab",
  "name":
"externallmg_1718695494471_WhatsApp_Image_20240419_at_80555_PM.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494471_WhatsApp_Image_20240419_at_80555_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535ac",
  "name":
"externallmg_1718695494507_WhatsApp_Image_20240419_at_80557_PM.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494507_WhatsApp_Image_20240419_at_80557_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535ad",
  "name":
"externallmg_1718695494546_WhatsApp_Image_20240419_at_80559_PM.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494546_WhatsApp_Image_20240419_at_80559_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535ae",
  "name":
"externallmg_1718695494669_WhatsApp_Image_20240419_at_80601_PM_1.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494669_WhatsApp_Image_20240419_at_80601_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535af",
  "name":
"externallmg_1718695494730_WhatsApp_Image_20240419_at_80603_PM_1.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494730_WhatsApp_Image_20240419_at_80603_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535b0",
  "name":
"externallmg_1718695494772_WhatsApp_Image_20240419_at_80604_PM.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494772_WhatsApp_Image_20240419_at_80604_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671364759d44b137cf535b1",
  "name":
"externallmg_1718695494798_WhatsApp_Image_20240419_at_80607_PM_1.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695494798_WhatsApp_Image_20240419_at_80607_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671365a59d44b137cf535f1",
  "name":
"externallmg_1718695513325_WhatsApp_Image_20240419_at_80616_PM.jpeg",
  "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513325_WhatsApp_Image_20240419_at_80616_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6671365a59d44b137cf535f2",
  "name":
"externallmg_1718695513376_WhatsApp_Image_20240419_at_80618_PM_1.jpeg",
```

```
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513376_WhatsApp_Image_20240419_at_80618_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535f3",
    "name":
"externallmg_1718695513413_WhatsApp_Image_20240419_at_80620_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513413_WhatsApp_Image_20240419_at_80620_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535f4",
    "name":
"externallmg_1718695513448_WhatsApp_Image_20240419_at_80621_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513448_WhatsApp_Image_20240419_at_80621_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535f5",
    "name":
"externallmg_1718695513497_WhatsApp_Image_20240419_at_80623_PM_1.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513497_WhatsApp_Image_20240419_at_80623_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535f6",
    "name":
"externallmg_1718695513570_WhatsApp_Image_20240419_at_80623_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513570_WhatsApp_Image_20240419_at_80623_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6671365a59d44b137cf535f7",
    "name":
"externallmg_1718695513683_WhatsApp_Image_20240419_at_80626_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513683_WhatsApp_Image_20240419_at_80626_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535f8",
    "name":
"externallmg_1718695513734_WhatsApp_Image_20240419_at_80627_PM_1.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513734_WhatsApp_Image_20240419_at_80627_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535f9",
    "name":
"externallmg_1718695513776_WhatsApp_Image_20240419_at_80627_PM_2.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513776_WhatsApp_Image_20240419_at_80627_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535fa",
    "name":
"externallmg_1718695513831_WhatsApp_Image_20240419_at_80628_PM_1.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513831_WhatsApp_Image_20240419_at_80628_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535fb",
    "name":
"externallmg_1718695513893_WhatsApp_Image_20240419_at_80631_PM_1.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513893_WhatsApp_Image_20240419_at_80631_PM_1.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535fc",
    "name":
"externallmg_1718695513967_WhatsApp_Image_20240419_at_80632_PM_1.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695513967_WhatsApp_Image_20240419_at_80632_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535fd",
    "name":
"externallmg_1718695514030_WhatsApp_Image_20240419_at_80633_PM_2.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695514030_WhatsApp_Image_20240419_at_80633_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535fe",
    "name":
"externallmg_1718695514126_WhatsApp_Image_20240419_at_80633_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695514126_WhatsApp_Image_20240419_at_80633_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf535ff",
    "name":
"externallmg_1718695514233_WhatsApp_Image_20240419_at_80634_PM_1.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695514233_WhatsApp_Image_20240419_at_80634_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf53600",
```

```

    "name":
    "externallmg_1718695514316_WhatsApp_Image_20240419_at_80634_PM_2.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695514316_WhatsApp_Image_20240419_at_80634_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6671365a59d44b137cf53601",
    "name":
    "externallmg_1718695514402_WhatsApp_Image_20240419_at_80635_PM.jpeg",
    "path": "cases/667134d559d44b137cf533e2/
externallmg_1718695514402_WhatsApp_Image_20240419_at_80635_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-18T07:18:45.473Z",
"updatedAt": "2024-06-18T07:25:14.617Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "M/s. Welspun Home Solutions Ltd.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
