

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a7c4a794dfc26ccf86dc61"
    },
    "firstName": "Umesh Devchand ",
    "type": "CREDITOFFICER",
    "_id": "64a7c4a794dfc26ccf86dc64",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar1@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1180"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a7c4a794dfc26ccf86dc61",
  "name": "Administrative Office Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "Nashik@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, BSNL CTTC, Building no 45-47, D Road MIDC, Satpur
Nashik-422007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
```

```
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1717656808118_image.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1717656808118_image.jpg"
},
"rateVerifier": null,
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
```

```
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.013377921285905",
  "longitude": "73.74352999151574"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ashok Tower",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gangapur Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Navshya Ganpati, Road",
  "label": false
},
"landmark": {
  "status": true,
```

```
"name": "Landmark",
"key": "landmark",
"value": "Near Zudio Shop, Navshya Ganapati Parisar,",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "304",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```



```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422013",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"landAndBuildingDetails": {
```

```
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "6672a176772310133b2195c7",
"ownerName": "Yadnesh Zavar",
"ownerPhoneNo": "8989004999",
"fullAddress": "Residential Cost Vetting No. 304, 3rd Floor, Ashok Tower, Near Zudio
Shop, Navshya Ganapati Parisar,, Gangapur Road, Navshya Ganpati, Road, Taluka -
Nashik, Nashik, 422013",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "009374",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "396424",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 19 2024 14:44:30 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Yadnesh Zavar",
    "phone": "8989004999",
    "ownershipShare": "",
    "email": ""
  }
]
```



```
    "id": "999848"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683f0",
    "name":
"externallmg_1718788657881_WhatsApp_Image_20240611_at_45334_PM.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788657881_WhatsApp_Image_20240611_at_45334_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683f1",
    "name":
"externallmg_1718788657970_WhatsApp_Image_20240611_at_45335_PM.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788657970_WhatsApp_Image_20240611_at_45335_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683f2",
    "name":
"externallmg_1718788658092_WhatsApp_Image_20240611_at_45336_PM_1.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658092_WhatsApp_Image_20240611_at_45336_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683f3",
```

```
"name":
"externallmg_1718788658144_WhatsApp_Image_20240611_at_45336_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658144_WhatsApp_Image_20240611_at_45336_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683f4",
  "name":
"externallmg_1718788658208_WhatsApp_Image_20240611_at_45337_PM_1.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658208_WhatsApp_Image_20240611_at_45337_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683f5",
  "name":
"externallmg_1718788658263_WhatsApp_Image_20240611_at_45337_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658263_WhatsApp_Image_20240611_at_45337_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683f6",
  "name":
"externallmg_1718788658326_WhatsApp_Image_20240611_at_45338_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658326_WhatsApp_Image_20240611_at_45338_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683f7",
  "name":
"externallmg_1718788658404_WhatsApp_Image_20240611_at_45339_PM_1.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658404_WhatsApp_Image_20240611_at_45339_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683f8",
  "name":
"externallmg_1718788658457_WhatsApp_Image_20240611_at_45339_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658457_WhatsApp_Image_20240611_at_45339_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683f9",
  "name":
"externallmg_1718788658510_WhatsApp_Image_20240611_at_45340_PM_1.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658510_WhatsApp_Image_20240611_at_45340_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683fa",
  "name":
"externallmg_1718788658581_WhatsApp_Image_20240611_at_45340_PM_2.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658581_WhatsApp_Image_20240611_at_45340_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683fb",
  "name":
"externallmg_1718788658656_WhatsApp_Image_20240611_at_45340_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658656_WhatsApp_Image_20240611_at_45340_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e683fc",
  "name":
"externallmg_1718788658721_WhatsApp_Image_20240611_at_45341_PM.jpeg",
```

```
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658721_WhatsApp_Image_20240611_at_45341_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683fd",
    "name":
"externallmg_1718788658773_WhatsApp_Image_20240611_at_45342_PM_1.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658773_WhatsApp_Image_20240611_at_45342_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683fe",
    "name":
"externallmg_1718788658831_WhatsApp_Image_20240611_at_45342_PM_2.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658831_WhatsApp_Image_20240611_at_45342_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e683ff",
    "name":
"externallmg_1718788658900_WhatsApp_Image_20240611_at_45342_PM.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658900_WhatsApp_Image_20240611_at_45342_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23324f3ba1343e68400",
    "name":
"externallmg_1718788658977_WhatsApp_Image_20240611_at_45343_PM.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788658977_WhatsApp_Image_20240611_at_45343_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6672a23324f3ba1343e68401",
  "name":
"externallmg_1718788659033_WhatsApp_Image_20240611_at_45344_PM_1.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788659033_WhatsApp_Image_20240611_at_45344_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e68402",
  "name":
"externallmg_1718788659113_WhatsApp_Image_20240611_at_45344_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788659113_WhatsApp_Image_20240611_at_45344_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23324f3ba1343e68403",
  "name":
"externallmg_1718788659151_WhatsApp_Image_20240611_at_45345_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788659151_WhatsApp_Image_20240611_at_45345_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23e59d44b137cf5b569",
  "name":
"externallmg_1718788669261_WhatsApp_Image_20240611_at_45330_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669261_WhatsApp_Image_20240611_at_45330_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6672a23e59d44b137cf5b56a",
  "name":
"externallmg_1718788669402_WhatsApp_Image_20240611_at_45331_PM.jpeg",
  "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669402_WhatsApp_Image_20240611_at_45331_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b56b",
    "name":
"externallmg_1718788669556_WhatsApp_Image_20240611_at_45332_PM_1.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669556_WhatsApp_Image_20240611_at_45332_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b56c",
    "name":
"externallmg_1718788669617_WhatsApp_Image_20240611_at_45332_PM_2.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669617_WhatsApp_Image_20240611_at_45332_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b56d",
    "name":
"externallmg_1718788669711_WhatsApp_Image_20240611_at_45332_PM_3.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669711_WhatsApp_Image_20240611_at_45332_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b56e",
    "name":
"externallmg_1718788669781_WhatsApp_Image_20240611_at_45332_PM.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669781_WhatsApp_Image_20240611_at_45332_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b56f",
```

```
    "name":
"externallmg_1718788669908_WhatsApp_Image_20240611_at_45333_PM_1.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669908_WhatsApp_Image_20240611_at_45333_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b570",
    "name":
"externallmg_1718788669996_WhatsApp_Image_20240611_at_45333_PM.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788669996_WhatsApp_Image_20240611_at_45333_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b571",
    "name":
"externallmg_1718788670062_WhatsApp_Image_20240611_at_45334_PM_1.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788670062_WhatsApp_Image_20240611_at_45334_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6672a23e59d44b137cf5b572",
    "name":
"externallmg_1718788670112_WhatsApp_Image_20240611_at_45334_PM_2.jpeg",
    "path": "cases/6672a176772310133b2195c7/
externallmg_1718788670112_WhatsApp_Image_20240611_at_45334_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-19T09:14:30.612Z",
"updatedAt": "2024-06-19T09:17:50.604Z",
"__v": 0,
"updatedBy": "63f9f4adce84bf289ba9956e",
```

```
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Yadnesh Zawar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8989004999"
```

}

Name	Length	Width	Total
Composition :			
Other Composition :			