

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Manish",
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "45000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "65dee3f79a876858ab30487f",
  "role": "SITEENGINEER",
  "firstName": "Saiprasad",
  "email": "saiprasadpatil1010@gmail.com",
```

```
"lastName": "Patil",
"mobileNo": "8830049996",
"designation": "Valuation Engineer",
"shortName": "SSP",
"workWithDocumentMaker": "60f91822f3dd69653a5922e3",
"profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "AM161706-3",
"label": "Chartered Engineer"
},
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.27167971469339",
  "longitude": "73.04986110000429"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamatghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Dev Drashti Empire Phase 1",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A & B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Dev Drashti Empire Phase 1",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "107/2, 107/2/A, 108/5, 108/6/1, 108/6/2, 177/7/B & 177/7/C",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421302",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
```

```
"coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"invoices": [],
```

```
"paymentIds": [],
"_id": "6673cabb772310133b21ed52",
"ownerName": "M/s. Shri Hari Realty",
"ownerPhoneNo": "9320041286",
"fullAddress": "Residential Project Finance No. Basement Floor, Wing - A & B, Dev
Drashti Empire Phase 1, Dev Drashti Empire Phase 1, New/Current Survey No. 107/2,
107/2/A, 108/5, 108/6/1, 108/6/2, 177/7/B & 177/7/C, Village - Kamatghar, Taluka -
Bhiwandi, District - Thane, 421302, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "08/09/2021",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    },
    "Document_No": "P51700020837"
  },
  {
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1718864563447_RERA_CERTIFICATE_SHR_300424.pdf",
    "path": "cases/6673cabb772310133b21ed52/
document_1718864563447_RERA_CERTIFICATE_SHR_300424.pdf",
    "id": "786708",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Thu Jun 20 2024 11:52:51 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "009396",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "335229",
```

```
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 20 2024 11:52:51 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Shri Hari Realty",
    "phone": "9320041286",
    "ownershipShare": "",
    "email": "",
    "id": "602819"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60dfa",
    "name": "externalImg_1718865455011_IMG20240605WA0117.jpg",
    "path": "cases/6673cabb772310133b21ed52/externalImg_1718865455011_IMG20240605WA0117.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60dfb",
    "name": "externalImg_1718865455018_IMG20240605WA0118.jpg",
    "path": "cases/6673cabb772310133b21ed52/externalImg_1718865455018_IMG20240605WA0118.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60dfc",
    "name": "externalImg_1718865455023_IMG20240605WA0119.jpg",
```

```
    "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455023_IMG20240605WA0119.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60dfd",
    "name": "externallmg_1718865455027_IMG20240605WA0120.jpg",
    "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455027_IMG20240605WA0120.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60dfe",
    "name": "externallmg_1718865455031_IMG20240605WA0121.jpg",
    "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455031_IMG20240605WA0121.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60dff",
    "name": "externallmg_1718865455035_IMG20240605WA0122.jpg",
    "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455035_IMG20240605WA0122.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60e00",
    "name": "externallmg_1718865455039_IMG20240605WA0123.jpg",
    "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455039_IMG20240605WA0123.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6673ce2f59d44b137cf60e01",
    "name": "externallmg_1718865455042_IMG20240605WA0124.jpg",
    "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455042_IMG20240605WA0124.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e02",
  "name": "externallmg_1718865455046_IMG20240605WA0125.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455046_IMG20240605WA0125.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e03",
  "name": "externallmg_1718865455049_IMG20240605WA0126.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455049_IMG20240605WA0126.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e04",
  "name": "externallmg_1718865455053_IMG20240605WA0127.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455053_IMG20240605WA0127.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e05",
  "name": "externallmg_1718865455056_IMG20240605WA0128.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455056_IMG20240605WA0128.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e06",
  "name": "externallmg_1718865455059_IMG20240605WA0129.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455059_IMG20240605WA0129.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e07",
  "name": "externallmg_1718865455063_IMG20240605WA0130.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455063_IMG20240605WA0130.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e08",
  "name": "externallmg_1718865455066_IMG20240605WA0131.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455066_IMG20240605WA0131.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e09",
  "name": "externallmg_1718865455069_IMG20240605WA0132.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455069_IMG20240605WA0132.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e0a",
  "name": "externallmg_1718865455082_IMG20240605WA0133.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455082_IMG20240605WA0133.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e0b",
  "name": "externallmg_1718865455085_IMG20240605WA0134.jpg",
  "path": "cases/6673cabb772310133b21ed52/
externallmg_1718865455085_IMG20240605WA0134.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e0c",
  "name": "externallmg_1718865455087_WhatsApp_Image_20240605_at_102719_dca54729.jpg",
  "path": "cases/6673cabb772310133b21ed52/externallmg_1718865455087_WhatsApp_Image_20240605_at_102719_dca54729.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6673ce2f59d44b137cf60e0d",
  "name": "externallmg_r_1718865455091_WhatsApp_Image_20240605_at_102910_a15f6804.jpg",
  "path": "cases/6673cabb772310133b21ed52/externallmg_r_1718865455091_WhatsApp_Image_20240605_at_102910_a15f6804.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "ARCH CERT - SHR B WING 95%.pdf",
    "filename": "1718865300538_ARCH_CERT__SHR_B_WING_95.pdf",
    "path": "cases/6673cabb772310133b21ed52/processingDocuments/1718865300538_ARCH_CERT__SHR_B_WING_95.pdf",
    "size": "302236",
    "createdAt": "Thu Jun 20 2024 12:05:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "ARCH CERT SHR A WING 98%.pdf",
    "filename": "1718865300562_ARCH_CERT_SHR__A_WING__98.pdf",
    "path": "cases/6673cabb772310133b21ed52/processingDocuments/1718865300562_ARCH_CERT_SHR__A_WING__98.pdf",
    "size": "276711",
    "createdAt": "Thu Jun 20 2024 12:05:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "SHR - Partnership Deed -1 (01.04.2008).pdf",
    "filename": "1718865311753_SHR__Partnership_Deed_1_01042008.pdf",
    "path": "cases/6673cabb772310133b21ed52/processingDocuments/1718865311753_SHR__Partnership_Deed_1_01042008.pdf",
```

```
"size": "3504695",
"createdAt": "Thu Jun 20 2024 12:05:14 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "SHR - Partnership Deed -2 (25.06.2013).pdf",
"filename": "1718865312040_SHR__Partnership_Deed_2_25062013.pdf",
"path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865312040_SHR__Partnership_Deed_2_25062013.pdf",
"size": "4115734",
"createdAt": "Thu Jun 20 2024 12:05:14 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "SHR - Partnership Deed -3 (11.01.2018).pdf",
"filename": "1718865312388_SHR__Partnership_Deed_3_11012018.pdf",
"path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865312388_SHR__Partnership_Deed_3_11012018.pdf",
"size": "4150797",
"createdAt": "Thu Jun 20 2024 12:05:14 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "SHR - Partnership Deed -4 (16.02.2018 ).pdf",
"filename": "1718865312737_SHR__Partnership_Deed_4_16022018_.pdf",
"path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865312737_SHR__Partnership_Deed_4_16022018_.pdf",
"size": "9919225",
"createdAt": "Thu Jun 20 2024 12:05:14 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "SHR - Partnership Deed-5 (22.03.2018).pdf",
"filename": "1718865313574_SHR__Partnership_Deed5_22032018.pdf",
"path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865313574_SHR__Partnership_Deed5_22032018.pdf",
"size": "6323089",
"createdAt": "Thu Jun 20 2024 12:05:14 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "1. SHR 14th Draft LIE Report 27.01.2024 (1).pdf",
"filename": "1718865325438_1_SHR_14th_Draft_LIE_Report_27012024_1.pdf",
"path": "cases/6673cabb772310133b21ed52/processingDocuments/171886532543
8_1_SHR_14th_Draft_LIE_Report_27012024_1.pdf",
"size": "17097496",
```



```
"createdAt": "Thu Jun 20 2024 12:05:27 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "DDE FLOOR PLAN BLUE PRINT 8 Nos.pdf",
"filename": "1718865326880_DDE_FLOOR_PLAN_BLUE_PRINT_8_Nos.pdf",
"path": "cases/6673cabb772310133b21ed52/processingDocuments/171886532688
0_DDE_FLOOR_PLAN_BLUE_PRINT_8_Nos.pdf",
"size": "6836610",
"createdAt": "Thu Jun 20 2024 12:05:27 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "Dev Drashti Empire Updated CC for Phase -1.pdf",
"filename": "1718865327457_Dev_Drashti_Empire_Updated_CC_for_Phase_1.pdf",
"path": "cases/6673cabb772310133b21ed52/processingDocuments/171886532745
7_Dev_Drashti_Empire_Updated_CC_for_Phase_1.pdf",
"size": "1372148",
"createdAt": "Thu Jun 20 2024 12:05:27 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "MOU Chatrapati,Hanuman,Satyavan,Shyam 6810 - 2019.pdf",
"filename":
"1718865347629_MOU_ChatrapatiHanumanSatyavanShyam_6810__2019.pdf",
"path": "cases/6673cabb772310133b21ed52/processingDocuments/171886534762
9_MOU_ChatrapatiHanumanSatyavanShyam_6810__2019.pdf",
"size": "5498452",
"createdAt": "Thu Jun 20 2024 12:05:49 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "MOU Gurudayal 5276-2019.pdf",
"filename": "1718865348091_MOU_Gurudayal_52762019.pdf",
"path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865348091_MOU_Gurudayal_52762019.pdf",
"size": "4614397",
"createdAt": "Thu Jun 20 2024 12:05:49 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
"originalname": "Project Valuation Shri. Hari realty (1).pdf",
"filename": "1718865348481_Project_Valuation_Shri_Hari_realty_1.pdf",
"path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865348481_Project_Valuation_Shri_Hari_realty_1.pdf",
"size": "9184788",
```

```
"createdAt": "Thu Jun 20 2024 12:05:49 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "RERA CERTIFICATE.- SHR 30.04.24.pdf",
  "filename": "1718865349256_RERA_CERTIFICATE_SHR_300424.pdf",
  "path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865349256_RERA_CERTIFICATE_SHR_300424.pdf",
  "size": "144466",
  "createdAt": "Thu Jun 20 2024 12:05:49 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "TITLE REPORT 2022.pdf",
  "filename": "1718865349269_TITLE_REPORT_2022.pdf",
  "path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865349269_TITLE_REPORT_2022.pdf",
  "size": "7581972",
  "createdAt": "Thu Jun 20 2024 12:05:49 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Dev Drashti Empire.xlsx",
  "filename": "1718865358868_Dev_Drashti_Empire.xlsx",
  "path": "cases/6673cabb772310133b21ed52/
processingDocuments/1718865358868_Dev_Drashti_Empire.xlsx",
  "size": "59346",
  "createdAt": "Thu Jun 20 2024 12:05:58 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-20T06:22:51.684Z",
"updatedAt": "2024-06-20T06:37:35.784Z",
"__v": 0,
"updatedBy": "65dee3f79a876858ab30487f",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Shri Hari Realty",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9320041286"

}

| Name | Length | Width | Total |
|---------------|---------------|--------------|--------------|
| <hr/> | | | |
| Composition : | | | |
| <hr/> | | | |
| Other | | | |
| Composition : | | | |
| <hr/> | | | |