

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba37"
    },
    "firstName": "Manoj Kumar",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231035",
    "email": "0_default_manoj.kumar31@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8756399708"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba37",
  "branchCode": "000247",
  "type": "BRANCH",
  "name": "Kanpur Main Branch",
  "email": "Manoj.Kumar31@sbi.co.in",
  "mobileNo": "512-2331895",
  "alternateMobileNo": "",
  "address": "16/101,The Mall ,Mahatma Gandhi Marg , Kanpur,Uttar
Pradesh,Kanpur-208001",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
```

```
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  ]
}
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.20049341321095",
  "longitude": "72.87748893649378"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-06-26",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Akurli",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kandivali (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "4",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lodha Woods, Tower 8",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Akurli Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Off. Western Express Highway",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "Lodha Woods",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "85, 86 (Part) & 87 (Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "174C/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "PIN Code - 400 101",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
},
```

```
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Under Construction Building",
  "west": "Under Construction Building",
  "south": "Under Construction Building",
  "east": "Akurli Road"
},
"asPerDocumentAgreement": {
  "north": "By BRADCO Property, C.T.S. No. 874A & 852B",
  "west": "By Raheja Willows, C.T.S. No. 174B/1",
  "south": "By 18.3 M Wide D. P. Road",
  "east": "By 18.3 M Wide D. P. Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": " Residential Flat",
  "rate": "154860",
  "landRate": "72870",
  "igrImage": "cases/66795a5d4c08775ede7096f1/igr_1719398300396_Image.png",
  "squareMeterGuideLineRate": "154860.00",
  "squareFeetGuideLineRate": "14387.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "154860.00",
  "squareMeterGuideLineRate": "154860.00",
  "squareFeetGuideLineRate": "14387.00"
},
"outgoingDetail": {
  "areaStatusList": {
```

```
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Proposed_Residential_Purpose",
"label": "Proposed Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "Proposed_R.C.C._Slab",
"label": "Proposed R.C.C. Slab"
},
"partitions": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
}
```

```
},
"carParking": "Proposed Along With One Car Parking Space",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_RCC_Slab",
  "label": "Proposed RCC Slab"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
```



```
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "859.10",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/66795a5d4c08775ede7096f1/
routeMap_1719401199139_Image.png",
    "routeLat": "19.200470",
    "routeLng": "72.877454",
    "stationName": "Kandivali",
    "routeDistance": "2.7 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "07cpt",
      "name": "07cpt",
      "image": "cases/66795a5d4c08775ede7096f1/
routeMap_1719401108756_Image.png"
    }
  ]
}
```

```
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "21087000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "21087000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
```

```
"percentage": "5",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "InProgress",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "5.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "12359872.00",
  "selectedBuildUpValue": "859.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "667ba143bc0925575bba9afc",
      "name": "externalImg_1719378243463_IMG20240626WA0029.jpg",
      "path": "cases/66795a5d4c08775ede7096f1/
externalImg_1719378243463_IMG20240626WA0029.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "667ba143bc0925575bba9af9",
```

```
    "name": "externallmg_1719378243440_IMG20240626WA0026.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243440_IMG20240626WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "667ba143bc0925575bba9afb",
    "name": "externallmg_1719378243457_IMG20240626WA0028.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243457_IMG20240626WA0028.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "667ba143bc0925575bba9afe",
    "name": "externallmg_1719378243472_IMG20240626WA0031.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243472_IMG20240626WA0031.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "667ba143bc0925575bba9afc",
    "name": "externallmg_1719378243463_IMG20240626WA0029.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243463_IMG20240626WA0029.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "26059.00",
    "max": "29438.00"
  },
  "builtUpRateRange": {
    "min": "23690.00",
    "max": "26762.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "781.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3",
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "66795a5d4c08775ede7096f1",
"ownerName": "Sachi Mishra & Anuj Mishra",
"ownerPhoneNo": "8655882163",
"fullAddress": "Residential Flat No. 101, 1st Floor, Lodha Woods, Tower 8, Lodha Woods, Off. Western Express Highway, Plot No. 4, Akurli Road, Village - Akurli, Taluka - Borivali, District - Mumbai, Kandivali (East), PIN Code - 400 101, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },
  "inputs": {
```

```
"documentDate": "14/06/2024",
"from": {
  "value": "Company",
  "label": "Company"
},
"Company": "Macrotech Developers Limited",
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Sachi Mishra & Anuj Mishra",
"number": {
  "value": "No",
  "label": "No"
},
"No": "9405/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "201731",
"path": "cases/66795a5d4c08775ede7096f1/
document_1719228964966_2242753_AFS_1.pdf",
"fileName": "document_1719228964966_2242753_AFS_1.pdf"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e5",
    "label": "Allotment Letter"
  },
  "inputs": {
    "documentDate": "12/06/2024",
    "from": {
      "value": "Builders_&_Developers",
      "label": "Builders & Developers"
    },
    "Builders_&_Developers": "Lodha",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Sachi Mishra & Anuj Mishra"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "970175",
  "path": "cases/66795a5d4c08775ede7096f1/
document_1719228977357_Untitled_1.pdf",
```

```
"fileName": "document_1719228977357_Untitled_1.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "24/01/2024",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / A - 4300 / BP (WS) / AR / FCC / 8 / Amend"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1719403175495_3_Commencement_Certificates___NA_Order_for_plotted_development_36.pdf",
  "path": "cases/66795a5d4c08775ede7096f1/document_1719403175495_3_Commencement_Certificates___NA_Order_for_plotted_development_36.pdf",
  "id": "770678",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Jun 26 2024 17:29:35 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "20/06/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800046114"
  },
}
```

```
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1719404334530_167377.pdf",
    "path": "cases/66795a5d4c08775ede7096f1/
document_1719404334530_167377.pdf",
    "id": "470034",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Wed Jun 26 2024 17:48:54 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009485",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "695447",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jun 24 2024 17:07:01 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sachi Mishra & Anuj Mishra",
    "phone": "8655882163",
    "ownershipShare": "",
    "email": "",
    "id": "443086"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "818935",
    "name": "Living Room",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
```

```
"width": "0.00",
"width1": "0",
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Kitchen",
  "length": "",
  "length1": "0",
  "length2": "0",
  "width": "",
  "width1": "0",
  "width2": "0",
  "totalArea": "0.00",
  "images": [],
  "finalArea": "0.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
```

```
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "0.00",
  "length1": "0",
  "length2": "00",
  "width": "0.00",
  "width1": "0",
  "width2": "00",
  "totalArea": "0.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "0.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Utility Area",
      "value": "Utility_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
    "width": "0.00",
    "width1": "0",
    "width2": "00",
```

```
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0",
"percentageBeforeTotal": "0.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "72.56",
  "totalAreaDocument": "781",
  "docBuiltpUpPercentage": "10",
  "docFinalBuiltpUp": "859.10",
  "docFinalBuiltpUpSquareMeter": "79.81",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "170407"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "719.00",
    "squareMeterArea": "66.80",
    "expectedRate": "28094.58",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "790.90",
    "squareMeterArea": "73.48",
    "expectedRate": "25540.52",
    "percentage": "10"
  }
},
]
```



```
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "667befd5968b1257131c9171",
"property": "Residential Flat",
"area": "719",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "20200000",
"expectedRate": "28094.58",
"builtUpExpectedRate": "25540.52",
"image": "cases/66795a5d4c08775ede7096f1/
indicator_1719398018398_Image.png",
"squareMeter": "66.80",
"id": "785152"
},
{
  "carpetArea": {
    "area": "693.00",
    "squareMeterArea": "64.38",
    "expectedRate": "29437.23",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "762.30",
    "squareMeterArea": "70.82",
    "expectedRate": "26761.12",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "667befd5968b1257131c9172",
  "property": " Residential Flat",
```

```
"area": "693",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "20400000",
"expectedRate": "29437.23",
"builtUpExpectedRate": "26761.12",
"image": "cases/66795a5d4c08775ede7096f1/
indicator_1719398047541_Image.png",
"squareMeter": "64.38",
"id": "999884"
},
{
"carpetArea": {
"area": "766.00",
"squareMeterArea": "71.16",
"expectedRate": "26058.59",
"percentage": ""
},
"builtUpArea": {
"area": "842.60",
"squareMeterArea": "78.28",
"expectedRate": "23689.62",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "667befd5968b1257131c9173",
"property": "Residential Flat",
"area": "766",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "19960878",
"expectedRate": "26058.59",
```

```
    "builtUpExpectedRate": "23689.62",
    "image": "cases/66795a5d4c08775ede7096f1/
indicator_1719398150467_Image.png",
    "squareMeter": "71.16",
    "id": "287787"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9af9",
    "name": "externallmg_1719378243440_IMG20240626WA0026.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243440_IMG20240626WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9afa",
    "name": "externallmg_1719378243449_IMG20240626WA0027.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243449_IMG20240626WA0027.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9afb",
    "name": "externallmg_1719378243457_IMG20240626WA0028.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243457_IMG20240626WA0028.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9afc",
    "name": "externallmg_1719378243463_IMG20240626WA0029.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externallmg_1719378243463_IMG20240626WA0029.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "667ba143bc0925575bba9afd",
    "name": "externalImg_1719378243467_IMG20240626WA0030.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externalImg_1719378243467_IMG20240626WA0030.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9afe",
    "name": "externalImg_1719378243472_IMG20240626WA0031.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externalImg_1719378243472_IMG20240626WA0031.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9aff",
    "name": "externalImg_1719378243475_IMG20240626WA0032.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externalImg_1719378243475_IMG20240626WA0032.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667ba143bc0925575bba9b00",
    "name": "externalImg_1719378243478_IMG20240626WA0033.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
externalImg_1719378243478_IMG20240626WA0033.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1719398327801_Calculation_Sheet_NEW.xlsx",
    "path": "cases/66795a5d4c08775ede7096f1/
processingDocuments/1719398327801_Calculation_Sheet_NEW.xlsx",
    "size": "3825735",
    "createdAt": "Wed Jun 26 2024 16:08:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
```

```
{
  "originalname": "1 Building Plan Approval _ NA Order for plotted development
(100).pdf",
  "filename": "1719463379682_1_Building_Plan_Approval___NA_Order_for_plotted_
development_100.pdf",
  "path": "cases/66795a5d4c08775ede7096f1/processingDocuments/1719463379682
_1_Building_Plan_Approval___NA_Order_for_plotted_development_100.pdf",
  "size": "328998",
  "createdAt": "Thu Jun 27 2024 10:13:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "2 Building Plan Approval _ NA Order for plotted development
(48).pdf",
  "filename": "1719463380104_2_Building_Plan_Approval___NA_Order_for_plotted_
development_48.pdf",
  "path": "cases/66795a5d4c08775ede7096f1/processingDocuments/1719463380104
_2_Building_Plan_Approval___NA_Order_for_plotted_development_48.pdf",
  "size": "330936",
  "createdAt": "Thu Jun 27 2024 10:13:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "3 Building Plan Approval _ NA Order for plotted development
(34).pdf",
  "filename": "1719463380530_3_Building_Plan_Approval___NA_Order_for_plotted_
development_34.pdf",
  "path": "cases/66795a5d4c08775ede7096f1/processingDocuments/1719463380530
_3_Building_Plan_Approval___NA_Order_for_plotted_development_34.pdf",
  "size": "167112",
  "createdAt": "Thu Jun 27 2024 10:13:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "3 Commencement Certificates _ NA Order for plotted development
(36).pdf",
  "filename": "1719463380740_3_Commencement_Certificates___NA_Order_for_plot
ted_development_36.pdf",
  "path": "cases/66795a5d4c08775ede7096f1/processingDocuments/1719463380740
_3_Commencement_Certificates___NA_Order_for_plotted_development_36.pdf",
  "size": "167436",
  "createdAt": "Thu Jun 27 2024 10:13:01 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "RERA Certificate.jpg",
```

```
    "filename": "1719463380830_RERA_Certificate.jpg",
    "path": "cases/66795a5d4c08775ede7096f1/
processingDocuments/1719463380830_RERA_Certificate.jpg",
    "size": "167377",
    "createdAt": "Thu Jun 27 2024 10:13:01 GMT+0530 (India Standard Time)",
    "uploadedBy": "627222afafd7d55eddeddd82"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "667bb0aa968b1257131c47ff",
    "note": "Value Given For Confirmation ",
    "taskId": "66795a65d3a6ba5eb25ee7d8",
    "createdAt": "2024-06-26T06:09:46.815Z"
  },
  {
    "createdBy": {
      "_id": "656aa949cebbe1714411d21b",
      "role": "FRONTDESK",
      "firstName": "Priyanka",
      "lastName": "Pawar"
    },
    "workType": "MAKER",
    "display": true,
    "status": true,
    "_id": "667cec08c01ce75768834c6a",
    "note": "Changes in Report (Task Reopen)",
    "taskId": "667ba155968b1257131c31e8",
    "createdAt": "2024-06-27T04:35:20.056Z"
  }
],
"createdAt": "2024-06-24T11:37:01.077Z",
"updatedAt": "2024-06-27T04:43:23.578Z",
```

```
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Shiva Prasad",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Project Manager",
"siteVisitContactNo": "9177755891",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 781.00",
"flatRate": "27000",
"landOtherRate": "24000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet",
"carpetTotal": "0.00",
"otherCarpetTotal": "0.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 692.00\nEBVT Area in Sq. Ft. = 89.00\n",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
```

```

"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Jun 26 2024 16:12:17 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-06-26"
}

```

Name	Length	Width	Total
Composition :			
Living Room	0'00"	0'00"	0.00
Dining	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Bedroom	0'00"	0'00"	0.00
Kitchen	0'0"	0'0"	0.00
Toilet	0'00"	0'00"	0.00
Toilet	0'00"	0'00"	0.00
Other Composition :			
Utility Area	0'00"	0'00"	0.00