

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Shivani ",
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Shivani ",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.114542417906808",
  "longitude": "72.93758299201727"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.93758299201727,
19.114542417906808
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-26",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-06-26",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Hariyali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "58",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Kurla",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "The Rising 58",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kannamwar Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Kannamwar Nagar Prabhat Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "356 (Pt)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1501",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S - ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 083",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vikhroli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Building_Under_Construction",
```

```
    "label": "Building Under Construction"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - A & Building No. 145",
    "west": "Vikarharta Galli",
    "south": "Road No. 2",
    "east": "Building No. 146"
  },
  "asPerDocumentAgreement": {
    "north": "Building No. 145",
    "west": "12.20 Meter Road",
    "south": "17.10 Meter Road",
    "east": "Building No. 146"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
```

```

    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Site Information, the composition of Residential Flat will be 1 Bedroom + Living Room + Kitchen + 2 Toilets.",
"dateOfIssusApprovePlan": "The property is constructed by MHADA & MHADA itself is an issuing authority\nCopy of Commencement Certificate Document No.MH / EE / (BP) / GM / MHADA-9 / 1055 / 2023 / FCC / 1 / New Dated 30.01.2023 issued by Maharashtra Housing And Area Development Authority ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for Internal site inspection, measurement and Internal Photographs of the property. The details about the work progress status has been provided by sales office person - Mr. Ravi Jadhav - Contact No. 9082452140",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
}

```

```
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "139830",
  "landRate": "58970",
  "igrImage": "cases/667ab234968b1257131c092a/igr_1719422938176_Image.png",
  "squareMeterGuideLineRate": "153813.00",
  "squareFeetGuideLineRate": "14290.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "139830.00",
  "squareMeterGuideLineRate": "153813.00",
  "squareFeetGuideLineRate": "14290.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "21,000/- Expected rental income per month after building completion",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA / MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2025",
    "fullDate": "1/1/2025"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
```



```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "15",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "432.30",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
},
"routeMapImg": "cases/667ab234968b1257131c092a/
routeMap_1719459464069_Image.png",
"routeLat": "19.114542",
"routeLng": "72.937583",
"stationName": "Vikhroli",
"routeDistance": "1.5 Km."
},
}
```

```
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "ciuhi",
    "name": "ciuhi",
    "image": "cases/667ab234968b1257131c092a/
routeMap_1719459416269_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8449500.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8449500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jun 27 2024 13:17:07 GMT+0530 (India Standard Time)",
  "number": "2306933",
  "dayCount": "6",
  "monthCount": "377",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "24",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "18",
    "percentage": "5.25",
```

```
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "24",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "24",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "65.75",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "6177567.00",
  "selectedBuildUpValue": "432.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "667be577c01ce757688305b3",
      "name": "externallmg_1719395641887_1719395504777_image_1.jpeg",
      "path": "cases/667ab234968b1257131c092a/externallmg_1719395641887_1719395504777_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "667be577c01ce757688305b5",
      "name": "externallmg_1719395656361_1719395504777_image_3.jpeg",
      "path": "cases/667ab234968b1257131c092a/externallmg_1719395656361_1719395504777_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "667be577c01ce757688305b2",
      "name": "externallmg_1719395638099_1719395504777_image_0.jpeg",
      "path": "cases/667ab234968b1257131c092a/externallmg_1719395638099_1719395504777_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "667be577c01ce757688305b9",
      "name": "externallmg_1719395679437_1719395504777_image_7.jpeg",
      "path": "cases/667ab234968b1257131c092a/externallmg_1719395679437_1719395504777_image_7.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18812.00",
    "max": "22647.00"
  },
  "builtUpRateRange": {
    "min": "17102.00",
    "max": "20588.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```



```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "393.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3",
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"invoices": [],
"paymentIds": [],
"_id": "667ab234968b1257131c092a",
"ownerName": "Mr. Santosh Krishna Kambli & Mrs. Sampada Santosh Kambli",
"ownerPhoneNo": "8108943920",
"appAddress": "Flat no. 1501, 15th Floor, Wing - B, The Rising 58, Building no. 58,
Kannamwar Nagar, Prabhat CHS, Vikroli East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/06/2024",
      "remark": " (5 Pages from documents)",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Ashapura United",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Santosh Krishna Kambli & Mrs. Sampada Santosh Kambli",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "12909/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "583402",
    "path": "cases/667ab234968b1257131c092a/
document_1719316980491_1719316848541_Racpc_GhatkoparSantosh_Kambli.pdf",
    "fileName":
"document_1719316980491_1719316848541_Racpc_GhatkoparSantosh_Kambli.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
  },

```

```

"inputs": {
  "documentDate": "28/04/2022",
  "nameOfApprovingAuthority": {
    "value": "Maharashtra_Real_Estate_Regulatory_Authority",
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51800034950"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1719462735754_P51800034950.pdf",
"path": "cases/667ab234968b1257131c092a/
document_1719462735754_P51800034950.pdf",
"id": "344298",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Jun 27 2024 10:02:16 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "30/01/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "remark": " (The C C is endorsed and further extended upto 19th upper floors {i.e.
for building comprising of Ground (pt.) for\nshops & Stilt (pt.) for meter room, entrance
lobby + 1st to 19thupper floors for residential users with total\nbuilding height60.25 mt.
from AGL as per last approved Amended plans issued by MHADA on dated-
12.12.2022\nvide u/no. MH/EE/B.P.Cell/GM/MHADA-09/1055/2022}.",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MH / EE / (BP) / GM / MHADA-9 / 1055 / 2023 / FCC / 1 / New"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "854231",

```

```
"path": "cases/667ab234968b1257131c092a/document_1719462794181_cc.pdf",
"fileName": "document_1719462794181_cc.pdf"
}
],
"caseNumber": "009523",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
" id": "591628",
" title": "Create Lead",
" description": "Create Lead",
" datetime": "Tue Jun 25 2024 17:34:04 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
" name": "Mr. Santosh Krishna Kambli & Mrs. Sampada Santosh Kambli",
" phone": "8108943920",
" ownershipShare": "",
" email": "",
" id": "577596"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
" typeOfDocument": {
" label": " Agreement",
" value": "652d16a0316e1359cebd3c15"
}
},
{
" docMeasurementType": {
" value": "Square_Feet",
" label": "Square Feet"
}
},
{
" selectAreaTypeDocument": "Carpet",
" squareMeterArea": "36.51",
" totalAreaDocument": "393",
" docBUILTUPPercentage": "10",
" docFinalBUILTUP": "432.30",
" docFinalBUILTUPSquareMeter": "40.16",
" docSaleablePercentage": "",
" docFinalSaleable": "0.00",
}
```

```
"docFinalSaleableSquareMeter": "0.00",
"id": "260467"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "380.00",
"squareMeterArea": "35.30",
"expectedRate": "21052.63",
"percentage": ""
},
"builtUpArea": {
"area": "418.00",
"squareMeterArea": "38.83",
"expectedRate": "19138.76",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "667c4fdec01ce75768833f31",
"property": "The Rising 58, Vikhroli",
"area": "380",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "https://www.99acres.com/",
"expectedPrice": "8000000",
"expectedRate": "21052.63",
"builtUpExpectedRate": "19138.76",
"image": "cases/667ab234968b1257131c092a/
indicator_1719422573556_Image.png",
"squareMeter": "35.30",
"id": "218554"
},
{
"carpetArea": {
"area": "381.00",
```

```
"squareMeterArea": "35.40",
"expectedRate": "21293.96",
"percentage": ""
},
"builtUpArea": {
  "area": "419.10",
  "squareMeterArea": "38.94",
  "expectedRate": "19358.15",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "667c4fdec01ce75768833f33",
"property": "The Rising 58, Vikhroli",
"area": "381",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Housing.Com",
"expectedPrice": "8113000",
"expectedRate": "21293.96",
"builtUpExpectedRate": "19358.15",
"image": "cases/667ab234968b1257131c092a/
indicator_1719422654588_Image.png",
"squareMeter": "35.40",
"id": "945883"
},
{
  "carpetArea": {
    "area": "398.00",
    "squareMeterArea": "36.98",
    "expectedRate": "18811.91",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "437.80",
    "squareMeterArea": "40.67",
    "expectedRate": "17101.74",
    "percentage": "10"
  }
}
```

```
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "667c4fdec01ce75768833f34",
"property": "Kannamwar Nagar, Vikhroli East",
"area": "398",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "5",
"source": "Index_no.2",
"expectedPrice": "7487142",
"expectedRate": "18811.91",
"builtUpExpectedRate": "17101.74",
"image": "cases/667ab234968b1257131c092a/
indicator_1719422727073_Image.png",
"squareMeter": "36.98",
"id": "297461"
},
{
  "carpetArea": {
    "area": "393.00",
    "squareMeterArea": "36.51",
    "expectedRate": "22646.31",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "432.30",
    "squareMeterArea": "40.16",
    "expectedRate": "20587.55",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "667c4fdec01ce75768833f35",
```

```
"property": "The Rising 58, Vikhroli",
"area": "393",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Dwello.com",
"expectedPrice": "8900000",
"expectedRate": "22646.31",
"builtUpExpectedRate": "20587.55",
"image": "cases/667ab234968b1257131c092a/
indicator_1719422795210_Image.png",
"squareMeter": "36.51",
"id": "763777"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667be577c01ce757688305b2",
  "name": "externalImg_1719395638099_1719395504777_image_0.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externalImg_1719395638099_1719395504777_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667be577c01ce757688305b3",
  "name": "externalImg_1719395641887_1719395504777_image_1.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externalImg_1719395641887_1719395504777_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667be577c01ce757688305b4",
  "name": "externalImg_1719395645368_1719395504777_image_2.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externalImg_1719395645368_1719395504777_image_2.jpeg",
  "orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667be577c01ce757688305b5",
    "name": "externallmg_1719395656361_1719395504777_image_3.jpeg",
    "path": "cases/667ab234968b1257131c092a/
externallmg_1719395656361_1719395504777_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667be577c01ce757688305b6",
    "name": "externallmg_1719395663296_1719395504777_image_4.jpeg",
    "path": "cases/667ab234968b1257131c092a/
externallmg_1719395663296_1719395504777_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667be577c01ce757688305b7",
    "name": "externallmg_1719395676991_1719395504777_image_5.jpeg",
    "path": "cases/667ab234968b1257131c092a/
externallmg_1719395676991_1719395504777_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667be577c01ce757688305b8",
    "name": "externallmg_1719395679156_1719395504777_image_6.jpeg",
    "path": "cases/667ab234968b1257131c092a/
externallmg_1719395679156_1719395504777_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667be577c01ce757688305b9",
    "name": "externallmg_1719395679437_1719395504777_image_7.jpeg",
    "path": "cases/667ab234968b1257131c092a/
externallmg_1719395679437_1719395504777_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "667be577c01ce757688305ba",
  "name": "externallmg_1719395698170_1719395504777_image_8.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externallmg_1719395698170_1719395504777_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667be4d9968b1257131c82be",
  "name": "externallmg_1719395493343_1719395362069_image_0.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externallmg_1719395493343_1719395362069_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667be4d9968b1257131c82bf",
  "name": "externallmg_1719395508784_1719395362069_image_1.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externallmg_1719395508784_1719395362069_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667be4d9968b1257131c82c0",
  "name": "externallmg_1719395515439_1719395362069_image_2.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externallmg_1719395515439_1719395362069_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667be4d9968b1257131c82c1",
  "name": "externallmg_1719395534962_1719395362069_image_3.jpeg",
  "path": "cases/667ab234968b1257131c092a/
externallmg_1719395534962_1719395362069_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "667be4d9968b1257131c82c2",
    "name": "externalimg_1719395543368_1719395362069_image_4.jpeg",
    "path": "cases/667ab234968b1257131c092a/
externalimg_1719395543368_1719395362069_image_4.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1716026508753_1715323634339_1711606660630_17008919755
73_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "filename": "1719422960576_1716026508753_1715323634339_1711606660630_1
700891975573_1695465043548_1694516251783_1694241590859_Calculation_1_2.xl
sx",
    "path": "cases/667ab234968b1257131c092a/processingDocuments/171942296057
6_1716026508753_1715323634339_1711606660630_1700891975573_169546504354
8_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "size": "1561970",
    "createdAt": "Wed Jun 26 2024 22:59:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1719422960576_1716026508753_1715323634339_17116066606
30_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1
_2.xlsx",
    "filename": "1719463445421_1719422960576_1716026508753_1715323634339_1
711606660630_1700891975573_1695465043548_1694516251783_1694241590859_
Calculation_1_2.xlsx",
    "path": "cases/667ab234968b1257131c092a/processingDocuments/171946344542
1_1719422960576_1716026508753_1715323634339_1711606660630_170089197557
3_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "size": "1560812",
    "createdAt": "Thu Jun 27 2024 10:14:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "cc.pdf",
    "filename": "1719463446878_cc.pdf",
    "path": "cases/667ab234968b1257131c092a/
processingDocuments/1719463446878_cc.pdf",
    "size": "181296",
    "createdAt": "Thu Jun 27 2024 10:14:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
```

```
    "originalname": "Maharashtra Real Estate Regulatory Authority.pdf",
    "filename": "1719463447020_Maharashtra_Real_Estate_Regulatory_Authority.pdf",
    "path": "cases/667ab234968b1257131c092a/processingDocuments/171946344702
0_Maharashtra_Real_Estate_Regulatory_Authority.pdf",
    "size": "2716796",
    "createdAt": "Thu Jun 27 2024 10:14:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "P51800034950.pdf",
    "filename": "1719463448522_P51800034950.pdf",
    "path": "cases/667ab234968b1257131c092a/
processingDocuments/1719463448522_P51800034950.pdf",
    "size": "153673",
    "createdAt": "Thu Jun 27 2024 10:14:08 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-25T12:04:04.424Z",
"updatedAt": "2024-06-27T07:48:39.172Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1501, 15th Floor, Building No 58, Wing - B, The
Rising 58, Kannamwar Nagar Prabhat Co-op. Hsg. Soc. Ltd., Kannamwar Nagar,
Village - Hariyali, Municipality Ward No. S - ward, Vikhroli (East), Taluka - Kurla, District
- Mumbai Suburban District, Mumbai, PIN Code - 400 083, State - Maharashtra, India",
"updatedAt": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Ravi Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "9082452140",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
```

```
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 393.00",
"flatRate": "21500",
"landOtherRate": "18500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Thu Jun 27 2024 09:00:49 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-06-26",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": ""
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			