

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae95ee191f7b344b005873"
    },
    "firstName": "Pooja ",
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418f1",
    "email": "pooja.mithbhavkar@cosmosbank.in",
    "mobileNo": "",
    "workMobileNo": "9820568493",
    "lastName": "Mithbhavkar"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Pooja ",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae95ee191f7b344b005873",
  "name": "Malad (East) Branch",
  "branchCode": "",
  "mobileNo": " 022 2881 0731",
  "alternateMobileNo": "",
  "email": "swapnil.deshmukh@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 1, 2 & 3 Khandwala Lane, Khandwala Arcade, Off Daffatry
Road, Malad East, Mumbai 400097"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "FRONTDESK",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
```

```
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.06517791377726",
```

```
"longitude": "72.88207701833532"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88207701833532,
    19.06517791377726
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "1/07/2024 11:04 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurar",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Easteren Plaza",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Daftary Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "near S K Patil hospital",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "Shop No 27",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66823a26991d670b8ad65a03",
"ownerName": "Deepak Satra ",
"ownerPhoneNo": "7506012685",
"appAddress": "Shop No 27 Eastern Plaza, Daftary Road, near SK Patil Hospital, Malad East ",
"remark": "Satra Dipak\n+917506012685",
"documents": [
  {
    "documentType": {
      "label": "Deed of Registered Mortgage",
      "value": "60ae1293aa6d152c1801b44a"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66823a26991d670b8ad65a03/
document_1719810504673_1719810377835_Mortgage_Further_charge_151117.pdf",
    "fileName":
"document_1719810504673_1719810377835_Mortgage_Further_charge_151117.pdf",
    "id": "911979",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Jul 01 2024 10:39:57 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009640",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "782064",
    "title": "Create Lead",
```

```
    "description": "Create Lead",
    "datetime": "Mon Jul 01 2024 10:39:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Deepak Satra ",
    "phone": "7506012685",
    "ownershipShare": "",
    "email": "",
    "id": "112007"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668244f4991d670b8ad670c1",
    "name": "externallmg_1719813357892_1719813200890_image_0.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813357892_1719813200890_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668244f4991d670b8ad670c2",
    "name": "externallmg_1719813358459_1719813200897_image_1.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813358459_1719813200897_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668244f4991d670b8ad670c3",
    "name": "externallmg_1719813358767_1719813200897_image_2.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813358767_1719813200897_image_2.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670c4",
  "name": "externallmg_1719813358769_1719813200897_image_3.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813358769_1719813200897_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670c5",
  "name": "externallmg_1719813359230_1719813200897_image_4.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813359230_1719813200897_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670c6",
  "name": "externallmg_1719813359628_1719813200897_image_5.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813359628_1719813200897_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670c7",
  "name": "externallmg_1719813360029_1719813200897_image_6.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813360029_1719813200897_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670c8",
  "name": "externallmg_1719813360482_1719813200897_image_7.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813360482_1719813200897_image_7.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670c9",
  "name": "externallmg_1719813361051_1719813200897_image_8.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813361051_1719813200897_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670ca",
  "name": "externallmg_1719813361418_1719813200897_image_9.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813361418_1719813200897_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670cb",
  "name": "externallmg_1719813361427_1719813200897_image_10.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813361427_1719813200897_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670cc",
  "name": "externallmg_1719813361437_1719813200897_image_11.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813361437_1719813200897_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670cd",
  "name": "externallmg_1719813361644_1719813200897_image_12.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813361644_1719813200897_image_12.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670ce",
  "name": "externallmg_1719813361998_1719813200897_image_13.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813361998_1719813200897_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670cf",
  "name": "externallmg_1719813362154_1719813200897_image_14.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813362154_1719813200897_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670d0",
  "name": "externallmg_1719813362324_1719813200897_image_15.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813362324_1719813200897_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670d1",
  "name": "externallmg_1719813362502_1719813200897_image_16.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813362502_1719813200897_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "668244f4991d670b8ad670d2",
  "name": "externallmg_1719813363080_1719813200897_image_17.jpeg",
  "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813363080_1719813200897_image_17.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668244f4991d670b8ad670d3",
    "name": "externallmg_1719813363270_1719813200897_image_18.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813363270_1719813200897_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668244f4991d670b8ad670d4",
    "name": "externallmg_1719813363478_1719813200897_image_19.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813363478_1719813200897_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425af6",
    "name": "externallmg_1719813401079_1719813245723_image_0.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813401079_1719813245723_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425af7",
    "name": "externallmg_1719813401287_1719813245723_image_1.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813401287_1719813245723_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425af8",
    "name": "externallmg_1719813401507_1719813245723_image_2.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813401507_1719813245723_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6682451bdcba8f0bc5425af9",
    "name": "externallmg_1719813401685_1719813245723_image_3.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813401685_1719813245723_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425afa",
    "name": "externallmg_1719813401873_1719813245723_image_4.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813401873_1719813245723_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425afb",
    "name": "externallmg_1719813402061_1719813245723_image_5.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402061_1719813245723_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425afc",
    "name": "externallmg_1719813402122_1719813245723_image_6.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402122_1719813245723_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425afd",
    "name": "externallmg_1719813402296_1719813245723_image_7.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402296_1719813245723_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6682451bdcba8f0bc5425afe",
    "name": "externallmg_1719813402352_1719813245723_image_8.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402352_1719813245723_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425aff",
    "name": "externallmg_1719813402615_1719813245723_image_9.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402615_1719813245723_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425b00",
    "name": "externallmg_1719813402671_1719813245723_image_10.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402671_1719813245723_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425b01",
    "name": "externallmg_1719813402879_1719813245723_image_11.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813402879_1719813245723_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425b02",
    "name": "externallmg_1719813403027_1719813245723_image_12.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externallmg_1719813403027_1719813245723_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6682451bdcba8f0bc5425b03",
```



```

    "name": "externalImg_1719813403179_1719813245723_image_13.jpeg",
    "path": "cases/66823a26991d670b8ad65a03/
externalImg_1719813403179_1719813245723_image_13.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-01T05:09:58.044Z",
"updatedAt": "2024-07-01T05:56:43.652Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Shop No. Shop No 27, 1st Floor, Eastern Plaza, Daftary
Road, near S K Patil hospital, Village - Kurar, Malad East, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Deepak Satra ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7506012685"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			