

```
{
  "typeOfReport": {
    "label": "Land",
    "value": "Land"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8e4"
    },
    "firstName": "Dinesh",
    "type": "CREDITOFFICER",
    "_id": "65b21bb04b70f72dd7628f61",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "8966009127",
    "email": "team3.04107@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
  }
}
```

```
"discussWithPerson": "Dinesh",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8e4",
  "branchCode": "000139",
  "type": "BRANCH",
  "name": "Stressed Assets Management Branch 1 (Colaba)",
  "email": "sanjay.gawhale@sbi.co.in",
  "mobileNo": "022-22160916 / 951",
  "alternateMobileNo": "",
  "address": "\\\"The Arcade\\\" 2nd Floor, World Trade Centre, Cuffe Parade, Colaba,
Mumbai - 400 005, State - Maharashtra, Country - India.\r\n",
  "ledgerName": " STATE BANK OF INDIA-CUFFE PARADE",
  "fax": "022-22154227",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
```

```
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60016f965256c07aec8e6dd6",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Akhilesh",
    "email": "akhilesh.yadav@vastukala.org",
    "lastName": "Yadav",
    "mobileNo": "9545753921",
    "designation": "Processing Officer",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "shortName": "AY"
  },
  "maker": {
    "type": "EMPLOYEE",
```

```
"_id": "60016f965256c07aec8e6dd6",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Proccer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
```

```
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.852717867554755",
  "longitude": "75.8774605999437"
},
"geo": {
  "type": "Point",
  "coordinates": [
    75.8774605999437,
    19.852717867554755
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Jalna",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kumbhar Gall",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
```

```
"key": "street2",
"value": "Near Pani Base, Kadrabad",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "6927",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": " Jalna,",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  },
}
```

```
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00"
  },
  "outgoingDetail": {
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "isSiteVisitAllowed": true
  },
  "finalPlinthArea": {
    "area": "0.00"
  },
  "routeMap": {
    "finalLatLng": {
      "coordinates": []
    }
  },
  "locationMapImg": [],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": ""
    }
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvancelInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66827c3cdcba8f0bc542a3e2",
"ownerName": "Kishor Shingare",
"ownerPhoneNo": "0000000000",
"appAddress": "CTS No 6927, situated at Kumbhar Galli, Near Pani Wes, Kadrabad,
Jalna, Admeasuring Total Area: 87.70Sq Mtrs.\n\nBelongs to : Kishor Shingare, Who is :
Director, Title Deed No : JNG1/4994, Registered On : 15-DEC97",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66827c3cdcba8f0bc542a3e2/
document_1719827508877_132549.pdf",
    "fileName": "document_1719827508877_132549.pdf",
    "id": "977587",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Jul 01 2024 15:21:56 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66827c3cdcba8f0bc542a3e2/document_1720007577376_172000745
3422_Title_Deed_CTS_6927_Kishore_Shingare_1.pdf",
    "fileName": "document_1720007577376_1720007453422_Title_Deed_CTS_6927_
Kishore_Shingare_1.pdf",
    "id": "399743",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Wed Jul 03 2024 17:23:06 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009658",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "980771",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jul 01 2024 15:21:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Kishor Shingare",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "545120"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f58240348",
    "name": "externalImg_1721478810044_MCH_No217100_CTS_No_2.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalImg_1721478810044_MCH_No217100_CTS_No_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f58240349",
    "name": "externalImg_1721478810077_MCH_No217100_CTS_No_3.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalImg_1721478810077_MCH_No217100_CTS_No_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f5824034a",
    "name": "externalImg_1721478810111_MCH_No217100_CTS_No_4.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalImg_1721478810111_MCH_No217100_CTS_No_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f5824034b",
    "name": "externalImg_1721478810154_MCH_No217100_CTS_No_5.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalImg_1721478810154_MCH_No217100_CTS_No_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "669bae9ae4681c3f5824034c",
  "name": "externalimg_1721478810181_MCH_No217100_CTS_No_6.jpeg",
  "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810181_MCH_No217100_CTS_No_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669bae9ae4681c3f5824034d",
  "name": "externalimg_1721478810206_MCH_No217100_CTS_No_7.jpeg",
  "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810206_MCH_No217100_CTS_No_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669bae9ae4681c3f5824034e",
  "name": "externalimg_1721478810230_MCH_No217100_CTS_No_8.jpeg",
  "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810230_MCH_No217100_CTS_No_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669bae9ae4681c3f5824034f",
  "name": "externalimg_1721478810254_MCH_No217100_CTS_No_9.jpeg",
  "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810254_MCH_No217100_CTS_No_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669bae9ae4681c3f58240350",
  "name": "externalimg_1721478810283_MCH_No217100_CTS_No_10.jpeg",
  "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810283_MCH_No217100_CTS_No_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "669bae9ae4681c3f58240351",
    "name": "externalimg_1721478810337_MCH_No217100_CTS_No_11.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810337_MCH_No217100_CTS_No_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f58240352",
    "name": "externalimg_1721478810383_MCH_No217100_CTS_No_12.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810383_MCH_No217100_CTS_No_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f58240353",
    "name": "externalimg_1721478810434_MCH_No217100_CTS_No_13.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810434_MCH_No217100_CTS_No_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669bae9ae4681c3f58240354",
    "name": "externalimg_1721478810477_MCH_No217100_CTS_No_14.jpeg",
    "path": "cases/66827c3cdcba8f0bc542a3e2/
externalimg_1721478810477_MCH_No217100_CTS_No_14.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-01T09:51:56.490Z",
"updatedAt": "2024-07-20T12:33:30.681Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60016f965256c07aec8e6dd6",
"assignmentType": {
  "value": "Commercial",
```

```
"label": "Commercial"
},
"fullAddress": "Residential Land No. Basement Floor, CTS No. 6927, Kumbhar Gall,
Near Pani Base, Kadrabad, Jalna,, Jalna",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Kishor Shingare",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}
```

Name	Length	Width	Total
Composition :			
Other Composition :			