

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "firstName": "Shravan",
    "type": "CREDITOFFICER",
    "_id": "6620d45d7e1d7332c88013d8",
    "lastName": "kumar",
    "mobileNo": "",
    "workMobileNo": "8424000434",
    "email": "shravankumar@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Shravan",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af3d172ffdf65bcd6585cd",
  "role": "PICKUPPERSON",
  "firstName": "Sachin",
  "email": "sachin.joshi@vastukala.org",
  "lastName": "Joshi",
  "mobileNo": "9167204063",
  "shortName": "SJ",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
    "mobileNo": "9529385821",
    "designation": "",
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.18196099724804",
  "longitude": "73.22696133173852"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.22696133173852,
    19.18196099724804
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-03",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Belavali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane ",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Thane ",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "10 to 14",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Varun Arcade Phase II",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
```

```
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```



```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 503",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Badlapur (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  }
},
```

```
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Aluminium_Sliding_Windows_with_window_grills",
  "label": "Aluminium Sliding Windows with window grills"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kulgaon_Badlapur_Municipal_Council",
    "label": "Kulgaon Badlapur Municipal Council"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Swanand Bungalow ",
    "west": "Open Plot ",
    "south": "Internal Road ",
    "east": "Residential Building "
  },
  "asPerDocumentAgreement": {
```

```
"north": "Plot No. 9",
"west": "Plot No. 19",
"south": "Lay Out Road ",
"east": "Plot No. 21"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
```

```
"documentsBuildingBoundaries": [],
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "412.5",
  "depreciatedCostOfConstruction": "3887.50",
  "depreciatedBuildingRate": "2087.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "48700",
  "landRate": "9440",
  "igrImage": "cases/6683c6a902a43d10c09d85bd/igr_1720005115515_Image.png",
  "squareMeterGuideLineRate": "46265.00",
  "squareFeetGuideLineRate": "4298.00"
},
"igrFinalRate": {
  "floorRatePercentage": "95",
  "depreciationPercentage": "89",
  "rate": "3922.00",
  "squareFeetGuideLineRate": "3922.00",
  "squareMeterGuideLineRate": "42214.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
```

```
"floorSpaceIndex": "As per KBMC norms ",
"tenantName": "",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2013",
    "fullDate": "1/1/2013"
  },
  "planningArea": {
    "value": "Residential",
```

```
"label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "49",
"ageOfBuilding": "11",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "650.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
```

```
    "label": "Railway Station"
  },
  "routeMapImg": "cases/6683c6a902a43d10c09d85bd/
routeMap_1720070286116_Image.png",
  "routeLat": "19.181667",
  "routeLng": "73.226528",
  "stationName": "Chikhloli",
  "routeDistance": "850 Mtrs. "
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "c62qxd",
    "name": "c62qxd",
    "image": "cases/6683c6a902a43d10c09d85bd/
routeMap_1720070185729_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
```



```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2527200.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "2527200.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2549300.00",
  "selectedBuildUpValue": "650.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe78",
      "name": "externallmg_r_1719998113055_1719997940649_image_18.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998113055_1719997940649_image_18.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe78",
      "name": "externallmg_r_1719998113055_1719997940649_image_18.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998113055_1719997940649_image_18.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe67",
      "name": "externallmg_r_1719998093075_1719997940649_image_3.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998093075_1719997940649_image_3.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe69",
      "name": "externallmg_r_1719998090072_1719997940649_image_2.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998090072_1719997940649_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe68",
      "name": "externallmg_r_1719998094440_1719997940649_image_4.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998094440_1719997940649_image_4.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe70",
      "name": "externallmg_r_1719998102855_1719997940649_image_9.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998102855_1719997940649_image_9.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe71",
      "name": "externallmg_r_1719998104365_1719997940649_image_11.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998104365_1719997940649_image_11.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe6f",
      "name": "externallmg_r_1719998103835_1719997940649_image_10.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998103835_1719997940649_image_10.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668516a7430c9b7f5804fe73",
      "name": "externallmg_r_1719998105791_1719997940649_image_13.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998105791_1719997940649_image_13.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668516a7430c9b7f5804fe76",
    "name": "externallmg_r_1719998109601_1719997940649_image_15.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998109601_1719997940649_image_15.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "3772.00",
    "max": "6309.00"
  },
  "builtUpRateRange": {
    "min": "3143.00",
    "max": "5258.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```



```
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "650.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6683c6a902a43d10c09d85bd",
"ownerName": "Mr. Sainath Gangadhar Sanvatsarakar & Mr. Malati Sainath
Sanvatsarakar ",
"ownerPhoneNo": "9588941857",
"appAddress": "Flat no 101 1st Floor, Varun Arcade Phase II,Belavali Village ,Badlapur
west ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "26/02/2018",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Samadhan Chandrakant Chavan",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Sainath Gangadhar Sanvatsarakar & Mr. Malati Sainath
Sanvatsarakar ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "586 / 2018"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "657748",
```

```
"path": "cases/6683c6a902a43d10c09d85bd/
document_1719912089856_1719911964471_Sainath_SBI_PBB_Fort.pdf",
"fileName":
"document_1719912089856_1719911964471_Sainath_SBI_PBB_Fort.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "12/04/2013",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KBMC / BP / 968"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1720066114512_Agreement.pdf",
"path": "cases/6683c6a902a43d10c09d85bd/
document_1720066114512_Agreement.pdf",
"id": "164384",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jul 04 2024 09:38:34 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2010",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "KBMC / BP / 1399 - 162"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720066287352_Agreement.pdf",
  "path": "cases/6683c6a902a43d10c09d85bd/
document_1720066287352_Agreement.pdf",
  "id": "186601",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jul 04 2024 09:41:27 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009680",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "326592",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 02 2024 14:51:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sainath Gangadhar Sanvatsarakar & Mr. Malati Sainath Sanvatsarakar",
    "phone": "9588941857",
    "ownershipShare": "",
    "email": "",
    "id": "514492"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "690934",
    "name": "Kitchen",
    "length": "7.50",
    "length1": "7",
    "length2": "6",
    "width": "9.08",
```

```
"width1": "9",
"width2": "1",
"totalArea": "68.12",
"images": [],
"extraAreas": [],
"finalArea": "68.12"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "26.67",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "66862aba5d6e897f7950238a",
      "name": "Extra ",
      "extraAreaType": "Add",
      "length": "5.00",
      "length1": "5",
      "length2": "00",
      "width": "1.00",
      "width1": "1",
      "width2": "00",
      "totalArea": "5.00"
    }
  ],
  "finalArea": "31.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "2",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "17.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "9.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "9.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "11.17",
  "width1": "11",
  "width2": "2",
  "totalArea": "100.50",
```

```
"images": [],
"extraAreas": [],
"finalArea": "100.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "15.42",
  "length1": "15",
  "length2": "5",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "140.03",
  "images": [],
  "extraAreas": [],
  "finalArea": "140.03"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "6.00",
    "length1": "6",
    "length2": "00",
    "width": "9.00",
    "width1": "9",
    "width2": "00",
    "totalArea": "54.00",
    "images": [],
```

```
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "66862b40bec4e37f7ac5ddf3",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "3.00",
    "length1": "3",
    "length2": "00",
    "width": "7.50",
    "width1": "7",
    "width2": "6",
    "totalArea": "22.50"
  }
],
"finalArea": "76.5",
"percentageBeforeTotal": "76.50",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "27.00",
  "length1": "27",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "27.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "27",
```

```
    "percentageBeforeTotal": "27.00",
    "percentage": "100"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "284641",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "650",
    "squareMeterArea": "60.39",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBultupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "449.17",
      "squareMeterArea": "41.73",
      "expectedRate": "4675.29",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "539.00",
      "squareMeterArea": "50.07",
      "expectedRate": "3896.10",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "0.00",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
```



```
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "668532195d6e897f7950020f",
  "property": "Flat",
  "area": "539",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "2100000",
  "expectedRate": "4675.29",
  "builtUpExpectedRate": "2100000",
  "image": "cases/6683c6a902a43d10c09d85bd/
indicator_1720004695243_Image.png",
  "squareMeter": "50.07",
  "id": "631018"
},
{
  "carpetArea": {
    "area": "428.00",
    "squareMeterArea": "39.76",
    "expectedRate": "6308.41",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "513.60",
    "squareMeterArea": "47.72",
    "expectedRate": "5257.01",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "668532195d6e897f79500210",
  "property": "Flat",
  "area": "428",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "2700000",
"expectedRate": "6308.41",
"builtUpExpectedRate": "5257.01",
"image": "cases/6683c6a902a43d10c09d85bd/
indicator_1720004725287_Image.png",
"squareMeter": "39.76",
"id": "736119"
},
{
  "carpetArea": {
    "area": "875.00",
    "squareMeterArea": "81.29",
    "expectedRate": "3771.43",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1050.00",
    "squareMeterArea": "97.55",
    "expectedRate": "3142.86",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "668532195d6e897f79500211",
  "property": "Flat",
  "area": "1050",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "3300000.00",
  "expectedRate": "3771.43",
  "builtUpExpectedRate": "3300000.00",
  "image": "cases/6683c6a902a43d10c09d85bd/
indicator_1720004767976_Image.png",
  "squareMeter": "97.55",
```

```
    "id": "865788"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516a7430c9b7f5804fe66",
    "name": "externalimg_1719998078285_1719997940649_image_1.png",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalimg_1719998078285_1719997940649_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516a7430c9b7f5804fe67",
    "name": "externalimg_r_1719998093075_1719997940649_image_3.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalimg_r_1719998093075_1719997940649_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516a7430c9b7f5804fe68",
    "name": "externalimg_r_1719998094440_1719997940649_image_4.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalimg_r_1719998094440_1719997940649_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516a7430c9b7f5804fe69",
    "name": "externalimg_r_1719998090072_1719997940649_image_2.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalimg_r_1719998090072_1719997940649_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516a7430c9b7f5804fe6a",
    "name": "externalimg_r_1719998067653_1719997940649_image_0.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalimg_r_1719998067653_1719997940649_image_0.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe6b",
  "name": "externallmg_r_1719998097856_1719997940649_image_6.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998097856_1719997940649_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe6c",
  "name": "externallmg_r_1719998096310_1719997940649_image_5.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998096310_1719997940649_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe6d",
  "name": "externallmg_r_1719998099170_1719997940649_image_7.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998099170_1719997940649_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe6e",
  "name": "externallmg_r_1719998101434_1719997940649_image_8.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998101434_1719997940649_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe6f",
  "name": "externallmg_r_1719998103835_1719997940649_image_10.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998103835_1719997940649_image_10.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "668516a7430c9b7f5804fe70",
      "name": "externallmg_r_1719998102855_1719997940649_image_9.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998102855_1719997940649_image_9.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "668516a7430c9b7f5804fe71",
      "name": "externallmg_r_1719998104365_1719997940649_image_11.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998104365_1719997940649_image_11.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "668516a7430c9b7f5804fe72",
      "name": "externallmg_r_1719998105030_1719997940649_image_12.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998105030_1719997940649_image_12.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "668516a7430c9b7f5804fe73",
      "name": "externallmg_r_1719998105791_1719997940649_image_13.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998105791_1719997940649_image_13.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "668516a7430c9b7f5804fe74",
      "name": "externallmg_r_1719998111200_1719997940649_image_16.jpg",
      "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998111200_1719997940649_image_16.jpg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe75",
  "name": "externallmg_r_1719998107345_1719997940649_image_14.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998107345_1719997940649_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe76",
  "name": "externallmg_r_1719998109601_1719997940649_image_15.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998109601_1719997940649_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe77",
  "name": "externallmg_r_1719998112310_1719997940649_image_17.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998112310_1719997940649_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe78",
  "name": "externallmg_r_1719998113055_1719997940649_image_18.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998113055_1719997940649_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668516a7430c9b7f5804fe79",
  "name": "externallmg_r_1719998113985_1719997940649_image_19.jpg",
  "path": "cases/6683c6a902a43d10c09d85bd/
externallmg_r_1719998113985_1719997940649_image_19.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516bd430c9b7f5804feb9",
    "name": "externalImg_r_1719998135255_1719998010455_image_1.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalImg_r_1719998135255_1719998010455_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516bd430c9b7f5804feba",
    "name": "externalImg_r_1719998134342_1719998010455_image_0.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalImg_r_1719998134342_1719998010455_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668516bd430c9b7f5804febb",
    "name": "externalImg_r_1719998137321_1719998010455_image_2.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalImg_r_1719998137321_1719998010455_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6685165b5d6e897f794fe8d5",
    "name": "externalImg_r_1719998022890_1719997899373_image_0.jpg",
    "path": "cases/6683c6a902a43d10c09d85bd/
externalImg_r_1719998022890_1719997899373_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2) - sainath.xlsx",
    "filename": "1720005137922_Calculation_2__sainath.xlsx",
    "path": "cases/6683c6a902a43d10c09d85bd/
processingDocuments/1720005137922_Calculation_2__sainath.xlsx",
    "size": "16064",
    "createdAt": "Wed Jul 03 2024 16:42:18 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
```

```
    },
    {
      "originalname": "igr1.pdf",
      "filename": "1720005137924_igr1.pdf",
      "path": "cases/6683c6a902a43d10c09d85bd/
processingDocuments/1720005137924_igr1.pdf",
      "size": "161860",
      "createdAt": "Wed Jul 03 2024 16:42:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "igr2.pdf",
      "filename": "1720005137929_igr2.pdf",
      "path": "cases/6683c6a902a43d10c09d85bd/
processingDocuments/1720005137929_igr2.pdf",
      "size": "162963",
      "createdAt": "Wed Jul 03 2024 16:42:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "igr3.pdf",
      "filename": "1720005137933_igr3.pdf",
      "path": "cases/6683c6a902a43d10c09d85bd/
processingDocuments/1720005137933_igr3.pdf",
      "size": "158935",
      "createdAt": "Wed Jul 03 2024 16:42:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Summary - sainath.xlsx",
      "filename": "1720005137938_Summary__sainath.xlsx",
      "path": "cases/6683c6a902a43d10c09d85bd/
processingDocuments/1720005137938_Summary__sainath.xlsx",
      "size": "1928700",
      "createdAt": "Wed Jul 03 2024 16:42:18 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-07-02T09:21:45.986Z",
  "updatedAt": "2024-07-04T05:18:46.761Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
```



```
"label": "Retail"
},
"fullAddress": "Residential Flat No. 101, 1st Floor, Varun Arcade Phase II, Plot No. 10
to 14, Village - Belavali, Badlapur (West), Taluka - Ambernath, District - Thane , Thane ,
PIN - 421 503, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Vaibhav Sanvatsarakar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner Son ",
"siteVisitContactNo": "7021801916",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 650.00",
"flatRate": "4300",
"landOtherRate": "1800",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "350.07",
"extendOfSiteRemark": "",
"finalBuiltupArea": "518.18",
"finalCarpetArea": "471.07",
"finalSalableArea": "569.99",
"otherCarpetTotal": "104.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 367.00\nBalcony Area in Sq. Ft.
= 77.00\nFlower Bed Area in Sq. Ft. = 27.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
WC",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "103.50",
```

```

"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			
Kitchen	7'6"	9'1"	68.12
Passage	8'00"	3'4"	26.67
Bathroom	5'00"	3'6"	17.50
WC	3'3"	3'00"	9.75
Bedroom	9'00"	11'2"	100.50
Living Room	15'5"	9'1"	140.03
Other Composition :			
Balcony Area	6'00"	9'00"	54.00
Flower Bed Area	27'00"	1'00"	27.00