

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb30"
    },
    "firstName": "P K ",
    "type": "CREDITOFFICER",
    "_id": "6673c9d559d44b137cf607c6",
    "email": "Kalbadevi.MumbaiSouth@bankofindia.co.in",
    "lastName": "Chaudhary",
    "mobileNo": "",
    "workMobileNo": "9137941408"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Ravikesh Bhimrao ",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb30",
  "branchCode": "000077",
  "type": "BRANCH",
  "name": "Kalbadevi Branch",
  "email": "Kalbadevi.MumbaiSouth@bankofindia.com",
  "mobileNo": "02222056394",
  "alternateMobileNo": "",
  "address": "Round Building,Shamaldas Gandhi Marg,Mumbai-400002",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4336576061dae469362",
  "zoneName": "Mumbai South Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "665ac13f42f4717ae30de3d5",
"role": "PICKUPPERSON",
"firstName": "NIDHI",
"email": "nidhi.kajwe97@gmail.com",
"lastName": "KAJWE",
"mobileNo": "8850520881",
"shortName": "NIDHI",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
```

```
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "_id": "64cde526dc9f3034f3fefa49",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "shortName": "RJ",
  "email": "rashmijadhav14feb@gmail.com",
  "designation": "Back Office Coordination",
  "mobileNo": "7738144625",
  "role": "FRONTDESK",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        }
      }
    ]
  }
],
```

```
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "18.956941049986234",
  "longitude": "72.82867805804885"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82867805804885,
    18.956941049986234
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
```

```
"schedule": [],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-07-08",
    "remark": "Sukriti Sukumar Singha . our bldg old name is Ganesh bhuvan, new
name is om shree kalba Devi chsl, .chama Galli cross lane, "
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-07-08",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhuleshwar Division ",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Mumbai ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kalbadevi Om Shree Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "36B, Champa Gali, X Lane ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kalbadevi Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "Cadastral Survey No. 809 ",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "7(5)",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "PIN - 400 002",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
    "label": "Teak Wood door frame, Flush doors shutters"
  },
  "windows": {
    "value": "Aluminium_Open_Windows",
    "label": "Aluminium Open Windows"
  },
  "fittings": {
    "value": "Open_plumbing_with_C.P._fittings._Casing_Capping_wiring",
    "label": "Open plumbing with C.P. fittings. Casing Capping wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
}
```

```
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MHADA",
  "label": "MHADA"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "H.S.K Enterprises ",
  "west": "Jalan Bhavan ",
  "south": "1st Cross Lane Road ",
  "east": "Shanti Bhuvan "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
```

```

    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "The property is constructed by MHADA, hence MHADA
itself is an issuing authority.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of site visit, residential property used as commercial
purpose<br /> All the above areas are within 2% of the Agreement for Sale Area. The
above calculations and detail measurements taken by us prove that the Agreement for
Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for
Sale area. <br /> As per site inspection, the premise unit does not have any attached
bath room and W.C , only found Nani in the said premises. W.C provided in the
common passage area",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "24100",
  "depreciatedBuildingRate": "1600"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "167530",
  "landRate": "85220",
  "igrImage": "cases/6683cd87d9f18310ed2dde8d/igr_1720591450926_Image.png",
  "squareMeterGuideLineRate": "167530.00",
  "squareFeetGuideLineRate": "15564.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",

```

```
"depreciationPercentage": "76",
"rate": "13729.00",
"squareFeetGuideLineRate": "13729.00",
"squareMeterGuideLineRate": "147776.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Commercial_Purpose",
    "label": "Commercial Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "9,000/- Present rental income per month ",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MHADA norms ",
  "tenantName": "Mr. Bimal Sawant<br />Occupied Since - Last 7 Years ",
  "maintenanceOfFlat": "Poor Condition "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
```

```
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Load-bearing_structure",
  "label": "Load-bearing structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
}
```

```
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
```



```

    "value": "as_per_site_information",
    "label": "As per site information"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "36",
  "ageOfBuilding": "24",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "5",
  "flatFloorNo": "2",
  "noOfLifts": "",
  "noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "222.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6683cd87d9f18310ed2dde8d/
routeMap_1720610530604_Image.png",
    "routeLat": "18.949250",
    "routeLng": "72.829639",
    "stationName": "Marine Lines ",
    "routeDistance": "1.00 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [

```

```
{
  "id": "a4n30s",
  "name": "a4n30s",
  "image": "cases/6683cd87d9f18310ed2dde8d/
routeMap_1720610404414_Image.png"
}
],
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4458500.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",

```

```
"finalValue": "4458500.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3047838.00",
  "selectedBuildUpValue": "222.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "668bdb52a5c60c02d349c463",
    "name": "externallmg_1720441682295_1720441554848_image_12.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441682295_1720441554848_image_12.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c459",
    "name": "externallmg_1720441677565_1720441554848_image_2.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441677565_1720441554848_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c45b",
    "name": "externallmg_1720441678281_1720441554848_image_4.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441678281_1720441554848_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c458",
    "name": "externallmg_1720441677298_1720441554848_image_1.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441677298_1720441554848_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c463",
    "name": "externallmg_1720441682295_1720441554848_image_12.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441682295_1720441554848_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c462",
    "name": "externallmg_1720441681919_1720441554848_image_11.jpeg",
```

```
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441681919_1720441554848_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c45c",
    "name": "externallmg_1720441679004_1720441554848_image_5.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441679004_1720441554848_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668bdb52a5c60c02d349c45d",
    "name": "externallmg_1720441679084_1720441554848_image_6.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441679084_1720441554848_image_6.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "23595.00",
    "max": "30646.00"
  },
  "builtUpRateRange": {
    "min": "19663.00",
    "max": "25538.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "185.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6683cd87d9f18310ed2dde8d",
"ownerName": "Mr. Jignesh Jayendra Dhandhukia",
"ownerPhoneNo": "8879417589",
"appAddress": "Room No 7(5) Second Floor Kalbadevi Om Shree Chs Ltd 36B
Champa Gali X Lane Kalbadevi Road Mumbai - 400002",
"remark": "Sukriti Sukumar Singha . our bldg old name is Ganesh bhuvan, new name
is om shree kalba Devi chsl, .chama Galli cross lane, ",
"documents": [
  {
    "documentType": {
      "value": "60ae1260aa6d152c1801b35f",
      "label": "Deed of Release"
    },
    "inputs": {
      "documentDate": "02/05/2023",
      "from": {
        "value": "Releasers",
        "label": "Releasers"
      },
      "Releasers": "Mrs. Amita Narendra Kapuriya Alais Miss. Amita Jayendra
Dhadhukia & Mr. Chetan Jayendra Dhandhukia ",
      "to": {
        "value": "Releasee",
        "label": "Releasee"
      }
    }
  },

```

```
    "Releasee": "Mr. Jignesh Jayendra Dhandhukia"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "173010",
  "path": "cases/6683cd87d9f18310ed2dde8d/
document_1719913837248_1719913770726_Sukriti_Sukumar_Singha.pdf",
  "fileName":
"document_1719913837248_1719913770726_Sukriti_Sukumar_Singha.pdf"
},
{
  "documentType": {
    "value": "60ae1256aa6d152c1801b330",
    "label": "Draft Agreement for sale"
  },
  "inputs": {
    "remark": " in the month of June 2024",
    "from": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Mr. Jignesh Jayendra Dhandhukia",
    "to": {
      "value": "Purchaser",
      "label": "Purchaser"
    },
    "Purchaser": "Mr. Sukriti Sukumar Singha "
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "573159",
  "path": "cases/6683cd87d9f18310ed2dde8d/
document_1719917582009_97653.pdf",
  "fileName": "document_1719917582009_97653.pdf"
}
],
"caseNumber": "009682",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
    "id": "444073",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 02 2024 15:21:03 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [  
  {  
    "name": "Mr. Jignesh Jayendra Dhandhukia",  
    "phone": "8879417589",  
    "ownershipShare": "",  
    "email": "",  
    "id": "777486"  
  }  
],
```

```
"proposePurchasers": [  
  {  
    "name": "Mr. Sukriti Sukumar Singha "  
  }  
],
```

```
"siteInspection": [],
```

```
"composition": [  
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "819149",  
    "name": "Living Room",  
    "length": "100.00",  
    "length1": "100",  
    "length2": "00",  
    "width": "1.00",  
    "width1": "1",  
    "width2": "00",  
    "totalArea": "100.00",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "100.00"  
  },
```

```
  {  
    "measurementType": {  
      "value": "Square_Feet",  
      "label": "Square Feet"  
    },  
    "id": "1",  
    "name": "Bathroom",  
    "length": "80.00",  
    "length1": "80",  
    "length2": "00",  
    "width": "1.00",  
    "width1": "1",
```

```
"width2": "00",
"totalArea": "80.00",
"images": [],
"extraAreas": [],
"finalArea": "80.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1256aa6d152c1801b330",
    "label": "Draft Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "974304",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "185",
  "squareMeterArea": "17.19",
  "docFinalBuiltUp": "222",
  "docFinalBuiltUpSquareMeter": "20.628",
  "docBultupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "208",
    "squareMeterArea": "19.32",
    "expectedRate": "28846.15",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "250.00",
    "squareMeterArea": "23.23",
    "expectedRate": "24000.00",
    "percentage": ""
  }
},
}
```

```
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "668e252aa7ea882b0985f7e4",
"property": "Residential Flat ",
"area": "250",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "6000000",
"expectedRate": "28846.15",
"builtUpExpectedRate": "6000000",
"image": "cases/6683cd87d9f18310ed2dde8d/
indicator_1720591251134_Image.png",
"squareMeter": "23.23",
"id": "377729"
},
{
  "carpetArea": {
    "area": "310.00",
    "squareMeterArea": "28.80",
    "expectedRate": "30645.16",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "372.00",
    "squareMeterArea": "34.56",
    "expectedRate": "25537.63",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "668e252aa7ea882b0985f7e5",
  "property": "Residential Flat",
```

```
"area": "310",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "9500000",
"expectedRate": "30645.16",
"builtUpExpectedRate": "25537.63",
"image": "cases/6683cd87d9f18310ed2dde8d/
indicator_1720591358890_Image.png",
"squareMeter": "28.80",
"id": "621855"
},
{
"carpetArea": {
"area": "185.00",
"squareMeterArea": "17.19",
"expectedRate": "23594.59",
"percentage": ""
},
"builtUpArea": {
"area": "222.00",
"squareMeterArea": "20.62",
"expectedRate": "19662.16",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "668e252aa7ea882b0985f7e6",
"property": "Residential Flat",
"area": "185",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4365000",
"expectedRate": "23594.59",
```

```
    "builtUpExpectedRate": "19662.16",
    "image": "cases/6683cd87d9f18310ed2dde8d/
indicator_1720591503796_Image.png",
    "squareMeter": "17.19",
    "id": "713794"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c457",
    "name": "externallmg_1720441676978_1720441554848_image_0.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441676978_1720441554848_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c458",
    "name": "externallmg_1720441677298_1720441554848_image_1.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441677298_1720441554848_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c459",
    "name": "externallmg_1720441677565_1720441554848_image_2.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441677565_1720441554848_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c45a",
    "name": "externallmg_1720441677860_1720441554848_image_3.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441677860_1720441554848_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "668bdb52a5c60c02d349c45b",
  "name": "externallmg_1720441678281_1720441554848_image_4.jpeg",
  "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441678281_1720441554848_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bdb52a5c60c02d349c45c",
  "name": "externallmg_1720441679004_1720441554848_image_5.jpeg",
  "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441679004_1720441554848_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bdb52a5c60c02d349c45d",
  "name": "externallmg_1720441679084_1720441554848_image_6.jpeg",
  "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441679084_1720441554848_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bdb52a5c60c02d349c45e",
  "name": "externallmg_1720441679719_1720441554848_image_7.jpeg",
  "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441679719_1720441554848_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bdb52a5c60c02d349c45f",
  "name": "externallmg_1720441680275_1720441554848_image_8.jpeg",
  "path": "cases/6683cd87d9f18310ed2dde8d/
externallmg_1720441680275_1720441554848_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "668bdb52a5c60c02d349c460",
    "name": "externalimg_1720441680876_1720441554848_image_9.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalimg_1720441680876_1720441554848_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c461",
    "name": "externalimg_1720441681527_1720441554848_image_10.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalimg_1720441681527_1720441554848_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c462",
    "name": "externalimg_1720441681919_1720441554848_image_11.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalimg_1720441681919_1720441554848_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bdb52a5c60c02d349c463",
    "name": "externalimg_1720441682295_1720441554848_image_12.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalimg_1720441682295_1720441554848_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668bdb37a5c60c02d349c3fe",
    "name": "externalimg_1720441653733_1720441525761_image_0.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalimg_1720441653733_1720441525761_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668bdb37a5c60c02d349c3ff",
```

```
    "name": "externalImg_1720441654083_1720441525761_image_1.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalImg_1720441654083_1720441525761_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "668bdb37a5c60c02d349c400",
    "name": "externalImg_1720441654666_1720441525761_image_2.jpeg",
    "path": "cases/6683cd87d9f18310ed2dde8d/
externalImg_1720441654666_1720441525761_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1720591642595_Calculation_Sheet_NEW.xlsx",
    "path": "cases/6683cd87d9f18310ed2dde8d/
processingDocuments/1720591642595_Calculation_Sheet_NEW.xlsx",
    "size": "1360270",
    "createdAt": "Wed Jul 10 2024 11:37:22 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Agreement.pdf",
    "filename": "1720610963689_Agreement.pdf",
    "path": "cases/6683cd87d9f18310ed2dde8d/
processingDocuments/1720610963689_Agreement.pdf",
    "size": "13271177",
    "createdAt": "Wed Jul 10 2024 16:59:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "document_1719917582009_97653.pdf",
    "filename": "1720610963908_document_1719917582009_97653.pdf",
    "path": "cases/6683cd87d9f18310ed2dde8d/
processingDocuments/1720610963908_document_1719917582009_97653.pdf",
    "size": "1107866",
    "createdAt": "Wed Jul 10 2024 16:59:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "668d2a7602fa372b4239dbd3",
    "note": "Value Given For The Confirmation",
    "taskId": "6683d78b77dbb210f4f37b47",
    "createdAt": "2024-07-09T12:17:58.269Z"
  },
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "668d2af0a7ea882b0985bed6",
    "note": "Value Given For The Confirmation",
    "taskId": "6683d78b77dbb210f4f37b47",
    "createdAt": "2024-07-09T12:20:00.766Z"
  }
],
"createdAt": "2024-07-02T09:51:03.377Z",
"updatedAt": "2024-07-11T05:08:18.720Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 7(5), 2nd Floor, Kalbadevi Om Shree Co-Op. Hsg.
Soc. Ltd., 36B, Champa Gali, X Lane , Kalbadevi Road, Village - Bhuleshwar Division ,
```

Taluka - Mumbai , District - Mumbai , PIN - 400 002, State - Maharashtra, Country - India",

```
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "Mr. Sukriti Sukumar Singha",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mr. Sukriti Sukumar Singha ",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Proposed Purchaser ",
"siteVisitContactNo": "8879417589",
"siteVisitDate": "2024-07-08",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 185.00",
"flatRate": "25000",
"landOtherRate": "22500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "100.00",
"extendOfSiteRemark": "",
"finalBuiltupArea": "198.00",
"finalCarpetArea": "180.00",
"finalSalableArea": "217.80",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "Living Room + Bathroom",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
```

```

"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
"lessorName": "",
"lesseeName": "",
"leasePremium": "",
"leaseRent": "",
"leasePeriod": 0,
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Wed Jul 10 2024 15:54:26 GMT+0530 (India Standard Time)"
}

```

Name	Length	Width	Total
Composition :			
Living Room	100'00"	1'00"	100.00
Bathroom	80'00"	1'00"	80.00
Other Composition :			