

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Shivani ",
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Shivani ",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.299318387642042",
  "longitude": "73.20774679284854"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.20774679284854,
    19.299318387642042
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-06",
      "remark": "LUMSUM APPROXIMATELY 50Lakh"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Manda",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "17",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Regency Sarvam Building No. 17 Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "42/1, 42/2, 42/6 & others ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "305",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN - 421 605",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Titwala (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
}
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Kalyan_Dombivali_Municipal_Corporation",
  "label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Building No. 18",
  "west": "Regency Sarvam Road ",
  "south": "Axis Bank ",
  "east": "Internal Road & Garden "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
```

```

    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Part Building completion Certificate is received may
be assumed that the construction is as per sanctioned plan. \n\n",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "13.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "337.5",
  "depreciatedCostOfConstruction": "8162.50",
  "depreciatedBuildingRate": "2162.5"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "54200",
  "landRate": "8600",
  "igrImage": "cases/6687c7f8194f4629de0a8a65/igr_1720418404035_Image.png",
  "squareMeterGuideLineRate": "54200.00",
  "squareFeetGuideLineRate": "5035.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "91",
  "rate": "4654.00",

```

```
"squareFeetGuideLineRate": "4654.00",
"squareMeterGuideLineRate": "50096.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per KDMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
```

```
"label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
```

```
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
}
```



```
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "51",
"ageOfBuilding": "9",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "12",
"flatFloorNo": "3",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "822.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6687c7f8194f4629de0a8a65/
routeMap_1720425130536_Image.png",
    "routeLat": "19.298611",
    "routeLng": "73.207333",
    "stationName": "Titwala ",
    "routeDistance": "1.1 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "pnczj",
```

```
    "name": "pnczj",
    "image": "cases/6687c7f8194f4629de0a8a65/
routeMap_1720425052895_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5591655.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "5591655.00"
},
```

```
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jul 08 2024 15:44:51 GMT+0530 (India Standard Time)",
  "number": "2307124",
  "dayCount": "10",
  "monthCount": "128",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3825588.00",
  "selectedBuildUpValue": "822.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66890eb9a403df7f574f33e8",
      "name": "externallmg_1720258226852_1720258099489_image_0.jpeg",
      "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258226852_1720258099489_image_0.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "66890eb9a403df7f574f33eb",
      "name": "Living Room",
      "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258229537_1720258099489_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66890eb9a403df7f574f33ec",
      "name": "Living Room",
      "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258229763_1720258099489_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66890eb9a403df7f574f33ed",
      "name": "Living Room",
      "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258230062_1720258099489_image_5.jpeg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "66890eb9a403df7f574f33f3",
      "name": "Living Room",
      "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258232137_1720258099489_image_11.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66890eb9a403df7f574f33f2",
    "name": "Living Room",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258231982_1720258099489_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66890eb9a403df7f574f33ee",
    "name": "Living Room",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258230517_1720258099489_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66890e807053ac2959a21354",
    "name": "Living Room",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258175958_1720258050384_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66890e807053ac2959a21353",
    "name": "Living Room",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258175437_1720258050384_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66890eb9a403df7f574f33ef",
    "name": "Living Room",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258230897_1720258099489_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66890eb9a403df7f574f33f1",
    "name": "Living Room",
```

```
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258231647_1720258099489_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66890eb9a403df7f574f33e8",
    "name": "Living Room",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258226852_1720258099489_image_0.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7883.00",
    "max": "8987.00"
  },
  "builtUpRateRange": {
    "min": "6569.00",
    "max": "7490.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```



```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "685.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3",
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6687c7f8194f4629de0a8a65",
"ownerName": "Mr. Manesh Ranapratap Deshmukh & Mrs. Priti Manesh Deshmukh ",
"ownerPhoneNo": "7718829353",
"appAddress": "Flat no. 305, 3rd Floor, Building no. 17, Regency Sarvam, Manda,
Titwala",
"remark": "LUMSUM APPROXIMATELY 50Lakh",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/06/2024",
      "from": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Miss. Geeta Lekhraj Khajuria ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Manesh Ranapratap Deshmukh & Mrs. Priti Manesh Deshmukh
",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "8918 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
```

```
    "id": "464057",
    "path": "cases/6687c7f8194f4629de0a8a65/document_1720174449383_1720174327245_Racpc_Ghatkopar_Manesh_Deshmukh.pdf",
    "fileName": "document_1720174449383_1720174327245_Racpc_Ghatkopar_Manesh_Deshmukh.pdf"
  },
  {
    "documentType": {
      "value": "60ae12a8aa6d152c1801b4a8",
      "label": "Part Building Completion Certificate"
    },
    "inputs": {
      "documentDate": "20/08/2015",
      "nameOfApprovingAuthority": {
        "value": "Kalyan_Dombivli_Municipal_Corporation",
        "label": "Kalyan Dombivli Municipal Corporation"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "KDMC / NRV / CC / KV / 114"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1720423151236_Agreement.pdf",
    "path": "cases/6687c7f8194f4629de0a8a65/document_1720423151236_Agreement.pdf",
    "id": "456260",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Mon Jul 08 2024 12:49:11 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009746",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "902386",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 05 2024 15:46:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Manesh Ranapratap Deshmukh & Mrs. Priti Manesh Deshmukh ",
```

```
"phone": "7718829353",
"ownershipShare": "",
"email": "",
"id": "945308"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Living Room",
"length": "170.00",
"length1": "170",
"length2": "0",
"width": "1.00",
"width1": "1",
"width2": "0",
"totalArea": "170.00",
"images": [],
"finalArea": "170.00",
"extraAreas": []
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Kitchen",
"length": "69.00",
"length1": "69",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "69.00",
"images": [],
"extraAreas": [
{
"measurementType": {
"value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "_id": "668b9662bf95d302cfae5266",
  "name": "Extra ",
  "extraAreaType": "Add",
  "length": "47.00",
  "length1": "47",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "47.00"
}
],
"finalArea": "116"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "113.00",
  "length1": "29",
  "length2": "0",
  "width": "1.00",
  "width1": "1",
  "width2": "0",
  "totalArea": "29.00",
  "images": [],
  "finalArea": "29.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "17.00",
  "length1": "17",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
```

```
"width2": "00",
"totalArea": "17.00",
"images": [],
"extraAreas": [],
"finalArea": "17.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "113.00",
  "length1": "113",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "113.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "113.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "100.00",
  "length1": "100",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "100.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "6",
  "name": "Toilet",
  "length": "31.00",
  "length1": "31",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "31.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    },
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    },
    "id": "0",
    "length": "38.00",
    "length1": "38",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "38.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "38",
    "percentageBeforeTotal": "38.00",
    "percentage": "100"
  },
  {
    "toBeAdded": {
      "label": "Carpet",
```



```
"value": "Carpet"
},
"name": {
  "label": "Dry Balcony Area",
  "value": "Dry_Balcony_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length": "27.00",
"length1": "27",
"length2": "00",
"width": "1.00",
"width1": "1",
"width2": "00",
"totalArea": "27.00",
"images": [],
"extraAreas": [],
"finalArea": "27",
"percentageBeforeTotal": "27.00",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Terrace Area",
    "value": "Terrace_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "length": "53.00",
  "length1": "53",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "53.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "53",
"percentageBeforeTotal": "53.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "584834",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "685",
"squareMeterArea": "63.64",
"docFinalBuiltUp": "822",
"docFinalBuiltUpSquareMeter": "76.368",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "612.00",
"squareMeterArea": "56.86",
"expectedRate": "8986.93",
"percentage": ""
},
"builtUpArea": {
"area": "734.40",
"squareMeterArea": "68.23",
"expectedRate": "7489.11",
"percentage": "20"
},
"saleableArea": {
"area": "",
```

```
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "668b8072a5c60c02d3494fc2",
"property": "Regency Sarvam, Titwala",
"area": "612",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Dwello.com",
"expectedPrice": "5500000",
"expectedRate": "8986.93",
"builtUpExpectedRate": "7489.11",
"image": "cases/6687c7f8194f4629de0a8a65/
indicator_1720417342255_Image.png",
"squareMeter": "56.86",
"id": "233686"
},
{
"carpetArea": {
"area": "492.00",
"squareMeterArea": "45.71",
"expectedRate": "7926.83",
"percentage": ""
},
"builtUpArea": {
"area": "590.40",
"squareMeterArea": "54.85",
"expectedRate": "6605.69",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "668b8072a5c60c02d3494fc3",
"property": "Regency Sarvam, Titwala",
"area": "492",
"builtUpPercentage": "20",
```

```
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "10",
"source": "https://www.99acres.com/",
"expectedPrice": "3900000",
"expectedRate": "7926.83",
"builtUpExpectedRate": "6605.69",
"image": "cases/6687c7f8194f4629de0a8a65/
indicator_1720417454386_Image.png",
"squareMeter": "45.71",
"id": "138447"
},
{
  "carpetArea": {
    "area": "439.00",
    "squareMeterArea": "40.78",
    "expectedRate": "7972.67",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "526.80",
    "squareMeterArea": "48.94",
    "expectedRate": "6643.89",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "668b8072a5c60c02d3494fc4",
  "property": "Regency Sarvam, Titwala",
  "area": "439",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "8",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3500000",
  "expectedRate": "7972.67",
  "builtUpExpectedRate": "6643.89",
  "image": "cases/6687c7f8194f4629de0a8a65/
indicator_1720417487760_Image.png",
```

```
"squareMeter": "40.78",
"id": "832018"
},
{
  "carpetArea": {
    "area": "445.00",
    "squareMeterArea": "41.34",
    "expectedRate": "8089.89",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "534.00",
    "squareMeterArea": "49.61",
    "expectedRate": "6741.57",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "668b8072a5c60c02d3494fc5",
  "property": "Regency Sarvam, Titwala",
  "area": "445",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4",
  "source": "magic_bricks",
  "expectedPrice": "3600000",
  "expectedRate": "8089.89",
  "builtUpExpectedRate": "6741.57",
  "image": "cases/6687c7f8194f4629de0a8a65/
indicator_1720417667367_Image.png",
  "squareMeter": "41.34",
  "id": "670269"
},
{
  "carpetArea": {
    "area": "628.00",
    "squareMeterArea": "58.34",
    "expectedRate": "7882.17",
    "percentage": ""
  },
```

```
    },
    "builtUpArea": {
      "area": "753.60",
      "squareMeterArea": "70.01",
      "expectedRate": "6568.47",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printInReport": true,
    "_id": "668b8072a5c60c02d3494fc6",
    "property": "Regency Sarvam, Titwala",
    "area": "628",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "8",
    "source": "Index_no.2",
    "expectedPrice": "4950000",
    "expectedRate": "7882.17",
    "builtUpExpectedRate": "6568.47",
    "image": "cases/6687c7f8194f4629de0a8a65/
indicator_1720418326727_Image.png",
    "squareMeter": "58.34",
    "id": "672278"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33e8",
    "name": "externalImg_1720258226852_1720258099489_image_0.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externalImg_1720258226852_1720258099489_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33ea",
```

```
    "name": "externallmg_1720258228575_1720258099489_image_2.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258228575_1720258099489_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33eb",
    "name": "externallmg_1720258229537_1720258099489_image_3.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258229537_1720258099489_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33ec",
    "name": "externallmg_1720258229763_1720258099489_image_4.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258229763_1720258099489_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33ed",
    "name": "externallmg_1720258230062_1720258099489_image_5.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258230062_1720258099489_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33ee",
    "name": "externallmg_1720258230517_1720258099489_image_6.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258230517_1720258099489_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33ef",
    "name": "externallmg_1720258230897_1720258099489_image_7.jpeg",
```

```
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258230897_1720258099489_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33f0",
    "name": "externallmg_1720258231237_1720258099489_image_8.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258231237_1720258099489_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33f1",
    "name": "externallmg_1720258231647_1720258099489_image_9.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258231647_1720258099489_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33f2",
    "name": "externallmg_1720258231982_1720258099489_image_10.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258231982_1720258099489_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33f3",
    "name": "externallmg_1720258232137_1720258099489_image_11.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258232137_1720258099489_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66890eb9a403df7f574f33f4",
    "name": "externallmg_1720258232528_1720258099489_image_12.jpeg",
    "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258232528_1720258099489_image_12.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66890eb9a403df7f574f33f5",
  "name": "externallmg_1720258232897_1720258099489_image_13.jpeg",
  "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258232897_1720258099489_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66890e807053ac2959a2134e",
  "name": "externallmg_1720258172763_1720258050383_image_0.jpeg",
  "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258172763_1720258050383_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66890e807053ac2959a2134f",
  "name": "externallmg_1720258173158_1720258050384_image_1.jpeg",
  "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258173158_1720258050384_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66890e807053ac2959a21350",
  "name": "externallmg_1720258173688_1720258050384_image_2.jpeg",
  "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258173688_1720258050384_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66890e807053ac2959a21351",
  "name": "externallmg_1720258174707_1720258050384_image_3.jpeg",
  "path": "cases/6687c7f8194f4629de0a8a65/
externallmg_1720258174707_1720258050384_image_3.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66890e807053ac2959a21352",
      "name": "externalImg_1720258174714_1720258050384_image_4.jpeg",
      "path": "cases/6687c7f8194f4629de0a8a65/
externalImg_1720258174714_1720258050384_image_4.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66890e807053ac2959a21353",
      "name": "externalImg_1720258175437_1720258050384_image_5.jpeg",
      "path": "cases/6687c7f8194f4629de0a8a65/
externalImg_1720258175437_1720258050384_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "66890e807053ac2959a21354",
      "name": "externalImg_1720258175958_1720258050384_image_6.jpeg",
      "path": "cases/6687c7f8194f4629de0a8a65/
externalImg_1720258175958_1720258050384_image_6.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [
    {
      "originalname": "1720174121221_1709206285749_Calculation.xlsx",
      "filename": "1720418458228_1720174121221_1709206285749_Calculation.xlsx",
      "path": "cases/6687c7f8194f4629de0a8a65/processingDocuments/1720418458228_1720174121221_1709206285749_Calculation.xlsx",
      "size": "1810817",
      "createdAt": "Mon Jul 08 2024 11:30:59 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f915d3f3dd69653a592199"
    },
    {
      "originalname": "1.pdf",
      "filename": "1720418471487_1.pdf",
      "path": "cases/6687c7f8194f4629de0a8a65/
processingDocuments/1720418471487_1.pdf",
      "size": "189654",
    }
  ]
}
```

```
"createdAt": "Mon Jul 08 2024 11:31:11 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "freesearchigrservice.maharashtra.gov.in...taHTMLReportSuchiKra
mank2_RegLive.pdf",
  "filename": "1720418471500_freesearchigrservicemaharashtrgovintaHTMLReport
SuchiKramank2_RegLive.pdf",
  "path": "cases/6687c7f8194f4629de0a8a65/processingDocuments/1720418471500
_freesearchigrservicemaharashtrgovintaHTMLReportSuchiKramank2_RegLive.pdf",
  "size": "166594",
  "createdAt": "Mon Jul 08 2024 11:31:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-05T10:16:24.347Z",
"updatedAt": "2024-07-08T10:15:33.320Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 305, 3rd Floor, Building No 17, Regency Sarvam
Building No. 17 Co-Op. Hsg. Soc. Ltd., Village - Manda, Titwala (East), Taluka - Kalyan ,
District - Thane , PIN - 421 605, State - Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Manesh Ranapratap Deshmukh \n",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"siteVisitContactNo": "7718829353",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
```

```

"finalValuationAreaString": "Carpet Area in Sq. Ft. = 685.00",
"flatRate": "8500",
"landOtherRate": "6000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "576.00",
"extendOfSiteRemark": "",
"finalBuiltupArea": "763.40",
"finalCarpetArea": "694.00",
"finalSalableArea": "839.74",
"otherCarpetTotal": "118.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 576.00\nBalcony Area in Sq. Ft.
= 38.00\nDry Balcony Area in Sq. Ft. = 27.00\nTerrace Area in Sq. Ft. = 53.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "118.00",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

Name	Length	Width	Total
Composition :			

Living Room	170'0"	1'0"	170.00
Kitchen	69'00"	1'00"	69.00
Toilet	29'0"	1'0"	29.00
Passage	17'00"	1'00"	17.00
Bedroom	113'00"	1'00"	113.00
Bedroom	100'00"	1'00"	100.00
Toilet	31'00"	1'00"	31.00
Other Composition :			
Balcony Area	38'00"	1'00"	38.00
Dry Balcony Area	27'00"	1'00"	27.00
Terrace Area	53'00"	1'00"	53.00