

```
{
  "typeOfReport": {
    "label": "Row House",
    "value": "Row_House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "650045afa8e9b70221e079ee"
    },
    "firstName": "Gaurishankar",
    "type": "CREDITOFFICER",
    "_id": "650045afa8e9b70221e079f0",
    "lastName": "Sir",
    "mobileNo": "7709049947",
    "workMobileNo": "7709049947",
    "email": "sbi.10376@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3500000",
    "discussWithPerson": "Gaurishankar",
    "expectedFees": 1750,
    "quotedAmount": "1770"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "650045afa8e9b70221e079ee",
  "name": "MERI Branch",
  "branchCode": "10376",
  "mobileNo": "2530294",
  "alternateMobileNo": "",
  "email": "sbi.10376@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Maharashtra Eng. Research Institute Branch\nDindori Road, MERI,
Nashik, Maharashtra,\nNashik - 422004, State - Maharashtra, Country - India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
```

```
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
```

```
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "20.054166674571803",
  "longitude": "73.80305436745901"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.80305436745901,
    20.054166674571803
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "8/07/2024 01:55 pm"
    }
  ]
},
"visitedDate": []
},
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mhasrul ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Lower Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
```

```
"name": "District",
"key": "district",
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "25/1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Krushnakunj Row Bungalow",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Renuka Nagar, Dindori Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opposite Renuka Nagar Udyan , ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
```

```
"key": "newSurveyNumber",
"value": "247",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```



```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422004",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
}
```

```
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6688cee7194f4629de0ac17e",
```



```
"ownerName": "Kavita bhaurao Deshmukh",
"ownerPhoneNo": "7507144610",
"appAddress": "Bungalow No 01 krushnkucha bungalow Mhasarul ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6688cee7194f4629de0ac17e/
document_1720241813407_1720241690040_null4.pdf",
    "fileName": "document_1720241813407_1720241690040_null4.pdf",
    "id": "291873",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Sat Jul 06 2024 10:28:15 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Approved Building Plan",
      "value": "60ae1277aa6d152c1801b3cc"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6688cee7194f4629de0ac17e/document_1720241856370_17202417
34379_1668186182_NMCB2283700_R0pdf_2_38DSE_SignpdfSign.pdf",
    "fileName": "document_1720241856370_1720241734379_1668186182_NMCB2283
700_R0pdf_2_38DSE_SignpdfSign.pdf",
    "id": "227699",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Sat Jul 06 2024 10:28:15 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Commencement Certificate",
      "value": "60ae1247aa6d152c1801b2ea"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6688cee7194f4629de0ac17e/
document_1720241876195_1720241753281_COMMECEMENT__25_1.pdf",
    "fileName":
"document_1720241876195_1720241753281_COMMECEMENT__25_1.pdf",
    "id": "615808",
```

```
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Sat Jul 06 2024 10:28:15 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009761",
"createdBy": "636a29b64d42487767af43ea",
"caseHistory": [
  {
    "id": "465647",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jul 06 2024 10:28:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Kavita bhaurao Deshmukh",
    "phone": "7507144610",
    "ownershipShare": "",
    "email": "",
    "id": "493301"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9360c",
    "name":
"externallmg_1720427551233_WhatsApp_Image_20240705_at_155540.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551233_WhatsApp_Image_20240705_at_155540.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9360d",
```

```
"name":
"externallmg_1720427551310_WhatsApp_Image_20240705_at_155541_1.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551310_WhatsApp_Image_20240705_at_155541_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d9360e",
  "name":
"externallmg_1720427551326_WhatsApp_Image_20240705_at_155541.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551326_WhatsApp_Image_20240705_at_155541.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d9360f",
  "name":
"externallmg_1720427551405_WhatsApp_Image_20240705_at_155542.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551405_WhatsApp_Image_20240705_at_155542.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93610",
  "name":
"externallmg_1720427551437_WhatsApp_Image_20240705_at_155543.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551437_WhatsApp_Image_20240705_at_155543.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93611",
  "name":
"externallmg_1720427551562_WhatsApp_Image_20240705_at_155544.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551562_WhatsApp_Image_20240705_at_155544.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93612",
  "name":
"externallmg_1720427551687_WhatsApp_Image_20240705_at_155546_1.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551687_WhatsApp_Image_20240705_at_155546_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93613",
  "name":
"externallmg_1720427551731_WhatsApp_Image_20240705_at_155546_2.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551731_WhatsApp_Image_20240705_at_155546_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93614",
  "name":
"externallmg_1720427551841_WhatsApp_Image_20240705_at_155546.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551841_WhatsApp_Image_20240705_at_155546.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93615",
  "name":
"externallmg_1720427551934_WhatsApp_Image_20240705_at_155547.jpeg",
  "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551934_WhatsApp_Image_20240705_at_155547.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668ba421e61b5802e8d93616",
  "name":
"externallmg_1720427551966_WhatsApp_Image_20240705_at_155548_1.jpeg",
```

```
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427551966_WhatsApp_Image_20240705_at_155548_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d93617",
    "name":
"externallmg_1720427552012_WhatsApp_Image_20240705_at_155548.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552012_WhatsApp_Image_20240705_at_155548.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d93618",
    "name":
"externallmg_1720427552076_WhatsApp_Image_20240705_at_155550.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552076_WhatsApp_Image_20240705_at_155550.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d93619",
    "name":
"externallmg_1720427552188_WhatsApp_Image_20240705_at_155551.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552188_WhatsApp_Image_20240705_at_155551.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9361a",
    "name":
"externallmg_1720427552279_WhatsApp_Image_20240705_at_155552.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552279_WhatsApp_Image_20240705_at_155552.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "668ba421e61b5802e8d9361b",
    "name":
"externallmg_1720427552355_WhatsApp_Image_20240705_at_155553_1.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552355_WhatsApp_Image_20240705_at_155553_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9361c",
    "name":
"externallmg_1720427552449_WhatsApp_Image_20240705_at_155553.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552449_WhatsApp_Image_20240705_at_155553.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9361d",
    "name":
"externallmg_1720427552510_WhatsApp_Image_20240705_at_155555.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552510_WhatsApp_Image_20240705_at_155555.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9361e",
    "name":
"externallmg_1720427552589_WhatsApp_Image_20240705_at_155556.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552589_WhatsApp_Image_20240705_at_155556.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba421e61b5802e8d9361f",
    "name":
"externallmg_1720427552680_WhatsApp_Image_20240705_at_155557_1.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427552680_WhatsApp_Image_20240705_at_155557_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba42aa5c60c02d34986ba",
    "name":
"externallmg_1720427562203_WhatsApp_Image_20240705_at_155557_2.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427562203_WhatsApp_Image_20240705_at_155557_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668ba42aa5c60c02d34986bb",
    "name":
"externallmg_1720427562339_WhatsApp_Image_20240705_at_155557.jpeg",
    "path": "cases/6688cee7194f4629de0ac17e/
externallmg_1720427562339_WhatsApp_Image_20240705_at_155557.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-06T04:58:15.706Z",
"updatedAt": "2024-07-08T08:32:42.696Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Row House No. 1, Lower Ground Floor, Krushnakunj Row
Bungalow, Opposite Renuka Nagar Udyan , , Plot No. 25/1, New/Current Survey No.
247, Renuka Nagar, Dindori Link Road, Village - Mhasrul , Taluka - nashik, District -
Nashik, Nashik, 422004",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Kavita bhaurao Deshmukh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "7507144610"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			