

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Rajesh",
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmecbhy@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 1500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
```

```
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "_id": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg",
  "firstName": "Nitesh",
  "lastName": "Khedekar",
  "shortName": "NK",
  "email": "nitesh.khedekar@vastukala.org",
  "designation": "",
  "mobileNo": "8369040652",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.448756904092217",
  "longitude": "72.79417076933076"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.79417076933076,
19.448756904092217
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "9/07/2024 05:15 pm"
    },
    {
      "dateTime": "9/07/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-10",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bolinj",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": true,
"name": "Taluka",
"key": "taluka",
"value": "Vasai",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chawre Garden Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```



```
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "178, H. No. 7A & 8B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```

```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 303",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
```

```
"value": "Cement_Plastering+_POP_Finish",
"label": "Cement Plastering + POP Finish"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Semi_Urban",
"label": "Semi Urban"
},
"townplanApprovedByList": {
"value": "Vasai_Virar_City_Municipal_Corporation",
"label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Durva Apartment",
"west": "Chaware One",
"south": "Open Plot",
"east": "Akash Apartment"
},
"asPerDocumentAgreement": {
"north": "Information not available",
"west": "Information not available",
"south": "Information not available",
"east": "Information not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
```

```
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "15",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "7080",
  "depreciatedBuildingRate": "2380"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "49300",
  "landRate": "9410",
```

```
"igrImage": "cases/668d1ac2d9bf3d181108db1f/igr_1720699705924_Image.png",
"squareMeterGuideLineRate": "49300.00",
"squareFeetGuideLineRate": "4580.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "90",
  "rate": "4210.00",
  "squareFeetGuideLineRate": "4210.00",
  "squareMeterGuideLineRate": "45311.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
```

```
"label": "R.C.C. slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Covered / Open Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2014",
  "fullDate": "1/1/2014"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
```

```
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
}
```



```
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "50",
"ageOfBuilding": "10",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "469.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/668d1ac2d9bf3d181108db1f/
routeMap_1720602110056_Image.png",
    "routeLat": "19.448553",
    "routeLng": "72.794003",
    "stationName": "Virar",
    "routeDistance": "2.4 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
}
```

```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "gdd6g6",
    "name": "gdd6g6",
    "image": "cases/668d1ac2d9bf3d181108db1f/
routeMap_1720601972942_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
```

```
"totalOthersRate": "0",
"finalTotal": "2768280.00",
"finalValue": "2768280.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Jul 12 2024 12:55:45 GMT+0530 (India Standard Time)",
  "number": "2307192",
  "dayCount": "9",
  "monthCount": "196",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "1974911.00",
  "selectedBuildUpValue": "469.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "668e47431f0c1619a680c77a",
      "name": "externalImg_1720600387324_externalImg_1720591643775_WhatsApp_I
mage_20240710_at_112404_1.jpeg",
      "path": "cases/668d1ac2d9bf3d181108db1f/externalImg_1720600387324_external
Img_1720591643775_WhatsApp_Image_20240710_at_112404_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "668e47431f0c1619a680c77d",
      "name": "externalImg_1720600387337_externalImg_1720591643785_WhatsApp_I
mage_20240710_at_112405.jpeg",
      "path": "cases/668d1ac2d9bf3d181108db1f/externalImg_1720600387337_external
Img_1720591643785_WhatsApp_Image_20240710_at_112405.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "668e47431f0c1619a680c77b",
      "name": "externalImg_1720600387329_externalImg_1720591643779_WhatsApp_I
mage_20240710_at_112404.jpeg",
      "path": "cases/668d1ac2d9bf3d181108db1f/externalImg_1720600387329_external
Img_1720591643779_WhatsApp_Image_20240710_at_112404.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [
    {
      "status": false,
```

```
    "_id": "668e475058650519d26bfae8",
    "name": "externalimg_1720600399535_externalimg_1720591643979_WhatsApp_I
mage_20240710_at_112410_1.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externalimg_1720600399535_external
img_1720591643979_WhatsApp_Image_20240710_at_112410_1.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "668e475058650519d26bfae3",
    "name": "Living Room",
    "path": "cases/668d1ac2d9bf3d181108db1f/externalimg_1720600399515_external
img_1720591643968_WhatsApp_Image_20240710_at_112408_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668e47431f0c1619a680c780",
    "name": "Living Room",
    "path": "cases/668d1ac2d9bf3d181108db1f/externalimg_1720600387349_external
img_1720591643963_WhatsApp_Image_20240710_at_112407.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668e56541f0c1619a680d662",
    "name": "Living Room",
    "path": "cases/668d1ac2d9bf3d181108db1f/externalimg_1720604243614_external
img_1720591643792_WhatsApp_Image_20240710_at_112406.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668e56541f0c1619a680d660",
    "name": "Living Room",
    "path": "cases/668d1ac2d9bf3d181108db1f/externalimg_1720604243605_external
img_1720591643782_WhatsApp_Image_20240710_at_112405_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "668e56541f0c1619a680d665",
    "name": "Living Room",
    "path": "cases/668d1ac2d9bf3d181108db1f/externalimg_1720604243623_external
```

```
Img_1720591643970_WhatsApp_Image_20240710_at_112408_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "668e56541f0c1619a680d666",
  "name": "Living Room",
  "path": "cases/668d1ac2d9bf3d181108db1f/externalImg_1720604243627_external
Img_1720591643972_WhatsApp_Image_20240710_at_112408.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6908.00",
    "max": "7790.00"
  },
  "builtUpRateRange": {
    "min": "5754.00",
    "max": "6492.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "390.92",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "668d1ac2d9bf3d181108db1f",
"ownerName": "Prakash Ratna Bhurkud",
"ownerPhoneNo": "9891057207",
"appAddress": "FLAT NO 101 A WING 1 ST FLOOR CHAWARE GARDEN BOLINJ
VIRAR WEST PALGHAR ",
"remark": "ANY QUERY SANJIV DAYAL 8446132065",
"documents": [
  {
    "documentType": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    },
    "inputs": {
      "documentDate": "22/03/2013",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Welldon Constructions ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Prakash Ratna Bhurkud & Meena Prakash Bhurkud"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "817909",
    "path": "cases/668d1ac2d9bf3d181108db1f/document_1720523078046_172052295
9291_PRAKASH_BHURKUD__AGREEMENT.pdf",
    "fileName": "document_1720523078046_1720522959291_PRAKASH_BHURKUD_
_AGREEMENT.pdf"
  },
  {
    "documentType": {
      "label": "Occupancy Certificate",
      "value": "60ae124baa6d152c1801b2fd"
    }
  }
]
```

```
},
"inputs": {
  "documentDate": "07/06/2014",
  "nameOfApprovingAuthority": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "VVCMC/TP/OC/VP-0626/49/2014-15"
},
"isHardCopy": false,
"displayStatus": false,
"id": "860222",
"path": "cases/668d1ac2d9bf3d181108db1f/
document_1720523092826_1720522974023_OC_5.pdf",
"fileName": "document_1720523092826_1720522974023_OC_5.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/03/2012",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "VVCMC/TP/OC/VP-0626/2640"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720603631570_CC.pdf",
  "path": "cases/668d1ac2d9bf3d181108db1f/document_1720603631570_CC.pdf",
  "id": "786045",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Wed Jul 10 2024 14:57:11 GMT+0530 (India Standard Time)"
}
],
```

```
"caseNumber": "009814",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "693641",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 09 2024 16:40:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Prakash Ratna Bhurkud",
    "phone": "9891057207",
    "ownershipShare": "",
    "email": "",
    "id": "412756"
  },
  {
    "name": "Meena Prakash Bhurkud",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "962448"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Living Room",
    "length": "8.92",
    "length1": "8",
    "length2": "11",
    "width": "15.00",
    "width1": "15",
    "width2": "00",
    "totalArea": "133.75",
    "images": [],
    "finalArea": "133.75",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "8.50",
  "width1": "8",
  "width2": "6",
  "totalArea": "56.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "56.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "12.25",
  "width1": "12",
  "width2": "3",
  "totalArea": "112.29",
  "images": [],
  "extraAreas": [],
  "finalArea": "112.29"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
```

```
"length2": "9",
"width": "5.83",
"width1": "5",
"width2": "10",
"totalArea": "21.87",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "668e5237ea3d3719a8b70afa",
    "name": "Toilet",
    "extraAreaType": "Add",
    "length": "1.25",
    "length1": "1",
    "length2": "3",
    "width": "2.25",
    "width1": "2",
    "width2": "3",
    "totalArea": "2.81"
  }
],
"finalArea": "24.68"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "28.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.12"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "14.51",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.51"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "1.42",
  "length1": "1",
  "length2": "5",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "12.40",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.4",
  "percentageBeforeTotal": "12.40",
  "percentage": "100"
},
{
```



```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "label": "Flowered Area",
  "value": "Flowered_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length": "1.42",
"length1": "1",
"length2": "5",
"width": "6.00",
"width1": "6",
"width2": "00",
"totalArea": "8.50",
"images": [],
"extraAreas": [],
"finalArea": "8.5",
"percentageBeforeTotal": "8.50",
"percentage": "100"
},
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae124faa6d152c1801b30f",
      "label": "Article of Agreement"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "188855",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "550",
    "squareMeterArea": "51.1",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
```

```
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "360.05",
"squareMeterArea": "33.45",
"expectedRate": "7585.75",
"percentage": ""
},
"builtUpArea": {
"area": "432.06",
"squareMeterArea": "40.14",
"expectedRate": "6321.46",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "668fcc12703f2e4ba733e763",
"property": "Chaware One, Bolinj Village, Virar West",
"area": "360.05",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "2731250.00",
"expectedRate": "7585.75",
"builtUpExpectedRate": "6321.46",
"image": "cases/668d1ac2d9bf3d181108db1f/
indicator_1720699442732_Image.png",
"squareMeter": "33.45",
"id": "307845"
},
{
"carpetArea": {
"area": "475.00",
```

```
"squareMeterArea": "44.13",
"expectedRate": "7789.47",
"percentage": ""
},
"builtUpArea": {
  "area": "570.00",
  "squareMeterArea": "52.95",
  "expectedRate": "6491.23",
  "percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "668fcc12703f2e4ba733e764",
"property": "1 BHK Flat In Gokul Samarpan-1 Chs For Sale In Virar West",
"area": "570.00",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "3700000.00",
"expectedRate": "7789.47",
"builtUpExpectedRate": "3700000.00",
"image": "cases/668d1ac2d9bf3d181108db1f/
indicator_1720699514467_Image.png",
"squareMeter": "52.95",
"id": "292839"
},
{
  "carpetArea": {
    "area": "304.00",
    "squareMeterArea": "28.24",
    "expectedRate": "6907.89",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "365.00",
    "squareMeterArea": "33.91",
    "expectedRate": "5753.42",
    "percentage": ""
  }
}
```

```
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "668fcc12703f2e4ba733e765",
"property": "1 RK Flat In Jesal Homes 2 For Sale In Virar West",
"area": "365.00",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "2100000.00",
"expectedRate": "6907.89",
"builtUpExpectedRate": "2100000.00",
"image": "cases/668d1ac2d9bf3d181108db1f/
indicator_1720699602178_Image.png",
"squareMeter": "33.91",
"id": "341137"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e251ca7ea882b0985f79f",
    "name":
"externallmg_1720591643763_WhatsApp_Image_20240710_at_112359.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/
externallmg_1720591643763_WhatsApp_Image_20240710_at_112359.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e251ca7ea882b0985f7a0",
    "name":
"externallmg_1720591643767_WhatsApp_Image_20240710_at_112400_1.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/
externallmg_1720591643767_WhatsApp_Image_20240710_at_112400_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e251ca7ea882b0985f7a1",
    "name":
"externallmg_1720591643773_WhatsApp_Image_20240710_at_112400.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/
externallmg_1720591643773_WhatsApp_Image_20240710_at_112400.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e47431f0c1619a680c77a",
    "name": "externallmg_1720600387324_externallmg_1720591643775_WhatsApp_I
mage_20240710_at_112404_1.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600387324_externall
mg_1720591643775_WhatsApp_Image_20240710_at_112404_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e47431f0c1619a680c77b",
    "name": "externallmg_1720600387329_externallmg_1720591643779_WhatsApp_I
mage_20240710_at_112404.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600387329_externall
mg_1720591643779_WhatsApp_Image_20240710_at_112404.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e47431f0c1619a680c77d",
    "name": "externallmg_1720600387337_externallmg_1720591643785_WhatsApp_I
mage_20240710_at_112405.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600387337_externall
mg_1720591643785_WhatsApp_Image_20240710_at_112405.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e47431f0c1619a680c780",
    "name": "externallmg_1720600387349_externallmg_1720591643963_WhatsApp_I
```

```
mage_20240710_at_112407.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600387349_externallmg_1720591643963_WhatsApp_Image_20240710_at_112407.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668e475058650519d26bfae3",
  "name": "externallmg_1720600399515_externallmg_1720591643968_WhatsApp_Image_20240710_at_112408_1.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600399515_externallmg_1720591643968_WhatsApp_Image_20240710_at_112408_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668e475058650519d26bfae6",
  "name": "externallmg_1720600399526_externallmg_1720591643975_WhatsApp_Image_20240710_at_112409_1.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600399526_externallmg_1720591643975_WhatsApp_Image_20240710_at_112409_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668e475058650519d26bfae8",
  "name": "externallmg_1720600399535_externallmg_1720591643979_WhatsApp_Image_20240710_at_112410_1.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600399535_externallmg_1720591643979_WhatsApp_Image_20240710_at_112410_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668e475058650519d26bfae9",
  "name": "externallmg_1720600399540_externallmg_1720591643982_WhatsApp_Image_20240710_at_112410_2.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600399540_externallmg_1720591643982_WhatsApp_Image_20240710_at_112410_2.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e475058650519d26bfaea",
    "name": "externallmg_1720600399543_externallmg_1720591643985_WhatsApp_I
mage_20240710_at_112410.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720600399543_externall
mg_1720591643985_WhatsApp_Image_20240710_at_112410.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e56541f0c1619a680d660",
    "name": "externallmg_1720604243605_externallmg_1720591643782_WhatsApp_I
mage_20240710_at_112405_1.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720604243605_externall
mg_1720591643782_WhatsApp_Image_20240710_at_112405_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e56541f0c1619a680d661",
    "name": "externallmg_1720604243609_externallmg_1720591643789_WhatsApp_I
mage_20240710_at_112406_1.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720604243609_externall
mg_1720591643789_WhatsApp_Image_20240710_at_112406_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e56541f0c1619a680d662",
    "name": "externallmg_1720604243614_externallmg_1720591643792_WhatsApp_I
mage_20240710_at_112406.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720604243614_externall
mg_1720591643792_WhatsApp_Image_20240710_at_112406.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668e56541f0c1619a680d665",
    "name": "externallmg_1720604243623_externallmg_1720591643970_WhatsApp_I
mage_20240710_at_112408_2.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720604243623_externall
```

```
mg_1720591643970_WhatsApp_Image_20240710_at_112408_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668e56541f0c1619a680d666",
  "name": "externallmg_1720604243627_externallmg_1720591643972_WhatsApp_I
mage_20240710_at_112408.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720604243627_externall
mg_1720591643972_WhatsApp_Image_20240710_at_112408.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668e56541f0c1619a680d667",
  "name": "externallmg_1720604243629_externallmg_1720591643975_WhatsApp_I
mage_20240710_at_112409_1.jpeg",
  "path": "cases/668d1ac2d9bf3d181108db1f/externallmg_1720604243629_externall
mg_1720591643975_WhatsApp_Image_20240710_at_112409_1.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "CC.pdf",
    "filename": "1720765216985_CC.pdf",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720765216985_CC.pdf",
    "size": "223366",
    "createdAt": "Fri Jul 12 2024 11:50:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Google Location.jpeg",
    "filename": "1720765217025_Google_Location.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720765217025_Google_Location.jpeg",
    "size": "135948",
    "createdAt": "Fri Jul 12 2024 11:50:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "OC.pdf",
```



```
    "filename": "1720765217062_OC.pdf",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720765217062_OC.pdf",
    "size": "421989",
    "createdAt": "Fri Jul 12 2024 11:50:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2013.pdf",
    "filename": "1720765217076_Sale_Deed__2013.pdf",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720765217076_Sale_Deed__2013.pdf",
    "size": "2723164",
    "createdAt": "Fri Jul 12 2024 11:50:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1720765217125_Site_Details.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720765217125_Site_Details.jpeg",
    "size": "120727",
    "createdAt": "Fri Jul 12 2024 11:50:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sketch.jpeg",
    "filename": "1720765217129_Sketch.jpeg",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720765217129_Sketch.jpeg",
    "size": "93503",
    "createdAt": "Fri Jul 12 2024 11:50:17 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "SBI - Prakash Ratna Bhurkud.pdf",
    "filename": "1720769412410_SBI__Prakash_Ratna_Bhurkud.pdf",
    "path": "cases/668d1ac2d9bf3d181108db1f/
processingDocuments/1720769412410_SBI__Prakash_Ratna_Bhurkud.pdf",
    "size": "6251346",
    "createdAt": "Fri Jul 12 2024 13:00:12 GMT+0530 (India Standard Time)",
    "uploadedBy": "60092304a16fab0f2af9b0c2"
  }
],
"leadRemarks": [],
"audioRemarks": [],
```

```
"remarks": [],
"createdAt": "2024-07-09T11:10:58.688Z",
"updatedAt": "2024-07-12T07:30:30.987Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 101, 1st Floor, Wing - A, Chawre Garden Co-op.
Hsg. Soc. Ltd., Village - Bolinj, Virar (West), Taluka - Vasai, District - Palghar, PIN - 401
303, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mrs. Meena Prakash Bhurkud",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9891057207",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "370.02000000000004",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "20.90",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "20.90",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "469.10",
"finalCarpetArea": "390.92",
"finalSalableArea": "469.10",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "<br />",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 370.02\nFlowerbed Area in Sq.
Ft. = 20.90\n<br />",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "actual site measurement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 390.92",
"buildingServicesRate": "2800",
```

```

"flatRate": "7500",
"landOtherRate": "4700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Fri Jul 12 2024 11:17:14 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-07-10",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}

```

Name	Length	Width	Total
Composition :			
Living Room	8'11"	15'00"	133.75
Kitchen	6'8"	8'6"	56.67
Bedroom	9'2"	12'3"	112.29
Toilet	3'9"	5'10"	21.87
Toilet	6'9"	4'2"	28.12
Passage	3'2"	4'7"	14.51
Other Composition :			
Flowered Area	1'5"	8'9"	12.40

Flowered Area

1'5"

6'00"

8.50

---