

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "668f8858703f2e4ba7338a33",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Rahul Vijay And Shreya Vijay",
"displayName": "Rahul Vijay And Shreya Vijay",
"initial": "R"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "MAKER + RATE VERIFIER + CHECKER",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
```

```
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
```

```
"value": "PRIVATE_CLIENT",
"label": "Private Clients"
},
"location": {
"latitude": "19.200224240517908",
"longitude": "72.868882362668"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [
{
"dateTime": "11/07/2024 12:51 pm"
},
{
"dateTime": "11/07/2024 12:00 am"
}
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
"status": true,
"name": "Country",
"key": "country",
```

```
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Akurli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "21",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
```

```
"status": false,
"name": "Taluka",
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Oasis Tower 2",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off Akurli Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
```

```
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
```

```
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2106",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
}
```



```
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
```

```
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",

```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "668f8858703f2e4ba7338a39",
"ownerName": "Rahul Vijay And Shreya Vijay",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9821611086",
"contactPersonName": "Ishwarn",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Rahul Vijay And Shreya Vijay",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "786925"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Agent",
"fullAddress": "Residential Flat No. 2106, 21st Floor, Oasis Tower 2, Off Akurli Road,
Village - Akurli, Kandivali East, Mumbai, State - Maharashtra, India",
```



```
"remark": "Valuation Report for F.Y. 2011-12 (corresponding to A.Y. 2012-13) for Flat No. 2106 on 21st Floor in Tower 2 in Building known as Oasis Acme situated at Village Akurli, Near Mahindra & Mahindra Gate No. 1, Kandivali East, Mumbai - 400101",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1720682402861_Annex_5_Project_Delay_Letter_from_Acme.pdf",
    "path": "cases/668f8858703f2e4ba7338a39/
document_1720682402861_Annex_5_Project_Delay_Letter_from_Acme.pdf",
    "id": "509504",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1720682464836_Annex_6_Agreement_for_Sale.pdf",
    "path": "cases/668f8858703f2e4ba7338a39/
document_1720682464836_Annex_6_Agreement_for_Sale.pdf",
    "id": "327077",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1720682519630_BGRPS9767E_Show_Cause_Notice_1050
4742101_07032023.pdf",
    "path": "cases/668f8858703f2e4ba7338a39/document_1720682519630_BGRPS97
67E_Show_Cause_Notice_10504742101_07032023.pdf",
    "id": "751702",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
```

```
"createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720682532112_Annex_7_Ready_Recknoner_Village_Aak
urli_along_with_Neighbouring_Building_Index_2_Copies.pdf",
  "path": "cases/668f8858703f2e4ba7338a39/document_1720682532112_Annex_7_
Ready_Recknoner_Village_Aakurli_along_with_Neighbouring_Building_Index_2_Copie
s.pdf",
  "id": "630937",
  "uploadedBy": "6006d4ce5080a310ac1fdfc2",
  "createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720682551544_Annex_4_Copy_of_Earnest_Money_Depo
sit_cum_Allottment_Letter.pdf",
  "path": "cases/668f8858703f2e4ba7338a39/document_1720682551544_Annex_4_
Copy_of_Earnest_Money_Deposit_cum_Allottment_Letter.pdf",
  "id": "402299",
  "uploadedBy": "6006d4ce5080a310ac1fdfc2",
  "createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1720682569689_Annex_5_Project_Delay_Letter_from_Acme.pdf",
  "path": "cases/668f8858703f2e4ba7338a39/
document_1720682569689_Annex_5_Project_Delay_Letter_from_Acme.pdf",
  "id": "792343",
  "uploadedBy": "6006d4ce5080a310ac1fdfc2",
```

```
"createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720682581956_Annex_6_Agreement_for_Sale.pdf",
  "path": "cases/668f8858703f2e4ba7338a39/
document_1720682581956_Annex_6_Agreement_for_Sale.pdf",
  "id": "234121",
  "uploadedBy": "6006d4ce5080a310ac1fdfc2",
  "createdAt": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "009861",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "604850",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Thu Jul 11 2024 12:53:04 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "6690b7c20f434e4ba8550f1a",
    "name": "externallmg_1720760251339_1720760127203_image_0.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760251339_1720760127203_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f1b",
    "name": "externallmg_1720760251474_1720760127209_image_1.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760251474_1720760127209_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f1c",
    "name": "externallmg_1720760251635_1720760127209_image_2.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760251635_1720760127209_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f1d",
    "name": "externallmg_1720760251882_1720760127209_image_3.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760251882_1720760127209_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f1e",
    "name": "externallmg_1720760252337_1720760127209_image_4.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760252337_1720760127209_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "6690b7c20f434e4ba8550f1f",
    "name": "externallmg_1720760252831_1720760127209_image_5.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760252831_1720760127209_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f20",
    "name": "externallmg_1720760253355_1720760127209_image_6.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760253355_1720760127209_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f21",
    "name": "externallmg_1720760253868_1720760127209_image_7.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760253868_1720760127209_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f22",
    "name": "externallmg_1720760254419_1720760127209_image_8.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760254419_1720760127209_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f23",
    "name": "externallmg_1720760254473_1720760127209_image_9.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760254473_1720760127209_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f24",
```

```
    "name": "externallmg_1720760254616_1720760127209_image_10.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760254616_1720760127209_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f25",
    "name": "externallmg_1720760254945_1720760127209_image_11.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760254945_1720760127209_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f26",
    "name": "externallmg_1720760255021_1720760127210_image_12.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760255021_1720760127210_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f27",
    "name": "externallmg_1720760255402_1720760127210_image_13.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760255402_1720760127210_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f28",
    "name": "externallmg_1720760255799_1720760127210_image_14.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760255799_1720760127210_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f29",
    "name": "externallmg_1720760255931_1720760127210_image_15.jpeg",
```

```
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760255931_1720760127210_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f2a",
    "name": "externallmg_1720760256306_1720760127210_image_16.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760256306_1720760127210_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f2b",
    "name": "externallmg_1720760256709_1720760127210_image_17.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760256709_1720760127210_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f2c",
    "name": "externallmg_1720760257007_1720760127210_image_18.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760257007_1720760127210_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6690b7c20f434e4ba8550f2d",
    "name": "externallmg_1720760257547_1720760127210_image_19.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760257547_1720760127210_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6690b7c80f434e4ba8550f5b",
    "name": "externallmg_1720760262133_1720760144453_image_0.jpeg",
    "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760262133_1720760144453_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6690b7c80f434e4ba8550f5c",
  "name": "externallmg_1720760262307_1720760144453_image_1.jpeg",
  "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760262307_1720760144453_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6690b7c80f434e4ba8550f5d",
  "name": "externallmg_1720760262717_1720760144453_image_2.jpeg",
  "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760262717_1720760144453_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6690b7c80f434e4ba8550f5e",
  "name": "externallmg_1720760262952_1720760144453_image_3.jpeg",
  "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760262952_1720760144453_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6690b7c80f434e4ba8550f5f",
  "name": "externallmg_1720760263353_1720760144453_image_4.jpeg",
  "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760263353_1720760144453_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6690b7c80f434e4ba8550f60",
  "name": "externallmg_1720760263544_1720760144454_image_5.jpeg",
  "path": "cases/668f8858703f2e4ba7338a39/
externallmg_1720760263544_1720760144454_image_5.jpeg",
  "orientation": "portrait"
}
```



```
}  
],  
"externalDocuments": [],  
"processingDocuments": [],  
"leadRemarks": [],  
"audioRemarks": [],  
"remarks": [],  
"createdAt": "2024-07-11T07:23:05.052Z",  
"updatedAt": "2024-07-12T04:57:44.256Z",  
"__v": 0,  
"addressForMap": "",  
"updatedBy": "62691c48afd7d55eddecfda3"  
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			