

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And
Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_
Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Uttam",
    "type": "CREDITOFFICER",
    "_id": "64cb5e480faf29427aca80c8",
    "lastName": "Sanap",
    "mobileNo": "02225009143",
    "workMobileNo": "7028022330",
    "email": "racpc.ghatkopar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
```

```
"discussWithPerson": "Uttam",
"expectedFees": null,
"quotedAmount": "2500"
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
```

```
"_id": "60e03dac6576061dae462469",
"zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "63fc4680ce84bf289ba9c7fc",
    "role": "SITEENGINEER",
    "firstName": "Nikhil ",
    "email": "valtechnical2022@gmail.com",
    "lastName": "Sonawane",
    "mobileNo": "9819470709",
    "designation": "",
    "shortName": "NS",
    "workWithDocumentMaker": "6006d4ce5080a310ac1fd2",
    "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": {
```

```
"type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.161887816338496",
  "longitude": "73.05523368509459"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.05523368509459,
    19.161887816338496
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-23",
      "remark": "NPA account "
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-19",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"schedule": []
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Desai",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Marathon Nextown Complex",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. Kalyan Shil Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A, Opal",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "140, 142/1, 142/3, 220/1B & others ",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 204",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Diva (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"doors": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"windows": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"fittings": {
"value": "External_site_visit_only",
"label": "External site visit only"
},
"finishing": {
"value": "External_site_visit_only",
"label": "External site visit only"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Thane_Municipal_Corporation",
"label": "Thane Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
```

```

    "north": "Wing - B",
    "west": "Marathon Emerald ",
    "south": "Internal Road ",
    "east": "Internal Road "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Staircase ",
      "east": "Marginal Space ",
      "south": "Marginal Space ",
      "west": "Flat No. 602"
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "Internal visit was not allowed at site. As per Sale Plan, 1 Bedroom + Living / Dining + Kitchen + Passage + 2 Toilets + Flower Bed Area. (i.e 1BHK)",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed that the construction is as per sanctioned plan. ",

```

```
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As per request from State Bank of India, RACPC Ghatkopar (West) Branch, our engineer visited the property but internal visit was not allowed hence the report is based on external visit & documents provided by bank to us. ",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "9037.5",
  "depreciatedBuildingRate": "2237.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "46900",
  "landRate": "7400",
  "igrImage": "cases/66976e22fda8892c71fe2181/igr_1724752116558_Image.png",
  "squareMeterGuideLineRate": "49245.00",
  "squareFeetGuideLineRate": "4575.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "93",
  "rate": "4303.00",
  "squareFeetGuideLineRate": "4303.00",
  "squareMeterGuideLineRate": "46316.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "External_Site_Visit_Only",
```

```
"label": "External Site Visit Only"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per TMC norms ",
"tenantName": "",
"maintenanceOfFlat": "External visit done only "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt / Open Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  }
}
```

```
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
}
```

```
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "53",
"ageOfBuilding": "7",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
```



```
"area": "548.40",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66976e22fda8892c71fe2181/
routeMap_1724828283260_Image.png",
    "routeLat": "19.162066",
    "routeLng": "73.054998",
    "stationName": "Diva ",
    "routeDistance": "5.8 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "sal7ld",
      "name": "sal7ld",
      "image": "cases/66976e22fda8892c71fe2181/
routeMap_1724827964567_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
```

```
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4130366.00",
"distressValuePercentage": "70",
"realizableValuePercentage": "85",
"bookValue": "0",
"finalValue": "4130366.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Aug 28 2024 15:11:54 GMT+0530 (India Standard Time)",
  "number": "2307912",
  "dayCount": "9",
  "monthCount": "390",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2359765.00",
  "selectedBuildUpValue": "548.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66c862d5c884d112334f73b3",
      "name": "externalimg_r_1724408529707_1724408519515_image_8.jpg",
      "path": "cases/66976e22fda8892c71fe2181/
externalimg_r_1724408529707_1724408519515_image_8.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
```

```
    "status": false,
    "_id": "66c862d5c884d112334f73b6",
    "name": "externallmg_r_1724408526725_1724408519515_image_5.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408526725_1724408519515_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c862d5c884d112334f73b7",
    "name": "externallmg_r_1724408530596_1724408519515_image_9.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408530596_1724408519515_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c862d5c884d112334f73b8",
    "name": "externallmg_r_1724408531625_1724408519515_image_10.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408531625_1724408519515_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c862d5c884d112334f73b3",
    "name": "externallmg_r_1724408529707_1724408519515_image_8.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408529707_1724408519515_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c862d5c884d112334f73b0",
    "name": "externallmg_r_1724408524765_1724408519515_image_3.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408524765_1724408519515_image_3.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "5736.00",
"max": "9570.00"
},
"builtUpRateRange": {
  "min": "4780.00",
  "max": "7975.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "457.00",
"empanelmentNo": [
  "SME/TCC/2021-22/85/13"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66976e22fda8892c71fe2181",
"ownerName": "Mr. Umashankar Chaturvedi & Mrs. Poonam Umashankar Chaturvedi",
"ownerPhoneNo": "9967373322",
"appAddress": "Flat no. 601, 6th Floor, Building A, Marathon Nextown, Village - Desai,
```

```
Div East",
"remark": "NPA account ",
"documents": [
{
"documentType": {
"value": "60ae1254aa6d152c1801b326",
"label": "Agreement For Sale"
},
"inputs": {
"documentDate": "02/03/2023",
"from": {
"value": "Vendor",
"label": "Vendor"
},
"Vendor": "Mr. Abhoy Vijaykumar Shah & Mrs. Parul Abhoy Shah",
"to": {
"value": "Purchasers",
"label": "Purchasers"
},
"Purchasers": "Mr. Umashankar Chaturvedi & Mrs. Poonam Umashankar
Chaturvedi",
"number": {
"value": "No",
"label": "No"
},
"No": "5334 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "564682",
"path": "cases/66976e22fda8892c71fe2181/
document_1723878952864_UMASHANKAR_CHATURVEDI_AGREEMENT_1.pdf",
"fileName":
"document_1723878952864_UMASHANKAR_CHATURVEDI_AGREEMENT_1.pdf"
},
{
"documentType": {
"value": "60ae124baa6d152c1801b2fd",
"label": "Occupancy Certificate"
},
"inputs": {
"documentDate": "05/05/2017",
"nameOfApprovingAuthority": {
"value": "Thane_Municipal_Corporation",
"label": "Thane Municipal Corporation"
},
},
},
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "S11 / 0014 / 10 / TMC / TDD / OCC / 0356 / 17"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1724761734613_411135.pdf",
"path": "cases/66976e22fda8892c71fe2181/
document_1724761734613_411135.pdf",
"id": "420898",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Aug 27 2024 17:58:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/11/2015",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "S11 / 0014 / 10 / TMC / TDD / 1544 / 15"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1724761816116_427119.pdf",
"path": "cases/66976e22fda8892c71fe2181/
document_1724761816116_427119.pdf",
"id": "230560",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Aug 27 2024 18:00:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009966",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
```

```
"id": "173261",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Wed Jul 17 2024 12:39:22 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Umashankar Chaturvedi & Mrs. Poonam Umashankar Chaturvedi",
"phone": "9967373322",
"ownershipShare": "",
"email": "",
"id": "849500"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
"typeOfDocument": {
"value": "60ae1254aa6d152c1801b326",
"label": "Agreement For Sale"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "42.46",
"totalAreaDocument": "457",
"docBuiltpupPercentage": "20",
"docFinalBUILTUp": "548.40",
"docFinalBUILTUpSquareMeter": "50.95",
"docSaleablePercentage": "0",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "687605"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
```

```
"area": "418.00",
"squareMeterArea": "38.83",
"expectedRate": "9569.38",
"percentage": ""
},
"builtUpArea": {
"area": "501.60",
"squareMeterArea": "46.60",
"expectedRate": "7974.48",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66cda1200f117327db774fb2",
"property": "Flat",
"area": "418",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "4000000",
"expectedRate": "9569.38",
"builtUpExpectedRate": "7974.48",
"image": "cases/66976e22fda8892c71fe2181/
indicator_1724751859853_Image.png",
"squareMeter": "38.83",
"id": "213487"
},
{
"carpetArea": {
"area": "420.00",
"squareMeterArea": "39.02",
"expectedRate": "9523.81",
"percentage": ""
},
"builtUpArea": {
"area": "504.00",
"squareMeterArea": "46.82",
"expectedRate": "7936.51",
```

```
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66cda1200f117327db774fb3",
  "property": "Flat",
  "area": "420",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4000000",
  "expectedRate": "9523.81",
  "builtUpExpectedRate": "7936.51",
  "image": "cases/66976e22fda8892c71fe2181/
indicator_1724751882378_Image.png",
  "squareMeter": "39.02",
  "id": "817750"
},
{
  "carpetArea": {
    "area": "462.00",
    "squareMeterArea": "42.92",
    "expectedRate": "5735.93",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "554.40",
    "squareMeterArea": "51.51",
    "expectedRate": "4779.94",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
```

```
"_id": "66cda1200f117327db774fb4",
"property": "Flat",
"area": "462",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "2650000",
"expectedRate": "5735.93",
"builtUpExpectedRate": "4779.94",
"image": "cases/66976e22fda8892c71fe2181/
indicator_1724751950009_Image.png",
"squareMeter": "42.92",
"id": "673863"
},
{
  "carpetArea": {
    "area": "456.00",
    "squareMeterArea": "42.36",
    "expectedRate": "7785.09",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "547.20",
    "squareMeterArea": "50.84",
    "expectedRate": "6487.57",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66cda1200f117327db774fb5",
  "property": "Flat",
  "area": "456",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
```

```

    "expectedPrice": "3550000",
    "expectedRate": "7785.09",
    "builtUpExpectedRate": "6487.57",
    "image": "cases/66976e22fda8892c71fe2181/
indicator_1724751982732_Image.png",
    "squareMeter": "42.36",
    "id": "145076"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c862d5c884d112334f73ae",
    "name": "externalimg_1724408522625_1724408519515_image_1.png",
    "path": "cases/66976e22fda8892c71fe2181/
externalimg_1724408522625_1724408519515_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c862d5c884d112334f73af",
    "name": "externalimg_r_1724408525852_1724408519515_image_4.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externalimg_r_1724408525852_1724408519515_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c862d5c884d112334f73b0",
    "name": "externalimg_r_1724408524765_1724408519515_image_3.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externalimg_r_1724408524765_1724408519515_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c862d5c884d112334f73b1",
    "name": "externalimg_r_1724408523660_1724408519515_image_2.jpg",
    "path": "cases/66976e22fda8892c71fe2181/
externalimg_r_1724408523660_1724408519515_image_2.jpg",
    "orientation": "portrait"
  },
  },

```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c862d5c884d112334f73b2",
  "name": "externallmg_r_1724408521803_1724408519515_image_0.jpg",
  "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408521803_1724408519515_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c862d5c884d112334f73b3",
  "name": "externallmg_r_1724408529707_1724408519515_image_8.jpg",
  "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408529707_1724408519515_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c862d5c884d112334f73b4",
  "name": "externallmg_r_1724408527459_1724408519515_image_6.jpg",
  "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408527459_1724408519515_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c862d5c884d112334f73b5",
  "name": "externallmg_r_1724408528511_1724408519515_image_7.jpg",
  "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408528511_1724408519515_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c862d5c884d112334f73b6",
  "name": "externallmg_r_1724408526725_1724408519515_image_5.jpg",
  "path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408526725_1724408519515_image_5.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66c862d5c884d112334f73b7",
"name": "externallmg_r_1724408530596_1724408519515_image_9.jpg",
"path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408530596_1724408519515_image_9.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66c862d5c884d112334f73b8",
"name": "externallmg_r_1724408531625_1724408519515_image_10.jpg",
"path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408531625_1724408519515_image_10.jpg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66c86215da840b1214cc00e1",
"name": "externallmg_r_1724408340931_1724408340354_image_0.jpg",
"path": "cases/66976e22fda8892c71fe2181/
externallmg_r_1724408340931_1724408340354_image_0.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "Calculation (2) - Umashankar.xlsx",
"filename": "1724752144096_Calculation_2__Umashankar.xlsx",
"path": "cases/66976e22fda8892c71fe2181/
processingDocuments/1724752144096_Calculation_2__Umashankar.xlsx",
"size": "16107",
"createdAt": "Tue Aug 27 2024 15:19:14 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "igr1.pdf",
"filename": "1724752144097_igr1.pdf",
"path": "cases/66976e22fda8892c71fe2181/
processingDocuments/1724752144097_igr1.pdf",
"size": "154176",
"createdAt": "Tue Aug 27 2024 15:19:14 GMT+0530 (India Standard Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
```

```
    },
    {
      "originalname": "igr2.pdf",
      "filename": "1724752144561_igr2.pdf",
      "path": "cases/66976e22fda8892c71fe2181/
processingDocuments/1724752144561_igr2.pdf",
      "size": "148895",
      "createdAt": "Tue Aug 27 2024 15:19:14 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "reference report.doc",
      "filename": "1724752144622_reference_report.doc",
      "path": "cases/66976e22fda8892c71fe2181/
processingDocuments/1724752144622_reference_report.doc",
      "size": "5524480",
      "createdAt": "Tue Aug 27 2024 15:19:14 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Summary - Umashankar.xlsx",
      "filename": "1724752152611_Summary__Umashankar.xlsx",
      "path": "cases/66976e22fda8892c71fe2181/
processingDocuments/1724752152611_Summary__Umashankar.xlsx",
      "size": "1247510",
      "createdAt": "Tue Aug 27 2024 15:19:14 GMT+0530 (India Standard Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalname": "Bank Mail.docx",
      "filename": "1724830005975_Bank_Mail.docx",
      "path": "cases/66976e22fda8892c71fe2181/
processingDocuments/1724830005975_Bank_Mail.docx",
      "size": "240587",
      "createdAt": "Wed Aug 28 2024 12:56:45 GMT+0530 (India Standard Time)",
      "uploadedBy": "62fe044a48a26047e6552796"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "5fc78e26625ecd20ec1f88e9",
        "role": "MAKER+CHECKER",
        "firstName": "Vaishali",
```

```
    "lastName": "Sarmalkar",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66c879fbc884d112334fa425",
  "note": "value share",
  "taskId": "66c04e4bc884d112334ae940",
  "createdAt": "2024-08-23T12:00:59.559Z"
}
],
"createdAt": "2024-07-17T07:09:22.903Z",
"updatedAt": "2024-08-28T09:50:28.261Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 601, 6th Floor, Wing - A, Opal, Marathon Nextown
Complex, Off. Kalyan Shil Road, Village - Desai, Diva (East), Taluka - Thane, District -
Thane, PIN - 421 204, State - Maharashtra, Country - India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Umashankar Chaturvedi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9967373322",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 457.00",
"flatRate": "9300",
"landOtherRate": "6800",
"shopDetails": {
  "typeOfShops": null,
```

```

    "roadFacing": false,
    "mall": false
  },
  "builtupPercentage": "10",
  "carpetTotal": "0",
  "extendOfSiteRemark": "",
  "finalBuiltupArea": "0.00",
  "finalCarpetArea": "0.00",
  "finalSalableArea": "0.00",
  "otherCarpetTotal": "0",
  "salablePercentage": "10",
  "siteMeasurementRemark": "",
  "toBeAdded": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    },
    "leaseDetails": {
      "lessorName": "",
      "lesseeName": "",
      "leasePremium": "",
      "leaseRent": "",
      "leasePeriod": 0,
      "leaseFrom": "",
      "leaseTo": "",
      "remainingLeasePeriod": 0,
      "leaseDate": ""
    }
  }
},
"reportGeneratedDate": "Wed Aug 28 2024 11:25:42 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-08-19"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			