

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6414170d720a3b25a9f3ba43"
    },
    "firstName": "Ajit Bane",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312ee",
    "email": "0_default_ajit.bane@cosmosbank.in\t",
    "mobileNo": "0_DEFAULT_022-25703557",
    "workMobileNo": "0_DEFAULT_91-8424042284"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6454645",
    "discussWithPerson": "Ajit Bane",
    "expectedFees": 3227.3225,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6414170d720a3b25a9f3ba43",
  "name": "Chembur East Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "cosmos@cosmos.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Plot no 239. Ground floor. Central avenue road. Near ambedkar garden.
Chembur east . Mumbai 400071\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
```

```
"role": "PICKUPPERSON",
"firstName": "Ramkrishna ",
"email": "rampatakar1991@gmail.com",
"lastName": "Patkar",
"mobileNo": "7045746060",
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    ]
  }
]
```

```
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "18.999318965199414",
  "longitude": "73.13176180096092"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.13176180096092,
    18.999318965199414
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "19/07/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-07-19",
    "remark": "MANUAL_IN_TASK"
  }
],
{
```

```
    "status": "COMPLETED",
    "dateTime": "2024-07-19",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Palidevad (Sukapur) ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "New Panvel",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Samruddhbhoomi Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Matheran Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Mumbai - Pune Express Highway",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "33A, Hissa No. 2 & 3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B/04",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
```

```
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tiles_flooring",
    "label": "Vitrified tiles flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Semi_Urban",
    "label": "Semi Urban"
  }
}
```

```
},
"townplanApprovedByList": {
  "value": "Grampanchayat_Pali_Devad",
  "label": "Grampanchayat Pali Devad"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Mumbai - Pune Express Highway",
  "south": "Mumbai - Pune Express Highway",
  "east": "Prabhat building / Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Village",
  "west": "6 Mtr. Wide Road",
  "south": "Ugantak Hsg. Complex",
  "east": "Ugantak Hsg. Complex"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses",
    "status": true
  },
  "taxies": {
    "title": "Taxies",
    "status": true
  }
},
```

```
"auto": {
  "title": "Auto",
  "status": true
},
"privateCars": {
  "title": "Private Cars",
  "status": true
}
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Building Completion Certificate is received it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "25.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "586.5",
  "depreciatedCostOfConstruction": "6413.50",
  "depreciatedBuildingRate": "1713.5"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "54200",
  "landRate": "6200",
  "igrImage": "cases/669a0f3aac43b53f525af24f/igr_1721646528503_Image.png",
  "squareMeterGuideLineRate": "54200.00",
  "squareFeetGuideLineRate": "5035.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "83",
  "rate": "4277.00",
  "squareFeetGuideLineRate": "4277.00",
  "squareMeterGuideLineRate": "46040.00"
},
```

```
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Information not available",
  "taxPaidHolderName": "Information not available",
  "taxAmount": "Information not available",
  "electricityServiceConnectionNo": "Information not available",
  "meterCardHolderName": "Information not available",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per Grampanchayat norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
```

```
"value": "Yes",
"label": "Yes"
},
"carParking": "Open Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2007",
  "fullDate": "1/1/2007"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
}
```

```
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "17",
```



```
"totalLifeBuilding": "60",
"estimatedAge": "43",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "475.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/669a0f3aac43b53f525af24f/
routeMap_1721457149860_Image.png",
    "routeLat": "18.999406",
    "routeLng": "73.131581",
    "stationName": "Panvel Junction",
    "routeDistance": "1.9 km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "a5pz2h",
      "name": "a5pz2h",
      "image": "cases/669a0f3aac43b53f525af24f/
routeMap_1721456922111_Image.png"
```

```
}
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "1092500.00",
    "depreciationPercentage": "25.5",
    "depreciatedCostOfConstruction": "278587.50",
    "totalFairMarketValue": "3046412.50"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3325000.00",
  "finalValue": "3325000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValueDocument": null,
  "purchaseValueDocument": null,
  "bookValue": "0"
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "2031575.00",
"selectedBuildUpValue": "475.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "669b586d35f7d73f39351c25",
"name": "externalImg_1721456748637_externalImg_1721445834997_WhatsApp_I
```

```
mage_20240720_at_082245_1.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748637_externallmg_1721445834997_WhatsApp_Image_20240720_at_082245_1.jpeg",
  "orientation": "portrait"
},
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "669b5855ac43b53f525b82ef",
    "name": "externallmg_1721456725388_externallmg_1721445821465_WhatsApp_Image_20240720_at_082241_1.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725388_externallmg_1721445821465_WhatsApp_Image_20240720_at_082241_1.jpeg",
    "orientation": "portrait"
  },
],
"externalPhotos": [
  {
    "status": false,
    "_id": "669b586d35f7d73f39351c27",
    "name": "externallmg_1721456748643_externallmg_1721445835000_WhatsApp_Image_20240720_at_082245.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748643_externallmg_1721445835000_WhatsApp_Image_20240720_at_082245.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669e542d2abbb93f33eae16b",
    "name": "externallmg_r_1721652269077_1.jpg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_r_1721652269077_1.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "669b5855ac43b53f525b82f0",
    "name": "Living Room",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725395_externallmg_1721445821474_WhatsApp_Image_20240720_at_082241_2.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "status": false,
  "_id": "669b5855ac43b53f525b82f1",
  "name": "Living Room",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725396_externallmg_1721445834974_WhatsApp_Image_20240720_at_082241_3.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "669b58602abbb93f33e9da9e",
  "name": "Living Room",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736297_externallmg_1721445834979_WhatsApp_Image_20240720_at_082242_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "669b58602abbb93f33e9da9f",
  "name": "Living Room",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736300_externallmg_1721445834981_WhatsApp_Image_20240720_at_082242_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "669b58602abbb93f33e9daa0",
  "name": "Living Room",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736301_externallmg_1721445834984_WhatsApp_Image_20240720_at_082242.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "669b58602abbb93f33e9daa1",
  "name": "Living Room",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736304_externallmg_1721445834987_WhatsApp_Image_20240720_at_082243_1.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7580.00",
    "max": "9524.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "6316.00",
      "max": "7937.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "475.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669a0f3aac43b53f525af24f",
"ownerName": "Mrs. Kalpana Manik Nikam, Mr. Avinash Manik Nikam & Mr.
Shashikant Manik Nikam",
"ownerPhoneNo": "9821801523",
"appAddress": "flat no - B 04 , Gr floor, B Wing, samruddha bhumi , Pali devad, Panvel
",
"remark": "staff case ",
"documents": [
```

```
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "31/08/2019",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mr. Pyarelal Mulchand Chouhan",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Mrs. Kalpana Manik Nikam, Mr. Avinash Manik Nikam & Mr.
Shashikant Manik Nikam",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "9502/2019"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "133266",
  "path": "cases/669a0f3aac43b53f525af24f/
document_1721372384044_1721372272536_Kalpana.pdf",
  "fileName": "document_1721372384044_1721372272536_Kalpana.pdf"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "07/05/2007",
    "nameOfApprovingAuthority": {
      "value": "Group_Grampanchayat_Palidevad",
      "label": "Group Grampanchayat Palidevad"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
}
```

```
    "No": "-",
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "646789",
  "path": "cases/669a0f3aac43b53f525af24f/document_1721459446425_BCC.pdf",
  "fileName": "document_1721459446425_BCC.pdf"
}
],
"caseNumber": "010009",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "986496",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 19 2024 12:31:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Kalpana Manik Nikam, Mr. Avinash Manik Nikam & Mr. Shashikant Manik Nikam",
    "phone": "9821801523",
    "ownershipShare": "",
    "email": "",
    "id": "231275"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "714386",
    "name": "Kitchen",
    "length": "7.92",
    "length1": "7",
    "length2": "11",
    "width": "6.75",
    "width1": "6",
    "width2": "9",
    "totalArea": "53.44",
```

```
"images": [],
"extraAreas": [],
"finalArea": "53.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "9.08",
  "length1": "9",
  "length2": "1",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "82.51",
  "images": [],
  "extraAreas": [],
  "finalArea": "82.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
```

```
"name": "Bathroom",
"length": "4.75",
"length1": "4",
"length2": "9",
"width": "4.08",
"width1": "4",
"width2": "1",
"totalArea": "19.40",
"images": [],
"finalArea": "19.40",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "8.08",
  "width1": "8",
  "width2": "1",
  "totalArea": "31.66",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.66"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "13.58",
  "width1": "13",
  "width2": "7",
  "totalArea": "119.99",
  "images": [],
  "finalArea": "119.99",
```

```
"extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "430102",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "475",
  "squareMeterArea": "44.13",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "420.00",
    "squareMeterArea": "39.02",
    "expectedRate": "9523.81",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "504.00",
    "squareMeterArea": "46.82",
    "expectedRate": "7936.51",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
```

```
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "669e3e44e4681c3f58248a50",
  "property": "Pushpa Kalash, Sukhapur Panvel",
  "area": "420",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "1",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4000000",
  "expectedRate": "9523.81",
  "builtUpExpectedRate": "7936.51",
  "image": "cases/669a0f3aac43b53f525af24f/indicator_1721645603428_Image.png",
  "squareMeter": "39.02",
  "id": "152595"
},
{
  "carpetArea": {
    "area": "426.67",
    "squareMeterArea": "39.64",
    "expectedRate": "8437.43",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "512.00",
    "squareMeterArea": "47.57",
    "expectedRate": "7031.25",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "669e3e44e4681c3f58248a51",
  "property": "Pushpa Kalash, Sukhapur Panvel",
  "area": "512",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
```



```
"floor": "Middle",
"source": "Nobroker.com",
"expectedPrice": "3600000",
"expectedRate": "8437.43",
"builtUpExpectedRate": "3600000",
"image": "cases/669a0f3aac43b53f525af24f/indicator_1721645711160_Image.png",
"squareMeter": "47.57",
"id": "513786"
},
{
  "carpetArea": {
    "area": "395.83",
    "squareMeterArea": "36.77",
    "expectedRate": "7579.01",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "475.00",
    "squareMeterArea": "44.13",
    "expectedRate": "6315.79",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "669e3e44e4681c3f58248a52",
  "property": "Samruddhbhumi CHSL., Sukhapur panvel",
  "area": "475",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "1",
  "source": "Index_no.2",
  "expectedPrice": "3000000",
  "expectedRate": "7579.01",
  "builtUpExpectedRate": "3000000",
  "image": "cases/669a0f3aac43b53f525af24f/indicator_1721645810489_Image.png",
  "squareMeter": "44.13",
  "id": "307306"
}
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b2dbeac43b53f525b5cb5",
    "name":
"externalImg_1721445821441_WhatsApp_Image_20240720_at_082238.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/
externalImg_1721445821441_WhatsApp_Image_20240720_at_082238.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b2dbeac43b53f525b5cb6",
    "name":
"externalImg_1721445821445_WhatsApp_Image_20240720_at_082239_1.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/
externalImg_1721445821445_WhatsApp_Image_20240720_at_082239_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b2dbeac43b53f525b5cb7",
    "name":
"externalImg_1721445821452_WhatsApp_Image_20240720_at_082239_2.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/
externalImg_1721445821452_WhatsApp_Image_20240720_at_082239_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b2dbeac43b53f525b5cb9",
    "name":
"externalImg_1721445821458_WhatsApp_Image_20240720_at_082239.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/
externalImg_1721445821458_WhatsApp_Image_20240720_at_082239.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b5855ac43b53f525b82eb",
    "name": "externalImg_1721456725377_externalImg_1721445821456_WhatsApp_I
```

```
mage_20240720_at_082239_3.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725377_externallm
g_1721445821456_WhatsApp_Image_20240720_at_082239_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b5855ac43b53f525b82ec",
  "name": "externallmg_1721456725380_externallmg_1721445821461_WhatsApp_I
mage_20240720_at_082240_1.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725380_externallm
g_1721445821461_WhatsApp_Image_20240720_at_082240_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b5855ac43b53f525b82ed",
  "name": "externallmg_1721456725383_externallmg_1721445821462_WhatsApp_I
mage_20240720_at_082240_2.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725383_externallm
g_1721445821462_WhatsApp_Image_20240720_at_082240_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b5855ac43b53f525b82ee",
  "name": "externallmg_1721456725386_externallmg_1721445821464_WhatsApp_I
mage_20240720_at_082240.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725386_externallm
g_1721445821464_WhatsApp_Image_20240720_at_082240.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b5855ac43b53f525b82ef",
  "name": "externallmg_1721456725388_externallmg_1721445821465_WhatsApp_I
mage_20240720_at_082241_1.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725388_externallm
g_1721445821465_WhatsApp_Image_20240720_at_082241_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b5855ac43b53f525b82f0",
    "name": "externallmg_1721456725395_externallmg_1721445821474_WhatsApp_I
mage_20240720_at_082241_2.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725395_externallm
g_1721445821474_WhatsApp_Image_20240720_at_082241_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b5855ac43b53f525b82f1",
    "name": "externallmg_1721456725396_externallmg_1721445834974_WhatsApp_I
mage_20240720_at_082241_3.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456725396_externallm
g_1721445834974_WhatsApp_Image_20240720_at_082241_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b58602abbb93f33e9da9d",
    "name": "externallmg_1721456736295_externallmg_1721445834976_WhatsApp_I
mage_20240720_at_082241.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736295_externallm
g_1721445834976_WhatsApp_Image_20240720_at_082241.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b58602abbb93f33e9da9e",
    "name": "externallmg_1721456736297_externallmg_1721445834979_WhatsApp_I
mage_20240720_at_082242_1.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736297_externallm
g_1721445834979_WhatsApp_Image_20240720_at_082242_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b58602abbb93f33e9da9f",
    "name": "externallmg_1721456736300_externallmg_1721445834981_WhatsApp_I
mage_20240720_at_082242_2.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736300_externallm
```

```
g_1721445834981_WhatsApp_Image_20240720_at_082242_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b58602abbb93f33e9daa0",
  "name": "externallmg_1721456736301_externallmg_1721445834984_WhatsApp_I
mage_20240720_at_082242.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736301_externallm
g_1721445834984_WhatsApp_Image_20240720_at_082242.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b58602abbb93f33e9daa1",
  "name": "externallmg_1721456736304_externallmg_1721445834987_WhatsApp_I
mage_20240720_at_082243_1.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736304_externallm
g_1721445834987_WhatsApp_Image_20240720_at_082243_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b58602abbb93f33e9daa2",
  "name": "externallmg_1721456736305_externallmg_1721445834988_WhatsApp_I
mage_20240720_at_082243_2.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736305_externallm
g_1721445834988_WhatsApp_Image_20240720_at_082243_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b58602abbb93f33e9daa3",
  "name": "externallmg_1721456736307_externallmg_1721445834990_WhatsApp_I
mage_20240720_at_082243.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456736307_externallm
g_1721445834990_WhatsApp_Image_20240720_at_082243.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "669b586d35f7d73f39351c21",
    "name": "externallmg_1721456748623_externallmg_1721445834991_WhatsApp_I
mage_20240720_at_082244_1.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748623_externallm
g_1721445834991_WhatsApp_Image_20240720_at_082244_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b586d35f7d73f39351c22",
    "name": "externallmg_1721456748628_externallmg_1721445834993_WhatsApp_I
mage_20240720_at_082244_2.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748628_externallm
g_1721445834993_WhatsApp_Image_20240720_at_082244_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b586d35f7d73f39351c23",
    "name": "externallmg_1721456748631_externallmg_1721445834995_WhatsApp_I
mage_20240720_at_082244_3.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748631_externallm
g_1721445834995_WhatsApp_Image_20240720_at_082244_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b586d35f7d73f39351c24",
    "name": "externallmg_1721456748635_externallmg_1721445834996_WhatsApp_I
mage_20240720_at_082244.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748635_externallm
g_1721445834996_WhatsApp_Image_20240720_at_082244.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b586d35f7d73f39351c25",
    "name": "externallmg_1721456748637_externallmg_1721445834997_WhatsApp_I
mage_20240720_at_082245_1.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748637_externallm
g_1721445834997_WhatsApp_Image_20240720_at_082245_1.jpeg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b586d35f7d73f39351c26",
  "name": "externallmg_1721456748640_externallmg_1721445834999_WhatsApp_I
mage_20240720_at_082245_2.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748640_externallm
g_1721445834999_WhatsApp_Image_20240720_at_082245_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b586d35f7d73f39351c27",
  "name": "externallmg_1721456748643_externallmg_1721445835000_WhatsApp_I
mage_20240720_at_082245.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748643_externallm
g_1721445835000_WhatsApp_Image_20240720_at_082245.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b586d35f7d73f39351c28",
  "name": "externallmg_1721456748646_externallmg_1721445835002_WhatsApp_I
mage_20240720_at_082246_1.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748646_externallm
g_1721445835002_WhatsApp_Image_20240720_at_082246_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b586d35f7d73f39351c29",
  "name": "externallmg_1721456748649_externallmg_1721445835004_WhatsApp_I
mage_20240720_at_082246.jpeg",
  "path": "cases/669a0f3aac43b53f525af24f/externallmg_1721456748649_externallm
g_1721445835004_WhatsApp_Image_20240720_at_082246.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669e542d2abbb93f33eae16b",
  "name": "externallmg_r_1721652269077_1.jpg",
```

```
    "path": "cases/669a0f3aac43b53f525af24f/externalimg_r_1721652269077_1.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1719900577742_alculation_123_2.xlsx",
    "filename": "1721646687046_1719900577742_alculation_123_2.xlsx",
    "path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721646687046_1719900577742_alculation_123_2.xlsx",
    "size": "997073",
    "createdAt": "Mon Jul 22 2024 16:41:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_8307.pdf",
    "filename": "1721646687688_igr_8307.pdf",
    "path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721646687688_igr_8307.pdf",
    "size": "194162",
    "createdAt": "Mon Jul 22 2024 16:41:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "BCC.pdf",
    "filename": "1721650972550_BCC.pdf",
    "path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972550_BCC.pdf",
    "size": "89700",
    "createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Conveyance Deed - 2008.pdf",
    "filename": "1721650972578_Conveyance_Deed__2008.pdf",
    "path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972578_Conveyance_Deed__2008.pdf",
    "size": "7038157",
    "createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Diamentiaon.jpeg",
    "filename": "1721650972689_Diamentiaon.jpeg",
    "path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972689_Diamentiaon.jpeg",
```



```
"size": "140477",
"createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Google Location.jpeg",
"filename": "1721650972692_Google_Location.jpeg",
"path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972692_Google_Location.jpeg",
"size": "211545",
"createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Other Documents.pdf",
"filename": "1721650972695_Other_Documents.pdf",
"path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972695_Other_Documents.pdf",
"size": "1444357",
"createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Sale Deed - 2019.pdf",
"filename": "1721650972714_Sale_Deed__2019.pdf",
"path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972714_Sale_Deed__2019.pdf",
"size": "2778341",
"createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Site Details.jpeg",
"filename": "1721650972750_Site_Details.jpeg",
"path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972750_Site_Details.jpeg",
"size": "235229",
"createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
"originalname": "Sketch.jpeg",
"filename": "1721650972754_Sketch.jpeg",
"path": "cases/669a0f3aac43b53f525af24f/
processingDocuments/1721650972754_Sketch.jpeg",
"size": "113286",
```

```
"createdAt": "Mon Jul 22 2024 17:52:52 GMT+0530 (India Standard Time)",
"uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-19T07:01:14.451Z",
"updatedAt": "2024-07-23T04:33:27.620Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "60f91b6f344e052188ffd1fc",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B/04, Ground Floor, Wing - B, Samruddhbhoomi
Co-op. Hsg. Soc. Ltd., Matheran Road, Near Mumbai - Pune Express Highway, Village -
Palidevad (Sukapur) , Taluka - Panvel, District - Raigad, New Panvel, PIN - 410 206,
State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mrs. Kalpana Manik Nikam",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9821801523",
"builtupPercentage": "20",
"carpetTotal": "319",
"extendOfSiteRemark": "",
"finalBuiltupArea": "382.80",
"finalCarpetArea": "319.00",
"finalSalableArea": "382.80",
"otherCarpetTotal": "0.00",
"salablePercentage": "0",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Toilet + Bathroom +
Passage",
"finalMeasurementType": "Sq. Ft.",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
```

```

"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 475.00",
"buildingServicesRate": "2300",
"flatRate": "7000",
"landOtherRate": "4700",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Tue Jul 23 2024 17:20:38 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-07-19",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

```

Name	Length	Width	Total
Composition :			
Kitchen	7'11"	6'9"	53.44
Bedroom	9'1"	9'1"	82.51
Toilet	3'00"	4'00"	12.00
Bathroom	4'9"	4'1"	19.40

Passage	3'11"	8'1"	31.66
Living Room	8'10"	13'7"	119.99
Other Composition :			