

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Shivani ",
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Shivani ",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      }
    }
  ]
}
```

```
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.124895772456835",
  "longitude": "72.9184129089117"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.9184129089117,
    19.124895772456835
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-21",
      "remark": ""
    }
  ]
},
],
```

```
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Tirandaz",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "12",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Excel Tower Co-op. Hsg. Soc. Ltd.",
  "label": false
},
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp IIT Main Gate, Jain Mandir Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "IIT Market",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```



```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "4 (Part)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "76, 76/1 to 3",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1202",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "S - Ward",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 076",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Powai",
```

```
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  }
}
```

```
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Hare Krishna Road",
  "west": "Open Plot",
  "south": "Gokhale Nagar Road",
  "east": "Bhavani Indu CHSL"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Open Space",
    "east": "Open Space",
    "south": "Flat No. 1203",
    "west": "Passage"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
```

```
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "",
"approvePlanVerified": "",
"empanelledOfApprovePlan": "",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "At the time of visit, building external repairs & renovation work is in progress.",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "25640",
  "depreciatedBuildingRate": "2640"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "153090.00",
  "landRate": "72800",
  "igrImage": "cases/669a26cf35f7d73f39348417/igr_1721458397700_Image.png",
  "squareMeterGuideLineRate": "168399.00",
  "squareFeetGuideLineRate": "15645.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "92",
  "rate": "14934.00",
  "squareFeetGuideLineRate": "14934.00",
  "squareMeterGuideLineRate": "160751.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
},
```

```
"propertyOccupiedByList": {
  "value": "Tenant_Occupied",
  "label": "Tenant Occupied"
},
"monthlyRent": "28,000/- Expected rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "Mr. Choudhary",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Basement, Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
```

```
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2016",
  "fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
```

```
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenancelssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "52",
"ageOfBuilding": "8",
"noOfBasement": "1",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "22",
"flatFloorNo": "12",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
```



```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/669a26cf35f7d73f39348417/
routeMap_1721638562542_Image.png",
    "routeLat": "19.124896",
    "routeLng": "72.918413",
    "stationName": "Kanjur Marg",
    "routeDistance": "1.9 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ntaexj",
      "name": "ntaexj",
      "image": "cases/669a26cf35f7d73f39348417/
routeMap_1721638505500_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
```

```
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11281600.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "11281600.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "7885152.00",
"selectedBuildUpValue": "528.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "669d37dce4681c3f58240f18",
"name": "externalImg_1721579479394_1721579369260_image_3.jpeg",
"path": "cases/669a26cf35f7d73f39348417/
externalImg_1721579479394_1721579369260_image_3.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "669d37dce4681c3f58240f1a",
"name": "externalImg_1721579480521_1721579369260_image_5.jpeg",
"path": "cases/669a26cf35f7d73f39348417/
externalImg_1721579480521_1721579369260_image_5.jpeg",
"orientation": "portrait"
}
]
```

```
],
"externalPhotos": [
  {
    "status": false,
    "_id": "669d37dce4681c3f58240f19",
    "name": "externallmg_1721579479969_1721579369260_image_4.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579479969_1721579369260_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669d37dce4681c3f58240f17",
    "name": "externallmg_1721579478561_1721579369260_image_2.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579478561_1721579369260_image_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "669d37dce4681c3f58240f1b",
    "name": "externallmg_1721579480790_1721579369260_image_6.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579480790_1721579369260_image_6.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24000.00",
    "max": "27231.00"
  },
  "builtUpRateRange": {
    "min": "20000.00",
    "max": "22693.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
}
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
```



```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "440.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669a26cf35f7d73f39348417",
"ownerName": "Shri. Ashok Ghatule & Renuka Ashok Ghatule",
"ownerPhoneNo": "8879862001",
"appAddress": "Flat no. 1202, 12th Floor, Excel Tower, Tirandaz Village, Powai",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669a26cf35f7d73f39348417/
document_1721378401430_1721378292459_Racpc_Ghatkopar_Ashok_Ghatule.pdf",
    "fileName":
"document_1721378401430_1721378292459_Racpc_Ghatkopar_Ashok_Ghatule.pdf",
    "id": "810696",
```

```
"uploadedBy": "60b7177d2ffdf65bcd65882a",
"createdAt": "Fri Jul 19 2024 14:11:51 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010016",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "360586",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 19 2024 14:11:51 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Ashok Ghatule & Renuka Ashok Ghatule",
    "phone": "8879862001",
    "ownershipShare": "",
    "email": "",
    "id": "212431"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "369978",
    "name": "Living Room",
    "length": "15.17",
    "length1": "15",
    "length2": "2",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "151.67",
    "images": [],
    "extraAreas": [],
    "finalArea": "151.67"
  },
  {
    "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "31.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "25.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "13.25",
  "length1": "13",
  "length2": "3",
  "width": "9.50",
  "width1": "9",
```

```
"width2": "6",
"totalArea": "125.87",
"images": [],
"extraAreas": [],
"finalArea": "125.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "23.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "7.08",
  "width1": "7",
  "width2": "1",
  "totalArea": "72.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "72.60"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
```

```
{
  "typeOfDocument": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "40.88",
  "totalAreaDocument": "440.00",
  "docBultupPercentage": "20",
  "docFinalBultUp": "528.00",
  "docFinalBultUpSquareMeter": "49.05",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "763478"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "448.00",
      "squareMeterArea": "41.62",
      "expectedRate": "25669.64",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "537.60",
      "squareMeterArea": "49.94",
      "expectedRate": "21391.37",
      "percentage": "20"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    },
    "printlnReport": true,
    "_id": "669b604de4681c3f5823b781",
    "property": "Excel Tower, Gokhale Nagar, Tirandaz, Powai, Mumbai, ",
    "area": "448.00",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "11500000.00",
"expectedRate": "25669.64",
"builtUpExpectedRate": "21391.37",
"image": "cases/669a26cf35f7d73f39348417/
indicator_1721457663808_Image.png",
"squareMeter": "41.62",
"id": "455874"
},
{
  "carpetArea": {
    "area": "550.00",
    "squareMeterArea": "51.10",
    "expectedRate": "24545.45",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "660.00",
    "squareMeterArea": "61.32",
    "expectedRate": "20454.55",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "669b604de4681c3f5823b782",
  "property": "2 BHK Flat In Tej Apartment For Sale In Powai",
  "area": "550.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "13500000.00",
  "expectedRate": "24545.45",
  "builtUpExpectedRate": "20454.55",
```

```
"image": "cases/669a26cf35f7d73f39348417/
indicator_1721457697443_Image.png",
"squareMeter": "51.10",
"id": "664655"
},
{
"carpetArea": {
"area": "475.00",
"squareMeterArea": "44.13",
"expectedRate": "24000.00",
"percentage": ""
},
"builtUpArea": {
"area": "570.00",
"squareMeterArea": "52.95",
"expectedRate": "20000.00",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "669b604de4681c3f5823b783",
"property": " Suncity Complex For Sale In Powai",
"area": "475.00",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "11400000.00",
"expectedRate": "24000.00",
"builtUpExpectedRate": "20000.00",
"image": "cases/669a26cf35f7d73f39348417/
indicator_1721458046873_Image.png",
"squareMeter": "44.13",
"id": "656054"
},
{
"carpetArea": {
"area": "650.00",
"squareMeterArea": "60.39",
```

```
    "expectedRate": "27230.77",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "780.00",
    "squareMeterArea": "72.46",
    "expectedRate": "22692.31",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "669b604de4681c3f5823b784",
  "property": "2 BHK Flat In Skyline Villa For Sale In Powai",
  "area": "650.00",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "17700000.00",
  "expectedRate": "27230.77",
  "builtUpExpectedRate": "22692.31",
  "image": "cases/669a26cf35f7d73f39348417/
indicator_1721458144831_Image.png",
  "squareMeter": "60.39",
  "id": "459392"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea4702",
    "name": "externalImg_1721579439495_1721579330564_image_0.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externalImg_1721579439495_1721579330564_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "669d37b42abbb93f33ea4703",
    "name": "externallmg_1721579439865_1721579330564_image_1.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579439865_1721579330564_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea4704",
    "name": "externallmg_1721579440249_1721579330564_image_2.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579440249_1721579330564_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea4705",
    "name": "externallmg_1721579440657_1721579330564_image_3.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579440657_1721579330564_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea4706",
    "name": "externallmg_1721579441018_1721579330564_image_4.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579441018_1721579330564_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea4707",
    "name": "externallmg_1721579441242_1721579330564_image_5.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579441242_1721579330564_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "669d37b42abbb93f33ea4708",
    "name": "externallmg_1721579441399_1721579330564_image_6.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579441399_1721579330564_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea4709",
    "name": "externallmg_1721579441625_1721579330564_image_7.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579441625_1721579330564_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea470a",
    "name": "externallmg_1721579442020_1721579330564_image_8.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579442020_1721579330564_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea470b",
    "name": "externallmg_1721579442588_1721579330564_image_9.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579442588_1721579330564_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea470c",
    "name": "externallmg_1721579442908_1721579330564_image_10.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579442908_1721579330564_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea470d",
```

```
    "name": "externallmg_1721579443237_1721579330564_image_11.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579443237_1721579330564_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea470e",
    "name": "externallmg_1721579443794_1721579330564_image_12.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579443794_1721579330564_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37b42abbb93f33ea470f",
    "name": "externallmg_1721579444382_1721579330564_image_13.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579444382_1721579330564_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f15",
    "name": "externallmg_1721579476621_1721579369260_image_0.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579476621_1721579369260_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f16",
    "name": "externallmg_1721579477696_1721579369260_image_1.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579477696_1721579369260_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f17",
    "name": "externallmg_1721579478561_1721579369260_image_2.jpeg",
```

```
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579478561_1721579369260_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f18",
    "name": "externallmg_1721579479394_1721579369260_image_3.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579479394_1721579369260_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f19",
    "name": "externallmg_1721579479969_1721579369260_image_4.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579479969_1721579369260_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f1a",
    "name": "externallmg_1721579480521_1721579369260_image_5.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579480521_1721579369260_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f1b",
    "name": "externallmg_1721579480790_1721579369260_image_6.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579480790_1721579369260_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669d37dce4681c3f58240f1c",
    "name": "externallmg_1721579481233_1721579369260_image_7.jpeg",
    "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579481233_1721579369260_image_7.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669d37dce4681c3f58240f1d",
  "name": "externallmg_1721579481703_1721579369260_image_8.jpeg",
  "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579481703_1721579369260_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669d37dce4681c3f58240f1e",
  "name": "externallmg_1721579481986_1721579369260_image_9.jpeg",
  "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579481986_1721579369260_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669d37dce4681c3f58240f1f",
  "name": "externallmg_1721579482378_1721579369260_image_10.jpeg",
  "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579482378_1721579369260_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669d37dce4681c3f58240f20",
  "name": "externallmg_1721579482843_1721579369260_image_11.jpeg",
  "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579482843_1721579369260_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669d37dce4681c3f58240f21",
  "name": "externallmg_1721579483139_1721579369260_image_12.jpeg",
  "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579483139_1721579369260_image_12.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "669d37dce4681c3f58240f22",
      "name": "externallmg_1721579483394_1721579369260_image_13.jpeg",
      "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579483394_1721579369260_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "669d37dce4681c3f58240f23",
      "name": "externallmg_1721579484008_1721579369260_image_14.jpeg",
      "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579484008_1721579369260_image_14.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "669d377f2abbb93f33ea46d4",
      "name": "externallmg_1721579390117_1721579282245_image_0.jpeg",
      "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579390117_1721579282245_image_0.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "669d377f2abbb93f33ea46d5",
      "name": "externallmg_1721579390706_1721579282245_image_1.jpeg",
      "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579390706_1721579282245_image_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "669d377f2abbb93f33ea46d6",
      "name": "externallmg_1721579390913_1721579282245_image_2.jpeg",
      "path": "cases/669a26cf35f7d73f39348417/
externallmg_1721579390913_1721579282245_image_2.jpeg",
      "orientation": "portrait"
    }
  }
```

```
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60092304a16fab0f2af9b0c2",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Nitesh",
      "lastName": "Khedekar",
      "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "669b601c35f7d73f39352b5b",
    "note": "DONE ",
    "taskId": "669a3027e4681c3f582341d8",
    "createdAt": "2024-07-20T06:58:36.558Z"
  }
],
"createdAt": "2024-07-19T08:41:51.489Z",
"updatedAt": "2024-07-22T09:23:17.304Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1202, 12th Floor, Excel Tower Co-op. Hsg. Soc.
Ltd., Opp IIT Main Gate, Jain Mandir Road, IIT Market, Village - Tirandaz, Municipality
Ward No. S - Ward, Powai, Taluka - Kurla, District - Mumbai Suburban District, Mumbai,
PIN Code - 400 076, State - Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Choudhary",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
```

```
"siteVisitContactNo": "0000000000",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 440.00",
"flatRate": "26000.00",
"landOtherRate": "23000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "358.35",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "517.14",
"finalCarpetArea": "430.95",
"finalSalableArea": "568.85",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": ""
}
```


Name	Length	Width	Total
Composition :			
Living Room	15'2"	10'00"	151.67
Passage	4'2"	7'6"	31.25
Toilet	7'4"	3'6"	25.67
Bedroom	13'3"	9'6"	125.87
Toilet	3'7"	6'8"	23.89
Kitchen	10'3"	7'1"	72.60
Other Composition :			