

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64475d5ad11ef125ab24cd9f"
    },
    "firstName": "Padma",
    "type": "CREDITOFFICER",
    "_id": "66696a9709a0de7b00a48aa6",
    "lastName": "Magdum",
    "mobileNo": "",
    "workMobileNo": "9096473962",
    "email": "1brmgr1216@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64475d5ad11ef125ab24cd9f",
  "name": "T M C Branch Thanet",
  "branchCode": "",
  "mobileNo": "02225335859\t",
  "alternateMobileNo": "",
  "email": "brmgr1216@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Thane Muncpal Corporation Building, Ground FLOOR, Panchpakhadi
Thane ( West)-400602\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90ffff3dd69653a591ae9",
  "zoneName": "THANE ZONE"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.06143339694203",
  "longitude": "72.88281731307507"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88281731307507,
    19.06143339694203
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-19",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Kurla",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "17",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kurla (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
}
```

```
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Nehru Nagar Siddhi Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Proposed Redevelopment of Building No. 69, Nehru Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
```



```
"key": "wing",
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "229 & 267",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "12 (Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1701",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```

    "value": "",
    "label": true
  },
  "postalCode": {
    "status": true,
    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN Code - 400 024",
    "label": false
  },
  "suburb": {
    "status": false,
    "name": "Suburb",
    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door",
    "label": "Teak Wood Door frame with Solid door with safety door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {

```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Mumbai_Housing_&_Area_Development_Board_(MHADA)",
  "label": "Mumbai Housing & Area Development Board (MHADA)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road",
  "west": "Kedarnath Mandir Marg",
  "south": "Internal Road",
  "east": "Building No. 58 & 67"
},
"asPerDocumentAgreement": {
  "north": "12.20 mtr. Road",
  "west": "Bldg. No. 58 & 67",
  "south": "12.20 mtr. Road\n",
  "east": "18.30 mtr. Road"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Flat No. 1702",
    "east": "Passage",
    "south": "Flat No. 1707",
    "west": "Open Plot"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  }
},
"isDisplay": true,
```

```
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "All the above areas are within 7% of the Agreement for Sale Area. The
above calculations and detail measurements taken by us prove that the Agreement for
Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for
Sale area.",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "113870",
  "landRate": "55810",
  "igrImage": "cases/669a3ea3ac43b53f525b2535/igr_1721648796790_Image.png",
  "squareMeterGuideLineRate": "125257.00",
```

```
"squareFeetGuideLineRate": "11637.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "95",
  "rate": "11314.00",
  "squareFeetGuideLineRate": "11314.00",
  "squareMeterGuideLineRate": "121785.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A.",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
}
```

```
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stack Parking",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2023",
  "fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
```



```
    "value": "stilt",
    "label": "Stilt"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_occupancy_certificate",
    "label": "As per occupancy certificate"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "59",
  "ageOfBuilding": "1",
  "noOfBasement": "",
  "noOfPodium": "3",
  "noOfAmenityFloors": "",
  "noOfFloors": "19",
  "flatFloorNo": "17",
  "noOfLifts": "2",
  "noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "696.30",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/669a3ea3ac43b53f525b2535/routeMap_1721718783749_Image.png",
    "routeLat": "19.061433",
    "routeLng": "72.882817",
    "stationName": "Kurla",
    "routeDistance": "550M"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
```

```
"latlng": true,
"finallatlng": true
},
"locationMapImg": [
  {
    "id": "ko3vbv",
    "name": "ko3vbv",
    "image": "cases/669a3ea3ac43b53f525b2535/
routeMap_1721718732246_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
```

```
"finaltotal": "12660000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "12660000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Tue Jul 23 2024 14:33:20 GMT+0530 (India Standard Time)",
  "number": "2307367",
  "dayCount": "18",
  "monthCount": "371",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "8102843.00",
  "selectedBuildUpValue": "696.30",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "669b4600ac43b53f525b6a51",
      "name": "externallmg_1721452027101_1721451905629_image_10.jpeg",
      "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452027101_1721451905629_image_10.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "669b4600ac43b53f525b6a54",
      "name": "externallmg_1721452028286_1721451905629_image_13.jpeg",
      "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452028286_1721451905629_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "669b4600ac43b53f525b6a52",
      "name": "externallmg_1721452027325_1721451905629_image_11.jpeg",
      "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452027325_1721451905629_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "669b45d5ac43b53f525b6978",
      "name": "externallmg_1721451982632_1721451863850_image_8.jpeg",
      "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451982632_1721451863850_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "669b45d5ac43b53f525b6972",
```

```
    "name": "externallmg_1721451974874_1721451863850_image_2.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451974874_1721451863850_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669b45d5ac43b53f525b6975",
    "name": "externallmg_1721451976383_1721451863850_image_5.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451976383_1721451863850_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669b45d5ac43b53f525b6979",
    "name": "externallmg_1721451985359_1721451863850_image_9.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451985359_1721451863850_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669b4600ac43b53f525b6a4d",
    "name": "externallmg_1721452022514_1721451905629_image_6.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452022514_1721451905629_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "669b4600ac43b53f525b6a4e",
    "name": "externallmg_1721452024439_1721451905629_image_7.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452024439_1721451905629_image_7.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "18910.00",
    "max": "25902.00"
```

```
    },
    "builtUpRateRange": {
      "min": "17191.00",
      "max": "23547.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "633.00",
"empanelmentNo": [
  "AX33 /CREMON/Valuer/Empanelment/Sr No.55/2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669a3ea3ac43b53f525b2535",
"ownerName": "Mr. Dayanand Rajaram Kadkuntla & Mrs. Veena Dayanand
Kadakuntla",
"ownerPhoneNo": "9860669732",
"fullAddress": "Residential Flat No. 1701, 17th Floor, Nehru Nagar Siddhi Co-Op. Hsg.
Soc. Ltd., Proposed Redevelopment of Building No. 69, Nehru Nagar, Village - Kurla,
```

Taluka - Kurla, District - Mumbai Suburban, Kurla (East), PIN Code - 400 024, State - Maharashtra, India",

"remark": "",

"documents": [

{

"documentType": {

"value": "60af48bf2ffdf65bcd6585fa",

"label": "Agreement for sale"

},

"inputs": {

"documentDate": "25/06/2024",

"from": {

"value": "Developers",

"label": "Developers"

},

"Developers": "M/s. Hiranimanthan Builders & Developers ",

"to": {

"value": "purchaser",

"label": "purchaser"

},

"purchaser": "Mr. Dayanand Rajaram Kadkuntla & Mrs. Veena Dayanand

Kadakuntla",

"number": {

"value": "No",

"label": "No"

},

"No": "13421/2024"

},

"isHardCopy": false,

"displayStatus": true,

"id": "711868",

"path": "cases/669a3ea3ac43b53f525b2535/

document\_1721384604114\_BOM\_TMC\_br.pdf",

"fileName": "document\_1721384604114\_BOM\_TMC\_br.pdf"

},

{

"documentType": {

"value": "60ae1247aa6d152c1801b2ea",

"label": "Commencement Certificate"

},

"inputs": {

"documentDate": "11/08/2021",

"nameOfApprovingAuthority": {

"value": "Maharashtra\_Housing\_And\_Area\_Development\_Authority",

"label": "Maharashtra Housing And Area Development Authority"

},

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "MH / EE / (BP) / GM / MHADA - 22 / 0706 / 2021 / FCC / 3 / Amend"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1721716376557_179759.pdf",
"path": "cases/669a3ea3ac43b53f525b2535/
document_1721716376557_179759.pdf",
"id": "221196",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Jul 23 2024 12:02:56 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b337",
    "label": "Full Occupation Certificate"
  },
  "inputs": {
    "documentDate": "12/06/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Housing_And_Area_Development_Authority",
      "label": "Maharashtra Housing And Area Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "MH / EE (B.P.) / GM / MHADA - 22 / 101 /2023"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1721716490250_115442.pdf",
"path": "cases/669a3ea3ac43b53f525b2535/
document_1721716490250_115442.pdf",
"id": "180532",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Tue Jul 23 2024 12:04:50 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

```
"caseNumber": "010021",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "301093",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jul 19 2024 15:53:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Dayanand Rajaram Kadkuntla & Mrs. Veena Dayanand Kadakuntla",
    "phone": "9860669732",
    "ownershipShare": "",
    "email": "",
    "id": "278667"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "212724",
    "name": "Living Room",
    "length": "19.00",
    "length1": "19",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "190.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "190.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "2",
```

```
"name": "Bedroom",
"length": "13.00",
"length1": "13",
"length2": "0",
"width": "9.00",
"width1": "9",
"width2": "0",
"totalArea": "117.00",
"images": [],
"finalArea": "117.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "84.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "84.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "0",
  "width": "8.00",
  "width1": "8",
  "width2": "0",
  "totalArea": "72.00",
  "images": [],
  "finalArea": "72.00",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "0",
  "width": "7.00",
  "width1": "7",
  "width2": "0",
  "totalArea": "28.00",
  "images": [],
  "finalArea": "28.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "5.00",
  "length1": "5",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
  "totalArea": "25.00",
  "images": [],
  "finalArea": "25.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "",
```

```
"length1": "5",
"length2": "0",
"width": "",
"width1": "4",
"width2": "0",
"totalArea": "20.00",
"images": [],
"finalArea": "20.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "25.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "16.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.00"
},
}
```



```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "0",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
  "totalArea": "10.00",
  "images": [],
  "finalArea": "10.00",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "58.81",
    "totalAreaDocument": "633",
    "docBultupPercentage": "10",
    "docFinalBultUp": "696.30",
    "docFinalBultUpSquareMeter": "64.69",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "966095"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"carpetArea": {
  "area": "610.00",
  "squareMeterArea": "56.67",
  "expectedRate": "21967.21",
  "percentage": ""
},
"builtUpArea": {
  "area": "671.00",
  "squareMeterArea": "62.34",
  "expectedRate": "19970.19",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "669e46c6e4681c3f58249423",
"property": "Residential Flat",
"area": "610",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "13400000",
"expectedRate": "21967.21",
"builtUpExpectedRate": "19970.19",
"image": "cases/669a3ea3ac43b53f525b2535/
indicator_1721648525078_Image.png",
"squareMeter": "56.67",
"id": "611550"
},
{
  "carpetArea": {
    "area": "305.00",
    "squareMeterArea": "28.34",
    "expectedRate": "25901.64",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "335.50",
    "squareMeterArea": "31.17",
```

```
    "expectedRate": "23546.94",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "669e46c6e4681c3f58249424",
  "property": "Residential Flat",
  "area": "305",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7900000",
  "expectedRate": "25901.64",
  "builtUpExpectedRate": "23546.94",
  "image": "cases/669a3ea3ac43b53f525b2535/
indicator_1721648558512_Image.png",
  "squareMeter": "28.34",
  "id": "121030"
},
{
  "carpetArea": {
    "area": "633.00",
    "squareMeterArea": "58.81",
    "expectedRate": "18909.95",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "696.30",
    "squareMeterArea": "64.69",
    "expectedRate": "17190.87",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
}
```

```
"printlnReport": true,
"_id": "669e46c6e4681c3f58249425",
"property": "Residential Flat",
"area": "633",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "11970000",
"expectedRate": "18909.95",
"builtUpExpectedRate": "17190.87",
"image": "cases/669a3ea3ac43b53f525b2535/
indicator_1721648606358_Image.png",
"squareMeter": "58.81",
"id": "339846"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669b45d5ac43b53f525b6970",
"name": "externalImg_1721451974022_1721451863850_image_0.jpeg",
"path": "cases/669a3ea3ac43b53f525b2535/
externalImg_1721451974022_1721451863850_image_0.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669b45d5ac43b53f525b6971",
"name": "externalImg_1721451974373_1721451863850_image_1.jpeg",
"path": "cases/669a3ea3ac43b53f525b2535/
externalImg_1721451974373_1721451863850_image_1.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669b45d5ac43b53f525b6972",
"name": "externalImg_1721451974874_1721451863850_image_2.jpeg",
"path": "cases/669a3ea3ac43b53f525b2535/
externalImg_1721451974874_1721451863850_image_2.jpeg",
"orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b45d5ac43b53f525b6973",
    "name": "externallmg_1721451975145_1721451863850_image_3.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451975145_1721451863850_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b45d5ac43b53f525b6974",
    "name": "externallmg_1721451975776_1721451863850_image_4.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451975776_1721451863850_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b45d5ac43b53f525b6975",
    "name": "externallmg_1721451976383_1721451863850_image_5.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451976383_1721451863850_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b45d5ac43b53f525b6976",
    "name": "externallmg_1721451978790_1721451863850_image_6.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451978790_1721451863850_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b45d5ac43b53f525b6977",
    "name": "externallmg_1721451980794_1721451863850_image_7.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451980794_1721451863850_image_7.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b45d5ac43b53f525b6978",
  "name": "externallmg_1721451982632_1721451863850_image_8.jpeg",
  "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451982632_1721451863850_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b45d5ac43b53f525b6979",
  "name": "externallmg_1721451985359_1721451863850_image_9.jpeg",
  "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451985359_1721451863850_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b45d5ac43b53f525b697a",
  "name": "externallmg_1721451987523_1721451863850_image_10.jpeg",
  "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451987523_1721451863850_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b45d5ac43b53f525b697b",
  "name": "externallmg_1721451988753_1721451863850_image_11.jpeg",
  "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721451988753_1721451863850_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669b4600ac43b53f525b6a47",
  "name": "externallmg_1721452016723_1721451905629_image_0.jpeg",
  "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452016723_1721451905629_image_0.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a48",
    "name": "externallmg_1721452018051_1721451905629_image_1.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452018051_1721451905629_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a49",
    "name": "externallmg_1721452018244_1721451905629_image_2.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452018244_1721451905629_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a4a",
    "name": "externallmg_1721452019803_1721451905629_image_3.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452019803_1721451905629_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a4b",
    "name": "externallmg_1721452021708_1721451905629_image_4.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452021708_1721451905629_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a4c",
    "name": "externallmg_1721452022284_1721451905629_image_5.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452022284_1721451905629_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "669b4600ac43b53f525b6a4d",
    "name": "externallmg_1721452022514_1721451905629_image_6.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452022514_1721451905629_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a4e",
    "name": "externallmg_1721452024439_1721451905629_image_7.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452024439_1721451905629_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a4f",
    "name": "externallmg_1721452025633_1721451905629_image_8.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452025633_1721451905629_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a50",
    "name": "externallmg_1721452026891_1721451905629_image_9.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452026891_1721451905629_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a51",
    "name": "externallmg_1721452027101_1721451905629_image_10.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452027101_1721451905629_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "669b4600ac43b53f525b6a52",
    "name": "externallmg_1721452027325_1721451905629_image_11.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452027325_1721451905629_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a53",
    "name": "externallmg_1721452027606_1721451905629_image_12.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452027606_1721451905629_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a54",
    "name": "externallmg_1721452028286_1721451905629_image_13.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452028286_1721451905629_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a55",
    "name": "externallmg_1721452028428_1721451905629_image_14.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452028428_1721451905629_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669b4600ac43b53f525b6a56",
    "name": "externallmg_1721452029320_1721451905629_image_15.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externallmg_1721452029320_1721451905629_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669b45a635f7d73f3934f575",
```

```
    "name": "externalImg_1721451941762_1721451833402_image_0.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externalImg_1721451941762_1721451833402_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669b45a635f7d73f3934f576",
    "name": "externalImg_1721451941789_1721451833403_image_1.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externalImg_1721451941789_1721451833403_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669b45a635f7d73f3934f577",
    "name": "externalImg_1721451942275_1721451833403_image_2.jpeg",
    "path": "cases/669a3ea3ac43b53f525b2535/
externalImg_1721451942275_1721451833403_image_2.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1721648846905_Calculation_Sheet_NEW.xlsx",
    "path": "cases/669a3ea3ac43b53f525b2535/
processingDocuments/1721648846905_Calculation_Sheet_NEW.xlsx",
    "size": "1939761",
    "createdAt": "Mon Jul 22 2024 17:17:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Reference Report - Sudhakar_Babu_Susvirkar.pdf",
    "filename": "1721648846946_Reference_Report__Sudhakar_Babu_Susvirkar.pdf",
    "path": "cases/669a3ea3ac43b53f525b2535/processingDocuments/1721648846946
_Reference_Report__Sudhakar_Babu_Susvirkar.pdf",
    "size": "11403963",
    "createdAt": "Mon Jul 22 2024 17:17:27 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-19T10:23:31.091Z",
"updatedAt": "2024-07-23T09:08:42.820Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Rakesh Mhatre",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8082368728",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 633.00",
"flatRate": "20000",
"landOtherRate": "17000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + 4 Passage",
"carpetTotal": "568.00",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "645.70",
"finalCarpetArea": "587.00",
"finalSalableArea": "710.27",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
```

```

"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Tue Jul 23 2024 11:22:23 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-07-19"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	19'00"	10'00"	190.00
Bedroom	13'0"	9'0"	117.00
Bedroom	12'00"	7'00"	84.00
Kitchen	9'0"	8'0"	72.00
Toilet	4'0"	7'0"	28.00
Toilet	5'0"	5'0"	25.00
Passage	5'0"	4'0"	20.00
Passage	5'00"	5'00"	25.00
Passage	4'00"	4'00"	16.00
Passage	2'0"	5'0"	10.00
Other Composition :			