

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8c9"
    },
    "firstName": "Manjunath Kote",
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b3f",
    "email": "manjunath@cosmosbank.in",
    "mobileNo": "9773289829",
    "workMobileNo": "9773289829",
    "lastName": "Kote"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8c9",
  "branchCode": "000002",
  "type": "BRANCH",
  "name": "Ghatkopar (West) Branch",
  "email": "ghatkopar@cosmosbank.in",
  "mobileNo": "022-25136117",
  "alternateMobileNo": "",
  "address": "S. No. 73, Plot No. 958, P.T. 4, Mira Sagar Building, Nauroji Lane,
Ghatkopar (West), Mumbai - 400 086, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "Cosmos Bank - Ghatkopar",
  "fax": "022-25132117",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
```

```
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
```

```
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },

```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.08101525138364",
  "longitude": "72.89367355406284"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.89367355406284,
    19.08101525138364
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-24",
      "remark": "Selfie taken with Sudhir's father"
    },
    {
      "status": "COMPLETED",
```

```
    "dateTime": "2024-07-23",
    "remark": "MANUAL_IN_TASK"
  }
],
"schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kirol",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Parasnath Darshan Co-Op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kirol Kurla Road, Near Credit Line Showroom",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "617, 618, 619, 630 & 631(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "505",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 086",
  "label": false
},
"suburb": {
```

```

    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Vidhyavihar (West)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
}

```

```
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Nathani Road ",
  "west": "Alexandria Apartment ",
  "south": "Slum Area ",
  "east": "Internal Road "
},
"asPerDocumentAgreement": {
  "north": "24.4 Mtrs. Wide Kirol Road ",
  "west": "A Plot of Vacant Land ",
  "south": "Rehabilitation Plot ",
  "east": "220 Feet Road Wide "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space ",
    "east": "Passage & Lift ",
    "south": "Passage ",
    "west": "Flat No. 504"
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  }
}
```

```
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and not verified.",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "36",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "20100",
  "depreciatedBuildingRate": "1600"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "147490",
  "landRate": "62250",
  "igrImage": "cases/669b4ccfac43b53f525b725f/igr_1721799081815_Image.png",
  "squareMeterGuideLineRate": "154865.00",
  "squareFeetGuideLineRate": "14387.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "76",
  "rate": "12322.00",
  "squareFeetGuideLineRate": "12322.00",
  "squareMeterGuideLineRate": "132637.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
},
```

```
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms ",
"tenantName": "",
"maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking Space ",
  "constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2000",
"fullDate": "1/1/2000"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Good",
"label": "Good"
},
"sewerageSystem": {
```

```
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
```



```
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "540.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/669b4ccfac43b53f525b725f/
routeMap_1721805147569_Image.png",
    "routeLat": "19.081015",
    "routeLng": "72.893674",
    "stationName": "Vidhya Vihar",
    "routeDistance": "800 Mtrs."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "incf9",
      "name": "incf9",
      "image": "cases/669b4ccfac43b53f525b725f/
routeMap_1721805080006_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
```

```
"costOfConstruction": "1350000.00",
"depreciationPercentage": "36",
"depreciatedCostOfConstruction": "486000.00",
"totalFairMarketValue": "8964000.00"
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9450000.00",
"finalValue": "9450000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Jul 24 2024 14:50:57 GMT+0530 (India Standard Time)",
  "number": "2307382",
  "dayCount": "6",
```

```
"monthCount": "386",
"generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "6653880.00",
"selectedBuildUpValue": "540.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "66a07ed0b178c60d94835405",
"name": "externalImg_1721794250978_1721794139738_image_5.jpeg",
```

```
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794250978_1721794139738_image_5.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1b6",
    "name": "externallmg_1721794311412_1721794195201_image_1.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794311412_1721794195201_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1ba",
    "name": "externallmg_1721794313031_1721794195201_image_5.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794313031_1721794195201_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1b8",
    "name": "externallmg_1721794312024_1721794195201_image_3.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794312024_1721794195201_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1b9",
    "name": "externallmg_1721794312519_1721794195201_image_4.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794312519_1721794195201_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1be",
    "name": "externallmg_1721794314576_1721794195201_image_9.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794314576_1721794195201_image_9.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "66a07f0d6e8f430d9508f1c1",
      "name": "externallmg_1721794316012_1721794195201_image_12.jpeg",
      "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794316012_1721794195201_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66a07ed0b178c60d94835406",
      "name": "externallmg_1721794251680_1721794139738_image_6.jpeg",
      "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794251680_1721794139738_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66a07ed0b178c60d94835401",
      "name": "externallmg_1721794246861_1721794139738_image_1.jpeg",
      "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794246861_1721794139738_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66a07ed0b178c60d94835405",
      "name": "externallmg_1721794250978_1721794139738_image_5.jpeg",
      "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794250978_1721794139738_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "16685.00",
    "max": "22223.00"
  },
  "builtUpRateRange": {
    "min": "13892.00",
    "max": "18519.00"
  }
}
```

```
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```

```
"status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "450.00",
"empanelmentNo": [
  "HO/CREDIT/67/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669b4ccfac43b53f525b725f",
"ownerName": "Sudhir Harishchandra Chile, Shweta S. Chile & Harishchandra Z. Chile",
"ownerPhoneNo": "9136768384",
"appAddress": "Flat no. 505, 5th Floor, Wing - B, Parasnath Darshan Complex, Vidyavihar West ",
"remark": "Selfie taken with Sudhir's father",
"documents": [
  {
    "documentType": {
```

```
"value": "60af48bf2ffdf65bcd6585fa",
"label": "Agreement for sale"
},
"inputs": {
  "documentDate": "17/11/2009",
  "from": {
    "value": "Builder",
    "label": "Builder"
  },
  "Builder": "M/s. Nadkar & Dharamashi Developers ",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Shri. Sudhir Harishchandra Chile ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "10668 / 2009"
},
"isHardCopy": false,
"displayStatus": true,
"id": "717223",
"path": "cases/669b4ccfac43b53f525b725f/document_1721453771644_78406.pdf",
"fileName": "document_1721453771644_78406.pdf"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "27/11/2024",
    "remark": " issued by ",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Sudhir Harishchandra Chile, Shweta S. Chile & Harishchandra Z.
Chile ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "53"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "826390",
    "path": "cases/669b4ccfac43b53f525b725f/
document_1721810612917_180003.pdf",
    "fileName": "document_1721810612917_180003.pdf"
  }
],
"caseNumber": "010035",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "940716",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jul 20 2024 11:06:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sudhir Harishchandra Chile, Shweta S. Chile & Harishchandra Z. Chile ",
    "phone": "9136768384",
    "ownershipShare": "",
    "email": "",
    "id": "608201"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "940353",
    "name": "Living Room",
    "length": "16.50",
    "length1": "16",
    "length2": "6",
    "width": "10.42",
    "width1": "10",
    "width2": "5",
    "totalArea": "171.87",
    "images": [],
```

```
"extraAreas": [],
"finalArea": "171.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "7.75",
  "width1": "7",
  "width2": "9",
  "totalArea": "80.73",
  "images": [],
  "extraAreas": [],
  "finalArea": "80.73"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "7.50",
  "length1": "7",
  "length2": "6",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "22.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
```

```
"length": "2.67",
"length1": "2",
"length2": "8",
"width": "3.92",
"width1": "3",
"width2": "11",
"totalArea": "10.44",
"images": [],
"extraAreas": [],
"finalArea": "10.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "14.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bathroom",
  "length": "",
  "length1": "4",
  "length2": "3",
  "width": "",
  "width1": "7",
  "width2": "5",
  "totalArea": "31.52",
  "images": [],
  "finalArea": "31.52",
  "extraAreas": []
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "12.08",
  "length1": "12",
  "length2": "1",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "116.81",
  "images": [],
  "finalArea": "116.81",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "312793",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "450",
    "squareMeterArea": "41.81",
    "docFinalBuiltUp": "540",
    "docFinalBuiltUpSquareMeter": "50.172000000000004",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
```

```
{
  "carpetArea": {
    "area": "450.00",
    "squareMeterArea": "41.81",
    "expectedRate": "22222.22",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "540.00",
    "squareMeterArea": "50.17",
    "expectedRate": "18518.52",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66a094a0c474b30d54cc562c",
  "property": "Residential Flat",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "10000000",
  "expectedRate": "22222.22",
  "builtUpExpectedRate": "18518.52",
  "image": "cases/669b4ccfac43b53f525b725f/indicator_1721798616651_Image.png",
  "squareMeter": "41.81",
  "id": "913181"
},
{
  "carpetArea": {
    "area": "458",
    "squareMeterArea": "42.55",
    "expectedRate": "21834.06",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "550.00",
    "squareMeterArea": "51.10",
```



```
"expectedRate": "18181.82",
"percentage": ""
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66a094a0c474b30d54cc562d",
"property": "Residential Flat",
"area": "550",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "10000000",
"expectedRate": "21834.06",
"builtUpExpectedRate": "10000000",
"image": "cases/669b4ccfac43b53f525b725f/indicator_1721798661303_Image.png",
"squareMeter": "51.10",
"id": "567397"
},
{
  "carpetArea": {
    "area": "383",
    "squareMeterArea": "35.58",
    "expectedRate": "16684.07",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "460.00",
    "squareMeterArea": "42.74",
    "expectedRate": "13891.30",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
```

```
    "_id": "66a094a0c474b30d54cc562e",
    "property": "Residential Flat",
    "area": "460",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "6390000",
    "expectedRate": "16684.07",
    "builtUpExpectedRate": "6390000",
    "image": "cases/669b4ccfac43b53f525b725f/indicator_1721798703386_Image.png",
    "squareMeter": "42.74",
    "id": "467629"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835400",
    "name": "externalImg_1721794246234_1721794139738_image_0.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externalImg_1721794246234_1721794139738_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835401",
    "name": "externalImg_1721794246861_1721794139738_image_1.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externalImg_1721794246861_1721794139738_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835402",
    "name": "externalImg_1721794247797_1721794139738_image_2.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externalImg_1721794247797_1721794139738_image_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835403",
    "name": "externallmg_1721794248140_1721794139738_image_3.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794248140_1721794139738_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835404",
    "name": "externallmg_1721794249951_1721794139738_image_4.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794249951_1721794139738_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835405",
    "name": "externallmg_1721794250978_1721794139738_image_5.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794250978_1721794139738_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835406",
    "name": "externallmg_1721794251680_1721794139738_image_6.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794251680_1721794139738_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07ed0b178c60d94835407",
    "name": "externallmg_1721794252525_1721794139738_image_7.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794252525_1721794139738_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a07ed0b178c60d94835408",
  "name": "externallmg_1721794252942_1721794139738_image_8.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794252942_1721794139738_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a07ed0b178c60d94835409",
  "name": "externallmg_1721794253331_1721794139738_image_9.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794253331_1721794139738_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a07ed0b178c60d9483540a",
  "name": "externallmg_1721794254254_1721794139738_image_10.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794254254_1721794139738_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a07ed0b178c60d9483540b",
  "name": "externallmg_1721794255201_1721794139738_image_11.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794255201_1721794139738_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a07f0d6e8f430d9508f1b5",
  "name": "externallmg_1721794310943_1721794195201_image_0.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794310943_1721794195201_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a07f0d6e8f430d9508f1b6",
    "name": "externallmg_1721794311412_1721794195201_image_1.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794311412_1721794195201_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1b7",
    "name": "externallmg_1721794311790_1721794195201_image_2.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794311790_1721794195201_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1b8",
    "name": "externallmg_1721794312024_1721794195201_image_3.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794312024_1721794195201_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1b9",
    "name": "externallmg_1721794312519_1721794195201_image_4.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794312519_1721794195201_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1ba",
    "name": "externallmg_1721794313031_1721794195201_image_5.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794313031_1721794195201_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1bb",
```

```
    "name": "externallmg_1721794313447_1721794195201_image_6.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794313447_1721794195201_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1bc",
    "name": "externallmg_1721794313734_1721794195201_image_7.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794313734_1721794195201_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1bd",
    "name": "externallmg_1721794314237_1721794195201_image_8.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794314237_1721794195201_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1be",
    "name": "externallmg_1721794314576_1721794195201_image_9.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794314576_1721794195201_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1bf",
    "name": "externallmg_1721794315002_1721794195201_image_10.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794315002_1721794195201_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1c0",
    "name": "externallmg_1721794315570_1721794195201_image_11.jpeg",
```

```
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794315570_1721794195201_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1c1",
    "name": "externallmg_1721794316012_1721794195201_image_12.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794316012_1721794195201_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1c2",
    "name": "externallmg_1721794316340_1721794195201_image_13.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794316340_1721794195201_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1c3",
    "name": "externallmg_1721794316593_1721794195201_image_14.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794316593_1721794195201_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1c4",
    "name": "externallmg_1721794316959_1721794195201_image_15.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794316959_1721794195201_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a07f0d6e8f430d9508f1c5",
    "name": "externallmg_1721794317201_1721794195201_image_16.jpeg",
    "path": "cases/669b4ccfac43b53f525b725f/
externallmg_1721794317201_1721794195201_image_16.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a07eadb178c60d948353d4",
  "name": "externalImg_1721794220669_1721794108523_image_0.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externalImg_1721794220669_1721794108523_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a07eadb178c60d948353d5",
  "name": "externalImg_1721794220849_1721794108523_image_1.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externalImg_1721794220849_1721794108523_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a07eadb178c60d948353d6",
  "name": "externalImg_1721794221272_1721794115254_image_0.jpeg",
  "path": "cases/669b4ccfac43b53f525b725f/
externalImg_1721794221272_1721794115254_image_0.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW COSMOS.xlsx",
    "filename": "1721799826945_Calculation_Sheet_NEW_COSMOS.xlsx",
    "path": "cases/669b4ccfac43b53f525b725f/
processingDocuments/1721799826945_Calculation_Sheet_NEW_COSMOS.xlsx",
    "size": "2145745",
    "createdAt": "Wed Jul 24 2024 11:13:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
```



```
"createdBy": {
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "lastName": "Jadhav",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "669b75efac43b53f525ba147",
"note": "Value Given For Confirmation",
"taskId": "669b4cd035f7d73f39350099",
"createdAt": "2024-07-20T08:31:43.743Z"
}
],
"createdAt": "2024-07-20T05:36:15.938Z",
"updatedAt": "2024-07-24T09:21:56.016Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 505, 5th Floor, Wing - B, Parasnath Darshan Co-
Op. Hsg. Soc. Ltd., KiroL Kurla Road, Near Credit Line Showroom, Village - KiroL,
Vidhyavihar (West), Taluka - Kurla , District - Mumbai Suburban , PIN - 400 086, State -
Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Sudhir Harishchandra Chile",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"siteVisitContactNo": "9136768384",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
```

```
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 450.00",
"flatRate": "21000",
"landOtherRate": "18500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "447.95",
"extendOfSiteRemark": "",
"finalBuiltupArea": "492.75",
"finalCarpetArea": "447.95",
"finalSalableArea": "542.02",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + WC +
Bathroom",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Wed Jul 24 2024 11:42:04 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-07-23",
"finalSaleablePercentage": "0"
}
```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Living Room | 16'6" | 10'5" | 171.87 |
| Kitchen | 10'5" | 7'9" | 80.73 |
| Passage | 7'6" | 3'00" | 22.50 |
| Passage | 2'8" | 3'11" | 10.44 |
| WC | 4'4" | 3'3" | 14.08 |
| Bathroom | 4'3" | 7'5" | 31.52 |
| Bedroom | 12'1" | 9'8" | 116.81 |
| Other Composition : | | | |