

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "669907b22abbb93f33e91e42"
    },
    "firstName": "Prakash ",
    "type": "CREDITOFFICER",
    "_id": "669907ecac43b53f525ab4cd",
    "email": "prakash.shetkar@cosmosbank.in",
    "lastName": "Shetkar",
    "mobileNo": "",
    "workMobileNo": "9821469030"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1494000",
    "discussWithPerson": "Prakash ",
    "expectedFees": 747,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "669907b22abbb93f33e91e42",
  "name": "Gorai Branch",
  "branchCode": "",
  "mobileNo": "02228673716",
  "alternateMobileNo": "",
  "email": "prakash.shetkar@cosmosbank.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bungalow No 120-125, RDP -1, Opp Saibaba Mandir Gorai 1 Borivali
West Mumbai 400081"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
```

```
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.216992929959567",
  "longitude": "72.82291258039817"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82291258039817,
    19.216992929959567
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"schedule": [
  {
    "dateTime": "20/07/2024 05:16 pm"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-07-22",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-07-22",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Charkop",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Borivali ",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "25, RSC - 22",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Charkop Anupam Co-Op. Hsg. Soc. Ltd. ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "41(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Swami samarth Mandir Road ",
    "west": "Shiv Veer Building ",
    "south": "Torna CHSL ",
    "east": "Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space ",
      "east": "Lobby ",
      "south": "Flat No. 201",
      "west": "Marginal Space "
    },
    "asPerDocument": {
      "north": "Details not available ",
      "east": "Details not available ",
      "south": "Details not available ",
      "west": "Details not available "
    }
  }
}
```

```
    },
    "isDisplay": true,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "classOfSanitary": {
    "value": "superior_colored",
    "label": "Superior Colored"
  },
  "compoundWall": "6'.0\" High, R.C.C. column with B. B. masonry wall"
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "27",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "buildingServicesDepreciatedRate": "729",
  "depreciatedCostOfConstruction": "17271.00",
  "depreciatedBuildingRate": "1971"
},
"igrRate": {
  "propertyName": "Residential",
```

```
"rate": "138620",
"landRate": "59310",
"igrImage": "cases/669b906be4681c3f5823dd51/igr_1721733120579_Image.png",
"squareMeterGuideLineRate": "138620.00",
"squareFeetGuideLineRate": "12878.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "82",
  "rate": "11552.00",
  "squareFeetGuideLineRate": "11552.00",
  "squareMeterGuideLineRate": "124344.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "24,000.00 (Expected rental income per month)",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Good "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "rcc_Slab",
  "label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2006",
  "fullDate": "1/1/2006"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
```



```
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "42",
"ageOfBuilding": "18",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "2",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
"area": "656.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Agreement for sale"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Metro_Station",
"label": "Metro Station"
}
},
"routeMapImg": "cases/669b906be4681c3f5823dd51/
routeMap_1721736798088_Image.png",
"routeLat": "19.216896",
"routeLng": "72.822408",
"stationName": "Kandivali ",
"routeDistance": "2.5 Km. "
},
"finalLatLng": {
"coordinates": [
null,
null
]
```

```
    ],
    "type": "Point"
  },
  "showLocation": {
    "latlng": true,
    "finallatlng": true
  },
  "locationMapImg": [
    {
      "id": "o7a7aa",
      "name": "o7a7aa",
      "image": "cases/669b906be4681c3f5823dd51/
routeMap_1721735150992_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "1771200.00",
    "depreciationPercentage": "27",
    "depreciatedCostOfConstruction": "478224.00",
    "totalFairMarketValue": "11329776.00"
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11808000.00",
"finalValue": "11808000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7578112.00",
  "selectedBuildUpValue": "656.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "669f26a635f7d73f39367b24",
      "name": "externallmg_1721706150378_IMG20240722WA0066.jpg",
      "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150378_IMG20240722WA0066.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "669f26a635f7d73f39367b26",
      "name": "externallmg_1721706150390_IMG20240722WA0070.jpg",
      "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150390_IMG20240722WA0070.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "669f26a635f7d73f39367b1f",
      "name": "externallmg_1721706150352_IMG20240722WA0072.jpg",
      "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150352_IMG20240722WA0072.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "669f26a635f7d73f39367b1d",
      "name": "externallmg_1721706150347_IMG20240722WA0065.jpg",
      "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150347_IMG20240722WA0065.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "669f26a635f7d73f39367b1b",
    "name": "externallmg_1721706150340_IMG20240722WA0063.jpg",
    "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150340_IMG20240722WA0063.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f26a635f7d73f39367b19",
    "name": "externallmg_1721706150335_IMG20240722WA0061.jpg",
    "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150335_IMG20240722WA0061.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f26a635f7d73f39367b15",
    "name": "externallmg_1721706150325_IMG20240722WA0053.jpg",
    "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150325_IMG20240722WA0053.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f26a635f7d73f39367b16",
    "name": "externallmg_1721706150327_IMG20240722WA0057.jpg",
    "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150327_IMG20240722WA0057.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f26a635f7d73f39367b14",
    "name": "externallmg_1721706150322_IMG20240722WA0052.jpg",
    "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150322_IMG20240722WA0052.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f26a635f7d73f39367b1a",
    "name": "externallmg_1721706150338_IMG20240722WA0062.jpg",
    "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150338_IMG20240722WA0062.jpg",
    "orientation": "portrait"
  }
}
```

```
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "19765.00",
    "max": "23527.00"
  },
  "builtUpRateRange": {
    "min": "16471.00",
    "max": "19606.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "656.00",
"empanelmentNo": [
  "HO/CREDIT/67/ 2019-20"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669b906be4681c3f5823dd51",
"ownerName": "Mr. Narendra Ragho Angan & Mrs. Neha Narendra Ragho ",
"ownerPhoneNo": "9930861740",
"appAddress": "Flat no 202 A-wing 2 nd floor Charkop Anupam Co-op HSG Soc Ltd
Charkop Borivali West ",
"remark": "plan copy nahi ahe ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "10/09/2005",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Drashti Corporation ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Narendra Ragho Angane & Mrs. Neha Narendra Ragho ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "5107 / 2005"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "169244",
    "path": "cases/669b906be4681c3f5823dd51/
document_1721470964345_1721470855440_CB_Gorai_Narendra_Angane.pdf",
    "fileName":
"document_1721470964345_1721470855440_CB_Gorai_Narendra_Angane.pdf"
  }
],
"caseNumber": "010048",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
```

```
"id": "358160",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Sat Jul 20 2024 15:54:43 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Narendra Ragho Angane & Mrs. Neha Narendra Ragho ",
"phone": "9930861740",
"ownershipShare": "",
"email": "",
"id": "739684"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "119790",
"name": "Living Room",
"length": "19.00",
"length1": "19",
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "190.00",
"images": [],
"extraAreas": [],
"finalArea": "190.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "1",
"name": "Passage",
"length": "5.50",
"length1": "5",
"length2": "6",
```

```
"width": "3.42",
"width1": "3",
"width2": "5",
"totalArea": "18.79",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "669fa0a9fa8cc80d550c6808",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "3.25",
    "width1": "3",
    "width2": "3",
    "totalArea": "32.50"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "669fa147c474b30d54cc2b3b",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "17.00",
    "length1": "17",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "17.00"
  }
],
"finalArea": "68.28999999999999"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "2",
"name": "Kitchen",
"length": "11.42",
"length1": "11",
"length2": "5",
"width": "6.67",
"width1": "6",
"width2": "8",
"totalArea": "76.11",
"images": [],
"extraAreas": [],
"finalArea": "76.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "11.92",
  "width1": "11",
  "width2": "11",
  "totalArea": "112.21",
  "images": [],
```

```
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "669fa11a6e8f430d9508dcf9",
    "name": "Extra ",
    "extraAreaType": "Add",
    "length": "7.00",
    "length1": "7",
    "length2": "00",
    "width": "2.00",
    "width1": "2",
    "width2": "00",
    "totalArea": "14.00"
  }
],
"finalArea": "126.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "12.83",
  "length1": "12",
  "length2": "10",
  "width": "9.42",
  "width1": "9",
  "width2": "5",
  "totalArea": "120.85",
  "images": [],
  "finalArea": "120.85",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.00",
```

```
"length1": "4",
"length2": "00",
"width": "5.92",
"width1": "5",
"width2": "11",
"totalArea": "23.67",
"images": [],
"extraAreas": [],
"finalArea": "23.67"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "916531",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "656",
  "squareMeterArea": "60.94",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "500.00",
    "squareMeterArea": "46.45",
    "expectedRate": "22000.00",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "600.00",
```



```
"squareMeterArea": "55.74",
"expectedRate": "18333.33",
"percentage": "20"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "669f90227251527c6f4cd9e0",
"property": "Pooja Enclave, Charkop Kandivali West",
"area": "500",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "8",
"source": "https://www.99acres.com/",
"expectedPrice": "11000000",
"expectedRate": "22000.00",
"builtUpExpectedRate": "18333.33",
"image": "cases/669b906be4681c3f5823dd51/
indicator_1721732911383_Image.png",
"squareMeter": "46.45",
"id": "349426"
},
{
  "carpetArea": {
    "area": "708.33",
    "squareMeterArea": "65.81",
    "expectedRate": "19764.80",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "850.00",
    "squareMeterArea": "78.97",
    "expectedRate": "16470.59",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  }
}
```

```
},
"printlnReport": true,
"_id": "669f90227251527c6f4cd9e1",
"property": "Anupam CHSL., Charkop",
"area": "850",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "14000000",
"expectedRate": "19764.80",
"builtUpExpectedRate": "14000000",
"image": "cases/669b906be4681c3f5823dd51/
indicator_1721732974265_Image.png",
"squareMeter": "78.97",
"id": "120326"
},
{
"carpetArea": {
"area": "359.17",
"squareMeterArea": "33.37",
"expectedRate": "23526.46",
"percentage": ""
},
"builtUpArea": {
"area": "431.00",
"squareMeterArea": "40.04",
"expectedRate": "19605.57",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "669f90227251527c6f4cd9e2",
"property": "Charkop Anupam CHSL., Kandivali West",
"area": "431",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
```

```
"floor": "6",
"source": "Index_no.2",
"expectedPrice": "8450000",
"expectedRate": "23526.46",
"builtUpExpectedRate": "8450000",
"image": "cases/669b906be4681c3f5823dd51/
indicator_1721733046659_Image.png",
"squareMeter": "40.04",
"id": "522703"
}
],
"externallimages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f269035f7d73f39367a91",
"name": "externallmg_1721706126583_IMG20240722WA0048.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706126583_IMG20240722WA0048.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f269035f7d73f39367a92",
"name": "externallmg_r_1721706126535_20240722_221845.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externallmg_r_1721706126535_20240722_221845.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f269035f7d73f39367a93",
"name": "externallmg_r_1721706126553_20240722_221849.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externallmg_r_1721706126553_20240722_221849.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f26a635f7d73f39367b14",
"name": "externallmg_1721706150322_IMG20240722WA0052.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150322_IMG20240722WA0052.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b15",
  "name": "externallmg_1721706150325_IMG20240722WA0053.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150325_IMG20240722WA0053.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b16",
  "name": "externallmg_1721706150327_IMG20240722WA0057.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150327_IMG20240722WA0057.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b17",
  "name": "externallmg_1721706150330_IMG20240722WA0058.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150330_IMG20240722WA0058.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b18",
  "name": "externallmg_1721706150333_IMG20240722WA0060.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150333_IMG20240722WA0060.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b19",
  "name": "externallmg_1721706150335_IMG20240722WA0061.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150335_IMG20240722WA0061.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b1a",
  "name": "externallmg_1721706150338_IMG20240722WA0062.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150338_IMG20240722WA0062.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b1b",
  "name": "externallmg_1721706150340_IMG20240722WA0063.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150340_IMG20240722WA0063.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b1c",
  "name": "externallmg_1721706150343_IMG20240722WA0064.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150343_IMG20240722WA0064.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b1d",
  "name": "externallmg_1721706150347_IMG20240722WA0065.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150347_IMG20240722WA0065.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b1e",
  "name": "externallmg_1721706150350_IMG20240722WA0067.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150350_IMG20240722WA0067.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b1f",
  "name": "externallmg_1721706150352_IMG20240722WA0072.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150352_IMG20240722WA0072.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b20",
  "name": "externallmg_1721706150355_IMG20240722WA0050.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150355_IMG20240722WA0050.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b21",
  "name": "externallmg_1721706150358_IMG20240722WA0051.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150358_IMG20240722WA0051.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b22",
  "name": "externallmg_1721706150367_IMG20240722WA0056.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150367_IMG20240722WA0056.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f26a635f7d73f39367b23",
  "name": "externallmg_1721706150373_IMG20240722WA0059.jpg",
  "path": "cases/669b906be4681c3f5823dd51/
externallmg_1721706150373_IMG20240722WA0059.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f26a635f7d73f39367b24",
"name": "externalImg_1721706150378_IMG20240722WA0066.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externalImg_1721706150378_IMG20240722WA0066.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f26a635f7d73f39367b25",
"name": "externalImg_1721706150385_IMG20240722WA0068.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externalImg_1721706150385_IMG20240722WA0068.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "669f26a635f7d73f39367b26",
"name": "externalImg_1721706150390_IMG20240722WA0070.jpg",
"path": "cases/669b906be4681c3f5823dd51/
externalImg_1721706150390_IMG20240722WA0070.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "1719900577742_alculation_123_2.xlsx",
"filename": "1721733143155_1719900577742_alculation_123_2.xlsx",
"path": "cases/669b906be4681c3f5823dd51/
processingDocuments/1721733143155_1719900577742_alculation_123_2.xlsx",
"size": "825975",
"createdAt": "Tue Jul 23 2024 16:42:24 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
```

```
    "firstName": "Shobha",
    "lastName": "Kuperkar",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "669f629d0c695d563ade7d90",
  "note": "Pending for OC, Rate verification done",
  "taskId": "669ba3ea2abbb93f33ea29ec",
  "createdAt": "2024-07-23T07:58:21.335Z"
}
],
"createdAt": "2024-07-20T10:24:43.429Z",
"updatedAt": "2024-07-24T07:57:55.879Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. A-202, 2nd Floor, Wing - A, Charkop Anupam Co-
Op. Hsg. Soc. Ltd. , Plot No. 25, RSC - 22, Village - Charkop, Kandivali (West), Taluka -
Borivali , District - Mumbai Suburban , PIN - 400 067, State - Maharashtra, Country -
India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Narendra Ragho Angan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner ",
"siteVisitContactNo": "9930861740",
"buildingServicesRate": "2700",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 656.00",
"flatRate": "18000",
"landOtherRate": "15300",
```



```

"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "631.56",
"extendOfSiteRemark": "",
"finalBuiltupArea": "696.44",
"finalCarpetArea": "633.13",
"finalSalableArea": "766.09",
"otherCarpetTotal": "0.00",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"reportGeneratedDate": "Wed Jul 24 2024 17:39:54 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-07-22"
}

```

Name	Length	Width	Total
Composition :			
Living Room	19'00"	10'00"	190.00
Passage	5'6"	3'5"	18.79

Kitchen	11'5"	6'8"	76.11
Toilet	7'00"	4'00"	28.00
Bedroom	9'5"	11'11"	112.21
Bedroom	12'10"	9'5"	120.85
Toilet	4'00"	5'11"	23.67
Other Composition :			