

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6363a4944d42487767aea48c"
    },
    "firstName": "Amresh",
    "type": "CREDITOFFICER",
    "_id": "667a41bca27f7d554f531f46",
    "email": "amresh.rai@sbi.co.in",
    "lastName": "Bahadur",
    "mobileNo": "0224163741",
    "workMobileNo": "9481528704"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Amresh",
    "expectedFees": null,
    "quotedAmount": "30000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6363a4944d42487767aea48c",
  "name": "SME NARIMAN POINT",
  "branchCode": "6945",
  "mobileNo": "022-22852674, 022-22028789",
  "alternateMobileNo": "",
  "email": "sbi.06945@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Dalamal House, Jamnalal Bajaj Marg, Nariman Point, Mumbai - 400 021."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "65dee3f79a876858ab30487f",
"role": "SITEENGINEER",
"firstName": "Saiprasad",
"email": "saiprasadpatil1010@gmail.com",
"lastName": "Patil",
"mobileNo": "8830049996",
"designation": "Valuation Engineer",
"shortName": "SSP",
"workWithDocumentMaker": "60f91822f3dd69653a5922e3",
"profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.05984653150938",
  "longitude": "73.04312017597385"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.04312017597385,
    19.05984653150938
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/07/2024 10:28 am"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
```

```
"key": "village",
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shade no W 59",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "T T C INdustrial Area",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```

```
"value": "",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```



```
"status": false,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
}
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```



```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669f2eebe4681c3f5824b32e",
"ownerName": "Sai Engineering Work ",
"ownerPhoneNo": "9820083232",
"appAddress": "Shed No W-59,Plot no N-7,T.T.C Industrial Area, Rabale Navi Mumbai",
"remark": "Or \n\nArun Guram- 9820083232",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669f2eebe4681c3f5824b32e/
document_1721707969756_1721707863044_2.pdf",
    "fileName": "document_1721707969756_1721707863044_2.pdf",
    "id": "848398",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Jul 23 2024 09:47:47 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Building Plan",
      "value": "60ae124eaa6d152c1801b308"
    },
    "isHardCopy": false,
```

```
    "displayStatus": false,
    "path": "cases/669f2eebe4681c3f5824b32e/
document_1721708324172_1721708207153_3.pdf",
    "fileName": "document_1721708324172_1721708207153_3.pdf",
    "id": "698274",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Jul 23 2024 09:49:16 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010086",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "615648",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 23 2024 09:47:47 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sai Engineering Work ",
    "phone": "9820083232",
    "ownershipShare": "",
    "email": "",
    "id": "148042"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669faafac474b30d54cc35ec",
    "name": "externalImg_1721739972409_1721739866261_image_0.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externalImg_1721739972409_1721739866261_image_0.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "669faafac474b30d54cc35ed",
  "name": "externallmg_1721739996577_1721739866261_image_1.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721739996577_1721739866261_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "669faafac474b30d54cc35ee",
  "name": "externallmg_1721739999975_1721739866261_image_2.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721739999975_1721739866261_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e70d",
  "name": "externallmg_1721740247579_1721740006523_image_0.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740247579_1721740006523_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e70e",
  "name": "externallmg_1721740247647_1721740006523_image_1.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740247647_1721740006523_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e70f",
  "name": "externallmg_1721740247740_1721740006523_image_2.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740247740_1721740006523_image_2.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e710",
    "name": "externallmg_1721740247882_1721740006523_image_3.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740247882_1721740006523_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e711",
    "name": "externallmg_1721740248092_1721740006523_image_4.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248092_1721740006523_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e712",
    "name": "externallmg_1721740248165_1721740006523_image_5.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248165_1721740006523_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e713",
    "name": "externallmg_1721740248335_1721740006523_image_6.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248335_1721740006523_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e714",
    "name": "externallmg_1721740248403_1721740006523_image_7.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248403_1721740006523_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "669fabda6e8f430d9508e715",
  "name": "externallmg_1721740248485_1721740006523_image_8.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248485_1721740006523_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e716",
  "name": "externallmg_1721740248644_1721740006523_image_9.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248644_1721740006523_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e717",
  "name": "externallmg_1721740248753_1721740006523_image_10.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248753_1721740006523_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e718",
  "name": "externallmg_1721740248846_1721740006523_image_11.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740248846_1721740006523_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fabda6e8f430d9508e719",
  "name": "externallmg_1721740249017_1721740006523_image_12.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249017_1721740006523_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "669fabda6e8f430d9508e71a",
    "name": "externallmg_1721740249137_1721740006523_image_13.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249137_1721740006523_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e71b",
    "name": "externallmg_1721740249261_1721740006523_image_14.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249261_1721740006523_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e71c",
    "name": "externallmg_1721740249322_1721740006523_image_15.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249322_1721740006523_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e71d",
    "name": "externallmg_1721740249416_1721740006523_image_16.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249416_1721740006523_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e71e",
    "name": "externallmg_1721740249510_1721740006523_image_17.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249510_1721740006523_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e71f",
```

```
    "name": "externallmg_1721740249658_1721740006523_image_18.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249658_1721740006523_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fabda6e8f430d9508e720",
    "name": "externallmg_1721740249787_1721740006523_image_19.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740249787_1721740006523_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36a5",
    "name": "externallmg_1721740287982_1721740181331_image_0.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740287982_1721740181331_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36a6",
    "name": "externallmg_1721740288048_1721740181331_image_1.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288048_1721740181331_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36a7",
    "name": "externallmg_1721740288132_1721740181331_image_2.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288132_1721740181331_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36a8",
    "name": "externallmg_1721740288217_1721740181331_image_3.jpeg",
```

```
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288217_1721740181331_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36a9",
    "name": "externallmg_1721740288302_1721740181331_image_4.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288302_1721740181331_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36aa",
    "name": "externallmg_1721740288456_1721740181331_image_5.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288456_1721740181331_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36ab",
    "name": "externallmg_1721740288528_1721740181331_image_6.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288528_1721740181331_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36ac",
    "name": "externallmg_1721740288648_1721740181331_image_7.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288648_1721740181331_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669fac01c474b30d54cc36ad",
    "name": "externallmg_1721740288729_1721740181331_image_8.jpeg",
    "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288729_1721740181331_image_8.jpeg",
```



```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fac01c474b30d54cc36ae",
  "name": "externallmg_1721740288858_1721740181331_image_9.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288858_1721740181331_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fac01c474b30d54cc36af",
  "name": "externallmg_1721740288962_1721740181331_image_10.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740288962_1721740181331_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fac01c474b30d54cc36b0",
  "name": "externallmg_1721740289074_1721740181331_image_11.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740289074_1721740181331_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fac01c474b30d54cc36b1",
  "name": "externallmg_1721740289176_1721740181331_image_12.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740289176_1721740181331_image_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669fac01c474b30d54cc36b2",
  "name": "externallmg_1721740289262_1721740181331_image_13.jpeg",
  "path": "cases/669f2eebe4681c3f5824b32e/
externallmg_1721740289262_1721740181331_image_13.jpeg",
  "orientation": "landscape"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-07-23T04:17:47.411Z",
  "updatedAt": "2024-07-23T13:11:29.831Z",
  "__v": 0,
  "uniqueNo": "",
  "updatedBy": "65dee3f79a876858ab30487f",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  },
  "fullAddress": "Residential Land and Building No. Ground Floor, Shade no W 59, T T C
Industrial Area, Navi Mumbai, State - Maharashtra, India",
  "addressForMap": "",
  "caseReferredBy": "60af3d172ffdf65bcd6585cd",
  "contactPersonName": "Sai Engineering Work ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9820083232"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			