

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b803"
    },
    "firstName": "Deepak",
    "type": "CREDITOFFICER",
    "_id": "657ade273fcadc677769e8b4",
    "lastName": "Barman",
    "mobileNo": "",
    "workMobileNo": "9854990340",
    "email": "deepak.barman@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "70000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b803",
  "branchCode": "000076",
  "type": "BRANCH",
  "name": "Commercial Branch (Vile Parle)",
  "email": "sbi.04115@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Parle Square Building, 3rd Floor, B.N. Agarwal Commercial Complex,
Monghibai Road, Vile Parle (East), Mumbai - 400 057, State - Maharashtra, Country -
India",
  "ledgerName": "STATE BANK OF INDIA - CM VILE PARLE",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
```

```
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
},
{
"value": "AM161706-3",
"label": "Chartered Engineer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.118418830511306",
  "longitude": "72.94083345567945"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Hariyali of MSD",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vikhroli (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Manas CHS",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Kannamwar Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
```



```
"value": "Sai Laxmi Residency",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "356 (pt.)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
```

```
"status": true,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "S",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400083",
```

```
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669f7c2ca139cc568c47fe49",
"ownerName": "M/s. Om Sai SSS Developers Thane",
"ownerPhoneNo": "9821615358",
"fullAddress": "Residential Project Finance No. Basement Floor, Manas CHS, Sai
Laxmi Residency, Kannamwar Nagar, CTS No. 356 (pt.), Village - Hariyali of MSD,
Municipality Ward No. S, Taluka - Kurla, District - Mumbai Suburban, Vikhroli (East),
400083",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "05/04/2022",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "P51800034454"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1721727966485_RERA_Certificate.pdf",
    "path": "cases/669f7c2ca139cc568c47fe49/
document_1721727966485_RERA_Certificate.pdf",
    "id": "870441",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Tue Jul 23 2024 15:17:24 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"gstNo": "",
"caseNumber": "010103",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "739498",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 23 2024 15:17:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Om Sai SSS Developers Thane",
    "phone": "9821615358",
    "ownershipShare": "",
    "email": "",
    "id": "422073"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a0dd3d73ce9d724ff9d0ae",
    "name": "externalImg_1721818427262_1721818318989_image_0.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/externalImg_1721818427262_1721818318989_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "66a0dd3d73ce9d724ff9d0af",
  "name": "externallmg_1721818427696_1721818318989_image_1.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818427696_1721818318989_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dd3d73ce9d724ff9d0b0",
  "name": "externallmg_1721818428117_1721818318989_image_2.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818428117_1721818318989_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66a0dd3d73ce9d724ff9d0b1",
  "name": "externallmg_1721818428503_1721818318989_image_3.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818428503_1721818318989_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dd7520bf0172211c04a7",
  "name": "externallmg_1721818469814_1721818347399_image_0.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818469814_1721818347399_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dd7520bf0172211c04a8",
  "name": "externallmg_1721818470850_1721818347399_image_1.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818470850_1721818347399_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a0dd7520bf0172211c04a9",
    "name": "externallmg_1721818471564_1721818347399_image_2.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818471564_1721818347399_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04aa",
    "name": "externallmg_1721818472557_1721818347399_image_3.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818472557_1721818347399_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04ab",
    "name": "externallmg_1721818473310_1721818347399_image_4.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818473310_1721818347399_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04ac",
    "name": "externallmg_1721818473995_1721818347399_image_5.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818473995_1721818347399_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04ad",
    "name": "externallmg_1721818474888_1721818347399_image_6.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818474888_1721818347399_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04ae",
```

```
    "name": "externallmg_1721818476087_1721818347399_image_7.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818476087_1721818347399_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04af",
    "name": "externallmg_1721818477061_1721818347399_image_8.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818477061_1721818347399_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b0",
    "name": "externallmg_1721818478180_1721818347399_image_9.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818478180_1721818347399_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b1",
    "name": "externallmg_1721818478744_1721818347399_image_10.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818478744_1721818347399_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b2",
    "name": "externallmg_1721818479217_1721818347399_image_11.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818479217_1721818347399_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b3",
    "name": "externallmg_1721818479875_1721818347399_image_12.jpeg",
```

```
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818479875_1721818347399_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b4",
    "name": "externallmg_1721818480443_1721818347399_image_13.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818480443_1721818347399_image_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b5",
    "name": "externallmg_1721818480993_1721818347399_image_14.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818480993_1721818347399_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b6",
    "name": "externallmg_1721818481500_1721818347399_image_15.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818481500_1721818347399_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b7",
    "name": "externallmg_1721818482465_1721818347399_image_16.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818482465_1721818347399_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0dd7520bf0172211c04b8",
    "name": "externallmg_1721818483201_1721818347399_image_17.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818483201_1721818347399_image_17.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dd7520bf0172211c04b9",
  "name": "externallmg_1721818484005_1721818347399_image_18.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818484005_1721818347399_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0dd7520bf0172211c04ba",
  "name": "externallmg_1721818484964_1721818347399_image_19.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818484964_1721818347399_image_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1a3",
  "name": "externallmg_1721818528429_1721818421944_image_0.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818528429_1721818421944_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1a4",
  "name": "externallmg_1721818529893_1721818421944_image_1.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818529893_1721818421944_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1a5",
  "name": "externallmg_1721818530946_1721818421944_image_2.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818530946_1721818421944_image_2.jpeg",
  "orientation": "landscape"
}
```



```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddb673ce9d724ff9d1a6",
    "name": "externallmg_1721818532343_1721818421944_image_3.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818532343_1721818421944_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddb673ce9d724ff9d1a7",
    "name": "externallmg_1721818533655_1721818421944_image_4.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818533655_1721818421944_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddb673ce9d724ff9d1a8",
    "name": "externallmg_1721818534313_1721818421944_image_5.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818534313_1721818421944_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddb673ce9d724ff9d1a9",
    "name": "externallmg_1721818536085_1721818421944_image_6.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818536085_1721818421944_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddb673ce9d724ff9d1aa",
    "name": "externallmg_1721818537316_1721818421944_image_7.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818537316_1721818421944_image_7.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1ab",
  "name": "externallmg_1721818539734_1721818421944_image_8.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818539734_1721818421944_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1ac",
  "name": "externallmg_1721818541904_1721818421944_image_9.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818541904_1721818421944_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1ad",
  "name": "externallmg_1721818543562_1721818421944_image_10.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818543562_1721818421944_image_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1ae",
  "name": "externallmg_1721818544120_1721818421944_image_11.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818544120_1721818421944_image_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1af",
  "name": "externallmg_1721818544905_1721818421944_image_12.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818544905_1721818421944_image_12.jpeg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a0ddb673ce9d724ff9d1b0",
"name": "externallmg_1721818545281_1721818421944_image_13.jpeg",
"path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818545281_1721818421944_image_13.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a0ddb673ce9d724ff9d1b1",
"name": "externallmg_1721818545803_1721818421944_image_14.jpeg",
"path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818545803_1721818421944_image_14.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a0ddb673ce9d724ff9d1b2",
"name": "externallmg_1721818546333_1721818421944_image_15.jpeg",
"path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818546333_1721818421944_image_15.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a0ddb673ce9d724ff9d1b3",
"name": "externallmg_1721818547116_1721818421944_image_16.jpeg",
"path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818547116_1721818421944_image_16.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a0ddb673ce9d724ff9d1b4",
"name": "externallmg_1721818547725_1721818421944_image_17.jpeg",
"path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818547725_1721818421944_image_17.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a0ddb673ce9d724ff9d1b5",
  "name": "externallmg_1721818548472_1721818421944_image_18.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818548472_1721818421944_image_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddb673ce9d724ff9d1b6",
  "name": "externallmg_1721818548952_1721818421944_image_19.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818548952_1721818421944_image_19.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddc833eb9d72554acb97",
  "name": "externallmg_1721818565613_1721818458230_image_0.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818565613_1721818458230_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddc833eb9d72554acb98",
  "name": "externallmg_1721818565904_1721818458230_image_1.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818565904_1721818458230_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0ddc833eb9d72554acb99",
  "name": "externallmg_1721818566497_1721818458230_image_2.jpeg",
  "path": "cases/669f7c2ca139cc568c47fe49/
externallmg_1721818566497_1721818458230_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a0ddc833eb9d72554acb9a",
    "name": "externalimg_1721818566757_1721818458230_image_3.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externalimg_1721818566757_1721818458230_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddc833eb9d72554acb9b",
    "name": "externalimg_1721818567233_1721818458230_image_4.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externalimg_1721818567233_1721818458230_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0ddc833eb9d72554acb9c",
    "name": "externalimg_1721818567467_1721818458230_image_5.jpeg",
    "path": "cases/669f7c2ca139cc568c47fe49/
externalimg_1721818567467_1721818458230_image_5.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-23T09:47:24.449Z",
"updatedAt": "2024-07-24T10:56:08.033Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Om Sai SSS Developers Thane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9821615358"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			