

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "firstName": "Shivani ",
    "type": "CREDITOFFICER",
    "_id": "64d4829d87258203eab0d8d8",
    "lastName": "Yadav",
    "mobileNo": "",
    "workMobileNo": "8240289378",
    "email": "racpcghatkopar.sanctions@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Shivani ",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.175226505189347",
  "longitude": "72.97253168861666"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.97253168861666,
    19.175226505189347
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "23/07/2024 05:49 pm"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-25T18:12:15.554Z",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "24000",
  "lumpsumValue": "1",
  "rateMax": "25000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai Suburban District",
    "label": true
  },
  "city": {
```

```
"status": false,
"name": "City",
"key": "city",
"value": "",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Brighton Tower Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
```



```
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Eastern Express Highway",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Hari Om Nagar",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "40/1 Part",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "95/1, 95/2, 95/3 & 96/1",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "603",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "T - Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```

```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 081",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund (East), Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  }
},
}
```

```
"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "label": "Powder coated Aluminum sliding windows",
  "value": "Powder_coated_Aluminum_sliding_windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Millennium Park Building No. 4",
    "west": "Road",
    "south": "Road",
    "east": "Jain Temple & Ratnashree Tower-2"
  },
  "asPerDocumentAgreement": {
```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Lift",
    "east": "Flat No. 601 & 602",
    "south": "Staircase",
    "west": "Flat No. 604"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Occupancy Certificate Document No. CE /
4751 / BPES / AT dated 04.02.2010 issued by Municipal Corporation of Greater
Mumbai",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
```

```
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "21",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "22370",
  "depreciatedBuildingRate": "2370"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "142910",
  "landRate": "59750",
  "igrImage": "cases/669f97cc98649b7c2c336a80/igr_1721912369330_Image.png",
  "squareMeterGuideLineRate": "150056.00",
  "squareFeetGuideLineRate": "13941.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "86",
  "rate": "12766.00",
  "squareFeetGuideLineRate": "12766.00",
  "squareMeterGuideLineRate": "137413.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": "47,000/- Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
```

```
"floorSpaceIndex": "As per MCGM noms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": "Along with Stilt Parking space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2010",
    "fullDate": "1/1/2010"
  },
  "planningArea": {
    "label": "Residential",
```

```
"value": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
}
```



```
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "46",
"ageOfBuilding": "14",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "1",
"noOfFloors": "17",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "1214.40",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/669f97cc98649b7c2c336a80/
routeMap_1721973286317_Image.png",
```

```
"routeLat": "19.175128",
"routeLng": "72.972075",
"stationName": "Thane",
"routeDistance": "1.6 Km.",
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
}
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "csidp",
    "name": "csidp",
    "image": "cases/669f97cc98649b7c2c336a80/
routeMap_1721973248730_Image.png"
  }
],
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "22638440.00",
"finalValue": "22638440.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "15503030.00",
  "selectedBuildUpValue": "1214.40",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66a295d2197cde340b3f2733",
      "name": "externalImg_1721931198828_image.jpeg",
      "path": "cases/669f97cc98649b7c2c336a80/
externalImg_1721931198828_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66a2951c8b202f344c31113e",
      "name": "externalImg_1721931005184_image.jpeg",
      "path": "cases/669f97cc98649b7c2c336a80/
externalImg_1721931005184_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66a295d2197cde340b3f2733",
      "name": "externalImg_1721931198828_image.jpeg",
```

```
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931198828_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a295d2197cde340b3f2735",
    "name": "externallmg_1721931207778_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931207778_image.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "66a295d2197cde340b3f2736",
    "name": "externallmg_1721931212749_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931212749_image.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "66a2951c8b202f344c31113d",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931001655_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c31113f",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931005909_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c311141",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931010629_image.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c311142",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931012579_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c311144",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931014889_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c311147",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931018304_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c311149",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931020159_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c311148",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931019544_image.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c31114a",
    "name": "Living Room",
```



```
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931021415_image.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "66a2951c8b202f344c31114c",
    "name": "Living Room",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931026399_image.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "21257.00",
    "max": "25239.00"
  },
  "builtUpRateRange": {
    "min": "17005.00",
    "max": "21033.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1012.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669f97cc98649b7c2c336a80",
"ownerName": "Mr. Shantaram Gurunath Shet & Mrs. Radha Gurunath Shet",
"ownerPhoneNo": "9820651422",
"appAddress": "Flat no. 603, 6th Floor, Brighton, Hari Om Nagar, Mulund East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/01/2006",
      "remark": "(8 Pages from documents)",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s. Gautam Enterprises",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Shantaram Gurunath Shet & Mrs. Radha Gurunath Shet",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "319/2006"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "545000",
    "path": "cases/669f97cc98649b7c2c336a80/
document_1721735034737_1721734929734_Racpc_Ghatkopar_Shatararam_Shet.pdf",
```

```
"fileName":
"document_1721735034737_1721734929734_Racpc_Ghatkopar_Shataran_Shet.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "04/02/2010",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CE / 4751 / BPES / AT"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName":
"document_1721976189063_Occupation_Certificate_of_Brighton_Society_PDF.pdf",
  "path": "cases/669f97cc98649b7c2c336a80/
document_1721976189063_Occupation_Certificate_of_Brighton_Society_PDF.pdf",
  "id": "940388",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Fri Jul 26 2024 12:13:09 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010114",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "103862",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 23 2024 17:15:16 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Shantaram Gurunath Shet & Mrs. Radha Gurunath Shet",
    "phone": "9820651422",
    "ownershipShare": ""
  }
]
```

```
"email": "",
  "id": "839194"
},
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "66a29435d45eb4344309de0a",
    "area": "1051",
    "providedByName": "Shantaram Gurunath Shet And Mrs Radha Gurunath Shet",
    "providedByContactNo": "9820651422"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "14",
    "name": "Living Room",
    "length": "10.50",
    "length1": "10",
    "length2": "6",
    "width": "18.83",
    "width1": "18",
    "width2": "10",
    "totalArea": "197.75",
    "images": [],
    "finalArea": "197.75",
    "extraAreas": []
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "14",
```

```
"name": "Passage",
"length": "11.50",
"length1": "11",
"length2": "6",
"width": "5.33",
"width1": "5",
"width2": "4",
"totalArea": "61.33",
"images": [],
"finalArea": "61.33",
"extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "8.67",
  "width1": "8",
  "width2": "8",
  "totalArea": "37.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "37.56"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "7.50",
  "length1": "7",
  "length2": "6",
  "width": "11.42",
  "width1": "11",
  "width2": "5",
  "totalArea": "85.62",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "85.62"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "28.26",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.26"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "13.33",
  "width1": "13",
  "width2": "4",
  "totalArea": "126.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "126.67"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.92",
```



```
"length1": "3",
"length2": "11",
"width": "7.92",
"width1": "7",
"width2": "11",
"totalArea": "31.01",
"images": [],
"extraAreas": [],
"finalArea": "31.01"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "1.58",
  "width1": "1",
  "width2": "7",
  "totalArea": "5.01",
  "images": [],
  "extraAreas": [],
  "finalArea": "5.01"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "5.50",
  "width1": "5",
  "width2": "6",
  "totalArea": "25.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.67"
},
}
```

```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "4.75",
  "length1": "4",
  "length2": "9",
  "width": "5.75",
  "width1": "5",
  "width2": "9",
  "totalArea": "27.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.31"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Bedroom",
  "length": "10.50",
  "length1": "10",
  "length2": "6",
  "width": "14.08",
  "width1": "14",
  "width2": "1",
  "totalArea": "147.87",
  "images": [],
  "extraAreas": [],
  "finalArea": "147.87"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
```

```
"width": "7.58",
"width1": "7",
"width2": "7",
"totalArea": "32.23",
"images": [],
"extraAreas": [],
"finalArea": "32.23"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "12.67",
  "length1": "12",
  "length2": "8",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "127.72",
  "images": [],
  "extraAreas": [],
  "finalArea": "127.72"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "13",
  "name": "Store Room",
  "length": "4.92",
  "length1": "4",
  "length2": "11",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "38.51",
  "images": [],
  "extraAreas": [],
  "finalArea": "38.51"
}
],
"otherComposition": [
```

```
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "8.58",
  "width1": "8",
  "width2": "7",
  "totalArea": "35.05",
  "images": [],
  "extraAreas": [],
  "finalArea": "35.05",
  "percentageBeforeTotal": "35.05",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "10.42",
  "width1": "10",
```

```
"width2": "5",
"totalArea": "29.51",
"images": [],
"extraAreas": [],
"finalArea": "29.51",
"percentageBeforeTotal": "29.51",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "length": "1.58",
  "length1": "1",
  "length2": "7",
  "width": "10.83",
  "width1": "10",
  "width2": "10",
  "totalArea": "17.15",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.15",
  "percentageBeforeTotal": "17.15",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "292345",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "1012",
  "squareMeterArea": "94.02",
  "docFinalBuiltUp": "1214.4",
  "docFinalBuiltUpSquareMeter": "112.824",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "1035.00",
      "squareMeterArea": "96.15",
      "expectedRate": "21256.04",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "1293.75",
      "squareMeterArea": "120.19",
      "expectedRate": "17004.83",
      "percentage": "25"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "66a24c39bc6e5d340a0aad73",
  "property": "Hari Om Nagar, Mulund East",
  "area": "1035",
  "builtUpPercentage": "25",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "22000000",
  "expectedRate": "21256.04",
```

```
"builtUpExpectedRate": "17004.83",
"image": "cases/669f97cc98649b7c2c336a80/
indicator_1721911998232_Image.png",
"squareMeter": "96.15",
"id": "164587"
},
{
"carpetArea": {
"area": "445.00",
"squareMeterArea": "41.34",
"expectedRate": "23595.51",
"percentage": ""
},
"builtUpArea": {
"area": "534.00",
"squareMeterArea": "49.61",
"expectedRate": "19662.92",
"percentage": "20"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "66a24c39bc6e5d340a0aad74",
"property": "Hari Om Nagar, Mulund East",
"area": "445",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Nobroker.com",
"expectedPrice": "10500000",
"expectedRate": "23595.51",
"builtUpExpectedRate": "19662.92",
"image": "cases/669f97cc98649b7c2c336a80/
indicator_1721912041193_Image.png",
"squareMeter": "41.34",
"id": "836285"
},
{
"carpetArea": {
"area": "645.83",
```

```
    "squareMeterArea": "60.00",
    "expectedRate": "25238.84",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "775.00",
    "squareMeterArea": "72.00",
    "expectedRate": "21032.26",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66a24c39bc6e5d340a0aad75",
  "property": "Millennium Park,Hari Om Nagar Mulund East",
  "area": "775",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "3",
  "source": "Index_no.2",
  "expectedPrice": "16300000",
  "expectedRate": "25238.84",
  "builtUpExpectedRate": "16300000",
  "image": "cases/669f97cc98649b7c2c336a80/
indicator_1721912193531_Image.png",
  "squareMeter": "72.00",
  "id": "337003"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31113a",
    "name": "externalImg_1721930991717_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externalImg_1721930991717_image.jpeg",
    "orientation": "landscape"
  },
  {
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31113b",
    "name": "externallmg_1721930994150_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721930994150_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31113c",
    "name": "externallmg_1721930998184_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721930998184_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31113d",
    "name": "externallmg_1721931001655_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931001655_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31113e",
    "name": "externallmg_1721931005184_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931005184_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31113f",
    "name": "externallmg_1721931005909_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931005909_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a2951c8b202f344c311140",
  "name": "externalimg_1721931008772_image.jpeg",
  "path": "cases/669f97cc98649b7c2c336a80/
externalimg_1721931008772_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a2951c8b202f344c311141",
  "name": "externalimg_1721931010629_image.jpeg",
  "path": "cases/669f97cc98649b7c2c336a80/
externalimg_1721931010629_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a2951c8b202f344c311142",
  "name": "externalimg_1721931012579_image.jpeg",
  "path": "cases/669f97cc98649b7c2c336a80/
externalimg_1721931012579_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a2951c8b202f344c311143",
  "name": "externalimg_1721931013964_image.jpeg",
  "path": "cases/669f97cc98649b7c2c336a80/
externalimg_1721931013964_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a2951c8b202f344c311144",
  "name": "externalimg_1721931014889_image.jpeg",
  "path": "cases/669f97cc98649b7c2c336a80/
externalimg_1721931014889_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a2951c8b202f344c311145",
    "name": "externallmg_1721931016904_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931016904_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c311146",
    "name": "externallmg_1721931017655_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931017655_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c311147",
    "name": "externallmg_1721931018304_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931018304_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c311148",
    "name": "externallmg_1721931019544_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931019544_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c311149",
    "name": "externallmg_1721931020159_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931020159_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31114a",
```

```
    "name": "externallmg_1721931021415_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931021415_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31114b",
    "name": "externallmg_1721931022769_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931022769_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a2951c8b202f344c31114c",
    "name": "externallmg_1721931026399_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931026399_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295d2197cde340b3f2733",
    "name": "externallmg_1721931198828_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931198828_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295d2197cde340b3f2734",
    "name": "externallmg_1721931204608_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931204608_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295d2197cde340b3f2735",
    "name": "externallmg_1721931207778_image.jpeg",
```

```
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931207778_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295d2197cde340b3f2736",
    "name": "externallmg_1721931212749_image.jpeg",
    "path": "cases/669f97cc98649b7c2c336a80/
externallmg_1721931212749_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1720174121221_1709206285749_Calculation.xlsx",
    "filename": "1721912394502_1720174121221_1709206285749_Calculation.xlsx",
    "path": "cases/669f97cc98649b7c2c336a80/processingDocuments/1721912394502
_1720174121221_1709206285749_Calculation.xlsx",
    "size": "880440",
    "createdAt": "Thu Jul 25 2024 18:29:55 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_14372.pdf",
    "filename": "1721912395250_igr_14372.pdf",
    "path": "cases/669f97cc98649b7c2c336a80/
processingDocuments/1721912395250_igr_14372.pdf",
    "size": "191376",
    "createdAt": "Thu Jul 25 2024 18:29:55 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "igr_15537.pdf",
    "filename": "1721912395323_igr_15537.pdf",
    "path": "cases/669f97cc98649b7c2c336a80/
processingDocuments/1721912395323_igr_15537.pdf",
    "size": "150739",
    "createdAt": "Thu Jul 25 2024 18:29:55 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "Occupation Certificate of Brighton Society PDF.pdf",
    "filename":
"1721912395347_Occupation_Certificate_of_Brighton_Society_PDF.pdf",
```

```
"path": "cases/669f97cc98649b7c2c336a80/processingDocuments/1721912395347_Occupation_Certificate_of_Brighton_Society_PDF.pdf",
"size": "143461",
"createdAt": "Thu Jul 25 2024 18:29:55 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "FINAL.xlsx",
"filename": "1721977079675_FINAL.xlsx",
"path": "cases/669f97cc98649b7c2c336a80/processingDocuments/1721977079675_FINAL.xlsx",
"size": "881760",
"createdAt": "Fri Jul 26 2024 12:28:00 GMT+0530 (India Standard Time)",
"uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-23T11:45:16.128Z",
"updatedAt": "2024-07-26T09:33:19.169Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
},
"fullAddress": "Residential Flat No. 603, 6th Floor, Brighton Tower Co-op. Hsg. Soc. Ltd., Hari Om Nagar, Plot No. 1, Eastern Express Highway, Village - Mulund, Municipality Ward No. T - Ward, Mulund (East), Mumbai, Taluka - Kurla, District - Mumbai Suburban District, PIN Code - 400 081, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Shantaram Gurunath Shet ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9820651422",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
```

```
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1012.00",
"flatRate": "23000",
"landOtherRate": "20000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 5 Passage + 3 Toilet +
Store Room",
"carpetTotal": "972.5199999999999",
"otherCarpetTotal": "81.71",
"siteVisitDate": "2024-07-25",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "81.71",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "1265.08",
"finalCarpetArea": "1054.23",
"finalSalableArea": "1391.58",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 973.00\nBalcony Area in Sq.
Ft. = 35.00\nFlowerbed Area in Sq. Ft. = 47.00\nTotal Carpet Area in Sq. Ft. =
1055.00\n(Area as per Actual Site Measurement)"
```

Name	Length	Width	Total
Composition :			
Living Room	10'6"	18'10"	197.75
Passage	11'6"	5'4"	61.33
Passage	4'4"	8'8"	37.56
Kitchen	7'6"	11'5"	85.62
Passage	3'1"	9'2"	28.26
Bedroom	9'6"	13'4"	126.67
Toilet	3'11"	7'11"	31.01
Passage	3'2"	1'7"	5.01
Toilet	4'8"	5'6"	25.67
Passage	4'9"	5'9"	27.31
Bedroom	10'6"	14'1"	147.87
Toilet	4'3"	7'7"	32.23
Bedroom	12'8"	10'1"	127.72
Store Room	4'11"	7'10"	38.51
Other Composition :			
Balcony Area	4'1"	8'7"	35.05
Flowered Area	2'10"	10'5"	29.51
Flowered Area	1'7"	10'10"	17.15