

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64c89274a5c3051014f5bc25"
    },
    "firstName": "Maitrayee Shrimali",
    "type": "CREDITOFFICER",
    "_id": "64c89274a5c3051014f5bc27",
    "lastName": "Shrimali",
    "mobileNo": "",
    "workMobileNo": "8879006150",
    "email": "Maitrayee.Shrimali@pnb.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Maitrayee Shrimali",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64c89274a5c3051014f5bc25",
  "name": "Mulund (W) Zaver Road Branch ",
  "branchCode": "",
  "mobileNo": "0222568",
  "alternateMobileNo": "",
  "email": "bo1277@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "51, Bhagwan Das Apartment, Near Raghvendra Swami Jain Temple,
Zaver Road, Mulund West, Mumbai - 400 080 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "648fcad91b499c2d52dc86f3",
    "role": "SITEENGINEER",
    "firstName": "Barkat",
    "email": "barkathodekar68@gmail.com",
    "lastName": "Hodekar",
    "mobileNo": "8879011615",
    "designation": "Site Engg",
    "shortName": "Barkat",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
```

```
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.187056730541148",
  "longitude": "72.94041305780411"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.94041305780411,
    19.187056730541148
  ]
}
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "23/07/2024 05:45 pm"
  },
  {
    "dateTime": "23/07/2024 12:00 am"
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B3",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Lok Nisarga CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Bal rajeshwar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Vaishali Nagar ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400080",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mulund West",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669f98e0c474b30d54cc1ff8",
"ownerName": "Vishal Deepak Rukhana And Ami Vishal Rukhana",
"ownerPhoneNo": "9820110026",
"appAddress": "Flat no. 001, Ground Floor, Building no. B/3, Lok Nisarg CHS, Mulund
West ",
"remark": "Documents Confirm With Binu Sir",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669f98e0c474b30d54cc1ff8/document_1721735318721_1721735213
166_PNB_Mulund_West_Vishal_Rukhana.pdf",
    "fileName": "document_1721735318721_1721735213166_PNB_Mulund_West_Vish
al_Rukhana.pdf",
    "id": "168191",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Tue Jul 23 2024 17:19:52 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010115",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "991909",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Tue Jul 23 2024 17:19:52 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Vishal Deepak Rukhana And Ami Vishal Rukhana",
"phone": "9820110026",
"ownershipShare": "",
"email": "",
"id": "676751"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a2955ed45eb4344309de38",
"name": "externallmg_1721931101338_1721930990180_image_0.jpeg",
"path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931101338_1721930990180_image_0.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a2955ed45eb4344309de39",
"name": "externallmg_1721931101607_1721930990180_image_1.jpeg",
"path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931101607_1721930990180_image_1.jpeg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "66a2955ed45eb4344309de3a",
"name": "externallmg_1721931101910_1721930990180_image_2.jpeg",
"path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931101910_1721930990180_image_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a2955ed45eb4344309de3b",
    "name": "externallmg_1721931102273_1721930990180_image_3.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931102273_1721930990180_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a29589197cde340b3f26f1",
    "name": "externallmg_1721931138092_1721931033382_image_0.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931138092_1721931033382_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a29589197cde340b3f26f2",
    "name": "externallmg_1721931138678_1721931033382_image_1.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931138678_1721931033382_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a29589197cde340b3f26f3",
    "name": "externallmg_1721931139278_1721931033382_image_2.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931139278_1721931033382_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a29589197cde340b3f26f4",
    "name": "externallmg_1721931140222_1721931033382_image_3.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931140222_1721931033382_image_3.jpeg",
    "orientation": "portrait"
  }
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a29589197cde340b3f26f5",
      "name": "externallmg_1721931140478_1721931033382_image_4.jpeg",
      "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931140478_1721931033382_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a29589197cde340b3f26f6",
      "name": "externallmg_1721931141110_1721931033382_image_5.jpeg",
      "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931141110_1721931033382_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a29589197cde340b3f26f7",
      "name": "externallmg_1721931141327_1721931033382_image_6.jpeg",
      "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931141327_1721931033382_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a29589197cde340b3f26f8",
      "name": "externallmg_1721931141836_1721931033382_image_7.jpeg",
      "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931141836_1721931033382_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a29589197cde340b3f26f9",
      "name": "externallmg_1721931142477_1721931033382_image_8.jpeg",
      "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931142477_1721931033382_image_8.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a29589197cde340b3f26fa",
  "name": "externallmg_1721931142864_1721931033382_image_9.jpeg",
  "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931142864_1721931033382_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a29589197cde340b3f26fb",
  "name": "externallmg_1721931143237_1721931033382_image_10.jpeg",
  "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931143237_1721931033382_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a29589197cde340b3f26fc",
  "name": "externallmg_1721931143614_1721931033382_image_11.jpeg",
  "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931143614_1721931033382_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a29589197cde340b3f26fd",
  "name": "externallmg_1721931143911_1721931033382_image_12.jpeg",
  "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931143911_1721931033382_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a29589197cde340b3f26fe",
  "name": "externallmg_1721931144352_1721931033382_image_13.jpeg",
  "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931144352_1721931033382_image_13.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de6a",
    "name": "externallmg_1721931174111_1721931067573_image_0.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931174111_1721931067573_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de6b",
    "name": "externallmg_1721931174371_1721931067573_image_1.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931174371_1721931067573_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de6c",
    "name": "externallmg_1721931174837_1721931067573_image_2.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931174837_1721931067573_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de6d",
    "name": "externallmg_1721931175263_1721931067573_image_3.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931175263_1721931067573_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de6e",
    "name": "externallmg_1721931175526_1721931067573_image_4.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externallmg_1721931175526_1721931067573_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66a295aad45eb4344309de6f",
    "name": "externalimg_1721931175955_1721931067573_image_5.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externalimg_1721931175955_1721931067573_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de70",
    "name": "externalimg_1721931176932_1721931067573_image_6.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externalimg_1721931176932_1721931067573_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de71",
    "name": "externalimg_1721931177485_1721931067573_image_7.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externalimg_1721931177485_1721931067573_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a295aad45eb4344309de72",
    "name": "externalimg_1721931177741_1721931067573_image_8.jpeg",
    "path": "cases/669f98e0c474b30d54cc1ff8/
externalimg_1721931177741_1721931067573_image_8.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-23T11:49:52.860Z",
"updatedAt": "2024-07-25T18:12:58.461Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. 001, Ground Floor, Building No B3, Lok Nisarga
CHSL, Bal rajeshwar Road, Vaishali Nagar , Village - Mulund, Mulund West, Mumbai,
400080, State - Maharashtra, India",
"updatedBy": "648fcad91b499c2d52dc86f3",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Vishal Deepak Rukhana And Ami Vishal Rukhana",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820110026"
```

Name	Length	Width	Total
Composition :			
Other Composition :			