

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "firstName": "Reshma",
    "type": "CREDITOFFICER",
    "_id": "66488ee66f40574290c1d472",
    "lastName": "Kulkarni",
    "mobileNo": "",
    "workMobileNo": "8591096604",
    "email": "1thane@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Reshma",
    "expectedFees": null,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.334273526970104",
  "longitude": "73.17762816024063"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.17762816024063,
    19.334273526970104
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/07/2024 06:35 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "20000",
  "lumpsumValue": "1",
  "rateMax": "21000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Manpada",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kothari Warehouse No 3 Premises CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S V Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Chitalsar Manpada",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Kothari Estate ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B/2/4",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Thane West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed RCC SLab",
    "value": "Proposed_RCC_SLab"
  },
  "flooring": {
    "label": "Vitrified tile flooring",
    "value": "Vitrified_tile_flooring"
  },
  "doors": {
    "label": "MS Rolling Shutter",
    "value": "MS_Rolling_Shutter"
  },
  "windows": {
    "label": "M.S. Grill Fixed Windows",
    "value": "M.S._Grill_Fixed_Windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
}
```

```
"finishing": {
  "label": "Normal",
  "value": "Normal"
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Thane Municipal Corporation",
    "value": "Thane_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "gala no B/2/3",
    "west": "gala no B/2/6",
    "south": "road",
    "east": "gala no B/2/2"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    },
    "asPerDocument": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Commercial use",
    "value": "Commercial_use"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonry",
    "value": "6\"_Thk._Brick_Masonry"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
}
```

```
"pavementLaid": {
  "label": "No",
  "value": "No"
},
"carParking": {
  "label": "Open Parking",
  "value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "Load-bearing structure",
  "value": "Load-bearing_structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
}
```

```
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "1",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```



```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
}
},
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```

```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669fa98e6e8f430d9508e4c4",
"ownerName": "Mangal Tukaram Parbakar ",
"ownerPhoneNo": "9870314938",
"appAddress": "Godown no. B-2/4, Kothari Warehouse no. 3 Premises CHS, Chitalisar,
Manpada Thane ",
"remark": "Urgent Visit Tomorrow & Required Soft copy Tomorrow ",
"documents": [
  {
    "documentType": {
```

```
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/669fa98e6e8f430d9508e4c4/document_1721739696822_57388.pdf",
  "fileName": "document_1721739696822_57388.pdf",
  "id": "256473",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
  "createdAt": "Tue Jul 23 2024 18:31:42 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010118",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "249029",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 23 2024 18:31:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mangal Tukaram Parbakar ",
    "phone": "9870314938",
    "ownershipShare": "",
    "email": "",
    "id": "224449"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    }
  },
  "_id": "66a0d15720bf0172211bf355",
  "area": "2364",
  "providedByName": "Mangal Tukaram Parbakar ",
  "providedByContactNo": "9870314938"
```

```
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "630856",
    "name": "Unit Area",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf5822d",
    "name": "externalImg_1721815576565_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalImg_1721815576565_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf5822e",
    "name": "externalImg_1721815581697_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalImg_1721815581697_image.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0d24d935bbf721bf5822f",
  "name": "externallmg_1721815584792_image.jpeg",
  "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815584792_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0d24d935bbf721bf58230",
  "name": "externallmg_1721815585701_image.jpeg",
  "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815585701_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0d24d935bbf721bf58231",
  "name": "externallmg_1721815585926_image.jpeg",
  "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815585926_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0d24d935bbf721bf58232",
  "name": "externallmg_1721815589346_image.jpeg",
  "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815589346_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a0d24d935bbf721bf58233",
  "name": "externallmg_1721815591146_image.jpeg",
  "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815591146_image.jpeg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf58234",
    "name": "externallmg_1721815595440_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815595440_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf58235",
    "name": "externallmg_1721815597660_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815597660_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf58236",
    "name": "externallmg_1721815599661_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815599661_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf58237",
    "name": "externallmg_1721815604730_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815604730_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf58238",
    "name": "externallmg_1721815607190_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externallmg_1721815607190_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "66a0d24d935bbf721bf58239",
    "name": "externalimg_1721815610845_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalimg_1721815610845_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf5823a",
    "name": "externalimg_1721815613315_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalimg_1721815613315_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf5823b",
    "name": "externalimg_1721815616036_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalimg_1721815616036_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf5823c",
    "name": "externalimg_1721815619601_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalimg_1721815619601_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a0d24d935bbf721bf5823d",
    "name": "externalimg_1721815623695_image.jpeg",
    "path": "cases/669fa98e6e8f430d9508e4c4/
externalimg_1721815623695_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
```

```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-23T13:01:02.562Z",
"updatedAt": "2024-07-24T10:07:47.219Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "65829f7c65d49d78457ec7be",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Shop No. B/2/4, Ground Floor, Kothari Warehouse No 3
Premises CHSL, Kothari Estate , S V Road, Chitalsar Manpada, Village - Manpada,
Thane West, Thane",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mangal Tukaram Parbakar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9870314938",
"briefDescOfProperty": "Unit Area",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Unit Area	1'00"	1'00"	1.00
Other Composition :			