

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Rajesh",
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmecbhy@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 3000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "_id": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg",
  "firstName": "Nitesh",
  "lastName": "Khedekar",
  "shortName": "NK",
  "email": "nitesh.khedekar@vastukala.org",
  "designation": "",
  "mobileNo": "8369040652",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.390410717055698",
  "longitude": "72.82731523491485"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.82731523491485,
19.390410717055698
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "25/07/2024 04:16 pm"
    },
    {
      "dateTime": "25/07/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-26",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-26",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Diwanman",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "13",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "6",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Blossom",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```



```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "124, Hissa No. 6 & 12, Survey No. 125, Hissa No. 7A & 7B (Old S. No. 7)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```

```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 401 202",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  }
}
```

```
},
"finishing": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - B (Under Construction Building)",
    "west": "Complex Road",
    "south": "Jasmine Building (Under Construction Building)",
    "east": "Wing - C & Open Plot"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Marginal Space",
      "south": "Flat No. 1302",
      "west": "Lobby & Staircase"
    }
  },
}
```

```
"asPerDocument": {
  "north": "Marginal Space",
  "east": "Marginal Space",
  "south": "Flat No. 1302",
  "west": "Lobby & Staircase"
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Plan Document No. VVCMC / TP /
CC / VP / 0104 / 506 / 2021 - 22 dated 04.01.2022 issued by Vasai Virar City Municipal
Corporation",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
```

```
"propertyName": "Residential ",
"rate": "57300.00",
"landRate": "14000.00",
"igrImage": "cases/66a22b988b202f344c30dd5d/igr_1721996542246_Image.png",
"squareMeterGuideLineRate": "63030.00",
"squareFeetGuideLineRate": "5856.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "57300.00",
  "squareMeterGuideLineRate": "63030.00",
  "squareFeetGuideLineRate": "5856.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "19,500/- Expected rental income per month after completion",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
```

```
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonry"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Stilt + Open Car Parking",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2027",
    "fullDate": "1/1/2027"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
    "value": "UnderConstruction",
```

```
"label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
```



```
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "",
"totalLifeBuilding": "",
"estimatedAge": "",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "13",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "660.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66a22b988b202f344c30dd5d/
routeMap_1722059355936_Image.png",
    "routeLat": "19.375411",
    "routeLng": "72.815743",
    "stationName": "Vasai Road",
    "routeDistance": "3.0 Km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
```

```
0
],
"type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "4y2j1e",
    "name": "4y2j1e",
    "image": "cases/66a22b988b202f344c30dd5d/
routeMap_1722059313146_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
```

```
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "7800000.00",
"finalValue": "7800000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jul 29 2024 18:15:50 GMT+0530 (India Standard Time)",
  "number": "2307485",
  "dayCount": "30",
  "monthCount": "489",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "16",
    "percentage": "35.55555555555556",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "14",
  "percentage": "5.44",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "14",
  "percentage": "5.44",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "8",
  "percentage": "1.56",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "7",
  "percentage": "1.36",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "59.36",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "3864960.00",
  "selectedBuildUpValue": "660.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66a392398b202f344c3181e1",
      "name":
"externallmg_1721995833016_WhatsApp_Image_20240726_at_162209_2.jpeg",
      "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833016_WhatsApp_Image_20240726_at_162209_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66a39248d45eb434430a50d3",
      "name":
"externallmg_1721995848649_WhatsApp_Image_20240726_at_162221.jpeg",
      "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848649_WhatsApp_Image_20240726_at_162221.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66a392398b202f344c3181e4",
      "name":
"externallmg_1721995833043_WhatsApp_Image_20240726_at_162212.jpeg",
      "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833043_WhatsApp_Image_20240726_at_162212.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "66a392398b202f344c3181df",
  "name":
"externallmg_1721995832995_WhatsApp_Image_20240726_at_162208.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995832995_WhatsApp_Image_20240726_at_162208.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66a392398b202f344c3181e0",
  "name":
"externallmg_1721995833008_WhatsApp_Image_20240726_at_162209_1.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833008_WhatsApp_Image_20240726_at_162209_1.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66a392398b202f344c3181e5",
    "name": "Living Room",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833048_WhatsApp_Image_20240726_at_162213_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a39248d45eb434430a50c8",
    "name": "Living Room",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848596_WhatsApp_Image_20240726_at_162213.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66a39248d45eb434430a50c9",
    "name": "Living Room",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848602_WhatsApp_Image_20240726_at_162216_1.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "status": false,
  "_id": "66a39248d45eb434430a50ca",
  "name": "Living Room",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848607_WhatsApp_Image_20240726_at_162216.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66a39248d45eb434430a50cc",
  "name": "Living Room",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848617_WhatsApp_Image_20240726_at_162217.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66a39248d45eb434430a50cd",
  "name": "Living Room",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848622_WhatsApp_Image_20240726_at_162219.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66a39248d45eb434430a50ce",
  "name": "Living Room",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848626_WhatsApp_Image_20240726_at_162220_1.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66a39248d45eb434430a50d0",
  "name": "Living Room",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848637_WhatsApp_Image_20240726_at_162220.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10245.00",
    "max": "14767.00"
  }
}
```



```
    },
    "builtUpRateRange": {
      "min": "9314.00",
      "max": "13425.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "600.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a22b988b202f344c30dd5d",
"ownerName": "Ms. Sheryl Gabriel Jathanna & Mr. Gabriel S. Jathanna",
"ownerPhoneNo": "9764581323",
"appAddress": "FLAT NO 1301 A WING BLOSSOM VILLAGE DIWANMAN VASAI
WEST PALGHAR 401202",
"remark": "FMV 60 LAKH REQUIRED \nAny query contact Ashish bhabad
```

```
7709815152\nGabrial jathana 9820473518",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "27/05/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Manav Builders & Developers",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Ms. Sheryl Gabriel Jathanna & Mr. Gabriel S. Jathanna",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "6980/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "542206",
    "path": "cases/66a22b988b202f344c30dd5d/document_1721903879771_17219037
76103_SHERYL_JATHANNA_AGREEMENT.pdf",
    "fileName": "document_1721903879771_1721903776103_SHERYL_JATHANNA_A
GREEMENT.pdf"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "22/09/2023",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "P99000052740"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1722061228308_P99000052740.pdf",
"path": "cases/66a22b988b202f344c30dd5d/
document_1722061228308_P99000052740.pdf",
"id": "564846",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Sat Jul 27 2024 11:50:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/01/2022",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "VVCMC / TP / CC / VP - 0104 / 506 / 2021 - 22"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1722061301971_cc.pdf",
  "path": "cases/66a22b988b202f344c30dd5d/document_1722061301971_cc.pdf",
  "id": "604497",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Sat Jul 27 2024 11:51:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "04/01/2022",
    "nameOfApprovingAuthority": {
```

```
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "VVCMC / TP / CC / VP - 0104 / 506 / 2021 - 22"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1722061340528_Plan.pdf",
"path": "cases/66a22b988b202f344c30dd5d/document_1722061340528_Plan.pdf",
"id": "870214",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Sat Jul 27 2024 11:52:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010164",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "259321",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jul 25 2024 16:10:24 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms. Sheryl Gabriel Jathanna & Mr. Gabriel S. Jathanna",
    "phone": "9764581323",
    "ownershipShare": "",
    "email": "",
    "id": "245891"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  "id": "949397",
```

```
"name": "Living Room",
"length": "17.17",
"length1": "17",
"length2": "2",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "154.50",
"images": [],
"extraAreas": [],
"finalArea": "154.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "7.92",
  "length1": "7",
  "length2": "11",
  "width": "2.67",
  "width1": "2",
  "width2": "8",
  "totalArea": "21.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "66.06",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "66.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "4.08",
  "length1": "4",
  "length2": "1",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "27.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "10.58",
  "length1": "10",
  "length2": "7",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "33.51",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.51"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "2.58",
```



```
"length1": "2",
"length2": "7",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "5.17",
"images": [],
"extraAreas": [],
"finalArea": "5.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "85.45",
  "images": [],
  "extraAreas": [],
  "finalArea": "85.45"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.75"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Bedroom",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "97.34",
  "images": [],
  "extraAreas": [],
  "finalArea": "97.34"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "26.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.67"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Balcony Area",
      "value": "Balcony_Area"
    }
  }
]
```

```
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "0",
"length": "5.00",
"length1": "5",
"length2": "00",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "45.00",
"images": [],
"extraAreas": [],
"finalArea": "45",
"percentageBeforeTotal": "45.00",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "6.67",
  "width1": "6",
  "width2": "8",
  "totalArea": "13.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.89",
  "percentageBeforeTotal": "13.89",
  "percentage": "100"
},
```

```
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "8.67",
  "width1": "8",
  "width2": "8",
  "totalArea": "18.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.06",
  "percentageBeforeTotal": "18.06",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length": "5.75",
  "length1": "5",
  "length2": "9",
  "width": "1.92",
  "width1": "1",
```

```
"width2": "11",
"totalArea": "11.02",
"images": [],
"extraAreas": [],
"finalArea": "11.02",
"percentageBeforeTotal": "11.02",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowered Area",
    "value": "Flowered_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "17.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.5",
  "percentageBeforeTotal": "17.50",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
"selectAreaTypeDocument": "Carpet",
"squareMeterArea": "55.74",
"totalAreaDocument": "600.00",
"docBuiltpUpPercentage": "10",
"docFinalBuiltpUp": "660.00",
"docFinalBuiltpUpSquareMeter": "61.32",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "589266"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "386.00",
"squareMeterArea": "35.86",
"expectedRate": "14766.84",
"percentage": ""
},
"builtUpArea": {
"area": "424.60",
"squareMeterArea": "39.45",
"expectedRate": "13424.40",
"percentage": "10"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
},
"printlnReport": true,
"_id": "66a39595bc6e5d340a0b2cd5",
"property": "Blossom 6A Village Diwanman, Chulna Bhabola Road, Vasai West",
"area": "386.00",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "5700000.00",
"expectedRate": "14766.84",
```

```
"builtUpExpectedRate": "13424.40",
"image": "cases/66a22b988b202f344c30dd5d/
indicator_1721995825908_Image.png",
"squareMeter": "35.86",
"id": "615952"
},
{
"carpetArea": {
"area": "430.00",
"squareMeterArea": "39.95",
"expectedRate": "13953.49",
"percentage": ""
},
"builtUpArea": {
"area": "473.00",
"squareMeterArea": "43.94",
"expectedRate": "12684.99",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "66a39595bc6e5d340a0b2cd6",
"property": "Manav Blossom 6A Near Jhaveri Complex, Bhabola Chulna Road,
Vasai West, Palghar ",
"area": "430.00",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "6000000.00",
"expectedRate": "13953.49",
"builtUpExpectedRate": "12684.99",
"image": "cases/66a22b988b202f344c30dd5d/
indicator_1721995876820_Image.png",
"squareMeter": "39.95",
"id": "338687"
},
{
"carpetArea": {
```

```
"area": "639.81",
"squareMeterArea": "59.44",
"expectedRate": "14535.57",
"percentage": ""
},
"builtUpArea": {
"area": "703.79",
"squareMeterArea": "65.38",
"expectedRate": "13214.17",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66a39595bc6e5d340a0b2cd7",
"property": "Blossom 6A Village Diwanman, Chulna Bhabola Road, Vasai West",
"area": "639.81",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "9300000.00",
"expectedRate": "14535.57",
"builtUpExpectedRate": "13214.17",
"image": "cases/66a22b988b202f344c30dd5d/
indicator_1721995926612_Image.png",
"squareMeter": "59.44",
"id": "752351"
},
{
"carpetArea": {
"area": "585.66",
"squareMeterArea": "54.41",
"expectedRate": "10244.85",
"percentage": ""
},
"builtUpArea": {
"area": "644.23",
"squareMeterArea": "59.85",
"expectedRate": "9313.44",
```



```
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66a39595bc6e5d340a0b2cd8",
  "property": "Blossom 6A Village Diwanman, Chulna Bhabola Road, Vasai West",
  "area": "585.66",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "6000000.00",
  "expectedRate": "10244.85",
  "builtUpExpectedRate": "9313.44",
  "image": "cases/66a22b988b202f344c30dd5d/
indicator_1721996357270_Image.png",
  "squareMeter": "54.41",
  "id": "327122"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181dc",
    "name":
"externallmg_1721995832974_WhatsApp_Image_20240726_at_162205.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995832974_WhatsApp_Image_20240726_at_162205.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181dd",
    "name":
"externallmg_1721995832980_WhatsApp_Image_20240726_at_162206_1.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995832980_WhatsApp_Image_20240726_at_162206_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181de",
    "name":
"externallmg_1721995832987_WhatsApp_Image_20240726_at_162206.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995832987_WhatsApp_Image_20240726_at_162206.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181df",
    "name":
"externallmg_1721995832995_WhatsApp_Image_20240726_at_162208.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995832995_WhatsApp_Image_20240726_at_162208.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181e0",
    "name":
"externallmg_1721995833008_WhatsApp_Image_20240726_at_162209_1.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833008_WhatsApp_Image_20240726_at_162209_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181e1",
    "name":
"externallmg_1721995833016_WhatsApp_Image_20240726_at_162209_2.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833016_WhatsApp_Image_20240726_at_162209_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a392398b202f344c3181e2",
```

```
    "name":
"externallmg_1721995833024_WhatsApp_Image_20240726_at_162209.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833024_WhatsApp_Image_20240726_at_162209.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a392398b202f344c3181e3",
  "name":
"externallmg_1721995833033_WhatsApp_Image_20240726_at_162212_1.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833033_WhatsApp_Image_20240726_at_162212_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a392398b202f344c3181e4",
  "name":
"externallmg_1721995833043_WhatsApp_Image_20240726_at_162212.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833043_WhatsApp_Image_20240726_at_162212.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a392398b202f344c3181e5",
  "name":
"externallmg_1721995833048_WhatsApp_Image_20240726_at_162213_1.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995833048_WhatsApp_Image_20240726_at_162213_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50c8",
  "name":
"externallmg_1721995848596_WhatsApp_Image_20240726_at_162213.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848596_WhatsApp_Image_20240726_at_162213.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50c9",
  "name":
"externallmg_1721995848602_WhatsApp_Image_20240726_at_162216_1.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848602_WhatsApp_Image_20240726_at_162216_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50ca",
  "name":
"externallmg_1721995848607_WhatsApp_Image_20240726_at_162216.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848607_WhatsApp_Image_20240726_at_162216.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50cb",
  "name":
"externallmg_1721995848613_WhatsApp_Image_20240726_at_162217_1.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848613_WhatsApp_Image_20240726_at_162217_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50cc",
  "name":
"externallmg_1721995848617_WhatsApp_Image_20240726_at_162217.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848617_WhatsApp_Image_20240726_at_162217.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50cd",
  "name":
"externallmg_1721995848622_WhatsApp_Image_20240726_at_162219.jpeg",
```

```
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848622_WhatsApp_Image_20240726_at_162219.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50ce",
    "name":
"externallmg_1721995848626_WhatsApp_Image_20240726_at_162220_1.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848626_WhatsApp_Image_20240726_at_162220_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50cf",
    "name":
"externallmg_1721995848630_WhatsApp_Image_20240726_at_162220_2.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848630_WhatsApp_Image_20240726_at_162220_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50d0",
    "name":
"externallmg_1721995848637_WhatsApp_Image_20240726_at_162220.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848637_WhatsApp_Image_20240726_at_162220.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50d1",
    "name":
"externallmg_1721995848641_WhatsApp_Image_20240726_at_162221_1.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848641_WhatsApp_Image_20240726_at_162221_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a39248d45eb434430a50d2",
  "name":
"externallmg_1721995848645_WhatsApp_Image_20240726_at_162221_2.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848645_WhatsApp_Image_20240726_at_162221_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50d3",
  "name":
"externallmg_1721995848649_WhatsApp_Image_20240726_at_162221.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848649_WhatsApp_Image_20240726_at_162221.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50d4",
  "name":
"externallmg_1721995848651_WhatsApp_Image_20240726_at_162222_1.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848651_WhatsApp_Image_20240726_at_162222_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50d5",
  "name":
"externallmg_1721995848654_WhatsApp_Image_20240726_at_162222_2.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848654_WhatsApp_Image_20240726_at_162222_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a39248d45eb434430a50d6",
  "name":
"externallmg_1721995848657_WhatsApp_Image_20240726_at_162222.jpeg",
  "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848657_WhatsApp_Image_20240726_at_162222.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50d7",
    "name":
    "externallmg_1721995848659_WhatsApp_Image_20240726_at_162223_1.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848659_WhatsApp_Image_20240726_at_162223_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50d8",
    "name":
    "externallmg_1721995848665_WhatsApp_Image_20240726_at_162223_2.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848665_WhatsApp_Image_20240726_at_162223_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a39248d45eb434430a50d9",
    "name":
    "externallmg_1721995848669_WhatsApp_Image_20240726_at_162223.jpeg",
    "path": "cases/66a22b988b202f344c30dd5d/
externallmg_1721995848669_WhatsApp_Image_20240726_at_162223.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "10164.xlsx",
    "filename": "1722062498262_10164.xlsx",
    "path": "cases/66a22b988b202f344c30dd5d/
processingDocuments/1722062498262_10164.xlsx",
    "size": "9033",
    "createdAt": "Sat Jul 27 2024 12:11:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "cc.pdf",
```

```
    "filename": "1722062498264_cc.pdf",
    "path": "cases/66a22b988b202f344c30dd5d/
processingDocuments/1722062498264_cc.pdf",
    "size": "982271",
    "createdAt": "Sat Jul 27 2024 12:11:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "Maharashtra Real Estate Regulatory Authority.pdf",
    "filename": "1722062499024_Maharashtra_Real_Estate_Regulatory_Authority.pdf",
    "path": "cases/66a22b988b202f344c30dd5d/processingDocuments/1722062499024
_Maharashtra_Real_Estate_Regulatory_Authority.pdf",
    "size": "2742021",
    "createdAt": "Sat Jul 27 2024 12:11:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "P99000052740.pdf",
    "filename": "1722062500725_P99000052740.pdf",
    "path": "cases/66a22b988b202f344c30dd5d/
processingDocuments/1722062500725_P99000052740.pdf",
    "size": "710767",
    "createdAt": "Sat Jul 27 2024 12:11:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  },
  {
    "originalname": "Plan.pdf",
    "filename": "1722062500950_Plan.pdf",
    "path": "cases/66a22b988b202f344c30dd5d/
processingDocuments/1722062500950_Plan.pdf",
    "size": "1441422",
    "createdAt": "Sat Jul 27 2024 12:11:41 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdcf2",
      "role": "ADMIN",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
profilePhoto_1622372166238_Jagdish Photo (2).jpg"
```



```
},
"workType": "SITE_INSPECTION",
"display": true,
"status": true,
"_id": "66a3918abc6e5d340a0b2927",
"note": "wrong Photos (Task Reopen)",
"taskId": "66a22d7b197cde340b3ee0b3",
"createdAt": "2024-07-26T12:07:38.519Z"
},
{
  "createdBy": {
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Nitesh",
    "lastName": "Khedekar",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66a3950dbc6e5d340a0b2c4d",
  "note": "done ",
  "taskId": "66a22d7b197cde340b3ee0ac",
  "createdAt": "2024-07-26T12:22:37.087Z"
},
{
  "createdBy": {
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Nitesh",
    "lastName": "Khedekar",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66a39532197cde340b3fc7d2",
  "note": "done ",
  "taskId": "66a22d7b197cde340b3ee0ac",
  "createdAt": "2024-07-26T12:23:14.835Z"
},
{
  "createdBy": {
    "_id": "60092304a16fab0f2af9b0c2",
```

```
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "firstName": "Nitesh",
    "lastName": "Khedekar",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66a395428b202f344c31840f",
  "note": "done ",
  "taskId": "66a22d7b197cde340b3ee0ac",
  "createdAt": "2024-07-26T12:23:30.161Z"
}
],
"createdAt": "2024-07-25T10:40:24.174Z",
"updatedAt": "2024-07-29T12:46:38.791Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1301, 13th Floor, Building No 6, Wing - A,
Blossom, Village - Diwanman, Vasai (West), Taluka - Vasai, District - Palghar, PIN Code
- 401 202, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Rohan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "7083578132",
"buildingServicesRate": "3000.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 600.00",
"flatRate": "13000.00",
"landOtherRate": "10000",
```

```
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet + 3
Passage",
"carpetTotal": "530.12",
"otherCarpetTotal": "60.47",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "699.15",
"finalCarpetArea": "635.59",
"finalSalableArea": "769.06",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 530.00\nCupboard Area in Sq.
Ft. = 11.00\nDry Balcony Area in Sq. Ft. = 14.00\nBalcony Area in Sq. Ft. =
45.00\nFlowerbed Area in Sq. Ft. = 36.00\nTotal Carpet Area in Sq. Ft. = 636.00\n(Area
as per Actual Site Measurement)",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "105.47",
"otherCompositionSaleableTotal": "0.00",
"reportGeneratedDate": "Mon Jul 29 2024 11:44:14 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-07-26"
}
```

Name	Length	Width	Total
Composition :			
Living Room	17'2"	9'00"	154.50
Dining	7'11"	2'8"	21.11
Kitchen	6'10"	9'8"	66.06
Toilet	4'1"	6'9"	27.56
Passage	10'7"	3'2"	33.51
Passage	2'7"	2'00"	5.17
Bedroom	8'11"	9'7"	85.45
Passage	4'3"	3'00"	12.75
Bedroom	8'11"	10'11"	97.34
Toilet	4'00"	6'8"	26.67
Other Composition :			
Balcony Area	5'00"	9'00"	45.00
Dry Balcony	2'1"	6'8"	13.89
Flowered Area	2'1"	8'8"	18.06
Cupboard	5'9"	1'11"	11.02
Flowered Area	2'00"	8'9"	17.50